

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA3560E

DATE: 7. Nov. 2018

MAKE : HYUNDAI

DOA: 5. Nov. 2018

QBE

MODEL : i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Rear Bumper <i>detached</i>			\$553.00
10	Rear Bumper Clips <i>new</i>		\$2.20	\$22.00
SUB TOTAL				\$575.00
LESS 20% <i>20%</i>				\$115.00
DISCOUNTED TOTAL				\$460.00
1	Rear Bumper Rubber Mat <i>(metal type) new</i>			\$50.00
Labour Charge				
Panel Beating				\$250.00 <i>20%</i>
Spray Painting Charge				\$250.00 <i>20%</i>
Remove/refix reverse sensor				\$100.00 <i>20%</i>
TOTAL LABOUR				\$600.00
ESTIMATE TOTAL				\$1,110.00
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor surveyor appointed by the insurance company. <i>Kalvi (Mck)</i> <i>7/11/18 Bosh</i> <i>2 Pys</i> <i>P/P</i> <i>Before Part photo</i> <i>Larry Ng</i> LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis Supplementary repair costs are surveyed and approved by the insurance company. Acknowledged by Repairer Signature: Date:				

Nett