

ASS. REC. BY:

REF:

CS/SPF18020194/Gtbez

Special Instruction:

Surveyor:

GQ

ASSIGNMENT (Office)

From (Person):

Chay Kim Pang

of

SPF

Date/Time:

08/12/08

1109am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

TP 1077B

Insured:

at Workshop m/s

Indeco Engineers

Tel:

of

39 Defu Lane 12

Policy No:

Claim No:

HOMSPFETA/7300218

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

TP 1077B - X

20/11/08

P.4/pa revised to Kim Pang by email.

Submit report inform by Kim Pang

Signature

Khal

REF: SPF

ASSIGNMENT

From: Date: 08/12/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: TP 1077B

at Workshop m/s

Indeo Engineers

of

39 Debu Lane 12

Insured:

Mignon Hakim
62816520

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: TP1077B Yr Regn: - /

Type: M.Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha XJ900P C.C. -

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 4471 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: -

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120 / 70 8R17

R: 150 / 70 8R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

METZELER

Front

Rear

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. 4 mm L/Bal. 4 mm

D.O.I. 09-11-18

Survey held at Ban Hock Hin 9AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

15/11

Total 30 Hrs. Finalized with Hakim

Parts: 12,054.30

man hour - 30

RECEIVED 15 JAN 2019

Date/Time, File Pass to?

14/11 Typist

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$)

☐ : Preli. Report
☒ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee: 200

Transportation: \$ + RS. \$

Photos

Others

TOTAL

200

Catherine Chong (LKK Auto)

From: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>
Sent: Thursday, 8 November, 2018 11:09 AM
To: assignments
Cc: Perry HE (SPF); Wei Yea LIM (SPF); Kwee Huat TAN (SPF); Ai Phing (LKKAuto); Shiau Chan (LKKAuto); Veron Chen (LKKAuto); Janice Lee (LKKAuto)
Subject: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ17300218 - TP1077B

Hi Catherine and Ashley,

Please provide Appraisal Service (Parts and Labour-man hours) for the following SPF vehicle at INDECO.

Vehicle No: TP1077B

Make& Model : YAMAHA XJ900P (M)

Parts:

S/N	PARTS DESCRIPTION	Quantity
1.1	BOLT STUD	
1.2	BOLT STUD	
1.3	BOLT STUD	
1.4	BOLT STUD	
1.5	BOX SIDE RH	
1.6	BRACKET FOOTREST REAR RH	
1.7	BRACKET LED LIGHT (50 MM)	
1.8	COVER CYLINDER HEAD	
1.9	COVER LED LIGHT (FOR 4 LED)	
1.10	COWLING FRONT ASSY	
1.11	CRASH BAR FRONT	
1.12	CRASH BAR REAR LH	
1.13	CRASH BAR REAR RH	
1.14	EMBLEM (YAMAHA) COWLING FRONT	
1.15	GASKET (PIN DOWEL)	
1.16	GASKET CYLINDER BLOCK	
1.17	GASKET CYLINDER HEAD 1	
1.18	GASKET EXHAUST PIPE	
1.19	GASKET HEAD COVER	
1.20	GASKET TENSIONER	

1.21	HEAD CYLINDER ASSY	
1.22	LAMP SIGNAL FRONT RH	
1.23	LEVER BRAKE	
1.24	LIGHT LED (JL) 4 LED BLUE - CLEAR LENS	
1.25	LIGHT STROBE REAR - RED	
1.26	METER ASSY	
1.27	MID GASKET MUFFLER	
1.28	MID PIN DOWEL	
1.29	MIRROR RH	
1.30	O-RING CYLINDER HEAD (SIDE COVER)	
1.31	O-RING JOINT CARBURETOR	
1.32	PEDAL BRAKE	
1.33	PEDAL GEAR	
1.34	PIPE EXHAUST 3	
1.35	PIPE EXHAUST 4	
1.36	POLE REAR FOR BEACON LIGHT (FIXED)	
1.37	PROTECTOR RH (STK 23743) WITH SPRAY PAINTING POLICE LIVERY (LINING)	
1.38	RUBBER MOUNT	
1.39	RUBBER SEAL (SMALL)	
1.40	SCREW (VISOR)	
1.41	SEAL VALVE	
1.42	STICKER (TP) FRONT COWLING (POLICE)LH/RH - SUPPLY BY AEMD	
1.43	STUD	
1.44	T-JOINT	
1.45	VALVE EXHAUST	
1.46	VALVE INTAKE	

Labour:

S/N	LABOUR DESCRIPTION	Man-Hour Qty
1.1	REPLACE ITEM 1.1 TO 1.46	

Thank you.

Regards

Chay Kim Pang
Senior Contract Management Engineer (Vehicle Maintenance)
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4827



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



Scope Of Work
Home Team Agency

SCOPE OF WORK

1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR :	Indeco Engineers Pte Ltd	VEH TYPE :	UNIT :	TP	Reference No.
VEH NO :	TP1077B	MC	REPAIR TYPE:	ACCIDENT	MHA/SPF/2018/10-0038
VEH MAKE/MODEL	YAMAHA XJ900P	Mileage:	41471		1100013329

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1.1	BOLT STUD	15.00	2.00	20%	18.00	36.00
1.2	BOLT STUD	5.70	4.00	20%	6.84	27.36
1.3	BOLT STUD	5.70	4.00	20%	6.84	27.36
1.4	BOLT STUD	2.00	2.00	20%	2.40	4.80
1.5	BOX SIDE RH	1,800.00	1.00	20%	2160.00	2160.00
1.6	BRACKET FOOTREST REAR RH	70.00	1.00	20%	84.00	84.00
1.7	BRACKET LED LIGHT (50 MM)	15.00	1.00	20%	18.00	18.00
1.8	COVER CYLINDER HEAD	197.00	1.00	20%	236.40	236.40
1.9	COVER LED LIGHT (FOR 4 LED)	78.00	1.00	20%	93.60	93.60
1.10	COWLING FRONT ASSY	870.00	1.00	20%	1044.00	1044.00
1.11	CRASH BAR FRONT	550.00	1.00	20%	660.00	660.00
1.12	CRASH BAR REAR LH	144.00	1.00	20%	172.80	172.80
1.13	CRASH BAR REAR RH	144.00	1.00	20%	172.80	172.80
1.14	EMBLEM (YAMAHA) COWLING FRONT	8.00	1.00	20%	9.60	9.60
1.15	GASKET (PIN DOWEL)	5.00	2.00	20%	6.00	12.00
1.16	GASKET CYLINDER BLOCK	31.00	1.00	20%	37.20	37.20
1.17	GASKET CYLINDER HEAD I	63.00	1.00	20%	75.60	75.60
1.18	GASKET EXHAUST PIPE	5.00	2.00	20%	6.00	12.00
1.19	GASKET HEAD COVER	63.00	1.00	20%	75.60	75.60
1.20	GASKET TENSIONER	1.00	1.00	20%	1.20	1.20
1.21	HEAD CYLINDER ASSY	1,485.00	1.00	20%	1782.00	1782.00
1.22	LAMP SIGNAL FRONT RH	34.00	1.00	20%	40.80	40.80
1.23	LEVER BRAKE	22.00	1.00	20%	26.40	26.40
1.24	LIGHT LED (JL) 4 LED BLUE - CLEAR LENS	260.00	1.00	20%	312.00	312.00
1.25	LIGHT STROBE REAR - RED	1,708.00	1.00	20%	2049.60	2049.60
1.26	METER ASSY	690.00	1.00	20%	828.00	828.00
1.27	MID GASKET MUFFLER	16.00	2.00	20%	19.20	38.40
1.28	MID PIN DOWEL	3.10	1.00	20%	3.72	3.72
1.29	MIRROR RH	138.00	1.00	20%	165.60	165.60
1.30	O-RING CYLINDER HEAD (SIDE COVER)	4.70	4.00	20%	5.64	22.56
1.31	O-RING JOINT CARBURETOR	6.00	4.00	20%	7.20	28.80
1.32	PEDAL BRAKE	38.00	1.00	20%	45.60	45.60
1.33	PEDAL GEAR	44.00	1.00	20%	52.80	52.80
1.34	PIPE EXHAUST 3	122.00	1.00	20%	146.40	146.40
1.35	PIPE EXHAUST 4	122.00	1.00	20%	146.40	146.40
1.36	POLE REAR FOR BEACON LIGHT (FIXED)	255.00	1.00	20%	306.00	306.00
1.37	PROTECTOR RH (STK 23743) WITH SPRAY PAINTING POLICE LIVERY (LINING)	425.00	1.00	20%	510.00	510.00
1.38	RUBBER MOUNT	6.00	12.00	20%	7.20	86.40
1.39	RUBBER SEAL (SMALL)	0.35	11.00	20%	0.42	4.62
1.40	SCREW (VISOR)	3.00	2.00	20%	3.60	7.20
1.41	SEAL VALVE	7.00	8.00	20%	8.40	67.20
1.42	STICKER (TP) FRONT COWLING (POLICE) LH/RH - SUPPLY BY AEMD	0.00	2.00	20%	0.00	0.00
1.43	STUD	7.30	8.00	20%	8.76	70.08
1.44	T-JOINT	126.90	1.00	20%	152.28	152.28
1.45	VALVE EXHAUST	42.00	4.00	20%	50.40	201.60
1.46	VALVE INTAKE	38.00	4.00	20%	45.60	182.40
2	Additional Services					
2.1	PIN PISTON					
2.2	RING PISTON (STD)					
2.3	BALANCER HANDLE					
2.4	BOX SIDE LH					
2.5	COVER SIDE I LH					
2.6	FOOTREST FRONT LH					
2.7	FOOTREST FRONT RH					
Remarks:		SPARE PARTS SUBJECTED TO AVAILABILITY *Spare parts subjected to availability (By air/sea 30 days)			Parts Total:	\$ 12,237.18

12054.78




ACCIDENT/DAMAGE REPAIR AND AD HOC WORKS REQUEST FORM

ILMS Notification No	1100013329		
Vehicle No	TP10778	Division/Unit	TP
Vehicle Type (e.g. FRC, minibus)	minibus	Date	8/10/18
Vehicle Make & Model	Yamaha XT900	Mileage (km)	41471

Description	Pls tick	Police Report No & Date of Accident (if applicable)
NP168 (Accident involve 3 rd Party)	☒	NP168 T20180809/2025
NP168 (Accident do not involve 3 rd Party)	☐	
NP299 Discovered Damage	☐	
NP299 Vandalism	☐	
Ad hoc, pls specify	☐	

Description of affected area/required works (e.g. dented, cracked, grazed etc)

- 1) front right lower scratches 2) front right crashbar bent and scratches
 3) rear right crashbar bent and scratches 4) right rear corner scratches
 5) left front siren minor scratches 6) To check wheel alignment
- Pls mark affected area with X after repair



Rank/Name
 & I. *Ken A H Chan*

Signature
Ken

Siren
 minor
 scratches

Right front
 crashbar
 bent
 and
 scratches

Right
 rear
 crashbar
 bent and
 scratches

Right
 front
 corner
 scratches

Left
 front
 scratches

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 20 November 2018 4:41 PM
To: Kim Pang CHAY (SPF); assignments
Cc: Perry HE (SPF); Wei Yea LIM (SPF); Kwee Huat TAN (SPF); SUR
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ17300218 - TP1077B
Attachments: TP1077 photo.pdf; TP 1077B.xls

Dear Kim Pang,

Please find the attachment of TP 1077B.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>
Sent: Thursday, 8 November 2018 11:09 AM
To: assignments <assignments@lkkauto.com>
Cc: Perry HE (SPF) <Perry_HE@spf.gov.sg>; Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Ai Phing (LKKAUTO) <aiphing@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>
Subject: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ17300218 - TP1077B

Hi Catherine and Ashley,

Please provide Appraisal Service (Parts and Labour-man hours) for the following SPF vehicle at INDECO.

Vehicle No: TP1077B

Make& Model : YAMAHA XJ900P (M)

Parts:

S/N	PARTS DESCRIPTION	Quantity
1.1	BOLT STUD	
1.2	BOLT STUD	
1.3	BOLT STUD	
1.4	BOLT STUD	
1.5	BOX SIDE RH	
1.6	BRACKET FOOTREST REAR RH	
1.7	BRACKET LED LIGHT (50 MM)	
1.8	COVER CYLINDER HEAD	

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	BOLT STUD	2	NECESSARY	\$18.00	\$36.00	
1.2	BOLT STUD	4	NECESSARY	\$6.84	\$27.36	
1.3	BOLT STUD	4	NECESSARY	\$6.84	\$27.36	
1.4	BOLT STUD	2	NECESSARY	\$2.40	\$4.80	
1.5	BOX SIDE RH	1	CUT	\$2,160.00	\$2,160.00	
1.6	BRACKET FOOTREST REAR RH	1	BROKEN	\$84.00	\$84.00	
1.7	BRACKET LED LIGHT (50MM)	1	BENT	\$18.00	\$18.00	
1.8	COVER CYLINDER HEAD	1	CUT	\$236.40	\$236.40	
1.9	COVER LED LIGHT (FOR 4 LED)	1	CUT	\$93.60	\$93.60	
1.10	COWLING FRONT ASSY	1	CRACKED	\$1,044.00	\$1,044.00	
1.11	CRASH BAR FRONT	1	BENT	\$660.00	\$660.00	
1.12	CRASH BAR REAR LH	1	REPAIR	\$172.80		
1.13	CRASH BAR REAR RH	1	BROKEN	\$172.80	\$172.80	
1.14	EMBLEM (YAMAHA) COWLING FRONT	1	NOT NECESSARY	\$9.60		
1.15	GASKET (PIN DOWEL)	2	NECESSARY	\$6.00	\$12.00	
1.16	GASKET CYLINDER BLOCK	1	NECESSARY	\$37.20	\$37.20	
1.17	GASKET CYLINDER HEAD 1	1	NECESSARY	\$75.60	\$75.60	
1.18	GASKET EXHAUST PIPE	2	NECESSARY	\$6.00	\$12.00	
1.19	GASKET HEAD COVER	1	NECESSARY	\$75.60	\$75.60	
1.20	GASKET TENSIONER	1	NECESSARY	\$1.20	\$1.20	
1.21	HEAD CYLINDER ASSY	1	CRACKED	\$1,782.00	\$1,782.00	
1.22	LAMP SIGNAL FRONT RH	1	CUT	\$40.80	\$40.80	
1.23	LEVER BRAKE	1	CUT	\$26.40	\$26.40	
1.24	LIGHT LED (IL) 4 LED BLUE - CLEAR LENS	1	CUT	\$312.00	\$312.00	
1.25	LIGHT STROBE REAR - RED	1	SCRATCHED	\$2,049.60	\$2,049.60	
1.26	METER ASSY	1	CRACKED	\$828.00	\$828.00	
1.27	MID GASKET MUFFLER	2	NECESSARY	\$19.20	\$38.40	
1.28	MID PIN DOWEL	1	NECESSARY	\$3.72	\$3.72	
1.29	MIRROR RH	1	CUT	\$165.60	\$165.60	
1.3	O-RING CYLINDER HEAD (SIDE COVER)	4	NECESSARY	\$5.64	\$22.56	
1.31	O-RING JOINT CARBURETOR	4	NECESSARY	\$7.20	\$28.80	
1.32	PEDAL BRAKE	1	CUT	\$45.60	\$45.60	
1.33	PEDAL GEAR	1	SCRATCHED	\$52.80	\$52.80	
1.34	PIPE EXHAUST 3	1	BENT	\$146.40	\$146.40	
1.35	PIPE EXHAUST 4	1	BENT	\$146.40	\$146.40	
1.36	POLE REAR FOR BEACON LIGHT (FIXED)	1	BENT	\$306.00	\$306.00	
1.37	PROTECTOR RH (STK 23743) WITH SPRAY PAINTING POLICE LIVERY (LINING)	1	CUT	\$510.00	\$510.00	
1.38	RUBBER MOUNT	12	NECESSARY	\$7.20	\$86.40	
1.39	RUBBER SEAL (SMALL)	11	NECESSARY	\$0.42	\$4.62	
1.4	SCREW (VISOR)	2	NECESSARY	\$3.60	\$7.20	
1.41	SEAL VALVE	8	NECESSARY	\$8.40	\$67.20	
1.42	STICKER (TP) FRONT COWLING (POLICE) LH/RH - SUPPLY BY AEMD	2	NECESSARY	\$0.00	\$0.00	
1.43	STUD	8	NECESSARY	\$8.76	\$70.08	
1.44	T-JOINT	1	NECESSARY	\$152.28	\$152.28	
1.45	VALVE EXHAUST	4	NECESSARY	\$50.40	\$201.60	
1.46	VALVE INTAKE	4	NECESSARY	\$45.60	\$182.40	
2	ADDITIONAL SERVICES					
2.1	PIN PISTON		NECESSARY			
2.2	RING PISTON (STD)		NECESSARY			
2.3	BALANCER HANDLE		CUT			
2.4	BOX SIDE LH		CUT			
2.5	COVER SIDE LH		CUT			
2.6	FOOTREST FRONT LH		CUT			
2.7	FOOTREST FRONT RH		CUT			

1						28
1.1	REPLACE ITEM 1.1 TO 1.46					
2						2
2.1	TRANSPORT CHARGES (SOR 8) (BILL UNDER MONTH END SOR BILLING)					
COSTING		TOTAL PARTS COST			\$12,054.78	
		TOTAL MAN-HOUR				28

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF18020194/Gtbe2

CONTRACT MANAGEMENT SECTION
(SINGAPORE POLICE FORCE) 1 MOUNT
PLEASANT ROAD BLK 8 OLD POLICE ACADEMY
SINGAPORE 298333

Date : 17-01-2019



ATTN : CHAY KIM PANG

Code : SPF3

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	TP 1077B
Policy No.		Coverage (\$)	0.00
Claim No.	HOMSPFETQ17300218	Excess (\$)	0.00
Assign From	CHAY KIM PANG	Assign Date	08/11/2018

2. Vehicle Particulars & Condition

Make & Model	YAMAHA XJ900P	c.c	892
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	JYA4KM00000130900	Colour	WHITE
Odometer	41471	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	120/70Z R17	METZELER	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	150/70Z R17	METZELER	4 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date		Inspection Date	09/11/2018
Survey held at	INDECO ENGINEERS PTE LTD 39 DEFU LANE 12 . SINGAPORE 539139		

5a. Remarks

--



Registration No. TP 1077B

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	BOLT STUD	2	NECESSARY	\$18.00	\$36.00	
1.2	BOLT STUD	4	NECESSARY	\$6.84	\$27.36	
1.3	BOLT STUD	4	NECESSARY	\$6.84	\$27.36	
1.4	BOLT STUD	2	NECESSARY	\$2.40	\$4.80	
1.5	BOX SIDE RH	1	CUT	\$2,160.00	\$2,160.00	
1.6	BRACKET FOOTREST REAR RH	1	BROKEN	\$84.00	\$84.00	
1.7	BRACKET LED LIGHT (50MM)	1	BENT	\$18.00	\$18.00	
1.8	COVER CYLINDER HEAD	1	CUT	\$236.40	\$236.40	
1.9	COVER LED LIGHT (FOR 4 LED)	1	CUT	\$93.60	\$93.60	
1.10	COWLING FRONT ASSY	1	CRACKED	\$1,044.00	\$1,044.00	
1.11	CRASH BAR FRONT	1	BENT	\$660.00	\$660.00	
1.12	CRASH BAR REAR LH	1	REPAIR	\$172.80		
1.13	CRASH BAR REAR RH	1	BROKEN	\$172.80	\$172.80	
1.14	EMBLEM (YAMAHA) COWLING FRONT	1	NOT NECESSARY	\$9.60		
1.15	GASKET (PIN DOWEL)	2	NECESSARY	\$6.00	\$12.00	
1.16	GASKET CYLINDER BLOCK	1	NECESSARY	\$37.20	\$37.20	
1.17	GASKET CYLINDER HEAD 1	1	NECESSARY	\$75.60	\$75.60	
1.18	GASKET EXHAUST PIPE	2	NECESSARY	\$6.00	\$12.00	
1.19	GASKET HEAD COVER	1	NECESSARY	\$75.60	\$75.60	
1.20	GASKET TENSIONER	1	NECESSARY	\$1.20	\$1.20	
1.21	HEAD CYLINDER ASSY	1	CRACKED	\$1,782.00	\$1,782.00	
1.22	LAMP SIGNAL FRONT RH	1	CUT	\$40.80	\$40.80	
1.23	LEVER BRAKE	1	CUT	\$26.40	\$26.40	
1.24	LIGHT LED (JL) 4 LED BLUE - CLEAR LENS	1	CUT	\$312.00	\$312.00	
1.25	LIGHT STROBE REAR - RED	1	SCRATCHED	\$2,049.60	\$2,049.60	
1.26	METER ASSY	1	CRACKED	\$828.00	\$828.00	
1.27	MID GASKET MUFFLER	2	NECESSARY	\$19.20	\$38.40	

1.28	MID PIN DOWEL	1	NECESSARY	\$3.72	\$3.72	
1.29	MIRROR RH	1	CUT	\$165.60	\$165.60	
1.3	O-RING CYLINDER HEAD (SIDE COVER)	4	NECESSARY	\$5.64	\$22.56	
1.31	O-RING JOINT CARBURETOR	4	NECESSARY	\$7.20	\$28.80	
1.32	PEDAL BRAKE	1	CUT	\$45.60	\$45.60	
1.33	PEDAL GEAR	1	SCRATCHED	\$52.80	\$52.80	
1.34	PIPE EXHAUST 3	1	BENT	\$146.40	\$146.40	
1.35	PIPE EXHAUST 4	1	BENT	\$146.40	\$146.40	
1.36	POLE REAR FOR BEACON LIGHT (FIXED)	1	BENT	\$306.00	\$306.00	
1.37	PROTECTOR RH (STK 23743) WITH SPRAY PAINTING POLICE LIVERY (LINING)	1	CUT	\$510.00	\$510.00	
1.38	RUBBER MOUNT	12	NECESSARY	\$7.20	\$86.40	
1.39	RUBBER SEAL (SMALL)	11	NECESSARY	\$0.42	\$4.62	
1.4	SCREW (VISOR)	2	NECESSARY	\$3.60	\$7.20	
1.41	SEAL VALVE	8	NECESSARY	\$8.40	\$67.20	
1.42	STICKER (TP) FRONT COWLING (POLICE) LH/RH - SUPPLY BY AEMD	2	NECESSARY	\$0.00	\$0.00	
1.43	STUD	8	NECESSARY	\$8.76	\$70.08	
1.44	T-JOINT	1	NECESSARY	\$152.28	\$152.28	
1.45	VALVE EXHAUST	4	NECESSARY	\$50.40	\$201.60	
1.46	VALVE INTAKE	4	NECESSARY	\$45.60	\$182.40	
2	ADDITIONAL SERVICES					
2.1	PIN PISTON		NECESSARY			
2.2	RING PISTON (STD)		NECESSARY			
2.3	BALANCER HANDLE		CUT			
2.4	BOX SIDE LH		CUT			
2.5	COVER SIDE LH		CUT			
2.6	FOOTREST FRONT LH		CUT			
2.7	FOOTREST FRONT RH		CUT			
1						
1.1	REPLACE ITEM 1.1 TO 1.46					28
2						
2.1	TRANSPORT CHARGES (SOR 8) (BILL UNDER MONTH END SOR BILLING)					2
COSTING		TOTAL PARTS COST			\$12,054.78	
		TOTAL MAN-HOUR				30

Registration No. TP 1077B

Vehicle Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.