SME Motor Pte Ltd 1 Kaki Bukit Ave 6,#02-15/16/17/18 AutoBay @ Kaki Bukit Singapore

Claim Reference:

Assessment Number: GS001809

Version: SMEMOT01/1

Date Calculated: 07/11/2018 04:54

Full Report - V1

Not After the sake

Registration: SJW2369J

Printed: 07/11/2018 12:53

SGD

02/11/2018

4-DOOR

TWO COAT METALLIC

Summary Information

Claim

Location:

Printed by:

Authorisation Status:

Work Provider:

Claim Reference:

Policy Number: Other Reference:

Third Party: Insured Amount: Under Warranty: Warranty Expired:

Singapore (SG)

Gary Seah Interim

AXA Insurance S'pore Pte

TP

MAZDA

I48 01

March

2010

SJW2369J

Not Known

BASE MODEL

3

Currency:

Date of Incident: Able to Authorise Repairs: TBA

Repairs Authorised:

Estimated Repair Time: Ouote Due Date: Actual Repair Days: Parts Ordered Date:

Hire Car Start: Hire Car End: Vehicle Collected:

Vehicle Details

Vehicle

Manufacturer: Model:

Sub Model:

Model Sheet Number: Registration:

Registration Month: Registration Year:

VIN Number:

Odometer:

Colour:

Engine Number: Fuel Level:

%

Model Specs

FROM 04/2010 SPORT BUMPER

PREPARE OFF VEHICLE

LKK Auto Consultants hence notify the Repairer of the following:

 To resurvey before/after spray painting To display damaged part(s) during resurvey

· Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

· Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer **Vehicle Condition** Signature:

Vehicle Status

Pre-Accident Condition:

Steering:

Brakes Pedal Travel: Place of Inspection:

Pre-Accident Damage:

Tyres Condition:

Tread Depth LHF: Tread Depth LHR:

Damage Areas:

Severity of Impact

Vehicle Status on Inspection:

Date of Inspection:

07/11/2018

Tread Depth RHF: Tread Depth RHR: Direction of Impact:


Claim Reference:


Assessment Number: GS001809

Version: SMEMOT01/1

Date Calculated: 07/11/2018 04:54

Full Report - V1 Registration: SJW2369J Printed: 07/11/2018 12:53





Addresses

Cost Summary	
	Total Labo
	Total Pain

Total Labour	\$1,858.50
Total Paint/Material	\$349.68
Total Parts	\$3,727.15
Total of Additional Costs	\$857.00
Excess:	TBA
Grand Total Exc GST:	\$6,792.33
7 % GST:	\$475.46
Grand Total Inc GST:	\$7,267.79

Repair Information

LABOUR	Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
	Price/Dent = \$0.00/HR

LABOUR	11110 20313 20 11	Price/Dent	
Repair /			
Guide Numbe	r Repair Details	WU	Cost Price (\$)
NO NUMBER	RENEW RIGHT REAR SIDE PANEL	90.0	405.00
NO NUMBER	RENEW REAR END PANEL	50.0	225.00
	(BUMPER REMOVED)		
	INCLUDES: BUMPER CARRIER		
	REMOVE AND REFIT		
S0206X-R-X	RENEW REAR BUMPER	6.0	27.00
	INCLUDES: R + R REAR BUMPER AND ALL		
	NECESSARY ATTACHED PARTS		
S0505X-R-X)	RENEW BOOT LID	4.0	18.00
S1402X-R-X	R + R REAR SCREEN	16.0	72.00
S0506B-R-X)	R + R L/BOOTLID HINGE	1.0	4.50
S0506A-R-X)	R + R R/BOOTLID HINGE	1.0	4.50
S1704B-R-X)	R + R L/UPPER C-PILLAR TRIM	2.0	9.00
S1704A-R-X)	R + R R/UPPER C-PILLAR TRIM	2.0	9.00
S1710X-R-X	R + R REAR PARCEL SHELF TRIM	2.0	9.00
	INCLUDES: R + R REAR SEAT CUSHION		
A0109X-A-X	ALIGN + ADJUST VEHICLE CPL	12.0	54.00
1782	REPAIR R/R DOOR	15.0* /0	67.50
3901	REPAIR BOOTFLOOR	30.0* 20	135.00
4108	REPAIR R/R INNER SIDE PANEL	40.0* 20	180.00
LAE	BOUR COST		
	Total Work Units	271.0	
	Panel / Mechanical Labour	25.9HRS	\$1,165.50
	Visual Alignment Labour	1.2 HRS	\$54.00
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	27.1HRS	\$1,219.50
	Paint Labour	14.2HRS	\$639.00

Claim Reference:

Assessment Number: GS001809

Version: SMEMOT01/1

Date Calculated: 07/11/2018 04:54

Full Report - V1 Registration: SJW2369J Printed: 07/11/2018 12:53

Total Labour	41.3HRS	\$1,858.50

PAINT WO	ORK T	ime Basis 10 WU = 1 HR. Price	= \$45.00/HR
Guide Nu	mber Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
2640	REAR BUMPER SUPPORT SURFACE PAIN	NT 4.0	
2711	REAR PANEL NEW PART PAINTING	18.0	
2931	BOOTLID NEW PART PAINTING	17.0	
3482	R/R WING NEW PART PAINTING	26.0	
2581	REAR BUMPER NEW PART PAINT K1R	16.0	
1782	R/R DOOR REPAIR PAINTING <50%	15.0	
3901	BOOTFLOOR SURFACE PAINT	11.0	
4108	R/R INNER SIDE PANELSURFACE PAIN	5.0	
	LABOUR COST - PAINT		
	TIME(PAINT)	112.0	
	Preparation Main Work Plastic	5.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	142.0	
	Total Paintwork Labour	14.2HRS	\$639.00
	MATERIAL COST - PAINT		Cost Price
	New Part Painting		\$102.44
	New Part Painting - Plastic K1R		\$81.18
	Material-Constant Main Work Meta		\$28.60
	Surface-/Blend Paint		\$47.57
	Repair Painting		\$22.61
	Material-Const Main Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$291.40
	Pearlescent Uplift @ 0.0%		\$0.00
	Increased by 20%		\$58.28
	Total Paint Material Cost		\$349.68

_	-	_	_	_
п	^	О	•	
_	м	ĸ		

PARIS						
				Pr	ice Valid: 0	1/06/2015
Guide N	o. Qty	Description	Part Number	Supplier	Bet.	Price (\$)
1000	1	2PC PETROL TANK	COVER RIVERT	ser	0%	10.00*
1000	1	2PCS R/R TAIL LAMP	CLIP	in	0%	6.00*
1000	1	4PC END PANEL TRIM	CLIPS	11	0%	10.00*×
1000	1	6PC R/R BOOT TRIM	CLIPS	11	0%	15.00*
1000	1	6PC R/R WHEELHOUSE	CVR CLIPS	11	0%	21.00* 💥
3023	1	BADGE, MAZDA	BBY451710	nu	0%	18.00*
3020	1	BADGE MODEL	BBY451721	su	0%	16.00*
2944	1	BOOT/TAILGATE SEAL	BBM456951A	14	0%	70.00*
2931	1	BOOTLID	BBY45261XD	Sup/	0% suc	420.00* -
2977	1	BOOTLID LOCK	BBW156820A	yn1	0%	110.00*
2953	1	L/BOOTLID HINGE	BBM452720B	11 34	0%	65.00* ×
2621	1	L/INN BUMPER BRACKET	BBM4502J1E	cm	0%	30.00*
3021	1	MANUFACTURER BADGE	BBY451730	in	0%	30.00*
4982	1	R/BOOT TRIM COVER	BBM468850C	17	0%	95.00*X
2954	1	R/BOOTLID HINGE	BBM452710B	1	0%	65.00*
2622	1	R/INN BUMPER BRACKET	BBM4502H1E	Ser!	0%	30.00*

Claim Reference:

Assessment Number: GS001809

Version: SMEMOT01/1

Date Calculated: 07/11/2018 04:54

Full Report - V1 Registration: SJW2369J Printed: 07/11/2018 12:53

2614	1	R/R BUMPER REFLECTOR	BBP2515L0A	0%	SU 50.00*
3284	1	R/R INNER LAMP CPL	BBM4513F0F	0%	cm 135.00*
3282	1	R/R OUTER LAMP CPL	BBP251150E	0%	Bre 380.00*
1000	1	R/R TAILLAMP PANEL	Renew	0%	<i>→</i> 55.00* <i>→</i>
3786	1	R/R VENT HOUSING	D35051920A	0%	40.00* ~
4202	1	R/R WHEELHOUSE CVR	BBP3561H1C	1,0%	Ta. 7 35.00*
3482	1	R/R WING	BCY37041X	3145 0%	430.00*
2581	1	REAR BUMPER	BCW750221J8N	0%	7 \$ 395.00* -
2640	1	REAR BUMPER SUPPORT	BBS250260A	0%	4 210.00* -
2711	1	REAR PANEL	BBM470750C	0%	195.00*
3161	1	REAR SCREEN SEAL	BBM450611	0%	2 65.00* -
2650	1	RR BUMPER CLAMP KIT	USE SINGLE PARTS	0%	nul 20.00*
4985	1	RR LUGG COMPART TRIM	BBP26889X	0%	220.00*>
f: OEM F	Parts		Sub Total		\$3,241.00
g: Origin			Mark Up From Cost	(15 %)	\$486.15
h: Seco			Total Parts	(/	\$3,727.15
p: Paral					
x: Excha					
A. LACITO	11.90				

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras	NB COLOGIC	CODED TIENS, INC	IT TAKT NOTIBERS			
Extras	Description NUMBER PLATE	SPECIALIST	Betterment 0%	cM	Price \$35.00	_
	REVERSE SENSOR	SPECIALIST		SW	\$250.00	200
	REVERSE CAMERA REAR WINDSCREEN GUM	SPECIALIST SPECIALIST	0%	in	\$350.00 \$60.00	
	TOWING KING ROLLER	SPECIALIST	0%		\$120.00	_
	AUDATEX FEE	SPECIALIST			\$42.00	_
			Total Extras		\$857.00	
Final Cal	culation					
Total Parts					\$3,727.15	
Labour						
	otal Panel/Mechanical			\$1,165.50		
	otal Paintwork			\$639.00		
	otal Visual Alignment wor	-k		\$54.00		
Total Labo	ur				\$1,858.50	
Additional						
	Corr Prot Materials Externa			\$0.00		
	Corr Prot Materials Interna	ıl		\$0.00		
	Cost of Specialist			\$857.00		
	ditional Costs				\$857.00	
	/Material Costs				\$349.68	
	l Excludes GST				\$6,792.33	
	SST @ 7 %				\$475.46	
Grand Tota	l Includes GST				\$7,267.79	

Assessment Notes

Claim Reference:

Assessment Number: GS001809

Version: SMEMOT01/1

Date Calculated: 07/11/2018 04:54

Full Report - V1 Registration: SJW2369J Printed: 07/11/2018 12:53