## COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

VEHICLE NO: SHD 3503E

MAKE

AXA-ep/P)

7/11/2018



PARTS DESCR	IPTION	QTY	UNIT PRICE	AMOL	ואנ
FRONT BUMPE				\$	499.90
BRACKET, FRO	ONT BUMPER SIDE, RH X			\$	82.30
	SUB TOT	AL		\$	582.2
	LESS 2			\$	145.5
	DISCOUNTED TOT			\$	436.6
	בי בי היים בי	^-		,	
LABOUR CHAR	2GE				
Panel Beating	KGL			\$	400.0
Spray Painting	Chargo				300.0
Tuff Kote	Charge				50.0
Tull Kote				* X	J. 0.0
	TOTAL LABO	LIP		\$	750.0
		UIXI		Ψ	7 00.0
	TOTAL LABO				
Ka	ESTIMATE TOT	AL		\$ 1	,186.6
Ko		LKK Auto Co the Repairer To resurvey by To display dar Parts prices a Third party su No illegal moto	nsultants hence no of the following: store/after spray paintin neged part(s) during re re subject to confirmation without a "Without Pater and the store is allowed discretizing in the festing of the store is allowed.	atify survey bn judice* basis	,186.6
Ko	ESTIMATE TOT	LKK Auto Co the Repairer To resurvey by To display dar Parts prices a Third party su No illegal moto	of the following: spre/after spray paintin naged part(s) during re re subject to confirmation recy is on a "Without F	atify survey bn judice* basis	,186.6
Ko	ESTIMATE TOT	LKK Auto Co the Repairer To resurvey by To display dar Parts prices a Third party su No illegal mo Suppumenta is subject to f	of the following: stre/after spray painting naged part(s) during re re subject to confirmationer is on a "Without Fatination(s) is allowed to item(s) must be result at approval from Insultation in the subject of the	atify survey bn judice* basis	,186.6
Ko	ESTIMATE TOT	LKK Auto Co the Repairer To resurvey by To display dar Parts prices a Third party su No illegal moto	of the following: stre/after spray painting naged part(s) during re re subject to confirmationer is on a "Without Fatination(s) is allowed to item(s) must be result at approval from Insultation in the subject of the	atify survey bn judice* basis	,186.6

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.