Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7554S

Vehicle No.: SHB 7554S

Chassis No.: KL1LA69RJBB078450

Not Norhain

Vehicle Make: CHEVROLET

Vehicle Model: EPICA 2.0

Date of Accident: 31.10.2018

Third Party Insurer : AIG

		PART		LIST
1	1	Rear Bumper		\$ Br 1,202.00 -
2	1	Rear Bumper Beam		\$ n 239.94 x
3	1	Rear Bumper Centre Absorber		\$ Sh 260.00 K
4	1	Rear Bumper Side Retainer RH		\$ Su 68.76 Y
5	1	Rear Bumper Side Retainer LH		\$ D11 68.76
6	1	Rear Bumper Reflectors RH		\$ 5° 119.74 ¥
7	1	Rear Bumper Reflectors LH		\$ an 119.74 —
8	1	Rear Bumper Tow Hook Cover		\$ In 93.00
9	1	Rear End Panel Outer		\$ n 623.76
10	1	Rear End Panel Inner Trim		\$ Sh 263.84
11	1	Rear Luggage Floor Panel		\$ 1 973.00 X
12	1	Rear Luggage Floor Panel Insulator		\$ Sh 63.50
13	1	Rear Luggage Floor Panel Trim Board		\$ 378.00
14	1	Rear Fender RH		\$ n 1,145.00
15	1	Rear Fender Inner Trim RH		\$ 54 418.44
16	1	Rear Tail Lamp LH		\$ √n 479.30 J
	·		TOTAL	\$ 6,516.78
			10%	\$ 651.68
				\$ 5,865.10
1		Specical Nett		

1		Specical Nett		
2	10.		¢	an 40.00 X
3	1Set	Bootlid inner trim board Clip	\$	
4	1Set	Rear Bumper Parking Sensor	\$	For 300.00
5		Rear Bumper Fastener Clip	\$	M 44.00 —
6	1Set	Rear Fender Inner Trim Clip LH	\$	30.00 X
7	1Set	Rear Bumper End Dust Cover Clip	\$	30.00 X
8	1	Rear Exhaust Mounting	\$	5℃ 300.00 ×
9	2	Rear Windscreen Sealant	\$	2 ≈ 80.00 ×
10	1	Rear Windscreen Inner Sponge Seal	\$	100.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7554S

TOTA	\L \$	924.00	
TOTAL PAR	TS \$	6,789.10	
Panel Beating, Knocking And Straightening The			
Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,100.00	1
To Check Electrical Lighting Concerned.	\$	170.00	
To Rust-Proofing Of The Affected Areas.	\$	170.00	,
Putty And Spray Painting Of The Affected Porti	on. \$	2,100.00	4
To reinstall rear bumper parking sensor.	\$	170.00	(
To transfer of end panel fittings and conduct water seepage test.	\$	NN 170.00	,
To transfer of rear fender fittings and conduct water seepage test.	\$	NA 170.00	
To transfer of rear bumper fittings and conduct water seepage test.	t \$	Nn 170.00	
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	~~ 380.00	
To check steering geometry and computer whalignment	eel \$	w~ 220.00).
LKK Auto Consultants hence notify the Repairer of the following:	\$	5,820.00	_
 To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation 	TAL \$	12,609.10	
Third party survey is on a "Without Prejudice" basis No illegal modification se is all we bays (LUMP SUM) Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		Hays 1/hday	
Acknowledged by Repairer Signature:			
Date:			