

S. REC. BY:

REF:

CS/FCU 80202/14/Ksbh2

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

CWS

Eileen Lee

of

FCL

Date/Time:

05/12/08 12.12pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 6434K

Insured:

SH6668S

at Workshop m/s

Hui Yang

Tel:

6451 5752

of

176 Sin Ming Drive #04-12

Policy No:

Claim No:

D18007971MFSH

Sum Insured:

Excess:

Make of Vehl:

D.O.A.

05/12/08

(Client's Record)

CA / REV / REP. / REV 24 HRS '03

H.O.D. Endorsement:

Date/Time:

05/12/08 1.09pm

Person Contacted:

Bel

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLQ 6434K - X

SH 6668S - CS/FCU 800729S / Attn2

QA: 17/11/08

05/12/08

@ 16:39 p.m. revised PA to G. Lee via email.

15/1

11 Lp 8420d email & confirm

ASS. REC. BY:

REF: 1021

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

20 %

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

9/11 File pass to Catherine

15/01/19 Confirmed HS \$ 4,200/- @ 5 days with Kenneth.
(\$ 4,319.71 Red - 51%)

RECEIVED 15 JAN 2019

Date/Time, File Pass to?

15/01/19

1)

Date/Time, File Return to?

2)



Prell. Report



Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

4,200/- HS

160
50
50+50
31
341



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007971MFSH

Date: 09 November 2018

Our Ref: CS/FCI18020214/Ksb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLQ 6434K .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 08/11/2018 at the premises of M/s Hui Yang Motor Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 8,519.71 .
Revised Estimate Amount	: S\$ 4,873.69 .
"Check" Items Amount	: S\$ 1,513.84 .
Market Value	: S\$.
LTA Reimbursement Value	: S\$.
Nett Value	: S\$.

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 5 Days

Yours faithfully,
Kenneth Kong
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	07-11-2018	Our Ref No. D18007971MFSH
Accident Date	05-11-2018	Claim Type. Third Party
Insured Vehicle	SH6668S	Third Party Vehicle. SLQ6434K
Survey Location	BLK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE	
Contact Person.	BEL	
Contact No.	64515752/ 0	Fax No. 64514658
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUI YANG MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 9 November 2018 4:39 PM
To: 'Eileen Lee'; 'CWS Motor Claims'
Cc: assignments; SUR
Subject: RE: SURVEY ASSESSMENT - D18007971MFSH/1
Attachments: SLQ 6434K - Preli Advise.pdf

Dear Eileen,

Enclosed preliminary revised of vehicle SLQ 6434K.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 8 November, 2018 12:13 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007971MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

辉陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

05/11/2018

Owner: ACE FLEET MANAGEMENT PTE LTD

ESTIMATE TO REPAIR TOYOTA PRIUS ALPHA 1.8S A - SLQ6434K

1pc	rear tailgate
1pc	rear tailgate outer garnish
1pc	rear tailgate "TOYOTA" logo
1pc	rear tailgate "PRIUS" emblem
1pc	rear tailgate "HYBRID" emblem
1set	rear tailgate windscreen glass moulding
1pc	rear tailgate inner lock
1pc	rear tailgate inner rubber
1pc	rear tailgate inner garnish
2pcs	rear taillamp @\$561.35
2pcs	rear taillamp lower bracket @\$132.25
1pc	rear bumper
2pcs	rear bumper side retainer @\$132.45
1pc	rear end panel
1pc	rear end panel outer sensor
1pc	rear end panel inner garnish

Rs \$ 1,218.45 ✓

Sm \$ 371.25 X

Rs \$ 61.10 —

Rs \$ 63.90 —

Rs \$ 61.10 —

Rs \$ 182.28 —

Rs \$ 374.45 ✓

Sm \$ 381.90 X

Sm \$ 781.90 X

o/smg n/i \$ 1,122.70 2x

\$ 264.50 X

Rs \$ 981.90 ✓

o/smg n/i \$ 264.90 4x

Rs \$ 781.10 ✓

Sm \$ 260.00 X

Rs \$ 374.85 ✓

\$ 7,546.28

less 25%

\$ 1,886.57

\$ 5,659.71

1set rear number plate & casing

Sm s.nett \$ 50.00 X

1set rear parking sensor

Sm s.nett \$ 280.00 2.00sm

remove & refix rear windscreen glass

\$ 150.00 12cl

sealant

\$ 80.00 40sm nec

tuffkote

\$ 120.00 6cl

wiring

\$ 80.00 2cl

spray painting

\$ 1,000.00 66cl

labour charges

\$ 1,100.00 66cl

Total

\$ 8,519.71

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18020214/Ksbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 15-01-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6668S	Veh. Inspected	SLQ 6434K	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007971MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	08/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ZVW400025288	Colour	METALLIC BLUE	
Odometer	133707	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	GOODRICH	2 mm	
L/H Front Tyre	205/60 R16	GOODRICH	2 mm	
R/H Rear Tyre	205/60 R16	YOKOHAMA	4 mm	
L/H Rear Tyre	205/60 R16	YOKOHAMA	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/11/2018	Inspection Date	08/11/2018	
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 6434K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE	BENT	1,218.45	1,218.45
1	REAR TAILGATE OUTER GARNISH	SERVICEABLE	371.25	-
1	REAR TAILGATE "TOYOTA" LOGO	NECESSARY	61.10	61.10
1	REAR TAILGATE "PRIUS" EMBLEM	NECESSARY	63.90	63.90
1	REAR TAILGATE "HYBRID" EMBLEM	NECESSARY	61.10	61.10
1	SET REAR TAILGATE WINDSCREEN GLASS MOULDING	NECESSARY	182.28	182.28
1	REAR TAILGATE INNER LOCK	DENTED	374.45	374.45
1	REAR TAILGATE INNER RUBBER	SERVICEABLE	381.90	-
1	REAR TAILGATE INNER GARNISH	SERVICEABLE	781.90	-
2	REAR TAILLAMP @\$561.35	O/S MTG DISTORTED	1,122.70	561.35
2	REAR TAILLAMP LOWER BRACKET @\$132.25	TO REPAIR SEE LABOUR	264.50	-
1	REAR BUMPER	BUCKLED	981.90	981.90
2	REAR BUMPER SIDE RETAINER @\$132.45	O/S DISTORTED	264.90	132.45
1	REAR END PANEL	BENT	781.10	781.10
1	REAR END PANEL OUTER SENSOR	SERVICEABLE	260.00	-
1	REAR END PANEL INNER GARNISH	DENTED	374.85	374.85
	LESS 25% DISCOUNT		-1,886.57	-1,198.23
			5,659.71	3,594.70
SPECIAL NETT ITEMS				
1	SET REAR NUMBER PLATE & CASING (SN)	SERVICEABLE	50.00	-
1	SET REAR PARKING SENSOR (SN)	SCRATCHED	280.00	200.00
1	SEALANT (SN)	NECESSARY	80.00	40.00
			410.00	240.00
LABOUR				
	REMOVE & REFIX REAR WINDSCREEN GLASS.		150.00	120.00
	TUFFKOTE.		120.00	60.00
	WIRING.		80.00	20.00
	SPRAY PAINTING.		1,000.00	660.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR CHARGES, INCLUSIVE OF THE REPAIR OF REAR TAILLAMP LOWER BRACKET.		1,100.00	600.00
			2,450.00	1,460.00
GRAND TOTAL			8,519.71	5,294.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,200.00

Report Ref No. CS/FCI18020214/Ksbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.