

The insurer has given adjuster a maximum mandate of S\$25,000.00 to authorize directly on their behalf, but the adjuster has disabled direct offer mode.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18020228/UVBN2
Date: 28/06/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: 29090793MKF
Claimant Vehicle No : BNF5587	Insured Vehicle No : YM6968D
Date of Loss: 01/11/2018	Nature of Claim: TP
	Claim No: 574963

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: BNF5587	Engine No: G20B96E
Make & Model: PERODUA ALZA, 1.5 SE (A)	Chassis No: PM2M502G002240118
Reg. Date: 27/04/2015 (Man. Year: 2015)	Odometer: 95768 km
Colour: Red	
Engine Capacity: 1495 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 185/55R15	Rear Tyre Size: 185/55R15
Front Left Side: Hankook 6 mm	Rear Left Side: Hankook 6 mm
Front Right Side: Hankook 6 mm	Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	35,036.00	13,391.12	21,644.88	61.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,500.00	4,710.00	2,790.00	37.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	42,536.00	18,101.12	24,434.88	57.45
Approved Total (Overridden) (S\$)		13,000.00		
(S\$)	42,536.00	13,000.00	29,536.00	69.44
+ GST 7.00/7.00% (S\$)	2,977.52	910.00	2,067.52	69.44
Nett Amount (S\$)	45,513.52	13,910.00	31,603.52	69.44

INSPECTION

Date of Assignment:	31/12/2018		Fastech Auto Pte Ltd (HQ)
Date Inspected:	08/11/2018	Inspected At:	1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	10.0 days		

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Jan 2019)
Parts: M1-MPV	PERODUA ALZA 1.5 SE (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for BNF5587)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,205.00 F	*750.00 FL
2	1		*TAILGATE OUTER TOP GARNISH	Not Necessary	450.00 F	*- FL
3	1		*TAILGATE REAR LOGO	Not Necessary	50.00 F	*- FL
4	1		*TAILGATE ALZA EMBLEM	Not Necessary	52.00 F	*- FL
5	1		*TAILGATE INNER LOCK	Dented/Jammed	245.00 F	*155.00 FL
6	1		*TAILGATE INNER TRIM BOARD	Deformed/Torn	391.00 F	*266.00 FL
7	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
8	1		*TAILGATE WEATHERSTRIP	Twisted	299.00 F	*180.00 FL
9	2		*TAILGATE DAMPERS	Not Necessary	610.00 F	*- FL
10	1		*REAR WINDSCREEN MOULDING	Necessary	110.00 F	*110.00 FL
11	1		*REAR BUMPER	Distorted	820.00 F	*480.00 FL
12	1		*REAR BUMPER BEAM	Not fitted	299.00 F	*- FL
13	2		*REAR BUMPER REFLECTORS	Cracked	170.00 F	*170.00 FL
14	1		*SET REAR BUMPER CLIPS	Necessary	45.00 F	*45.00 FL
15	2		*REAR BUMPER SIDE RETAINERS	Bent	170.00 F	*110.00 FL
16	1		*REAR END PANEL	Badly Dented	785.00 F	*580.00 FL
17	1		*REAR END PANEL TOP GARNISH	Deformed/Twisted	192.00 F	*95.00 FL
18	1		*REAR FLOOR PANEL	Crumpled/Buckled	1,120.00 F	*780.00 FL
19	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	805.00 F	*- FL
20	1		*REAR FLOOR PANEL TOP TRAY	Deformed/Cracked	699.00 F	*485.00 FL
21	2		*TAILLAMPS	Cracked	1,300.00 F	*850.00 FL
22	2		*TAILLAMP LOWER GARNISHS	Deformed/Torn	410.00 F	*336.00 FL
23	1		*REAR EXHAUST PIPE	Repair	485.00 F	*- FL
24	2		*REAR EXHAUST PIPE MOUNTINGS	Not Necessary	120.00 F	*- FL
25	2		*REAR FENDERS	Repair	1,970.00 F	*- FL
26	2		*REAR FENDER INNER TRIMS	Deformed/Cracked	1,360.00 F	*810.00 FL
27	1		*REAR SPARE TYRE BRACKET	Bent	215.00 F	*215.00 FL
28	1		*BONNET	Buckled	1,105.00 F	*685.00 FL
29	2		*BONNET HINGES	Bent	210.00 F	*180.00 FL
30	1		*BONNET INSULATOR	Deformed/Warped	320.00 F	*148.00 FL
31	1		*SET BONNET INSULATOR CLIPS	Necessary	50.00 F	*50.00 FL
32	1		*BONNET LOCK	Bent/Twisted	145.00 F	*95.00 FL
33	1		*FRONT GRILLE	Broken	325.00 F	*188.00 FL
34	1		*FRONT BUMPER	Distorted	825.00 F	*495.00 FL
35	2		*FRONT BUMPER SIDE RETAINERS	Bent	130.00 F	*130.00 FL
36	1		*FRONT BUMPER REINFORCEMENT	Bent	485.00 F	*300.00 FL
37	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
38	1		*FRONT BUMPER TOW COVER	Not Necessary	30.00 F	*- FL
39	2		*FRONT BUMPER FOG LAMPS	Not Necessary	900.00 F	*- FL
40	2		*FRONT FENDERS	Repair	1,210.00 F	*- FL
41	1		*FRONT FENDER INNERSHIELDS	N/s Torn	370.00 F	*185.00 FL
42	1		*SET FRONT FENDER INNERSHIELD CLIPS	Not Necessary	50.00 F	*- FL
43	2		*HEADLAMPS	Cracked	1,700.00 F	*1,030.00 FL
44	1		*FRONT SUPPORT PANEL	Bent	915.00 F	*499.00 FL
45	2		*FRONT CONDENSE SIDE GARNISHS	Torn	410.00 F	*170.00 FL
46	1		*AIRCON CONDENSER	Bent/Punctured	1,120.00 F	*861.30 FL
47	1		*AIRCON SUCTION HOSE	Not Necessary	311.00 F	*- FL
48	1		*AIRCON DISCHARGE HOSE	Not Necessary	380.00 F	*- FL
49	1		*AIRCON LIQUID PIPE	Not Necessary	195.00 F	*- FL
50	1		*RADIATOR	Bent/Punctured	1,480.00 F	*899.50 FL
51	1		*RADIATOR FAN ASSY	Cracked/Jammed	885.00 F	*366.00 FL
52	1		*RADIATOR SPARE TANK	Not Necessary	105.00 F	*- FL
53	1		*FRONT BRACE PANEL	Bent	110.00 F	*110.00 FL
54	1		*FRONT GRILLE CHROME MOULDING	Cracked	388.00 F	*388.00 FL
55	1		*FRONT SIPER TANK	Not Necessary	185.00 F	*- FL
56	2		*ENGINE MOUNTINGS	Not Necessary	410.00 F	*- FL
57	1		*ALTERNATOR	Not Necessary	1,800.00 F	*- FL
58	1		*COMPRESSOR	Not Necessary	1,550.00 F	*- FL
59	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
60	1		*REAR LICENCE PLATE	Not Necessary	50.00 FS	*- FS
61	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
62	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
63	1		*SET REAR FLOOR PANEL INSULATOR	Necessary	220.00 FS	*120.00 FS
64	1		*REAR BUMPER LOWER SKIRTING	Broken	880.00 FS	*500.00 FS
65	1		*FRONT BUMPER LOWER SKIRTING	Deformed/Torn	880.00 FS	*500.00 FS
66	1		*FRONT LICENCE PLATE	Cracked	50.00 FS	*14.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	35,036.00	14,720.80
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	1,329.68
Total Parts (\$)	35,036.00	13,391.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items**There are no new miscellaneous items selected.****Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
5	TO SPRAY RUST PROOFING	New	180.00	150.00
6	TO REFILL AIR CON GAS	New	150.00	100.00
7	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	60.00
8	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	-
9	TO DISMANTLE & REFIX PETROL TANK	New	100.00	60.00
10	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY	New	180.00	80.00
11	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	3,000.00	2,200.00
12	TO PUTTY & SPRAY PAINTING	New	3,000.00	1,800.00
Gross Labour Cost (S\$)			7,500.00	4,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >