

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18020256/T1KA3Q2

Date: 13/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800042374

Claimant
Vehicle No : SHB5136D **Insured Vehicle No :** SJK7757C

Date of Loss: 02/11/2018 Nature of Claim: TP Claim No: 6368037502SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB5136D		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZRS099777
Reg. Date:	01/11/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU503573246
Colour:	Maroon	Odometer:	77078 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	44,434.64	19,140.50	25,294.14	56.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,867.00	3,806.00	3,061.00	44.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	51,301.64	22,946.50	28,355.14	55.27
+ Car Rental (78.0 x S\$117.17/day) (S\$)		9,139.26		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		32,092.76		
Global Sum Settlement (S\$)		28,500.00		

INSPECTION

Date of Assignment: 05/11/2018

Date Inspected: 05/11/2018 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 12.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MOULDING RH (DISC 25%)	Deformed	83.30 F	*62.48 F
2	1		*SUPPORT ,FR BUMPER RH (DISC 25%)	Deformed	76.90 F	*57.68 F
3	1		*SUPPORT ,RADIATOR UPPER RH (DISC 25%)	Bent	76.70 F	*57.53 F
4	1		*COVER ,FR BUMPER (DISC 25%)	Deformed	495.50 F	*371.63 F
5	1		*CLIPS PIECE ,FRT & RR BUMPER (DISC 25%) (10 PCS)	Necessary	15.00 F	*11.25 F
6	1		*CABLE ASSY ,HOOD (DISC 25%)	Distorted	53.20 F	*39.90 F
7	1		*LINER ,FR FENDER ,RH (DISC 25%)	Deformed	198.40 F	*148.80 F
8	1		*HOOD SUB-ASSY (DISC 25%)	Bent	938.40 F	*703.80 F
9	1		*WIPER WASHER JAR (DISC 25%)	Deformed	183.60 F	*137.70 F
10	1		*RETAINER ,FR WHEEL RH (DISC 25%)	Deformed	3.10 F	*2.33 F
11	1		*COVER SUB-ASSY ,FRONT PILLAR ,UPR RH (DISC 25%)	Deformed	96.90 F	*72.68 F
12	1		*EMBLEM ,SIDE PANEL (HYBRID) (DISC 25%)	Necessary	52.90 F	*39.68 F
13	1		*FENDER SUB-ASSY ,FR RH (DISC 25%)	Bent	933.10 F	*699.83 F
14	1		*HINGE ASSY ,HOOD ,LH (DISC 25%)	Bent	57.00 F	*42.75 F
15	1		*SEAL SUB-ASSY ,RH (DISC 25%)	Necessary	50.20 F	*37.65 F
16	1		*ABSORBER ,FR BUMPER LOWER (DISC 25%)	Deformed	117.00 F	*87.75 F
17	1		*GRILLE ,RADIATOR (DISC 25%)	Cracked	165.00 F	*123.75 F
18	1		*WIPER GARNISH SHIELD ,COWL WATER ,RH (DISC 25%)	Deformed	18.90 F	*14.18 F
19	1		*HINGE ASSY ,HOOD, RH (DISC 25%)	Bent	57.00 F	*42.75 F
20	1		*COVER ,FR BUMPER RH (DISC 25%)	Distorted	28.10 F	*21.08 F
21	1		*COVER ,ENGINE UNDER SIDE RH (DISC 25%)	Deformed	76.90 F	*57.68 F
22	1		*BRACKET ,FR BUMPER (DISC 25%)	Deformed	99.80 F	*74.85 F
23	1		*ABSORBER ,FR BUMPER (DISC 25%)	Deformed	70.30 F	*52.73 F
24	1		*EMBLEM ASSY FRONT (DISC 25%)	Necessary	87.10 F	*65.33 F
25	1		*PAD ,FR WHEEL RH (DISC 25%)	Distorted	57.70 F	*43.28 F
26	1		*TANK ,RESERVE SEALED W/O CAP (DISC 25%)	Deformed	127.00 F	*95.25 F
27	1		*KNUCKLE ,STEERING ,RH (DISC 25%)	Bent	555.20 F	*416.40 F
28	1		*SUPPORT SUB -ASSY LOWER (DISC 25%)	Bent	397.40 F	*298.05 F
29	1		*ABSORBER SET ,SHOCK ,FRONT RH (DISC 25%)	Bent	398.10 F	*298.58 F
30	1		*COVER ASSY ,ENGINE (DISC 25%)	Deformed	180.10 F	*135.08 F
31	1		*SUPPORT S/A LH (DISC 25%)	Bent	237.00 F	*177.75 F
32	1		*COVER ,ENGINE UNDER SIDE LH (DISC 25%)	Deformed	76.90 F	*57.68 F
33	1		*SUPPORT S/A UPPER (DISC 25%)	Bent	364.90 F	*273.68 F
34	1		*WIPER GARNISH LOUVER SUB-ASSY (DISC 25%)	Deformed	666.90 F	*500.18 F
35	1		*APRON SUB-ASSY ,FRONT FENDER ,RH (DISC 25%)	Deformed	944.20 F	*708.15 F
36	1		*TUBE & ACCESSORY (DISC 25%)	Deformed	574.40 F	*430.80 F
37	1		*SET COVER ASSY ,ENGINE UNDER CENTER (DISC 25%)	Deformed	452.80 F	*339.60 F
38	1		*LOWER ARM SUB-ASSY ,FRONT RH (DISC 25%)	Bent	631.60 F	*473.70 F
39	1		*WIPER WASHER INLET (DISC 25%)	Deformed	55.40 F	*41.55 F
40	1		*AIR CON CONDENSER ASSY (DISC 25%)	Bent	1,317.70 F	*988.28 F
41	1		*JOINT ASSY ,LWR BALL ,RH & LH (DISC 25%)	Bent	200.10 F	*150.08 F
42	1		*HUB & BEARING ASSY, RH & LH (DISC 25%) (2 PCS)	Bent	554.20 F	*415.65 F
43	1		*WHEEL DISC (DISC 25%)	Bent	1,555.10 F	*1,166.33 F
44	1		*SUPPORT S/A RH (DISC 25%)	Bent	237.00 F	*177.75 F
45	1		*WIRE ,ENGINE ROOM MAIN (DISC 10%)	Torn	6,138.00 F	*5,524.20 F
46	1		*LAMP ASSY ,FOG, RH (DISC 10%)	Cracked	910.20 F	*819.18 F
47	1		*UNIT ,HEADLAMP ,RH (DISC 10%)	Cracked	2,558.90 F	*2,303.01 F
48	1			Distorted	245.00 F	*220.50 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*MOTOR AND PUMP ASSY ,WINDSHIELD WASHER (DISC 10%)			
49	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F
50	1		*PILLAR FRONT BODY ,RH	Repair	339.40 F	*- F
51	1		*WHEEL ,DISC	Repair	1,555.10 F	*- F
52	1		*HINGE ASSY ,FRONT DOOR ,LOWER RH	Repair	92.10 F	*- F
53	1		*MOULDING ASSY ,BODY ROCKER PANEL ,RH	Repair	576.00 F	*- F
54	1		*HINGE ASSY ,FRONT DOOR ,UPPER RH	Repair	82.10 F	*- F
55	1		*CHECK ASSY ,FRONT DOOR	Repair	153.50 F	*- F
56	1		*PANEL SUB-ASSY ,FRONT DOOR RH	Repair	1,249.60 F	*- F
57	1		*COVER ,FR BUMPER LH	Not Necessary	28.10 F	*- F
58	1		*NUMBER PLATE	Not Necessary	35.00 F	*- F
59	1		*HOSE ,WINDSHIELD WASHER (FROM JOINT TO)	Not Necessary	16.60 F	*- F
60	1		*WIPER GARNISH LOUVER SUB-ASSY	Not Necessary	666.90 F	*- F
61	1		*HOSE SUB-ASSY DISCHARGE	Not Necessary	337.10 F	*- F
62	1		*HOSE, WINDSHIELD WASHER	Not Necessary	14.00 F	*- F
63	1		*HOSE ,WATER BY-PASS NO.4	Not Necessary	13.20 F	*- F
64	1		*INSULATOR ,HOOD CLIP	Not Necessary	2.30 F	*- F
65	1		*INLET ,AIR CLEANER ,NO3	Not Necessary	35.30 F	*- F
66	1		*REINFORCEMENT FRONT UPPER	Not Necessary	691.10 F	*- F
67	1		*ABOSRBER SET ,SHOCK FRONT RH	Not Necessary	398.10 F	*- F
68	1		*HOSE ,WINDSHIELD WASHER	Not Necessary	14.00 F	*- F
69	1		*TYRE	Not Necessary	126.74 F	*- F
70	1		*TUBE & ACCESSORY	Not Necessary	574.40 F	*- F
71	1		*PIPE,WATER BY-PASS NO.2	Not Necessary	11.00 F	*- F
72	1		*KNUCKLE STEERING ,RH	Not Necessary	555.20 F	*- F
73	1		*REINFORCEMENT FRONT LOWER	Not Necessary	238.50 F	*- F
74	1		*LOCK ASSY ,HOOD	Not Necessary	131.10 F	*- F
75	1		*WIRE ,ENGINE ROOM MAIN	Not Necessary	6,138.00 F	*- F
76	1		*TANK ,RESERVE SEALED W/O CAP	Not Necessary	127.00 F	*- F
77	1		*JOINT ,WINDSHIELD WASHER HOSE	Not Necessary	2.70 F	*- F
78	1		*SUPPORT S/A RH	Not Necessary	237.00 F	*- F
79	1		*INLET ,AIR CLEANER ,NO 2	Not Necessary	93.90 F	*- F
80	1		*JOINT WINDSHIELD WASHER HOSE NO.2	Not Necessary	3.60 F	*- F
81	1		*COVER ENGINE UNDER CENTER	Not Necessary	94.50 F	*- F
82	1		*SET COVER ASSY ,ENGINE UNDER CENTER		452.80 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Not Necessary		
83	1		*NUMBER PLATE FRAME	Not Necessary	25.00 F	*- F
84	1		*SUPPORT S/A UPPER	Not Necessary	364.90 F	*- F
85	1		*HOSE SUB-ASSY SUCTION	Not Necessary	541.90 F	*- F
86	1		*WIPER WASHER INLET	Not Necessary	55.40 F	*- F
87	1		*COVER ,RADIATOR	Not Necessary	227.80 F	*- F
88	1		*CAP SUB-ASSY ,WHEEL	Not Necessary	175.80 F	*- F
89	1		*EXTENSION SUBASSY RH	Not Necessary	116.30 F	*- F
90	1		*SUPPORT SUB-ASSY LOWER	Not Necessary	397.40 F	*- F
91	2		*JOINT ASSY ,LWR BALL,RH & LH	Not Necessary	200.10 F	*- F
92	1		*COVER ASSY ,ENGINE	Not Necessary	180.10 F	*- F
93	1		*INSULATOR HOOD	Not Necessary	393.90 F	*- F
94	1		*GRILLE SUB-ASSY	Not Necessary	335.60 F	*- F
95	1		*APRON SUB-ASSY ,FRONT FENDER RH	Not Necessary	944.20 F	*- F
96	1		*SEAL ,HOOD TO FR END	Not Necessary	24.40 F	*- F
97	1		*SUPPORT ,FR BUMPER LH	Not Necessary	82.30 F	*- F
98	1		*EXTENSION SUBASSY ,LH	Not Necessary	116.30 F	*- F
99	1		*LAMP ASSY ,FOG,LH	Not Necessary	910.20 F	*- F
100	1		*HOSE WATER BY-PASS NO.1	Not Necessary	37.40 F	*- F
101	1		*HOSE WATER BY-PASS NO.8	Not Necessary	37.90 F	*- F
102	1		*LOWER ARM SUB-ASSY FRONT RH	Not Necessary	631.60 F	*- F
103	1		*HOSE ,WATER BY-PASS NO.3	Not Necessary	20.10 F	*- F

F=Franchise part.

Total Parts (S\$) 44,434.64 19,140.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	2,259.00	1,150.00
2	SPRAY PAINT	New	2,412.00	1,300.00
3	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	200.00	90.00
4	TO CHECK & RESET SYSTEM FUNCTION	New	350.00	150.00
5	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	40.00
6	TO CONDUCT RADIATOR PRESSURE CHECK	New	100.00	100.00
7	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	80.00
8	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	New	150.00	150.00
9	TO REMOVE AND REFIT TYRE	New	120.00	30.00
10	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	30.00
11	TO REMOVE AND REFIT WIRE HARDESS	New	150.00	150.00
12	TO REMOVE AND REFIX UNDERCARRIAGE	New	350.00	150.00
13	TO REPLACE SUNDRY PARTS	New	100.00	30.00
14	TO TOP UP A/C GAS	New	120.00	120.00
15	TO TRANSFER DOOR MECHANISM	New	120.00	120.00
16	TO WASH AND VACUUM	New	60.00	60.00
17	TOWING CHARGE	New	56.00	56.00
Gross Labour Cost (\$\$)			6,867.00	3,806.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >