

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CS3/MSG18012601/GQBS2-1  
**Date:** 23/11/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 27724091QMY  
**Claimant Vehicle No :** SKX7067E **Insured Vehicle No :** SFQ718C  
Date of Loss: 06/07/2018 Nature of Claim: TP Claim No: 563822

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX7067E**  
Make & Model: BMW 316I, 1.6 AT D/AB 4DR ABS HID (A) Engine No: A968J463N13B16A  
Reg. Date: 31/05/2013 (Man. Year: 2013) Chassis No: WBA3A12080J720411  
Colour: Black Odometer: 96463 km  
Engine Capacity: 1598 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50R17 Rear Tyre Size: 225/50R17  
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,205.40	1,759.40	4,446.00	71.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,050.00	1,220.00	1,830.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,255.40</b>	<b>2,979.40</b>	<b>6,276.00</b>	<b>67.81</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,350.00</b>		
<b>(S\$)</b>	9,255.40	2,350.00	6,905.40	74.61
<b>+ GST 7.00/7.00% (S\$)</b>	647.88	164.50	483.38	74.61
<b>Nett Amount (S\$)</b>	<b>9,903.28</b>	<b>2,514.50</b>	<b>7,388.78</b>	<b>74.61</b>

INSPECTION

Date of Assignment: 10/07/2018  
Date Inspected: 12/07/2018 Inspected At: 889 Car Servicing Pte Ltd  
10 Kaki Bukit Road 2, #03-34 First East Centre  
Singapore 417868  
Estimated Period of Repair: 4.0 days

**Adjuster:** XING GUO QIANG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference****Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 23 Nov 2018)**Parts:** 143      BMW 316I 1.6 AT D/AB 4DR ABS HID (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's      (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SKX7067E)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT N/S DOOR	Repair	1,605.00 FL	*- FL
2	1		*FRONT N/S DOOR LOCK	Not Necessary	285.00 FL	*- FL
3	1		*FRONT N/S DOOR RUBBER	Not Necessary	197.00 FL	*- FL
4	1		*REAR N/S DOOR	Dented	1,655.00 FL	*1,655.00 FL
5	1		*REAR N/S DOOR INNER LOCK	Not Necessary	393.00 FL	*- FL
6	1		*REAR N/S DOOR REGULATOR	Not Necessary	345.00 FL	*- FL
7	1		*REAR N/S DOOR REGULATOR MOTOR	Not Necessary	305.00 FL	*- FL
8	1		*REAR N/S DOOR RUBBER	Necessary	197.00 FL	*197.00 FL
9	1		*REAR N/S FENDER	Repair	1,550.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,532.00</b>	<b>1,852.00</b>
<b>- List Item Discount on L Items 5.00/5.00% (\$\$)</b>	326.60	92.60
<b>Total Parts (\$\$)</b>	<b>6,205.40</b>	<b>1,759.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIT DOORS COMPLETE FITTINGS AND REPLACE DAMAGED PARTS, TRANSFER ALL FITTINGS TO NEW DOOR.	New	300.00	60.00
2	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.	New	150.00	60.00
3	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT.	New	1,400.00	500.00
4	TO RESPRAY PAINTING INCLUDING POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.	New	1,200.00	600.00
			<b>Gross Labour Cost (\$)</b>	<b>3,050.00</b>
				<b>1,220.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >