

SGJ833B.
Toyota Wish. 1.754cc
ZNE100325146

TP111
Xiao Yang.

Rear Bumper	defound	485	✓
Rear Bumper Clips	na	30	✓
Rear Bumper Side Holder x02	na	58.1 x 2 = 116.20	✓
Rear Bumper Impact Bracket x02	na	68.4 x 2 = 136.80	✓
Rear Bumper	Damaged	280(SN) 200(SN)	
Rear End Panel	Repair	581.10	+
Rear End Panel Top Garnish	defound	326.20	✓
Rear End Panel Sealant	na	60(SN)	✓
Taillamp x02	na	417.9 x 2 = 835.80	+
Taillgate	Repair	1272.90	+
Taillgate Lock	Not in	487	+
Taillgate Weatherstripe		276.10	+
Taillgate Glass Moulding	na	140.60	+
Taillgate Glass Sealant	na	60(SN)	+
Toyota Logo	Na	74.10	✓

SGI8333B.

Panel Beating	1000 300
Spray Painting	800 400
Wiring	50 30
To remove reuse sensor	100 50
To remove upholstery	150 30
To remove tailgate (1/11)	180 +
To transfer tailgate fittings.	x. 150.

Inst: 1031.50 Labor: 810
Un 25%: 773.62 Total: 1783.62
S.N: 200 4/S: 1.4K
03 Pumps

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: