

ASS. REC. BY:

REF: CS/FCL18020317/Dsbm2

Special Instruction:

Surveyor: Bryan

ASSIGNMENT (Office)

From (Person): Mrs Eileen Lee

of FCL

Date/Time: 09.11.2018 11.55am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 8263U

Insured:

Q10 3608L

at Workshop m/s

Chunni Motor

Tel:

6542 5119

of

10 AMK Ind Park 2A #01-05

Policy No:

Claim No:

D18008000MFCM

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A.

07.11.2018

CA / REV / REP. / REV 24 HRS DS

Date/Time:

09.11.2018 1207pm

Person Contacted:

Irene

H.O.D. Endorsement:

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 8263U - NA / II 09107527 / SI
	SHD 3608L - R3 / CTL15015397 / Hlwu3n2
14/11/18	@ 16:37 p.m revised PA to Giken via email.

DOA: 06042009

DOA: 011092015

REF:

ASSIGNMENT

COE 2023 July

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 8HC 8263 U Yr Regn: July 2015
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Truck / Prime Mover /

Truck / Trailer or _____

Make: Hyundai I40 C.C. 1685Colour: Blue A/C Insured / Std / NI / NASp. Reading: 610288 T/Radio: Insured / Std / NI / NAEng/No: D4FDFU530101C/No: KMHLB41UM6U075697Gen. Cond: Good / Fair / Poor / BurntSteering: Insider / Jammed / Leaked / Burnt orBrake: Insider / Jammed / Leaked / Burnt orModi: Std / S/Rim / STD A/Rim orTyre Size: F: 205/60 R16R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wootke

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 07/11/2018 D.O.I. 09/11/2018Survey held at Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Body y o/s Rev

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
First Report SHD 3608L

04/12/18 Inspected H/S 11850/- with 9 days review

04/12/18 Confirmed H/S \$11,850/- @ 9 days with Bryan.
(\$7,464.48 Red - 39%)

RECEIVED 05 DEC 2018

Date/Time, File Pass to?

1) 05/12/18

Date/Time, File Return to?

2) 7/12/18☐ : Preli. Report☒ : Final ReportDays Of Repair: 9Resurvey No. of Trip: 2Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos OSP) Other 5/12/18

TOTAL

9x15 = 135170 + 1355050 + 50120575

Report Format :

Lump Sum / I.B.I: (\$ 11,850/- H/S)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008000MFSH

Date: 14 November 2018

Our Ref: CS/FCI18020317/Dsb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 8263U

Please be informed that we had conducted the inspection of the abovementioned vehicle on 09/11/2018 at the premises of M/s Chunni Motor Work Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 19,314.48</u>
Revised Estimate Amount	: <u>S\$ 16,866.80</u>
"Check" Items Amount	: <u>S\$</u>
Market Value	: <u>S\$</u>
LTA Reimbursement Value	: <u>S\$</u>
Nett Value	: <u>S\$</u>

Description of Damage:

The vehicle sustained damages at the o/s body & o/s rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 7 Days

Yours faithfully,

Bryan Ang

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	08-11-2018	Our Ref No. D18008000MFSH
Accident Date	07-11-2018	Claim Type. Third Party
Insured Vehicle	SHD3608L	Third Party Vehicle. SHC8263U
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	65427162/ 65425119	Fax No. 65426039
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 14 November 2018 4:57 PM
To: 'Eileen Lee'; 'CWS Motor Claims'
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: SURVEY ASSESSMENT - D18008000MFSH/1
Attachments: SHC 8263U - Preli Advise.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SHC 8263U.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 9 November 2018 12:08 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008000MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Friday, 9 November, 2018 11:55 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008000MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHC 8263U

DATE : 7.11.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

7C1

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Fender With Housing (RH) <i>Dented</i>			\$ 4,736.80	<i>✓</i>
	Rear Fender Inner Lining (RH) <i>SVC</i>			\$ 169.30	<i>X</i>
	Rear Windscreen Moulding <i>Hec</i>			\$ 28.30	<i>✓</i>
	Rear Door (RH) <i>Dented</i>			\$ 2,201.10	<i>✓</i>
	Rear Door Rubber (RH) <i>Hec</i>			\$ 280.50	<i>✓</i>
	Rear Door Gear/Regulator (RH) <i>OK</i>			\$ 242.80	<i>✓</i>
	Rear Door Power Motor (RH) <i>NH</i>			\$ 158.60	<i>X</i>
	Front Door (RH) <i>Dented</i>			\$ 2,256.40	<i>✓</i>
	Front Door Gear / Regulator (RH) <i>OK</i>			\$ 250.60	<i>✓</i>
	Front Door Power Motor, RH <i>NH</i>			\$ 296.40	<i>X</i>
	Door Centre Pillar Outer (RH) <i>Dented</i>			\$ 2,527.80	<i>✓</i>
	Rocker Panel Outer Garnish (RH) <i>cut</i>			\$ 341.40	<i>✓</i>
	Rear Tyre Rim (RH) <i>distorted</i>			\$ 325.30	<i>✓</i>
	Rear Wheel Hup-Cap (RH) <i>cut</i>			\$ 107.10	<i>✓</i>
	Rear Wheelbearing ING & Hub <i>OK</i>			\$ 362.00	<i>✓</i>
	Rear Trailing Arm (RH) <i>distorted</i>			\$ 192.00	<i>✓</i>
	Rear Assist (RH) <i>distorted</i>			\$ 145.70	<i>✓</i>
	Rear Shock Absorber (RH) <i>distorted</i>			\$ 276.30	<i>✓</i>
	Rear Shock Absorber Mounting (RH) <i>NH</i>			\$ 81.30	<i>X</i>
	Rear Crossmember <i>NH</i>			\$ 1,021.50	<i>X</i>
	Stabilizer Bar <i>distorted</i>			\$ 199.60	<i>✓</i>
	Stabilizer Link <i>distorted</i>			\$ 85.90	<i>✓</i>
	Rear Upper Arm (RH) <i>distorted</i>			\$ 335.75	<i>✓</i>
	Rear Lower Arm (RH) <i>distorted</i>			\$ 353.80	<i>✓</i>
	Rear Knuckle Arm (RH) <i>distorted</i>			\$ 545.60	<i>✓</i>
			15794.75		
			12635.80		
	SUB TOTAL			\$ 17,521.85	
	LESS 20%			\$ 3,504.37	
	DISCOUNTED TOTAL			\$ 14,017.48	
	Rear Windscreen Sealant <i>Hec</i>			\$ 46.00	Nett <i>✓</i>
	Rear Door Comfortdelgro & Apps Sticker (RH) <i>Hec</i>			\$ 80.00	Nett <i>✓</i>
	Front Door Coloured Comfort Logo (RH) <i>Hec</i>			\$ 75.00	Nett <i>✓</i>
	Rear Tyre (RH) <i>SVC</i>			\$ 216.00	Nett <i>X</i>
			201.00		
				\$ 417.00	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHC 8263 U

Technician:

Mileage: 610288

Time Printed 9.11.18 3:00 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°05'		-3°00' 3°00'
3°47'		-0°19' 5°41'
-0°48'		-1°30' 1°30'
16°08'		
16°03'		

Camber

Caster

Toe

SAI

Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°32'		-3°00' 3°00'
4°24'		-0°19' 5°41'
0°40'		-1°30' 1°30'
16°21'		
15°49'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
0°27'		-3°00' 3°00'
-0°37'		-3°00' 3°00'
-0°13'		-3°00' 3°00'
-0°09'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
0°35'		-3°30' 2°30'
0°20'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
5°40'		-3°30' 2°30'
7°09'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-5°05'		-3°00' 3°00'
7°29'		-3°00' 3°00'
-3°24'		-3°00' 3°00'



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18020317/Dsbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 10-12-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3608L	Veh. Inspected	SHC 8263U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008000MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	09/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KMHLB41UMGU075697	Colour	BLUE	
Odometer	610288	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND O/S REAR PORTION . DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/11/2018	Inspection Date	09/11/2018	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8263U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR FENDER WITH HOUSING (RH)	DENTED	4,736.80	4,736.80
1	REAR FENDER INNER LINING (RH)	SERVICEABLE	169.30	-
1	REAR WINDSCREEN MOULDING	NECESSARY	28.30	28.30
1	REAR DOOR (RH)	DENTED	2,201.10	2,201.10
1	REAR DOOR RUBBER (RH)	NECESSARY	280.50	280.50
1	REAR DOOR GEAR/REGULATOR (RH)	CRACKED	242.80	242.80
1	REAR DOOR POWER MOTOR (RH)	NOT NECESSARY	158.60	-
1	FRONT DOOR (RH)	DENTED	2,256.40	2,256.40
1	FRONT DOOR GEAR/REGULATOR (RH)	CRACKED	250.60	250.60
1	FRONT DOOR POWER MOTOR, RH	NOT NECESSARY	296.40	-
1	DOOR CENTRE PILLAR OUTER (RH)	DENTED	2,527.80	2,527.80
1	ROCKER PANEL OUTER GARNISH (RH)	CUT	341.40	341.40
1	REAR TYRE RIM (RH)	DISTORTED	325.30	325.30
1	REAR WHEEL HUP-CAP (RH)	CUT	107.10	107.10
1	REAR WHEELBEARING ING & HUB	DAMAGED	362.00	362.00
1	REAR TRAILING ARM (RH)	DISTORTED	192.00	192.00
1	REAR ASSIST (RH)	DISTORTED	145.70	145.70
1	REAR SHOCK ABSORBER (RH)	DISTORTED	276.30	276.30
1	REAR SHOCK ABSORBER MOUNTING (RH)	NOT NECESSARY	81.30	-
1	REAR CROSSMEMBER	NOT NECESSARY	1,021.50	-
1	STABILIZER BAR	DISTORTED	199.60	199.60
1	STABILIZER LINK	DISTORTED	85.90	85.90
1	REAR UPPER ARM (RH)	DISTORTED	335.75	335.75
1	REAR LOWER ARM (RH)	DISTORTED	353.80	353.80
1	REAR KNUCKLE ARM (RH)	DISTORTED	545.60	545.60
	LESS 20% DISCOUNT		-3,504.37	-3,158.95
			14,017.48	12,635.80
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (RH) (SN)	NECESSARY	80.00	80.00

Report Ref No. CS/FCI18020317/Dsbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DOOR COLOURED COMFORT LOGO (RH)(SN)	NECESSARY	75.00	75.00
1	REAR TYRE (RH)(SN)	SERVICEABLE	216.00	-
			417.00	201.00
	LABOUR			
	PANEL BEATING.		1,600.00	800.00
	SPRAY PAINTING CHARGE.		1,250.00	700.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX REVERSE SENSOR.	NOT NECESSARY	120.00	-
	REMOVE/REFIX UNDERCARRIAGE (RR).		200.00	150.00
	TRANSFER OF DOOR.		240.00	120.00
	REAR WHEEL ALIGNMENT.		120.00	60.00
	RE-SET REAR ABS SYSTEM.	NOT NECESSARY	200.00	-
	RE-SET REAR POWER WINDOW SYSTEM.	NOT NECESSARY	200.00	-
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	480.00	-
			4,880.00	2,030.00
	GRAND TOTAL		19,314.48	14,866.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			11,850.00

Report Ref No. CS/FC118020317/Dsbn2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.