

ASS. REC. BY:

REF:

CS/FCU18020323/Ktbz

Special Instruction:

Surveyor:

Kermit

## ASSIGNMENT (Office)

From (Person):

CWS Serene Lee

of

FCL

Date/Time:

08-11-2018 6:40pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFB 5000K

Insured:

SHC 1189Y

at Workshop m/s

Lim Tan Motor.

Tel:

8484 5418

of

176 Sin Ming Drive #03-05

Policy No:

Claim No:

D1800793-TMFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

02.11.2018

CA / REV / REP. / REV 24 HRS '08'

H.O.D. Endorsement:

Date/Time:

08/12/2018 8:59am

Person Contacted:

Richard

Vehicle: IN / OUT

| Date/Time      | Action/Instruction (✓) Estimate      |
|----------------|--------------------------------------|
|                | SFB 5000K - X                        |
|                | SHC 1189Y - NS / INC 17011702 / Ktbz |
|                | DA: 260317                           |
| 21/12 @ 4.23pm | Revised preli via email.             |
| 6/1/2          | 84346.24 Costum (Red: 1261.60 '2070) |

REF: FCI

## ASSIGNMENT

From: Date: 09-11-08

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SFB 5000K

at Workshop m/s: Lim Tan

of 176 Sin Ming Drd #03-09

Insured:

Policy No:


Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: 880k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4-5 days Res.: Yes or No

Lum Sum: 1.81 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SFB 5000K Yr Regn: 08 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Subaru Forester 0.0

Colour: M. Black A/C: Insured / Std / NI / NA

Sp. Reading: 24225 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / 8/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 2/11/18

Survey held at

Rear

R/Bal. 9 mm

L/Bal. 9 mm

D.O.I. 9/11/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12/11 Make parts Certificate

RECEIVED 11 DEC 2018

Date/Time, File Pass to?

1) 11/12 Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.S. (\$) TP 4346.24

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

) S+RS: \$

) Photos

) Other:

TOTAL

140

50

50

22

262



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007937MFSH

Date: 12/11/2018

Our Ref: CS/FC118020323/Ktb

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SFB 5000K

Please be informed that we had conducted the inspection of the abovementioned vehicle 9/11/2018 at the premises of M/s Lim Tan Motor have the following to report: -

|                          |                |
|--------------------------|----------------|
| Workshop Estimate Amount | : S\$ 5,607.84 |
| Revised Estimate Amount  | : S\$ 3,846.24 |
| "Check" Items Amount     | : S\$ 1,381.60 |
| Market Value             | : S\$          |
| LTA Reimbursement Value  | : S\$          |
| Nett Value               | : S\$          |

Description of Damage:

The vehicle sustained damages at the  
Rear O/S portion.



**Comments/ Present Status:**

Damages Consistent.

Yours faithfully

Rasul

Automotive Assessor

## Denise Tay (LKKAUTO)

---

**From:** Denise Tay (LKKAUTO)  
**Sent:** Monday, 12 November 2018 4:28 PM  
**To:** Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments  
**Cc:** 'Serene Ler'; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18007937MFSH/1  
**Attachments:** PRELI ADVISED SFB 5000K.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SFB 5000K**

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Friday, 9 November 2018 8:59 AM  
**To:** 'CWS Motor Claims' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Serene Ler' <[Sereneler@msfirstcapital.com.sg](mailto:Sereneler@msfirstcapital.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D18007937MFSH/1

Dear Sir / madam,

Thank you for the assignment.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Thursday, 8 November, 2018 6:40 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; Serene Ler <[Sereneler@msfirstcapital.com.sg](mailto:Sereneler@msfirstcapital.com.sg)>  
**Subject:** PRI: SURVEY ASSESSMENT - D18007937MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note:** All the accident reports are uploaded into CWS for your perusal.

**MOTOR SURVEY ASSIGNMENT**

|                           |                                                       |                                      |
|---------------------------|-------------------------------------------------------|--------------------------------------|
| <b>Date</b>               | 05-11-2018                                            | <b>Our Ref No.</b> D18007937MFSH     |
| <b>Accident Date</b>      | 02-11-2018                                            | <b>Claim Type.</b> Third Party       |
| <b>Insured Vehicle</b>    | SHC1189Y                                              | <b>Third Party Vehicle.</b> SFB5000K |
| <b>Survey Location</b>    | BLK 176 SIN MING DRIVE #03-09/10/06 SIN MING AUTOCARE |                                      |
| <b>Contact Person.</b>    | RICHARD ANG                                           |                                      |
| <b>Contact No.</b>        | 64520893/ 84845418                                    | <b>Fax No.</b> 64589127              |
| <b>Survey Type</b>        | DIRECT SETTLEMENT: EST. COR - \$5,607.84              |                                      |
| <b>Appointed Surveyor</b> | LKK AUTO CONSULTANTS PTE LTD                          |                                      |
| <b>Contact Person</b>     | NA                                                    | <b>Fax No.</b> 68416315              |
| <b>Contact Number.</b>    | NA                                                    |                                      |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                          |                       |                                |
|--------------------------|-----------------------|--------------------------------|
| <b>Cc : Workshop</b>     | LIM TAN MOTOR PTE LTD | <b>Attention.</b> NIL          |
| <b>Cc : TP Solicitor</b> | NA                    | <b>TP Solicitor Fax No.</b> NA |
| <b>Officer Incharge</b>  | SERENE                |                                |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC  
Owner ID: 9983G

**Vehicle Details**

Vehicle No.: SFB5000K  
Vehicle to be Exported: No  
Intended Deregistration Date: 07 Nov 2018  
Vehicle Make: SUBARU  
Vehicle Model: FORESTER 2.0XT CVT AWD SR  
Primary Colour: Black  
Manufacturing Year: 2015  
Engine No.: FA20K883055  
Chassis No.: JF1SJGK85FG053734  
Maximum Power Output: 177.0 kW (237 bhp)  
Open Market Value: \$17,141.00  
Original Registration Date: 28 Aug 2015  
First Registration Date: 28 Aug 2015  
Transfer Count: 0  
Actual ARF Paid: \$17,141.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 27 Aug 2025  
PARF Rebate Amount: \$12,855.00

**Intended COE Rebate Details**

COE Expiry Date: 27 Aug 2025  
COE Category: B - Car above 1600cc or 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$60,789.00  
COE Rebate Amount: \$41,359.00  
**Total Rebate Amount: \$54,214.00**

The information contained herein is correct as at 07 Nov 2018

OK





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18020323/Ktbn2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 17-12-2018



Code : FCI2

#### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |               |                |            |
|--------------|---------------|----------------|------------|
| Insured Veh. | SHC 1189Y     | Veh. Inspected | SFB 5000K  |
| Policy No.   |               | Coverage (\$)  | 0.00       |
| Claim No.    | D18007937MFSH | Excess (\$)    | 0.00       |
| Assign From  | SERENE        | Assign Date    | 08/11/2018 |

#### 2. Vehicle Particulars & Condition

|              |                     |              |                |
|--------------|---------------------|--------------|----------------|
| Make & Model | SUBARU FORESTER (A) | c.c          | 1998           |
| Engine No.   | HIDDEN              | Year of Reg. | 2015           |
| Chassis No.  | JF1SJGK85FG053734   | Colour       | METALLIC BLACK |
| Odometer     | 24225               | Steering     | IN ORDER       |
| Brakes       | IN ORDER            | Modification | SPORTS RIM     |
| General      | GOOD                |              |                |

#### 3. Conditions of Tyres

|                | Size       | Make        | Balance |
|----------------|------------|-------------|---------|
| R/H Front Tyre | 235/55 R18 | BRIDGESTONE | 9 mm    |
| L/H Front Tyre | 235/55 R18 | BRIDGESTONE | 9 mm    |
| R/H Rear Tyre  | 235/55 R18 | BRIDGESTONE | 9 mm    |
| L/H Rear Tyre  | 235/55 R18 | BRIDGESTONE | 9 mm    |

#### 4. Description of Damages

|                                                                                |
|--------------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.<br>DAMAGES SEE DETAILS. |
|--------------------------------------------------------------------------------|

#### 5. General Information

|                |                                                                                                 |                 |            |
|----------------|-------------------------------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 02/11/2018                                                                                      | Inspection Date | 09/11/2018 |
| Survey held at | LIM TAN MOTOR PTE LTD<br>BLK 176 SIN MING DRIVE<br>#03-09 SIN MING AUTOCARE<br>SINGAPORE 575721 |                 |            |

#### 5a. Remarks

|                                                                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

#### 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 5 Working Days |
|-------------------------------------|----------------|





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFB 5000K

| Qty                         | Description of Parts                       | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|--------------------------------------------|----------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                            |                      |                           |                   |
| 1                           | REAR BUMPER                                | BUCKLED              | 600.00                    | 600.00            |
| 1                           | REAR BUMPER REINFORCEMENT                  | TO REPAIR SEE LABOUR | 320.00                    | -                 |
| 1                           | O/S REAR BUMPER STABILIZER                 | SERVICEABLE          | 16.00                     | -                 |
| 1                           | O/S REAR BUMPER REFLECTOR                  | CRACKED              | 22.80                     | 22.80             |
| 1                           | REAR BUMPER TOP PANEL                      | CRACKED              | 410.00                    | 410.00            |
| 10                          | REAR BUMPER CLIPS @\$3.80                  | NECESSARY            | 38.00                     | 38.00             |
| 1                           | REAR END PANEL                             | TO REPAIR SEE LABOUR | 320.00                    | -                 |
| 1                           | TAILGATE                                   | BENT                 | 1,192.00                  | 1,192.00          |
| 1                           | CENTRE EMBLEM                              | NECESSARY            | 88.00                     | 88.00             |
| 1                           | TAILGATE SUBARU EMBLEM                     | NECESSARY            | 72.00                     | 72.00             |
| 1                           | TAILGATE FORESTER EMBLEM                   | NECESSARY            | 56.00                     | 56.00             |
| 1                           | TAILGATE XT EMBLEM                         | NECESSARY            | 72.00                     | 72.00             |
| 1                           | REAR WINDSCREEN MOULDING                   | NECESSARY            | 64.00                     | 64.00             |
| 1                           | O/S REAR EXHAUST SILENCER                  | BENT                 | 688.00                    | 688.00            |
| 1                           | REAR EXHAUST SILENCER CHROME PIPE          | DENTED               | 80.00                     | 80.00             |
| 2                           | REAR EXHAUST MOUNTING @\$48.00             | SERVICEABLE          | 96.00                     | -                 |
|                             | LESS 20% DISCOUNT                          |                      | -826.96                   | -676.56           |
|                             |                                            |                      | 3,307.84                  | 2,706.24          |
| <b>SPECIAL NETT ITEMS</b>   |                                            |                      |                           |                   |
| 1                           | TUBE REAR WINDSCREEN SEALANT (SN)          | NECESSARY            | 40.00                     | 40.00             |
| 1                           | SET REAR BUMPER SENSOR (SN)                | SHORTED              | 200.00                    | 200.00            |
|                             |                                            |                      | 240.00                    | 240.00            |
| <b>LABOUR</b>               |                                            |                      |                           |                   |
|                             | TO PUTTY AND SPRAY PAINTING.               |                      | 1,000.00                  | 660.00            |
|                             | TO TRANSFER TAILGATE FITTINGS.             |                      | 80.00                     | 60.00             |
|                             | TO REMOVE AND REFIX REAR WINDSCREEN GLASS. |                      | 120.00                    | 120.00            |
|                             | TO ANTI-RUST.                              | NOT NECESSARY        | 80.00                     | -                 |
|                             | TO REPLACE REAR EXHAUST SILENCER BOX.      |                      | 80.00                     | 60.00             |

Report Ref No. CS/FCI18020323/Ktbn2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                         | Description of Parts                                                                   | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|----------------------------------------------------------------------------------------|-----------|---------------------------|-------------------|
|                             | LABOUR CHARGES INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT AND REAR END PANEL |           | 700.00                    | 500.00            |
|                             |                                                                                        |           | 2,060.00                  | 1,400.00          |
| GRAND TOTAL                 |                                                                                        |           | 5,607.84                  | 4,346.24          |
| RECOMMENDED COST OF REPAIRS |                                                                                        |           |                           | 4,346.24          |

Report Ref No. CS/FCI18020323/Ktbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.