

ASS. REC. BY: CS3/MSG18012468/Gvb-1 ^{er} Special Instruction: _____

Surveyor: Guo Qiang ASSIGNMENT (Office)

Meimen Fievel Foo of MSIG Date/Time: 07.11.2018

From (Person): _____

Estimated Cost: _____ Bill to: _____

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV7 CS

To Inspect Vehicle No: SJG 5848H Insured: SJQ 529J

at Workshop in/s: Htiap Lek Automobile Tel: 9660 1347

of: 160 8th Ming Drive # 05-17

Policy No: 2907 4773SMA Claim No: 563729

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A: 04/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS ^{up}

Date/Time: 5.01pm @ 9/7/18 Person Contacted: Mr Ong H.O.D. Endorsement: _____

Vehicle IN (OUT)

Date/Time	Action/Instruction (X) Estimate	Don't Finalize
	<u>SJG 5848H - X</u>	
	<u>SJQ 529J - X</u>	
	<u>Dismantle Part: 20072018</u>	
	<u>\$2950, 5 Day.</u>	
<u>19/11/18</u>	<u>Submit LS \$3000, 4 days</u>	
	<u>(Red 1550, 341)</u>	
	<u>Repair days 5</u>	
		<u>16/11/2018</u>

RECEIVED 19 NOV 2018

TGim

lin

15/11/18

PRS

REF: MSLH

6377E

ASSIGNMENT

C-2023)

From: Date: 19072018

Estimated Cost:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJG 5848H

at Workshop m/s

of

Hicap Lek
160 Sim Ming Drive # 05-17

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SJG 5848H

Yr Regn:

08 Jul 2008

Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota

C.C

1497

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading:

160542

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR053HY 9305070843

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/55R15

R:

"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Naxen

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

19-07-18

Survey held at

W/S

2230pm

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S Lt

The ☒ UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$4000 - \$5000

23/7/18

Submit PRS Report.

RECEIVED 23 JUL 2018

Date/Time, File Pass to?

☐

Preli. Report

☐

Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee.

Transportation

) S + RS SI

) Photos

) Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

120

10

130

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Jul 2018		09 Jul 2018 16:05 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS			[Created by insurer]
Insured:	Kulandaisamy Antony, Ilamchelian, ID: S7784496A		
Main Claimant:	Caron Ong Kai Loon, ID: S8276377E		
Vehicle Reg. No.:	SJG5848H	Date of Loss:	04/07/2018 22:00 - :59 [119 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 563729	Policy/Cover Note No.:	29074773SMA (Comprehensive) Coverage: 23/04/2018 - 22/04/2019
Vehicle Reg. No. (Insured):	SJQ529J	Policy No. (Claimant):	
		Excess:	
Repairer:	Hiap Lek Automobile Trading (HQ) 160 Sin Ming Drive, #05-17 Sin Ming Autocity, 575722 Sin Ming - Tel: 64531743		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wen-yao - 6643 1316]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 09/11/2018]		
Adj Asg. Remarks:	OI not reported SJE disagree - assign LKK Contact : Hanwei at 9660 1347		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
● MSIG_SG (07/11/2018): Report Send Back Alerts - SJG5848H (TP)		

ALL ASSOCIATED TASKS						View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6377E
Vehicle Details	
Vehicle No.:	SJG5848H
Vehicle to be Exported:	No
Intended De-registration Date:	20 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	1NZX775499
Chassis No.:	MR053HY9305070843
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,344.00
Original Registration Date:	08 Jul 2008
First Registration Date:	08 Jul 2008
Transfer Count:	2
Actual ARF Paid:	\$12,344.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	07 Jul 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$18,583.00
COE Rebate Amount:	\$18,446.00
Total Rebate Amount:	\$18,446.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 20 Jul 2018

OK

UNITED Appraisal And Management Pte Ltd

Motor Vehicle Appraiser and Insurance Loss Adjuster
No. 8 Kaki Bukit Ave 4 #06-21 Premier @ Kaki Bukit Singapore 415875
Handphone No. : +65 9146 1186 Email : united.appraisal@live.com.sg
Business Registration Nos. : 200817301N

INVOICE

To : Caron Ong Kai Loon
c/o : Hiap Lek Automobile Trading
160 Sin Ming Drive
#05-17 Sin Ming Autocity
Singapore 575722

Date : 15 Aug 2018

Invoice No. : 8092973

DESCRIPTION	AMOUNT
Service rendered for appraisal / inspection report :	
Professional inspection fees	SGD 450.00
Photographs 40 pcs	
Transport fees	
Re-inspection fees (work in progress, post repair inspection)	
Total	SGD 450.00
Singapore dollar : FOUR HUNDRED FIFTY ONLY.	
Registration no. : SJG5848H	
Make/Model : Toyota Vios E Auto	
Our reference : UAM18.07.13-AK-STP-HLA-SJG5848H	
<i>All payments made payee to:-</i> " UNITED APPRAISAL & MANAGEMENT PTE LTD "	



for UNITED APPRAISAL & MANAGEMENT PTE LTD

UNITED Appraisal And Management Pte Ltd

Motor Vehicle Appraiser and Insurance Loss Adjuster
No. 8 Kaki Bukit Ave 4 #06-21 Premier @ Kaki Bukit Singapore 415875
Handphone No. : +65 9146 1186 Email : united.appraisal@live.com.sg
Business Registration Nos. : 200817301N

Our ref. : UAM18.07.13-AK-STP-HLA-SJG5848H

Date : 15 Aug 2018

Caron Ong Kai Loon

WITHOUT PREJUDICE

Dear Sir,

Re : Third Party Claim For Vehicle Registration No. SJG5848H

We refer to your instruction to appraise the above-mentioned vehicle on 18 July 2018

A static inspection was carried out and our report is enclosed for your perusal. The estimated cost of repair submitted by Messrs. Hiap Lek Automobile Trading for SGD 7,802.22 as per our attached schedule has been inspected thoroughly by us against the actual damages sustained on the above-mentioned vehicle and we recommend the replacement and rectification accordingly.

Our revised quotation for the repair is SGD 5,725.75. In our opinion, it to be excessive. Therefore, we recommend a contract lump-sum repair cost. This is more economical than to have the above-mentioned vehicle repaired on parts by/for parts basis. Invariably, the repairer has the prerogative/option for the recommended replacement parts to either be repaired or be replaced.

We have negotiated with the repairer and they have agreed to repair the above-mentioned vehicle for SGD 4,550.00 NETT. Which, in our opinion is fair and reasonable.

The repairer has agreed to undertake the repairs to your requirement at the recommended contract lump-sum. However, we have not given any instruction and authorisation to the repairer to proceed with the repairs.

Under normal circumstances, the entire repair of the damaged vehicle should be completed within a reasonable period of 4 (Four) days.

We are reverting the matter to you for a decision, and enclosed is our vehicle inspection report, appraisal schedule and invoice for services rendered.

Please do not hesitate to contact us if you have any queries on this matter.

Yours faithfully,

United Appraisal & Management Pte Ltd



Ananda K. Biswas Marc

Motor Vehicle Appraiser

Encls. :

The information contained in these document may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you received this document by error, please contact us immediately to arrange for its return.

UNITED Appraisal And Management Pte Ltd

Motor Vehicle Appraiser and Insurance Loss Adjuster
No. 8 Kaki Bukit Ave 4 #06-21 Premier @ Kaki Bukit Singapore 415875
Handphone No. : +65 9146 1186 Email : united.appraisal@live.com.sg
Business Registration Nos. : 200817301N

VEHICLE INSPECTION REPORT

To : Caron Ong Kai Loon

Our ref. : UAM18.07.13-AK-STP-HLA-SJG5848H

Date : 15 Aug 2018

REFERENCE

Assign by	: Caron Ong Kai Loon	Insured	: To be advice
Assign on	: 18 Jul 2018	Policy no.	: To be advice
Inspection on	: 18 Jul 2018	Claim no.	: To be advice
Accident on	: 04 Jul 2018	Sum insured	: To be advice
Workshop name	: Hiap Lek Automobile Trading	Excess	: Not applicable
Inspection at	: 160 Sin Ming Drive	3rd party Veh.	: To be advice
	#05-17 Sin Ming Autocity	3rd party ins.	: To be advice
	Singapore 575722		

PARTICULARS OF DAMAGED VEHICLE

Registration no.	: SJG5848H	Odometer	: 160542 km
Make / Model	: Toyota Vios E Auto	Chassis no.	: MR053HY9305070843
Regn. date	: 08 Jul 2008	Engine no.	: 1NZX775499
Body colour	: Green	Engine cap.	: 1497 cc

PRE-ACCIDENT CONDITION OF VEHICLE (STATIC CHECK ONLY)

Steering	: In order	Paintwork	: Good
Footbrake	: In order	Undercarriage	: Serviceable
Handbrake	: In order	Gen. condition	: Good

TYRE CONDITION ON VEHICLE


	Make	Size	Tread depth	Type of road wheel
Front N/S	: Nexen	195/55R15	70%*	Alloy*
Front O/S	: Nexen	195/55R15	70%	Alloy
Rear N/S	: Nexen	195/55R15	70%	Alloy
Rear O/S	: Nexen	195/55R15	70%	Alloy

NOTE: The above percentages represent the estimated remaining life of tyre threads.

* Denotes damaged component/s

POINT OF IMPACT

On the near side front in the direction from left to right.

**SYNOPSIS OF DAMAGES RESULTANT FROM THE ACCIDENT**

The impact of the collision has damaged / affected the n/s front fender, front undercarriage, headlamp, front bumper and etc...

Please refer to Annex A (Appraisal Schedule) for a detailed account of the damages and photographs taken.

Note: Reinspection vehicle on 20 Jul 2018 for repair in progress.

RECOMMENDATION

The estimate cost of repair submitted by Messrs Hiap Lek Automobile Trading as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairers have agreed to undertake the repairs to the owner's satisfaction at our revision. We have not authorised the repairs.

Our adjusted cost of repair is SGD 4,550.00 to carry out the repairs. Please refer to Annex A (Appraisal Schedule) for a detailed account of the cost estimates.

REMARKS

We have not authorised the repair. However, for information, under normal circumstances, the repair would take approximately 4 (Four) working days to complete.

In accordance with your instruction, we have **NOT AUTHORISED** the repair to the damaged vehicle and the survey was conducted strictly on a "**WITHOUT PREJUDICE**" basis.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Appraisal Report, which includes evidence photographs.

Yours faithfully,
United Appraisal & Management Pte Ltd



Ananda K. Biswas Marc
Motor Vehicle Appraiser

APPRAISEMENT SCHEDULE

Annex A

Registration no. : SJG5848H

Our reference : UAM18.07.13-AK-STP-HLA-SJG5848H

S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adjusted Amt SGD
<u>LIST ITEMS</u>					
1	1	Front fender n/s	Dented	447.32	< 447.32 DD
2	1	Front fender inner shield n/s	Deformed	125.90	< 125.90 CRA
3	1 set	Front fender inner shield clip n/s	Necessary	25.00	< 25.00 NEC
4	1	Front knuckle arm n/s	Affected	295.40	< 295.40
5	1	Front knuckle arm bearing n/s	Affected	261.20	< 261.20 BT
6	1	Front lower arm n/s	Affected	362.00	< 362.00
7	1	Front shock absorber n/s	Affected	270.50	X 270.50 X
8	1	Front shock absorber mounting n/s	Affected	98.90	X 98.90 X
9	1	Front anti-roll bar link n/s	Re-Used	110.00	0.00
10	1	Driveshaft n/s	Affected	878.80	X 878.80 NND
11	1	Headlamp assy n/s	Cracked	585.60	< 585.60 CRA
12	1	Front bumper	Deformed	469.00	< 469.00 CUT
13	1 set	Front bumper clip	Necessary	50.00	< 50.00 NEC
14	2	Front bumper side retainer @ SGD 54.55	N/S Distorted	109.10	< 54.55 NEC
15	1	Front fog lamp	Cracked	324.00	< 324.00 CRA
16	1	Front fog lamp garnish	Deformed	102.00	< 102.00 CUT
17	1	Front fog lamp garnish chrome	Cracked	97.50	< 97.50 CRA
				4612.22	4447.67
				Less 0% / 25%	0.00 1111.92
				4612.22	3335.75
<u>SPECIAL NETT ITEMS</u>					
1	1	Sundries	Necessary	50.00	30.00 NND
2	1	Front alloy rim n/s	Grazed	380.00	280 350.00 CX
3	1	Front tyre n/s	Cut NO PIC	180.00	150.00 NNX
4	1	Front number plate with casing	Bend	100.00	80.00 NND
				710.00	610.00
TOTAL				5322.22	3945.75

2/99.47

25%: 2399.6

APPRAISEMENT SCHEDULE

Annex A

Registration no. : SJG5848H

Our reference : UAM18.07.13-AK-STP-HLA-SJG5848H

S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adjusted Amt SGD
			Balance C/F	5322.22	3945.75
<u>LABOUR & MISC CHARGES</u>					
1		To dismantle / renew the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.		1000.00	600.00 400
2		To disconnect wire harness of electrical component to facilitate repairs, reconnect and check functions.		80.00	40.00 60.00
3		To remove and refit rear undercarriage for replacement of part.		300.00	100.00 280.00
4		To remove and refit n/s front tyre to replace n/s front alloy rim. To perform tyre balancing.		80.00	60.00 30
5		To conduct computerize full wheel alignment.		120.00	100.00 50
6		To apply undercoating on the accident repair and replaced panel for rust protection.		100.00	80.00 60
7		Supply spray paint material and necessary items to respray n/s front fender, front bumper and other affected area / panel.		800.00	400.00 600.00
TOTAL				2480.00	1780.00
Total Parts and Labour Cost of Repair				7802.22	5725.75
Less (Lumpsum repair adjustment)					1175.75
Adjustment Parts and Labour Cost of Repair					4550.00

Repair days 5
3729.6
20% = 2950

TCUim

im

15/11/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Jul 2018		09 Jul 2018 16:05 Edit Adj Rpt	S\$3,000.00 Edit Estimates	S\$3,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: Kulandaisamy Antony, Ilamchelian , ID: S7784496A									
Main Claimant: Caron Ong Kai Loon , ID: S8276377E									
Vehicle Reg. No.: SJG5848H		Date of Loss:	04/07/2018 22:00 - :59 [119 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type: TP / 563729		Policy/Cover Note No.:	29074773SMA (Comprehensive) Coverage: 23/04/2018 - 22/04/2019						
Vehicle Reg. No. (Insured): SJQ529J		Policy No. (Claimant):							
		Excess:							
Repairer: Hiap Lek Automobile Trading (HQ) 160 Sin Ming Drive, #05-17 Sin Ming Autocity, 575722 Sin Ming - Tel: 64531743									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 09/11/2018]									
Adj Asg. Remarks: OI not reported SJE disagree - assign LKK Contact : Hanwei at 9660 1347									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (07/11/2018): Report Send Back Alerts - SJG5848H (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJG5848H (563729)**
[SJQ529J]
TP
Caron Ong Kai Loon
Jul 4 2018 10:00PM
[Kulandaisamy Antony, Ilamchelian]
Hiap Lek Automobile Trading

Upload Documents	Upload Photos	Compose New Letter	View	View in Browser
------------------	---------------	--------------------	-------------	-----------------

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	12/07/18 14:12	Accident Statement From: SC - Reg. No: SJQ529J, Claimant: KULANDAISAMY ANTONY ILAMCHELIAN		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/07/18 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
2	20/07/18 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
3	20/07/18 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
4	20/07/18 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
5	20/07/18 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
6	20/07/18 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
7	20/07/18 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
8	20/07/18 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
9	20/07/18 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
10	20/07/18 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
11	20/07/18 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
12	20/07/18 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
13	20/07/18 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
14	20/07/18 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
15	20/07/18 11:00	General View		Load JPG	<input checked="" type="checkbox"/>
16	20/07/18 11:00	General View		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	09/07/18 09:50	PRI from C Paglar & Co		Load PDF	
2	09/07/18 10:25	Our reply that we are unable to accept their nominated - assign LKK		Load PDF	
3	09/07/18 10:25	Survey workshop - Hiap Lek Automobile Trading		Load PDF	
4	12/07/18 14:12	SJG5848H E-FILE & POLICE REPORT From: SC - Reg. No: SJQ529J, Claimant: KULANDAISAMY ANTONY ILAMCHELIAN		Load PDF	
5	07/11/18 11:14	Survey report & Photos		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

--

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18012468/GVBE2-1

Date: 21/11/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29074773SMA

Claimant Vehicle No : SJG5848H

Insured Vehicle No : SJQ529J

Date of Loss: 04/07/2018

Nature of Claim: TP

Claim No: 563729

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJG5848H**

Make & Model: TOYOTA VIOS, 1.5 E (A)

Reg. Date: 08/07/2008 (Man. Year: 2008)

Colour: Silver

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 1NZX775499

Chassis No: MR053HY9305070843

Odometer: 160542 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15

Rear Tyre Size: 195/55 R15

Front Left Side: Nexen 6 mm

Rear Left Side: Nexen 6 mm

Front Right Side: Nexen 6 mm

Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,322.22	2,679.60	2,642.62	49.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,480.00	1,090.00	1,390.00	56.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,802.22	3,769.60	4,032.62	51.69
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	7,802.22	3,000.00	4,802.22	61.55

INSPECTION

Date of Assignment: 09/07/2018

Date Inspected: 19/07/2018 Inspected At:

Hiap Lek Automobile Trading (HQ)
160 Sin Ming Drive, #05-17 Sin Ming
Autocity
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Nov 2018)
Parts: 143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJG5848H)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER N/S	Dented	447.32 F	*447.32 FL
2	1		*FRONT FENDER INNER SHIELD N/S	Cracked	125.90 F	*125.90 FL
3	1		*SET FRONT FENDER INNER SHIELD CLIP N/S	Necessary	25.00 F	*25.00 FL
4	1		*FRONT KNUCKLE ARM N/S	Bent	295.40 F	*295.40 FL
5	1		*FRONT KNUCKLE ARM BEARING N/S	Bent	261.20 F	*261.20 FL
6	1		*FRONT LOWER ARM N/S	Bent	362.00 F	*362.00 FL
7	1		*FRONT SHOCK ABSORBER N/S	Not Necessary	270.50 F	*- FL
8	1		*FRONT SHOCK ABSORBER MOUNTING N/S	Not Necessary	98.90 F	*- FL
9	1		*FRONT ANTI-ROLL BAR LINK N/S	Re-used	110.00 F	*- FL
10	1		*DRIVESHAFT N/S	Not Necessary	878.80 F	*- FL
11	1		*HEADLAMP ASSY N/S	Cracked	585.60 F	*585.60 FL
12	1		*FRONT BUMPER	Cut	469.00 F	*469.00 FL
13	1		*SET FRONT BUMPER CLIP	Necessary	50.00 F	*50.00 FL
14	1		*FRONT BUMPER SIDE RETAINER	N/S Necessary	109.10 F	*54.55 FL
15	1		*FRONT FOG LAMP	Cracked	324.00 F	*324.00 FL
16	1		*FRONT FOG LAMP GARNISH	Cut	102.00 F	*102.00 FL
17	1		*FRONT FOG LAMP GARNISH CHROME	Cracked	97.50 F	*97.50 FL
18	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
19	1		*FRONT ALLOY RIM N/S	Cut	380.00 FS	*280.00 FS
20	1		*FRONT TYRE N/S	Not Necessary	180.00 FS	*- FS
21	1		*FRONT NUMBER PLATE WITH CASING	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,322.22	3,479.47
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	799.87
Total Parts (\$\$)	5,322.22	2,679.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	1,000.00	400.00
2	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS	New	80.00	40.00
3	TO REMOVE AND REFIT REAR UNDERCARRIAGE FOR REPLACEMENT OF PART	New	300.00	100.00
4	TO REMOVE AND REFIT N/S FRONT TYRE TO REPLACE N/S FRONT ALLOY RIM. TO PERFORM TYRE BALANCING	New	80.00	30.00
5	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	60.00
6	TO APPLY UNDERCOATING ON THE ACCIDENT REPAIR AND REPLACED PANEL FOR RUST PROTECTION	New	100.00	60.00
7	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY N/S FRONT FENDER, FRONT BUMPER AND OTHER AFFECTED AREA / PANEL	New	800.00	400.00
Gross Labour Cost (\$\$)			2,480.00	1,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >