

12802260

REF: CS/CT118020352 / NGBS2 Special Instruction:

ASS. REC. BY:

ASSIGNMENT (Office)

SURVEYOR

Mulimen

From (Person):

Dng Chim Kiat

of

CTI

Date/Time: 09/11/2018 3:06pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PC 7635S

Insured:

686 7953T

at Workshop n/s

Connect 3

Tel:

9850 9666

of

566 Woodlands Rd

Policy No:

DmCVS/3067991800

Claim No:

SNM18005281002

Sum Insured:

Excess:

D.O.A.

07/11/2018

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS w/p

12-11-2018 @ 10am

H.O.D. Endorsement:

Date/Time:

09-11-2018 3:26pm

Person Contacted:

Winnie

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	PC 7635S - NGA (CT118020189 / Y	DA-07112018
	686 7953T - X	
05/07/19	@ 17:45 pm checked with Winnie Gopner, vehicle has not sent in for repair.	

27/11/19 re-open case for finalize: ~~Callie 27/11/19~~

~~27/11/19~~ file pass to typist after re-open.
28/11/19 reopen ref only * 1st closedate 12/11/19 ↓

Shirley Hiew (LKK Auto)

From: Winnie Chai <connect3winnie@gmail.com>
Sent: Friday, 22 November 2019 9:52 am
To: Naz (LKKAuto)
Cc: Shirley Hiew (LKK Auto); SUR
Subject: Re: Finalization for PC 76355

Please proceed.

On Thu, Nov 21, 2019 at 11:43 AM Naz (LKKAuto) <Naz@lkkauto.com> wrote:

Dear Ms Chai,

Apologies for the miscalculation. Attached herewith is the amended marked estimate. We will proceed to finalize if you are agreeable with the
Lump Sum COR of \$4650.00 / 4 REPAIR DAYS.

I humbly apologize for my oversight.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Winnie Chai <connect3winnie@gmail.com>
Sent: Wednesday, 20 November 2019 10:05 AM
To: Naz (LKKAuto) <Naz@lkkauto.com>
Cc: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: Re: Finalization for PC 76355

Yes, please proceed.

On Tue, Nov 19, 2019 at 6:02 PM Naz (LKKAuto) <Naz@lkkauto.com> wrote:

Dear Ms Chai,

Apologies for the late reply. Attached herewith is the amended marked estimate following a check on part prices. We will proceed to finalize if you are agreeable with the

Lump Sum COR of \$4850.00 / 4 REPAIR DAYS.

Thank you.

Best Regards,

Naz | Technical Investigator

C O N N E C T 3

566 Woodlands Road (Mandai Estate) Singapore 728697
Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L
GST : 53360061L

QT18/PC7635S/TPC-346

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Rd #15-02
Springleaf Tower
Singapore 079909

QUOTATION

Dear Sir,
Cost of Repair to Vehicle PC7635S
With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (SS)	AMOUNT (SS)	
1.	Front bumper	1	2,341.76	2,341.76	XR
2.	Front bumper bracket	1	231.46	231.46	? XSVL
3.	RH rear view mirror (round - bottom)	1	98.31	98.31	/MIS
4.	RH rear view mirror (-round-bottom)	1	491.76	350 491.76	MIS CRK
5.	RH rear view mirror bracket	1	105.90	105.90	/CRK
6.	Front RH headlamp upper moulding	1	164.69	164.69	? XSVL
7.	Front RH signal lamp	1	265.56	265.56	/SER
8.	Front RH door	1	3,565.60	3,000 3,565.60	/DEF
9.	Front RH driver step panel	1	558.00	558.00	? XSVL
10.	Front RH driver door hinge	1	335.90	335.90	? XSVL
11.	Front RH driver door inner trims	1	765.80	765.80	? XSVL
12.	Front panel	1	3,809.58	3,809.58	XR
13.	Mark fuso	1	60.58	60.58	XND
14.	Mark Rosa	1	54.14	54.14	XND
15.	Sealant	4	40.00	160.00	XND
16.	Remove & refit front windscreen	1	500.00	500.00	XND

17.	Transfer Rh driver door fittings	1	200.00	200.00	100
18.	Apply anti rust	1	200.00	200.00	100
19.	Check wiring	1	80.00	80.00	50
20.	Spray painting	1	1,600.00	1,600.00	1,100
21.	Labour charges	1	1,500.00	1,500.00	1,000
SUB-TOTAL				SS17,089.04	

• Price before 7% gst

Thank you.
Yours faithfully,

Winnie Chai

Winnie Chai
HP: 9850-9666



NAZ LKK
12/11/18
L/S
4 DAYS

[Signature]
15/1/18

CHECK ITEMS PHOTO
AFTER REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

PARTS \$3,819.77
LESS 10% \$3,437.79
LABOUR \$2,350.00
TOTAL \$5,787.79
LESS 20% LIS \$4,630.23
LIS TOTAL \$4,650.00
/4 REPAIR DAYS

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18020352/NSBS2

Date: 28/11/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN3067991800

Claimant Vehicle No: PC7635S Insured Vehicle No: GBG7953T

Date of Loss: 07/11/2018 Nature of Claim: TP Claim No: SNM18D05281C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC7635S**

Make & Model: MITSUBISHI BE639JRMHDEA, 3.9 D (M) Engine No: 4D34K84214

Reg. Date: 03/07/2006 (Man. Year: 2006) Chassis No: BE639JD00305

Colour: White Odometer: 653061 km

Engine Capacity: 3908 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/75 R17.5 Rear Tyre Size: 215/75 R17.5

Front Left Side: Michelin 5 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Michelin 5 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,009.04	3,437.79	9,571.25	73.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,080.00	2,350.00	1,730.00	42.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,089.04	5,787.79	11,301.25	66.13
Approved Total (Overridden) (S\$)		4,650.00		
	17,089.04	4,650.00	12,439.04	72.79
+ GST 7.00/7.00% (S\$)	1,196.23	325.50	870.73	72.79
Nett Amount (S\$)	18,285.27	4,975.50	13,309.77	72.79

INSPECTION

Date of Assignment: 09/11/2018

Date Inspected: 12/11/2018 Inspected At: 566 Woodlands Road
Singapore 728697
Repairer: Connect3

Estimated Period of Repair: 4.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 28 Nov 2019)	
Parts:	N/A	MITSUBISHI BE639JRMHDEA 3.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC7635S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,341.76 F	*-FL
2	1		*FRONT BUMPER BRACKET	Serviceable	231.46 F	*-FL
3	1		*RH REAR VIEW MIRROR (ROUND & BOTTOM)	Missing	98.31 F	*98.31 FL
4	1		*RH REAR VIEW MIRROR	Cracked	491.76 F	*350.00 FL
5	1		*RH REAR VIEW MIRROR BRACKET	Cracked	105.90 F	*105.90 FL
6	1		*FRONT RH HEADLAMP UPPER MOULDING	Serviceable	164.69 F	*-FL
7	1		*FRONT RH SIGNAL LAMP	Scratched	265.56 F	*265.56 FL
8	1		*FRONT RH DOOR	Deformed	3,565.60 F	*3,000.00 FL
9	1		*FRONT RH DRIVER STEP PANEL	Serviceable	558.00 F	*-FL
10	1		*FRONT RH DRIVER DOOR HINGE	Serviceable	335.90 F	*-FL
11	1		*FRONT RH DRIVER DOOR INNER TRIMS	Serviceable	765.80 F	*-FL
12	1		*FRONT PANEL	Repair	3,809.58 F	*-FL
13	1		*MARK FUSO	Not Necessary	60.58 F	*-FL
14	1		*MARK ROSA	Not Necessary	54.14 F	*-FL
15	4		*SEALANT	Not Necessary	160.00 F	*-FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	13,009.04	3,819.77
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	381.98
Total Parts (\$\$)	13,009.04	3,437.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIT FRONT WINDSCREEN	New	500.00	0.00
2	TRANSFER RH DRIVER DOOR FITTINGS	New	200.00	100.00
3	APPLY ANTI RUST	New	200.00	100.00
4	CHECK WIRING	New	80.00	50.00
5	SPRAY PAINTING	New	1,600.00	1,100.00
6	LABOUR CHARGES	New	1,500.00	1,000.00
Gross Labour Cost (S\$)			4,080.00	2,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >