## PREMIER APPRAISER SERVICES

bur Ref: PT1703004-L

Vehicle No: SKG 1960 E

	·						
Qty	Parts Descriptions	Corditions		Repairer's Est.	(	Our Revised	
	LIST ITEMS:						
1	tail gate	derted - repair	S\$	1,712.95	S\$		
1	tail gate inner lock	stiffened	Οψ	226.80	ΟΨ	R 226.80	X
1	tail gate lower lock catch	serviceable		172.20		220.00	/\
1	tail gate weatherstrip					<b></b>	
1	tail gate "VW" emblem	serviceable		392.70			No.
		damaged		214.40		214.40	
1	tail gate " SCIROCCO " emblem	damaged		108.00		108.00	-
1	tail gate "TSI " emblem	damaged		96.05		96.05	
1	o/s taillamp	chafed/damaged		523.00		523.00	8 P3./
1	n/s taillamp	chafed/damaged		523.00		523.00	& P3.60 & P3.60
1	rear end panel	badly dented		962.80		962.80	13.60
1	rear end panel garnish	damaged		247.15		247.15	638.80
1	rear bumper	badly dented		1 498.10		1 400 40	1.00
1	rear bumper reinforcement	badly dented				1,498.10	1093.10
1	rear bumper centre top bracket	Control of the Contro		678.30		678.30	375.10
1		damaged		213.35		213.35	18
	rear bumper o/s bracke:	damaged		143.10		143.10	87.20
1	rear bumper n/s bracket	damaged		143.10		143.10	8120
1	rear bumper tow hook cover	damaged		54.55		54.55	20
1	rear bumper o/s reflector	damaged		85.95		85.95	
1	rear bumper n/s reflector	serviceable		85.95		-	
1	rear bumper o/s mud cover	damaged		106.90	S	106.90	J
1	rear bumper n/s mud cover	serviceable		106.90		100.00	$\wedge$
1	exhaust silencer assembly	badly dented		1,712.80		1 712 00	1284.70
1	exhaust o/s mounting	damaged		128.75		1,7 12.00	1004-10
1	exhaust o/s mounting bkt	damaged				128.75	62.70
1	exhaust heat shield cover			125.40		125.40	62.70
2		buckled		250.25	9.17	250.25	134.50
	exhaust front mountings	damaged		257.50	300,	257.50	
1	exhaust centre pipe	bent		1,499.05	41	7 1,499.05	\$ 4005a
1	spare wheel tightening screw	snapped		143.90	94	Siz 143.90	<b>(</b>
1	rear number plate lamp wire	serviceable		538.85		_	X
2	rear number plate lamp bulbs	da naged		87.80		87.80	
1	rear susp sub-frame / axle	bent/distorted		2,861.05	Su	2,861.05	1
- 1	rear susp o/s lower arm	dented/bent		549.70	Se	549.70	7
1	rear susp n/s lower arm	dented/bent		549.70	5.	549.70	>
		a o modroom	S\$	17,000.00	S\$	13,990.45	. 1
		LESS					
		LESS	10%_	1,700.00	10%	1,399.05	-
	S/NETT ITEMS:			15,300.00		12,591.41	
1	rear windscreen sealart			2004.007 1004.00			
ā.		not required		70.00		-	
1	rear number plate	damaged		70.00		50.00	
1	reverse sensors	damaged		320.00		220.00	
1	n/s rear ABS sensor	serviceable	-	2,346.90		-	
							-
		TOTAL S/PARTS	S\$	18,106.90	S\$	12,861.41	
	5 <u>-</u> 1 528 100.0						
	To remove/refit rear seat, upholstery	, interior trims and		480.00		120.00	
	garnish to assist repairs. (luggage on	ly)					
<u> </u>	2° 100 100 100 100 100 100 100 100 100 10						
	To remove/refit rear windscreen to a	ssist repairs.		180.00			
		in and the second secon			-		-
		Balance c/d	S\$	13,766.90	S\$	12,981.41	
					4	CONTRACTOR DESCRIPTION OF THE	