

Surveyor

REF: C01 / ICS18010379 / Bth

Special Instruction:

ASSIGNMENT (Office)

From (Person): Janice Goh of ICS Date/Time: 17092018
Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor:

Workshop:

OD/TP Re-inspection / (Evaluation)

To Inspect Vehicle No: SBU 1300T Insured: SLJ 6797A
at Workshop m/s Motor Image Tel:
of 19 Lorong 8 Toa Payoh
Policy No: Claim No: DMPC1700260H / DL
Sum Insured: Excess:
Make of Veh: D.O.A. 11.04.2017
(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original days)
Date/Time: 18/12/18 Submit Final Fig 3210.00, 6 days (Red \$ 16972.12 50%; Original 13 days)

Date/Time	Action/Instruction
	SBU 1300T - NA / MG / 11301578 / r3
	SLJ 6797A - CS / MS / 1801573 / Urban2

DOA: 12102013
DOA: 290818

rfu - Received file from Catherine

Remarks Repair cost will be review when additional provided
(indicate in report)

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 18 DEC 2018

URGENT

Para(3) : Nett Value

Market Value :
Salvage Value :
Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

1) Date/Time 18/12 File Pass to Typist
3) Date/Time File Pass to
5) Date/Time File Pass to

2) Date/Time File Return to
4) Date/Time File Return to
6) Date/Time File Return to

Denise Tay (LKKAUTO)

From: Sayedinah <sayedinah@motorimage.net>
Sent: Saturday, 8 December 2018 10:18 AM
To: Denise Tay (LKKAUTO)
Cc: Mohamed Isman; TPY Insurance Team; Desmond Lee Ker Wen (ECICS, Claims)
Subject: Re: SBU1300T-AIG-TP(SLJ6797A)ECICS-FINALIZED / Our Ref: DMPC1700260H/DL

Importance: High

Hi Denise,
we do not have damaged photos. You can however seek a soft copy of the GIA report from insured. The GIA report given to us was without damaged photos. From what i recall survey and resurvey check items and BP was taken by Mr Lionel.

Regards,
Sayedinah Ali

Service Executive
Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
Tel: +65-6703 8333 DID: +65-6703 8109 HP:+65-92992693
Fax: +65-6253 5535
Email: sayedinah@motorimage.net
Website: www.tanchong.com :: www.motorimage.net

From: Desmond Lee Ker Wen (ECICS, Claims) <Desmond_Lee@ecics.com.sg>
Sent: Tuesday, 4 December 2018 10:21:24 AM
To: Sayedinah; TPY Insurance Team
Cc: Daniel Jude; Mohamed Isman; denisetay@lkkauto.com
Subject: RE: SBU1300T-AIG-TP(SLJ6797A)ECICS-FINALIZED / Our Ref: DMPC1700260H/DL

Dear Sayedinah

We understand from our surveyors that the photos submitted is insufficient for assessment and finalisation of the damage.

We would require more photographs of the damaged vehicle for our further assessment.

Do liaise directly with our surveyor Miss Denise Tay at 6256-3561
email: denisetay@lkkauto.com / fax: 6256-4315

Thank you.

Best regards,
Desmond Lee
Claims Division
DID: +65 6303 0167
FAX: +65 6338 9267

Catherine Chong (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Monday, 17 September, 2018 2:34 PM
To: 'assignments'
Cc: Desmond Lee Ker Wen (ECICS, Claims)
Subject: FW: SBU1300T-AIG-TP(SLJ6797A)ECICS-FINALIZED
Attachments: RE: SBU1300T-AIG-TP(SLJ6797A)ECICS-FINALIZED (3.78 MB)

Importance: High

Hi LKK

Please assist to do paper survey for the above TP's vehicle.

Our claim no DMPC1700260H/DL and case handler is Mr Desmond Lee.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Sayedinah [mailto:sayedinah@motorimage.net]
Sent: Thursday, 6 September, 2018 12:59 PM
To: lionel_chua@ecics.com.sg
Cc: ECICS Claims; Valerie Yap Jia Pei (ECICS, Operations); Daniel Jude; Kuan Wei Loong
Subject: RE: SBU1300T-AIG-TP(SLJ6797A)ECICS-FINALIZED
Importance: High

Hi Lionel and claims team,
Can I have an update and closure for the above mentioned vehicle on an urgent basis.

Regards,
Sayedinah Ali
Service Executive
Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
HP:92992693 DID:67038109 FAX:+65-62535535
Email:sayedinah@motorimage.net
Website:www.tanchong.com :: www.motorimage.net

From: Sayedinah
Sent: Friday, 3 August 2018 2:24 PM
To: lionel_chua@ecics.com.sg

Cc: ECICS Claims <claims@ecics.com.sg>; Valerie Yap Jia Pei (ECICS, Operations) <Valerie_Yap@ecics.com.sg>; Daniel Jude <danieljude@motorimage.net>; Kuan Wei Loong <weiloong@motorimage.net>

Subject: SBU1300T-AIG-TP(SLJ6797A)ECICS-FINALIZED

Importance: High

Hi Lionel,
Attached for your reference

Regards
Sayedinah Ali
Service Executive
Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
HP:92992693 DID:67038109 FAX:+65-62535535
Email:sayedinah@motorimage.net
Website:www.tanchong.com :: www.motorimage.net

From: Sayedinah Bin Ali /MIE - Svc [<mailto:sayedinah@motorimage.net>]

Sent: Wednesday, 3 May 2017 1:48 PM

To: lionel_chua@ecics.com.sg

Cc: Ivan Tan Chen Hwee /MIE - Mgt <ivantan@motorimage.net>; ECICS Claims <claims@ecics.com.sg>; Valerie Yap Jia Pei (ECICS, Operations) <Valerie_Yap@ecics.com.sg>

Subject: Re: SBU1300T 3RD PARTY LIABILITY STATUS- TP (SLJ6797A)

Importance: High

Hi Lionel,
kindly arrange B/P survey for the above mentioned vehicle. cannot get thru when i called.

Regards,

Sayedinah Ali

Service Executive

Motor Image Enterprises Pte Ltd

19 Lorong 8 Toa Payoh Singapore 319255

Tel: +65-6703 8333 DID: +65-6703 8109 HP:+65-92992693

Fax: +65-6253 5535

Email: sayedinah@motorimage.net

Website: www.tanchong.com :: www.motorimage.net

From: "Valerie Yap Jia Pei (ECICS, Operations)" <Valerie_Yap@ecics.com.sg>

To: Sayedinah Bin Ali /MIE - Svc <sayedinah@motorimage.net>

Cc: Ivan Tan Chen Hwee /MIE - Mgt <ivantan@motorimage.net>, ECICS Claims <claims@ecics.com.sg>, "Phoebe Jay Xie (ECICS, Operations / Claims)" <PhoebeJay_Xie@ecics.com.sg>

Sent: 4/25/2017 11:22 AM

Subject: RE: SBU1300T 3RD PARTY LIABILITY STATUS- TP (SLJ6797A)

*Dear Sayedinah,

Liability is clear.

Kindly note that Lionel will be assisting to conduct the survey.

Aside to Lionel, car is in the workshop.

Thank you.

Kind Regards,

Valerie Yap

Operations

DID: +65 6303 0181

FAX: +65 6338 9267

ECICS LIMITED

Email: valerie_yap@ecics.com.sg

follow us on  follow us on  visit our website ecics.com.sg 

From: Sayedinah Bin Ali /MIE - Svc [<mailto:sayedinah@motorimage.net>]

Sent: Thursday, 20 April, 2017 12:11 AM

To: ECICS Claims

Cc: Ivan Tan Chen Hwee /MIE - Mgt

Subject: SBU1300T 3RD PARTY LIABILITY STATUS- TP (SLJ6797A)

Importance: High

Hi Claims Team,

kindly advise liability status and arrange survey for the above mentioned vehicle. vehicle @ Motor Image Toa Payoh

Regards,

Sayedinah Ali

Service Executive

Motor Image Enterprises Pte Ltd


19 Lorong 8 Toa Payoh Singapore 319255

Tel: +65-6703 8333 DID: +65-6703 8109 HP: +65-92992693

Fax: +65-6253 5535

Email: sayedinah@motorimage.net

Website: www.tanchong.com :: www.motorimage.net



BUILT ON THE ALL-NEW
SUBARU GLOBAL PLATFORM

THE ALL-NEW IMPREZA

LEARN MORE

SUBARU



This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.



Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0159/2017
DATE : 25-APR-2017

ECICS LIMITED

S()
TEL :
FAX :

OWNER'S NAME : YAP KOK CHENG DERRICK *3YRS OR 60,000KM*
ADDRESS : APT BLK 543 SERANGOON NORTH AVENUE 3
#10-184
S(550543)
TELEPHONE NO : 9666 5509

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : GA046067/1
VEHICLE NO : SBU1300T
MODEL CODE : SJGBKK8
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20H951539
CHASSIS NO : JF1SJGK85EG02B497
MILEAGE : 48785 KM
DATE IN : 25/04/2017
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 11/04/2017

Print Date : 26/04/2017
Print Time : 10:32:09

MOTORIMAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH

SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SBUL300T

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	22/001	REPLACE/REPAIR RR TAILGATE, RR BUMPER, RR END PANEL, RR FLOOR PAN, LH/RR RR FENDER	3360.00	2800/-
2	22/002	REPLACE/REPAIR FRT BUMPER, PANEL AND FRT BONNET	1680.00	560/-
3	22/003	REMOVE /REFIX RR U CARRIAGE TO FACILITATE REPAIR	600.00	250/-
4	22/004	REMOVE/REINSTALL FUEL TANK TO FACILITATE REPAIR	300.00	200/-
5	22/005	REMOVE/REFIX EXHAUST	150.00	nett
6	22/006	REMOVE & REFIX AIRCON CONDENSER/ RADIATOR TO FACILITATE REPAIR	220.00	X
7	22/007	CONDUCT WATER SEEPAGE TEST TO RR PORTION AFTER REPAIR	100.00	50.00
8	22/008	TRANSFER TAILGATE MECHANISM	150.00	nett
9	22/009	REMOVE/REFIX CARPET, SEATS, GARNISH & TRIM TO FACILITATE REPAIR	550.00	400.00
10	22/011	CONDUCT LIGHTING TEST	50.00	20.00
11	22/012	CONDUCT PAINT PROTECTANT COATING	500.00	250
12	22/013	CONDUCT ANTI RUST COATING TO RR PANEL AFTER REPAIR	500.00	280
13	22/014	SUPPLY AND INSTALL REVERSE SENSOR	300.00	nett
14	22/015	REMOVE AND INSTALL REAR WINDSCREEN	250.00	nett
15	22/016	SUPPLY AND INSTALL RR TINTED FILM	145.00	nett
16	22/017	SUNDRIES	100.00	60.00
17	22/018	RESPRAY FRT BUMPER, FRT PANEL	840.00	nett
18	22/019	RESPRAY RR TAILGATE, END PANEL, RR BUMPER, FLOOR PAN, LH/RR FENDER	2520.00	nett
19	22/10	REMOVE/REFIX WIRE HARNESS TO FACILITATE REPAIR	300.00	150.00
TOTAL LABOUR CHARGES			12695.00	

Both rear

Per Side 4300.00

X 2

= \$500/- removed 3/5/17

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SBUI300T

TOTAL LABOUR CHARGES	12695.00
TOTAL SPARE PARTS CHARGES	0.00
GRAND TOTAL	12695.00 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

without Predeal

take photos before sent for resurvey

working 13 days

lionel - chue@ecics.com.sg

M/P 92783198

6 day of repairs

Estimate

Date 04/18/2017

001 / 004

Name	QUOTATION FOR SBY130CT	Tel (Home)	
Address		Tel (Office)	
E-Mail		Tel (Portable)	
		Fax	
		Model Name	S13
		Eddy Model	SJGBKK8
		Vin-Code	JF1SJGRE5EG-028497

Part Number	Part Code Name	Part Code	Q'ty	Price	
57709SG011	BUMPER FACE-FRONT <i>new</i>	✓ FIG-590 57704	1	594.00	DD
57707SG00C	BRACKET-FRONT BUMPER CORNER, RIGHT	FIG-590 57707AF	1	36.00	NNX
57707SG01C	BRACKET-FRONT BUMPER CORNER, LEFT	✓ FIG-590 57707AG	1	36.00	BRV
57707SG02C	BRACKET-FRONT BUMPER SIDE, RIGHT	FIG-590 57707F	1	12.60	} NN
57707SG03C	BRACKET-FRONT BUMPER SIDE, LEFT	FIG-590 57707G	1	12.60	
57711SG0009P	BACK BEAM COMPLETE-F RONT	FIG-590 57711	1	288.00	
57722SG020	ENERGY ABSORBER-FRONT T BUMPER	✓ FIG-590 57705	1	126.00	NNX
53029SG0009P	PANEL COMPLETE-RADIA TOR	FIG-505 53010	1	360.00	} NN
51231SG0009P	FRAME COMPLETE-RADIA TOR, LOWER	FIG-505 51231G	1	108.00	
91121SG060	FRONT GRILLE ASSEMBLY Y, LOWER	FIG-911 91121F	1	324.00	
91121SG050	FRONT GRILLE ASSEMBLY Y, CENTER	FIG-911 91121G	1	126.00	} NN
91121SG011	FRONT GRILLE ASSEMBLY Y, UPPER	FIG-911 91121E	1	126.00	
91165SG013	BRACKET-GRILL LOWER	FIG-911 91165JA	1	21.60	
84002SG001	LAMP ASSEMBLY-HEAD R IGHT	FIG-840 84001A	1	2,160.00	} NN
84002SG011	LAMP ASSEMBLY-HEAD L EFT	✓ FIG-840 84001B	1	2,160.00	
84501AJ060	FOG LIGHT ASSEMBLY-F RONT	FIG-845 84501B	2	544.00	
		Page-Total		7,034.80	

Memo

Grand Total
16,487.80

Tel

Estimate

Date 04/18/2017

002 / 004

Name	QUOTATION FOR SEY1300T	Tel (Home)	
Address		Tel (Office)	
E-Mail		Tel (Portable)	
		Fax	
		Model Name	S13
		Body Model	SJGBKK8
		Vin-Code	JF1SJGK85EG-028497

Part Number	Part Code Name	Part Code	Q'ty	Price
63019SG000	GLASS-REAR GATE <i>✓ nest</i>	<i>✓</i> FIG-621 63011	1	799.20
63232SG010	RUBBER-REAR GATE <i>messy</i>	<i>✓</i> FIG-621 63232	1	12.60
63232SG000	DAM RUBBER-REAR GATE <i>X</i> GLASS	FIG-621 63232C	2	7.20
51439SG0009P	REAR QUARTER COMPLET E-OUTER, RIGHT <i>X</i>	FIG-522 51410	1	864.00
51439SG0119P	REAR QUARTER COMPLET E-OUTER, LEFT <i>X</i>	FIG-522 51410A	1	864.00
59122SG000	MUD GUARD, REAR RIGHT ?	FIG-541 59112	1	57.60
59122SG010	MUD GUARD, REAR LEFT <i>crack</i>	<i>✓</i> FIG-541 59112A	1	57.60
60809SG0509P	PANEL-REAR GATE <i>Pump</i>	<i>✓</i> FIG-620 60810	1	1,072.80
63516SG001	WEATHER STRIP-REAR G ATE <i>X</i>	FIG-901 63516	1	111.60
63032SG001	LATCH & ACTUATOR-REA R GATE <i>X</i>	FIG-622 63176A	1	504.00
63264AG100	STRIKER-REAR GATE <i>X</i>	FIG-622 63264	1	21.60
94026SG000VH	TRIM PANEL-REAR SKIR <i>four</i> T	FIG-940 94046	1	36.00
57704SG012	BUMPER-FACE, REAR <i>crack</i>	<i>✓</i> FIG-591 57704A	1	540.00
57707SG080	BRACKET-REAR BUMPER <i>X</i> SIDE, RIGHT	FIG-591 57707H	1	14.40
57707SG090	BRACKET-REAR BUMPER <i>X</i> SIDE, LEFT	FIG-591 57707I	1	14.40
57707SG060	BRACKET-REAR BUMPER <i>X</i> CORNER, RIGHT	FIG-591 57707AC	1	18.00
Page-Total				4,995.00

Memo

Grand Total
16,487.80

--

Tel

Estimate

Date 04/18/2017

003 / 004

Name:	QUOTATION FOR SBY1300T	Tel (Home):	
Address:		Tel (Office):	
E-Mail:		Tel (Portable):	
		Fax:	
		Model Name:	S13
		Body Model:	SJGKKK8
		Vin-Code:	JF1SJGK65EG-026497

Part Number	Part Code Name	Part Code	Q'ty	Price	
57707SG070	BRACKET-REAR BUMPER X CORNER, LEFT	FIG-591 57707AD	1	18.00	NN
57711SG0219F	BACK BEAM COMPLETE-R Bent EAR	✓ FIG-591 57711D	1	288.00	NNX
44370SG000	TAIL PIPE CUTTER ?	FIG-440 44371	2	244.00	NN
52401SG0109F	SKIRT COMPLETE-REAR Bent	✓ FIG-505 52411	1	288.00	NN
52129SG0019F	FLOOR PAN COMPLETE-R Bent EAR, REAR	✓ FIG-505 52110	1	432.00	NN
84912SG020	LENS & BODY-REAR COM ? BINATION LAMP RIGHT	FIG-842 84912B	1	388.80	NN
84912SG011	LENS & BODY-REAR COM ? BINATION LAMP LEFT	FIG-842 84912C	1	388.80	NN
84281SC000	REFLEX REFLECTOR ASS crack EMBLY-RIGHT	✓ FIG-842 84281	1	20.40	CRA ✓
84281SC010	REFLEX REFLECTOR ASS ? EMBLY-LEFT	FIG-842 84281A	1	20.40	NNX
91111SG500V2	GARNISH ASSEMBLY-REA crack R GATE, B	✓ FIG-914 91111P	1	216.00	CRA ✓
91713SG000	PROTECTOR-REAR GARNI ? SH	FIG-914 91713	1	21.60	NN
91713SG010	PROTECTOR-REAR GARNI ? SH	FIG-914 91713C	2	10.80	NN
93033SG001	ORNAMENT ?	FIG-914 93033D	1	79.20	NN
93079SG010	LETTER MARK-REAR req	✓ FIG-919 93073Y	1	64.80	HE ✓
93079SG030	LETTER MARK-REAR req	✓ FIG-919 93073Y	1	64.80	HE ✓
57731SG070	COVER-FRONT BUMPER X	FIG-590 57731	1	5.40	NN X
		Page-Total		2,451.00	

Memo

Grand Total
16,487.80

--

Tel

Estimate

Date 04/18/2017

004 / 004

Name	QUOTATION FOR SEY1300T	Tel (Home):	
Address		Tel (Office):	
E-Mail		Tel (Portable):	
		Fax	
		Model Name	S13
		Body Model	SJGKK8
		Vin-Code	JF1SJK85EG-028497

Part Number	Part Code Name	Part Code	Q'ty	Price
57731SG01CNN	COVER-REAR BUMPER <i>w/straps</i>	✓ FIG-591 57731C	1	12.60
44200SG031	EXHAUST PIPE ASSEMBLY-REAR <i>Bent</i>	FIG-440 44200	1	792.00
44300SG050	MUFFLER ASSEMBLY-RIG <i>Bent</i>	FIG-440 44300A	1	601.20
44300SG040	MUFFLER ASSEMBLY-LEFT <i>Bent</i>	FIG-440 44300B	1	601.20
		Page-Total		2,007.00
		Sub-Total		16,487.80
		Total		16,487.80
		Tax		
		Grand Total		16,487.80

no pic - indicates no photographic evidences

Memo

Grand Total
16,487.80
29952.80

--

Tel



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh
Singapore 319255
Tel: (65) 6703 8101/8102
Fax: (65) 6253 5535
www.motorimage.net
Co Reg No: 198702032R

Insurance Co: _____

Survey Date: _____

SUPPLEMENTARY LABOUR FOR VEHICLE REGISTRATION NO SBU 13007.

Surveyor: _____

LABOUR DESCRIPTION

AMOUNT

1 Remove and refix crossmember and axle

^{1/2}
220/h
\$ ~~350~~, 00k

Resurvey
name
2/5/12
1630hrs

2 Use Subaru special tool DSTI calibration and reset
Power tailgate

^{1/2}
350/h
\$ ~~400~~, 00k

NECV

3 4 wheel alignment

^{1/2}
200/h
\$ ~~250~~, 00k

4 _____

5 _____

6 _____

7 _____

8 _____

9 _____

10 _____


11 _____

12 _____

MOTOR IMAGE ENTERPRISES PTE LTD
19, LORONG 8, TOA PAYOH, SINGAPORE 319255
MAIN LINE : (65) 6703 8333
FAX : (65) 6252 5655
SERVICE CENTRE TEL : 6703 8101/02
WEBSITE : www.motorimage.net

Work Order: R000039
 Name 2: YAP KOK CHENG DERRICK
 License: SBU1300T
 Year: 14
 Technician: ALBERT
 Odometer: 48785
 Date: 11.5.17 10:40

Subaru 2013-15 Forester SJ
4-Wheel Total Alignment



MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0159/2017
DATE : 25-APR-2017

ECICS LIMITED
7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
S(038987)
TEL : 6337 4779
FAX : 6338 9267

OWNER'S NAME : YAP KOK CHENG DERRICK
ADDRESS : APT BLK 543 SERANGOON NORTH AVENUE 3
#10-184
S(550543)
TELEPHONE NO : 96665509

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : GA046067/1
VEHICLE NO : SBUI300T
MODEL CODE : SJGBKK8
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20H951539
CHASSIS NO : JF1SJGK85EG028497
MILEAGE : 48785 KM
DATE IN : 25/04/2017
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 11/04/2017

Print Date : 28/06/2018
Print Time : 23:39:44

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SBUI300T

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	REPLACE/REPAIR RR TAILGATE,RR BUMPER,RR END PANEL, RR FLOOR PAN, LH/RH RR FENDER	3360.00	2800.00
2	ZZ/002	REPLACE/REPAIR FRT BUMPER, PANEL AND FRT BONNET	1680.00	560.00
3	ZZ/003	REMOVE /REFIX RR U CARRIAGE TO FACILITATE REPAIR	600.00	500.00
4	ZZ/004	REMOVE/REINSTALL FUEL TANK TO FACILITATE REPAIR	300.00	200.00
5	ZZ/005	REMOVE/REFIX EXHAUST	150.00	150.00
6	ZZ/006	REMOVE & REFIX AIRCON CONDENSER/ RADIATOR TO FACILITATE REPAIR	220.00	.00
7	ZZ/007	CONDUCT WATER SEEPAGE TEST TO RR PORTION AFTER REPAIR	100.00	50.00
8	ZZ/008	TRANSFER TAILGATE MECHANISM	150.00	150.00
9	ZZ/009	REMOVE/REFIX CARPET,SEATS, GARNISH & TRIM TO FACILITATE REPAIR	550.00	400.00
10	ZZ/011	CONDUCT LIGHTING TEST	50.00	20.00
11	ZZ/012	CONDUCT PAINT PROTECTANT COATING	500.00	250.00
12	ZZ/013	CONDUCT ANTI RUST COATING TO RR PANEL AFTER REPAIR	580.00	280.00
13	ZZ/014	SUPPLY AND INSTALL REVERSE SENSOR	300.00	300.00 PM
14	ZZ/015	REMOVE AND INSTALL REAR WINDSCREEN	250.00	250.00
15	ZZ/016	SUPPLY AND INSTALL RR TINTED FILM	145.00	145.00 NEL
16	ZZ/017	SUNDRIES	100.00	60.00 NEL
17	ZZ/018	RESPRAY FRT BUMPER,FRT PANEL	840.00	840.00
18	ZZ/019	RESPRAY RR TAILGATE,END PANEL,RR BUMPER,FLOOR PAN, LH/RH FENDER	2520.00	2520.00
19	ZZ/020	REMOVE AND REFIX CROSSMEMBER AND AXER (SUPP)-	220.00	220.00
20	ZZ/021	SUBARU SPECIAL TOOL DSTI CALIBRATION AND RESET POWER TAILGATE (SUPP)-	350.00	350.00
21	ZZ/022	4 WHEEL ALIGNMENT-(SUPP)-	200.00	200.00
22	ZZ/10	REMOVE/REFIX WIRE HARNESS TO FACILITATE REPAIR	300.00	150.00

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SBUL300T

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
TOTAL LABOUR CHARGES			13465.00	10395.00

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SBUI300T

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	FLOOR PAN R R CP	52129SG0019P	432.00			OK
2	SKIRT COMPL R	(SUPP) 52401SG0109P	288.00			OK
3	BUMPER FACE R	57704SG012	540.00			OK
4	BRKT CORNER FRONT LH	57707SG010	36.00			OK
5	BUMPER FACE FRONT	57709SG011	594.00			OK
6	BEAM COMPL R EU	(SUPP) 57711SG0219P	288.00			OK
7	FRONT BUMPER FOAM	57722SG020	126.00			OK
8	REAR BUMPER TOW COVER	57731SG010NN	12.60			OK
9	MUD GUARD R LH	59122SG010	57.60			OK
10	PANEL CPL R/G	60809SG0509P	1072.80			OK
11	GLASS R/G	63019SG000	799.20			OK
12	RUBBER R/G	63232SG010	12.60			OK
13	LAMP ASSY HEAD LH	84002SG011	2160.00			OK
14	REAR BUMPER REFLECTOR RHS	84281SC000	20.40			OK
15	GARNISH RG COLOR	91111SG500V2	216.00			OK
16	LETTER MK R XT	93079SG010	64.80			OK
17	LETTER MK R SUB	93079SG030	64.80			OK
SUB TOTAL			6784.80	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			1356.96	0.00	0.00	0.00
GRAND TOTAL			5427.84	0.00	0.00	0.00
OVERALL TOTAL			5427.84			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SBUL300T

NETT ITEM	6784.80
LESS 20 %	-1356.96
NETT AMOUNT	5427.84
LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00
SPECIAL NETT AMOUNT	0.00
S/LIST ITEM	0.00
LESS 30 %	0.00
S/LIST AMOUNT	0.00
TOTAL LABOUR CHARGES	10395.00
TOTAL SPARE PARTS CHARGES	5427.84
TOTAL CHARGES	15822.84
ADD 7 % GST	1107.60
GRAND TOTAL	16930.44



Your Ref: DMPC1700260H/DL

Date: 18th December 2018

Our Ref: CS1/ICS18020379/Btbs2

M/s ECICS Ltd

10 Eunoss Road 8

Singapore Post Centre #09-04A

Singapore 408600

(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SBU 1300T INSURED VEHICLE: SLJ 6797A ACCIDENT DATE: 11/04/2017**

We thank you for your instruction on 17/09/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SBU 1300T from M/s MotorImage Enterprises Pte. Ltd.
- b) Colour damaged vehicle photographs of SBU 1300T.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -
Registration Number : SBU 1300T
Make & Model : Subaru Forester 2.0
Chassis Number : JF1SJGK85EG028497
2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBU 1300T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER FACE - FRONT	DENTED	594.00	594.00
1	BRACKET - FRONT BUMPER CORNER, RIGHT	NOT NECESSARY	36.00	-
1	BRACKET - FRONT BUMPER CORNER, LEFT	BROKEN	36.00	36.00
1	BRACKET - FRONT BUMPER SIDE, RIGHT	NOT NECESSARY	12.60	-
1	BRACKET - FRONT BUMPER SIDE, LEFT	NOT NECESSARY	12.60	-
1	BACK BEAM COMPLETE - FRONT	NOT NECESSARY	288.00	-
1	ENERGY ABSORBER - FRONT BUMPER	NOT NECESSARY	126.00	-
1	PANEL COMPLETE - RADIATOR	NOT NECESSARY	360.00	-
1	FRAME COMPLETE - RADIATOR, LOWER	NOT NECESSARY	108.00	-
1	FRONT GRILLE ASSEMBLY, LOWER	NOT NECESSARY	324.00	-
1	FRONT GRILLE ASSEMBLY, CENTER	NOT NECESSARY	126.00	-
1	FRONT GRILLE ASSEMBLY, UPPER	NOT NECESSARY	126.00	-
1	BRACKET - GRILL LOWER	NOT NECESSARY	21.60	-
1	LAMP ASSEMBLY - HEAD RIGHT	NOT NECESSARY	2,160.00	-
1	LAMP ASSEMBLY - HEAD LEFT	NOT NECESSARY	2,160.00	-
2	FOG LIGHT ASSEMBLY - FRONT	NOT NECESSARY	544.00	-
1	GLASS - REAR GATE	NOT NECESSARY	799.20	-
1	RUBBER - REAR GATE	NECESSARY	12.60	12.60
2	DAM RUBBER - REAR GATE GLASS	NOT NECESSARY	7.20	-
1	REAR QUARTER COMPLETE - OUTER, RIGHT	NOT NECESSARY	864.00	-
1	REAR QUARTER COMPLETE - OUTER, LEFT	NOT NECESSARY	864.00	-
1	MUD GUARD, REAR RIGHT	NOT NECESSARY	57.60	-
1	MUD GUARD, REAR LEFT	CRACKED	57.60	57.60
1	PANEL - REAR GATE	DENTED	1,072.80	1,072.80
1	WEATHER STRIP - REAR GATE	NOT NECESSARY	111.60	-
1	LATCH & ACTUATOR - REAR GATE	NOT NECESSARY	504.00	-
1	STRIKER - REAR GATE	NOT NECESSARY	21.60	-
1	TRIM PANEL - REAR SKIRT	CRACKED	36.00	36.00
1	BUMPER - FACE, REAR	CRACKED	540.00	540.00
1	BRACKET - REAR BUMPER SIDE, RIGHT	NOT NECESSARY	14.40	-
1	BRACKET - REAR BUMPER SIDE, LEFT	NOT NECESSARY	14.40	-
1	BRACKET - REAR BUMPER CORNER, RIGHT	NOT NECESSARY	18.00	-
1	BRACKET - REAR BUMPER CORNER, LEFT	NOT NECESSARY	18.00	-
1	BACK BEAM COMPLETE - REAR	NOT NECESSARY	288.00	-

Report Ref No. CS1/ICS18020379/Btbs2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	TAIL PIPE CUTTER	NOT NECESSARY	144.00	-
1	SKIRT COMPLETE - REAR	NOT NECESSARY	288.00	-
1	FLOOR PAN COMPLETE - REAR, REAR	NOT NECESSARY	432.00	-
1	LENS & BODY - REAR COMBINATION LAMP RIGHT	NOT NECESSARY	388.80	-
1	LENS & BOSOY - REAR COMBINATION LAMP LEFT	NOT NECESSARY	388.80	-
1	REFLEX REFLECTOR ASSEMBLY - RIGHT	CRACKED	20.40	20.40
1	REFLEX REFLECTOR ASSEMBLY - LEFT	NOT NECESSARY	20.40	-
1	GARNISH ASSEMBLY - REAR GATE, B	CRACKED	216.00	216.00
1	PROTECTOR - REAR GARNISH	NOT NECESSARY	21.60	-
2	PROTECTOR - REAR GARNISH	NOT NECESSARY	10.80	-
1	ORNAMENT	NOT NECESSARY	79.20	-
1	LETTER MARK - REAR	NECESSARY	64.80	64.80
1	LETTER MARK - REAR	NECESSARY	64.80	64.80
1	COVER - FRONT BUMPER	NOT NECESSARY	5.40	-
1	COVER - REAR BUMPER	MISSING	12.60	12.60
1	EXHAUST PIPE ASSEMBLY - REAR	BENT	792.00	792.00
1	MUFFLER ASSEMBLY - RIGHT	NOT NECESSARY	601.20	-
1	MUFFLER ASSEMBLY - LEFT	NOT NECESSARY	601.20	-
	LESS 20% DISCOUNT		-	-703.92
			16,487.80	2,815.68
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (SN)	DAMAGED	300.00	300.00
1	RR TINTED FILM (SN)	NECESSARY	145.00	145.00
1	SUNDRIES (SN)	NECESSARY	100.00	60.00
			545.00	505.00
	LABOUR			
	REPLACE / REPAIR RR TAILGATE, RR END PANEL, RR FLOOR PAN, LH/RH FENDER.		3,360.00	2,800.00
	REPLACE / REPAIR FRT BUMPER, PANEL AND FRT BONNET.		1,680.00	560.00
	REMOVE / REFIX RR U CARRIAGE TO FACILITATE REPAIR.		600.00	500.00
	REMOVE / REINSTALL FUEL TANK TO FACILITATE REPAIR.		300.00	200.00
	REMOVE / REFIX EXHAUST.		150.00	150.00
	REMOVE & REFIX AIRCON CONDENSER / RADIATOR TO FACILITATE REPAIR.	NOT NECESSARY	220.00	-

Report Ref No. CS1/ICS18020379/Btbs2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CONDUCT WATER LEAKAGE TEST TO RR PROTION AFTER REPAIR.		100.00	50.00
	TRANSFER TAILGATE MECHANISM.		150.00	150.00
	REMOVE / REFIX CARPET, SEATS, GARNISH & TRIM TO FACILITATE REPAIR.		550.00	400.00
	CONDUCT LIGHTING TEST.		50.00	20.00
	CONDUCT PAINT PROTECTANT COATING.		500.00	250.00
	CONDUCT ANTI RUST COATING TO RR PANEL AFTER REPAIR.		580.00	280.00
	REMOVE AND INSTALL REAR WINDSCREEN.		250.00	250.00
	RESPRAY FRT BUMPER, FRT PANEL		840.00	840.00
	RESPRAY RR TAILGATE, END PANEL, RR BUMPER, FLOOR PAN, LH/RH FENDER.		2,520.00	2,520.00
	REMOVE AND REFIX CROSSMEMBER AND AXER.		220.00	220.00
	SUBARU SPECIAL TOOL DSTI CALIBRATION AND RESET POWER TAILGATE.		350.00	350.00
	4 WHEEL ALIGNMENT.		200.00	200.00
	REMOVE / REFIX WIRE HARNESS TO FACILITATE REPAIR.		300.00	150.00
			12,920.00	9,890.00
GRAND TOTAL			29,952.80	13,210.68
RECOMMENDED COST OF REPAIRS				13,210.68

Report Ref No. CS1/ICS18020379/Btbs2

REPAIR COST WILL BE REVIEW WHEN ADDITIONAL PROVIDED.

LIM TEOW GUAN

Asst. Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.