

Surveyor:

REF: C01 / ICS18010379 / Bth

Special Instruction:

ASSIGNMENT (Office)

From (Person): Janice Goh of ICS Date/Time: 17092018

Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor:

Workshop:

OD/TP Re-inspection / (Evaluation)

To Inspect Vehicle No: SBU 1300T Insured: SLJ 6797A

at Workshop m/s Motor Image
of 19 Lorong 8 Toa Payoh

Tel:

Policy No: Claim No: DMPC1700260H/DL

Sum Insured: Excess:

Make of Veh: D.O.A. 11.04.2017
(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original days)

Date/Time: 18/12/18 Submit Final Fig 3210.00, 6 days (Red \$ 16972.12 50%; Original 13 days)

Date/Time	Action/Instruction
	SBU 1300T - NA/MG/1301178/r3
	SLJ 6797A - C03/MG/1801573 / Urban2

DA: 12102013

DA: 270818

12/11 - Received file from Catherine

Remarks Repair cost will be review when additional photos provided (indicate in report)

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 18 DEC 2018

URGENT

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

1) Date/Time 18/12 File Pass to Typist

2) Date/Time File Return to

3) Date/Time File Pass to 4) Date/Time File Return to

5) Date/Time File Pass to 6) Date/Time File Return to