ASS REC BY	the state of the s	REF CS3/AWA	18014863	Gtd3 = Hitmenson	/
Surveyor		ASSIGN	MENT (Office		
From (Person		00	AWAC	Dete/Time (2)	3018
Estimated Co	The state of the s)	Bill to		
DO FTP W	S/TP RES/OD RE	SIEVAINVIM	V7CS		
to Inspect V	chiele No	31K 470	B	Insured: GBH	5943F
ii Workshop	10/2 8 K	3+K Aur	to	Tel 9123 70	
of	8 K	aki BK+ +	tve 4 # 0	3-21	
olicy No	AVC PSB00	92 42 1800	Claim No.	NSV 1800462 /KW	
Sum Insured.				-17-00-602 (100	
Make of Veh			Excess:		-1
CHent's Recor				1618/18 Ouft	08/3012
CA / REV	REP. / REV 24 H	irs (up)		1618118 O afte 11.0.D. Endorsemen	rioum
Date/Time	12:46pm/8)18/8	K Person Contact	Mr.GU	Vehicle IN (OU)	
	1 0 3 19	TO TO STAND	11/ 0100	A suite Ity (O(1)	
Date/Fime	Action/Instruction	(x) Estim	ate		
	914 470	B-X			
	G18H 59-431	F-X			1
					(la la la
		11		/ 2 /	Mach
-	Jump Run	MAHON)	10001: 10	20100011	
	lump Run	- PHO601-	(Red: 19	30,32%/	
Mn-	lump sum File pass		(Red. 19	30,32%)	

RECEIVED 0 7 DEC 2018

(Jd/11/13) Wef PK	MQ. REF. AWA	C		25/2	LE	
		ASSIGNMENT		1 000		
From: Estimated Cost	Date: 16 8	Veh No: Type: MCar / M.C	SUK 47d5 ycle/Bus/Van/Lor	Yr Regn: G3	Jan'	201
ON TP WS I TP RES I	OD RES / EVA / INV / MV	Truck / Tra	iler or	2.4		
To Inspect Vehicle No:	SIK 470 B	Make	Menda ody	sseu co	2356	
at Workshop m/s	3+K Auto	Colour	1. 40		Std / NI / N	A
of 8 kaki B	kt Ave 4 # 03-2	Sp.Reading	(10978	T/Radio: Insured	/ Std / NI / N	IA
Insured:	111.4 11 03	Eng/No:	9 110			
Policy No.		C/No:	SHMRC	1890.GC	2078	64
Claims No.		Gen. Cond: good	/ Fair / Poor / Burnt	1 -1		
Sum Insured:	Excess:	Steering; Indian	Jammed / Leaked / E	Burnt or		
(Client's Record)	After 10am.	Brake: Incer	Jammed / Leaked / E	Burnt or		
Make of Veh:	Mr. Guo@ 9123	7949 Modi: Nil 15/R	m / STD A/Rim or			
		Tyre Size: F:	215/	15R17		
(Policy Condition)		R:	-//	И		
Remark: The veh had co	mmenced its N	S OS BS / PUN EXNO	/A/GY/FS/LIZA/N	MIC / OHTSU / PIR /	SUMI/	
repair at the tin	ne of inspection.	тоуотуоко о				
Bal, or Market Value:	_	Front		Rear	^	
DAC Accident Rport:	Consistent? : Yes or No		mm	R/Bal.	, m	m ·
SIA / PR Seen:	Consistent? : Yes or No	L/Bal. 6	mm	L/Bal.	m	m
est. Repairs.	days Res.: Yes or No	D.O.A.		D.O.I. 16-0	08-18	
um Sum.	0 % 3 Val.: Yes or No	Survey held at	w/3	10-0		5 pu
	24 Upe (Up)		Frt / Rear / Q/S / N	N/S / U/C / Roofte		Jpu
CA / REV / REP. /	Vehicl	e. IN / OUT	ds 1	THE PART NAME OF THE		
Date: Pe	rson Contacted:		ssis frame / Body S		ue to collisio	in.
1	2000 - & Coo					
Date/Time, File Pass to?	: Preli. Report	Days Of Repair:				
)	: Final Report	Resurvey No. of	Trip:	Survey Fee:	100	
late/Time, File Return to?				Transportation:		
		Add Fee: Site Insp		S + RS,SI		
		: Interview	1	Photos		
Report Format :		: Tech. Invs	(5	Others		
ump Sum / I.B.I: (\$	1	- Weekend	(\$			

100

TOTAL

Catherine Chong (LKK Auto)

From:

Tan, KahLeong < KahLeong. Tan@awac.com > on behalf of Motorsurvey

<Motorsurvey@awac.com>

Sent:

Monday, 12 November, 2018 10:43 AM

To:

assignments

Cc:

SUR

Subject:

Paper Survey for TP Veh No: SLK 470B Our ref: NSV1800462/KW

Attachments:

Survey Report.pdf; Photographs.pdf

Insured Vehicle No:

GBH 5943 E

Date of Accident:

08/08/2018

Hi,

Please assist to do a paper survey.

Thank you

Regards,

Claims Division

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.

Correspondence Address: 1 Simei St.3 #02-24 S(529890) Mobile: 9295 2204 Fax: 6722 8508 Email: pasvos@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No.: PAS/TP/0290818

Date of Report

: 29/10/2018

To: Ms Lan Shu Yan

C/o. 8 Kaki Bukit Avenue 4

Report requested by : Ms Lan Shu Yan

Date of Assignment : 15/08/2018

#03-21 Premier @ Kaki Bukit

Date of Accident

: 08/08/2018

Singapore 415875

Date of Inspection

: 15/08/2018

Claim No.

: Third Party Claim

Policy No.

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No.

: SLK470B

Engine Capacity (cc) : 2356cc

: 40889km

Make & Model

: Honda Odyssey : 03/01/2017

Mileage (km)

Chassis / Frame No. : JHMRC1890GC207864

Date of Registration Colour

: Pearl White

Engine No.

: K24W72013389

TYRE CONDITION

Front LH

: 7 mm

Front RH

: 7 mm

Make : Dunlop Make

: Dunlop

Rear LH

: 7 nm

Rear RH

: 7 mm

Make

: Dunlop

Make

: Dunlop

Road wheels Type: Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork

: Good

Paintwork

: Good

Handbrake

: Serviceable

Footbrake

: Serviceable

Steering

: Scrviceable

Apparent Engine Modification

: Nil

Location

M/s. STK Auto (S) Pte Ltd

8, Kaki Bukit Avenue 4, #03-21, Premier @ Kaki Bukit, Singapore 415875

PLACE OF REPAIRER OFFICE/WORKSHOP

ASSESSMEN'T

Repairer's Estimate

Revised Amount

: \$ 8,964.32 : \$ 7,414.08

Less Excess

\$:

Recommended Reserve : \$ 5,930.00 (Lump Sum)

Estimated Normal Period of Repairs : 8 Working Days

Disclaimer: This report is intended for the exclusive use of the addresses solely in relation to the loss occurrence in which the assessed vehicle involved. No flability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTB LTD for any reliance on this report by any third party.

PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers Correspondence Address: 1 Simei St.3 #02-24 S(529890) Mobile: 9295 2204 Fax: 6722 8508 Email; pasycs@hotmail.com

Business Reg. 201404434D

Vehicle No: SLK470B

Report No.: PAS/TP/0290818

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. STK Auto (S) Pte Ltd, 8, Kaki Bukit Avenue 4, #03-21, Premier @ Kaki Bukit, Singapore 415875.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the RHR portion. (The RHR roadwheel was also affected)

DAMAGES

The rear bumper, RH taillamp, RHR fender, RHR alloy rim, RHR shock absorber, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT/RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$7,414.08.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$5,930.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd

Andrew How

Automobile Appraiser

MSAAA

Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD
Qualified Loss Adjusters And Motor Appraisers
Correspondence Address: 1 Simei St.3 #02-24 S(529890)
Mobile: 9295 2204 Fax: 6722 8508 Email: pasves@hotmail.com

Business Reg. 201404434D

Vehicle No.: SLK470B

Report No.: PAS/TP/0290818

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition				airer!s imate (S\$)	COMPANIES STATES	Our ment (S\$)
1	l pc	Rr bumper	Dented			S	624.10	\$	624.10
2	6 pcs	Rr bumper clip	Necessary	\$	3.50	S	21.00	\$	21.00
3	2 pcs	Rr bumper retainer R/L RH	Cracked/Necessary	5	31.20	S	62.40	\$	62.40 31,20
4	l pc	Taillamp RH	Cracked			\$	891.60	\$	891.60
5	1 pc	Rr fender panel RH	Dented/Distorted			\$	1,057.30	\$	1,057.30
6	1 pc	Rr fender qtr glass moulding RH	Necessary			S	142.30	\$	142.30
7	1 pc	Rr radar assy RH	Dented/Damaged			\$	1,032.60	\$	1,032.60 × NN
8	1 pc	Rr radar bracket RH	Cracked			\$	43.00	\$	43.00×NN
9	1 pc	Rr alloy rim RH	Dented/Defaced			S	973.20	\$	973.20 CUT
10	1 pc	Rr wheel hub assy RH	Warped/Distorted			\$	341.40	\$	341.40
11	1 pc	Rr shock absorber RH	Bent			S	403.70	\$	403.70×NN
12	1 pc	Rr axle beam assy	Realign			\$	1,062.80	\$	-
13	l pc	Rr fender inner panel RH	Dented/Repair				(Refer	labour n	0.1,2 & 4)
						\$	6,655.40	-\$	5,592.60 4082.1
				Less D	iscount: 20%	\$	1,331.08	20% \$	
			Lis	st Parts Su	b-Total:	\$	5,324.32	\$	4,474.08 3265.6
1	1 pc	Rr fender panel sealant RH	Necessary		S/N	\$	50.00	S	50.0030
. 2	1 pc	Rr fender quarter glass sealant RH	Necessary		S/N	\$	50.00	\$	50.00 30
3	1 pc	Rr tyre RH (Depreciate 10%)	Cut		S/N	\$	300.00	\$	270.00X HN
4	1 bot	Brake fluid	Necessary		S/N	\$	20.00	\$	20.00×NN
			Spec	ial Nett Su	b-Total:	\$	420.00	\$	390.00
				Part	s Total :	\$	5,744.32	_\$	4,864.08



PROMINENT APPRAISER SERVICES PTE LTD Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 6508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No.: SLK470B Report No.: PAS/TP/0290818 Repairer's Our S/No. Labour Descriptions Estimate (S\$) Assessment (S\$) To straighten, repair, realign on affected area and replace damaged parts. 990.00 500 1,200.00 To spray painting, blending on affected and adjacent area. 1,000.00 700.00 5 To remove and reinstall RHR quarter glass for necessary repairs. 100.00 80.00 To remove and reinstall rear interior trims, garnishes, seats, etc. for necessary repairs. 120.00 140.00 To check rear electrical wiring system. 30.00 50.00 To transfer rear reverse sensors to new bumper. \$ 80.00 7 To remove, check, replace RHR undercarriage parts and realign rear axle beam. (Include flush and bleed brakes system) 2 180.00 200.00 8 To conduct wheel alignment. \$ 120.00 120.00 To inspection, diagnose, reset and perform coding programming on:-9.1) Rear reverse control unit. 9.2) Rear radar control module. 220.00 250.00 10 To spray anti-rust coating on new and affected panels. 80.00 50.00 Labour Total: 3,220.00 2,550.00 Total (Parts & Labour) : 8,964.32 7,414.08

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 5,930.00

Under normal circumstances, the repairs should be completed within a reasonable period

of 8 Working Days. (Exclude waiting days of PRI, Sunday, Pubic Holiday and awaiting of shipment for spare parts)

44 Photographs were taken at the time of inspection.

<u>N.B:</u> By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD Ref: CS3/AWA18014883/Gtd3e2-1

(SINGAPORE BRANCH)

60 ANSON ROAD #08-01 (8th FLOOR)

MAPLETREE ANSON

Date: 11-12-2018

			Code: AWA	
1.		Policy Particula	ars :- THIRD PARTY CLA	MIM
	Insured Veh.	GBH 5943E	Veh. Inspected	SLK 470B
	Policy No.	AVCPSB0092421800	Coverage (\$)	0.00
	Claim No.	NSV1800462/KW	Excess (\$)	0.00
	Assign From	TAN KAH LEONG	Assign Date	12/11/2018
2.		Vehicle Pa	articulars & Condition	
	Make & Model	HONDA ODYSSEY 2.4	c.c	2356
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JHMRC1890GC207864	Colour	WHITE
	Odometer	40978	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.		Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	215/55 R17	DUNLOP	6 mm
	L/H Front Tyre	215/55 R17	DUNLOP	6 mm
	R/H Rear Tyre	215/55 R17	DUNLOP	6 mm
	L/H Rear Tyre	215/55 R17	DUNLOP	6 mm
4.		Descri	ption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	O/S REAR PORTION.	
	DAMAGES SEE D	ETAILS.		
5.		Gen	eral Information	
	Accident Date	08/08/2018	Inspection Date	16/08/2018
	Survey held at	STK AUTO (S) PTE LTD		
		8 KAKI BUKIT AVE 4 #03-21 PREMIER@KAKI BU SSINGAPORE 415875	JKIT	
5a.			Remarks	
		ON WAS CONDUCTED ON A" CE TO YOUR INSTRUCTIONS		
5b.		Estim	ate Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	5 Working Da	iys



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 470B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	RR BUMPER	DENTED	624.10	624.10
6	RR BUMPER CLIP @\$3.50	NECESSARY	21.00	21.00
2	RR BUMPER RETAINER R/L @\$31.20	O/S CRACKED	62.40	31.20
1	TAILLAMP RH	CRACKED	891.60	891.60
1	RR FENDER PANEL RH	DENTED / DISTORTED	1,057.30	1,057.30
1	RR FENDER QTR GLASS MOULDING RH	NECESSARY	142.30	142.30
1	RR RADAR ASSY RH	NOT NECESSARY	1,032.60	-
1	RR RADAR BRACKET RH	NOT NECESSARY	43.00	-
1	RR ALLOY RIM RH	сит	973.20	973.20
1	RR WHEEL HUB ASSY RH	WARPED / DISTORTED	341.40	341.40
1	RR SHOCK ABSORBER RH	NOT NECESSARY	403.70	-
1	RR AXLE BEAM ASSY	REALIGN	1,062.80	-
1	RR FENDER INNER PANEL RH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-1,331.08	-816.42
			5,324.32	3,265.68
	SPECIAL NETT ITEMS			
1	RR FENDER PANEL SEALANT RH (SN)	NECESSARY	50.00	30.00
1	RR FENDER QUARTER GLASS SEALANT RH (SN)	NECESSARY	50.00	30.00
1	RR TYRE RH (SN)	NOT NECESSARY	300.00	-
1	BOT BRAKE FLUID (SN)	NOT NECESSARY	20.00	-
			420.00	60.00
	LABOUR			
	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF RR FENDER INNER PANEL RH.		1,200.00	600.00
	TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA.		1,000.00	500.00
	TO REMOVE AND REINSTALL RHR QUARTER GLASS FOR NECESSARY REPAIRS.		100.00	60.00
	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISHES, SEATS, ETC. FOR NECESSARY REPAIRS.		140.00	80.00
	TO CHECK REAR ELECTRICAL WIRING SYSTEM.	NOT NECESSARY	50.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER REAR REVERSE SENSORS TO NEW BUMPER.		80.00	50.00
	TO REMOVE, CHECK, REPLACE RHR UNDERCARRIAGE PARTS AND REALIGN REAR AXLE BEAM. (INCLUDE FLUSH AND BLEED BRAKES SYSTEM)		200.00	150.00
	TO CONDUCT WHEEL ALIGNMENT.		120.00	60.00
	TO INSPECTION, DIAGNOSE, RESET AND PERFORM CODING PROGRAMMING ON:- 9.1)REAR REVERSE CONTROL UNIT. 9.2)REAR RADAR CONTROL MODULE.		250.00	120.00
	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS.		80.00	40.00
			3,220.00	1,660.00
	GRAND TOTAL		8,964.32	4,985.68

RECOMMENDED COST OF LUMP SUM REPAIRS	4,000.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS3/AWA18014883/Gtd3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Automotive Assessor

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.