

22/3/2007

ASS. REC. BY:

REF: CS3/MSG18015249/RW-1<sup>021</sup>

Special Instruction:

Surveyor: Rasul  
menmen

ASSIGNMENT (Office)

From (Person): Pauline Thumof MSGDate/Time: 12.11.2018

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SMC 2719CInsured: SV 56Zat Workshop m/s KOK WING CARTel: 68631790of No. 1, Soon Lee Street #06-40Policy No: 80335810 QMXClaim No: 567289

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 20/08/2018CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 4:17pm 21/8/18

Person Contacted:

Mr. JerryVehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate	DI Not Finalize
	SMC 2719C-X	
	SV 56Z-CS/MSG18011415/Ar d3	DOA: 20/6/18
23/8/18	Disassembled.	
24/8/18	After repair.	

RECEIVED 27 NOV 2018

27/11/18 @ 1010am Spoken to Rasul, Submit LS \$2600p  
(Red 650, 2090), 4 days

26/11/2018.

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SMC 2719C Yr Regn: 2018 / Jun  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or

Make: TOYOTA SIENNA 1.5 X C.C. 1496  
 Colour: BLACK A/C: Insured / Std / NI / NA  
 Sp.Reading: 11233 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_  
 C/No: NHP 170712226

Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15  
 R: \_\_\_\_\_

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front		Rear	
R/Bal.	<u>6</u> mm	R/Bal.	<u>6</u> mm
L/Bal.	<u>6</u> mm	L/Bal.	<u>6</u> mm
D.O.A.	<u>15/08/18</u>	D.O.I.	<u>21/08/18</u>

Survey held at Kok Wah  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
o/s frt  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Estimated repair range \$3,000 - \$3,800.

*John*  
6/9/2018

Date/Time File Pass to?

☐ : Preli. Report  
☐ : Final Report

1) \_\_\_\_\_  
 Date/Time File Return to?

2) \_\_\_\_\_

Report Format : PR2

Lump Sum / I.B.I.: (\$ \_\_\_\_\_)

Days Of Repair:

Resurvey No. of Trip: 2

Survey Fee:

Transportation

) S + RS. SI

) Photos

) Others

TOTAL

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Invs (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

120
10
130



**ABSOLUTE APPRAISAL SERVICES PTE LTD**  
**LOSS ADJUSTERS & MOTOR APPRAISERS**  
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722  
Mobile: 9688-0413 Fax: 6266-7396  
Email: absolute.app.svcs@gmail.com

### Invoice

Customer: SJ Motor Enterprise  
C/o: 1 Soon Lee Street #06-40 Pioneer Centre  
Singapore 627605

Date: 04.09.2018

Invoice No: NS-2018-350

Description		Amount
Vehicle No:	SMC2719C	
Make & Model:	Toyota Sienta Hybrid (A)	
Our reference:	AAS/2018/350	
Services rendered for appraiser / inspection report		
Survey Fee		
Photographs		
Transport Fees		
Re-inspection Fees		
SGD Dollar : Four hundred seventy eight dollar only	Total:	SGD \$ 478.00

**Notes:**

All cheques payment should be crossed and made payment to "Absolute Appraisal Services Pte Ltd"

Please indicate our "Invoice No." on the reverse side of the cheque.

Please do not hesitate to contact us should you have any enquires.



Absolute Appraisal Services Pte Ltd





**ABSOLUTE APPRAISAL SERVICES PTE LTD**  
**LOSS ADJUSTERS & MOTOR APPRAISERS**  
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722  
Mobile: 9688-0413 Fax: 6266-7396  
Email: absolute.app.svcs@gmail.com

### Vehicle Inspection Report

To: SJ Motor Enterprise  
C/o: 1 Soon Lee Street #06-40 Pioneer Centre  
Singapore 627605

Date of report: 04.09.2018  
Date of request: 20.08.2018  
Date of inspection: 20.08.2018  
Date of accident: 15.08.2018  
Claim type: Third Party Claim

Report No: AAS/2018/350

#### Particulars of affected vehicle:

Registration no:	SMC2719C	Odometer:	11233 km
Make/Model:	Toyota Sienta Hybrid (A)	Engine Capacity:	1496 cc
Year of registration:	2018	Engine no:	1N28499797
Colour:	Metallic Black	Chassis no:	NHP1707122266

#### Condition of tires:

Front Left:	7mm	Front Right:	7mm
Make:	Bridgestone	Make:	Bridgestone
Rear Left:	7mm	Rear Right:	7mm
Make:	Bridgestone	Make:	Bridgestone

Type of road wheel: STD (The above represent the remaining life of the tire thread)

#### Pre-accident condition (Static tests only)

General Bodywork	: Good
Paintwork	: Good
Handbrake	: In order
Footbrake	: In order
Steering	: In order
Apparent engine modification	: Nil

#### The Assignment

The inspection was conducted at M/s. Kok Wang Car Grooming  
1 Soon Lee Street #06-40 Pioneer Centre  
Singapore 627605

(Subsequent inspection was conducted)

#### Assessment

Repairer's estimate:	\$ 5,813.80
Revised estimate:	\$ 4,069.83
Recommended reserve:	\$ 3,250.00 (Lump sum)

Estimated normal duration of repairs : 4 Working days



**ABSOLUTE APPRAISAL SERVICES PTE LTD**  
**LOSS ADJUSTERS & MOTOR APPRAISERS**

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Vehicle No: SMC2719C

Report No: AAS/2018/350

W/O PREJUDICE

Point of impact

At the RHF portion.

General description of damages

The front bumper, RH headlamp, RHF fender, etc.

Other parts were also found damaged. (See schedule for details)

Recommendation

The estimate cost of repair submitted by M/s Kok Wang Car Grooming as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$4,069.83

Conclusion

The repairer has agreed to undertake the repair at a lumpsum of SGD \$3,250.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of 4 working days.

We have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a 'Without Prejudice' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes 38 photographs.

Your Faithfully

Absolute Appraisal Services Pte Ltd



Nicky Seah

Automobile Appraiser

MSAAA / MSMCTA



**ABSOLUTE APPRAISAL SERVICES PTE LTD**  
**LOSS ADJUSTERS & MOTOR APPRAISERS**  
 160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722  
 Mobile: 9688-0413 Fax: 6266-7396  
 Email: absolute.app.svcs@gmail.com

Vehicle No: SMC2719C  
 Appraisal Schedule

Report No: AAS/2018/350

S/N	Parts Description	Qty	Condition		Repairer's Est	Revised Est
1	Front bumper	1	Dented		\$ 1,230.60	\$ 1,230.60
2	Front bumper fog lamp cover RH	1	Torn		\$ 167.60	\$ 167.60
3	Front bumper retainer LH/RH	2	RH Cracked	\$ 95.80	\$ 191.60	\$ 95.80
4	Front bumper bracket	1	Serviceable		\$ 113.60	-
5	Front bumper seal	1	Necessary		\$ 29.00	\$ 29.00
6	Front bumper emblem	1	Necessary		\$ 69.00	\$ 69.00
7	Front bumper absorber	1	Cracked		\$ 116.10	\$ 116.10
8	Front bumper reinforcement	1	Serviceable		\$ 374.60	-
9	Front grille	1	Serviceable		\$ 1,221.30	-
10	Headlamp RH	1	Grazed/Cracked		\$ 1,300.00	\$ 1,300.00
11	RHF fender	1	Dented/Distorted		\$ 650.70	\$ 650.70 repair
12	RHF fender inner shield	1	Torn		\$ 209.00	\$ 209.00
13	RHF fender nameplate 'Hybrid'	1	Necessary		\$ 65.30	\$ 65.30

Total: \$ 5,738.40  
 -25% \$ 1,434.60  
 List total: \$ 4,303.80

Revised Est: \$ 3,933.10  
 \$ 983.28  
 \$ 2,949.83

3213.41  
 252  
 2410.01

1 Front bumper clips 1set Necessary \$ 50.00 \$ 50.00 30

Special nett total: \$ 50.00 \$ 50.00 30

Parts Total: \$ 4,353.80 \$ 2,999.83

S/N	Labour Description		Repairer's Est	Revised Est
1	To check lightings & wirings.		\$ 60.00	\$ 40.00 30
2	Rust proofing on affected & replacement panels.		\$ 50.00	\$ 30.00
3	Spray painting on affected & replacement panels.		\$ 600.00	\$ 500.00 300
4	Conduct panel beating, straightening, cutting & reforming. Renew front damaged parts. Re-align all affected area.		\$ 750.00	\$ 500.00 400

Labour Total: \$ 1,460.00 \$ 1,070.00 760

Grand Total: \$ 5,813.80 \$ 4,069.83

The final adjusted lump sum amount is \$3,250.00

Under normal circumstances, the repair should be completed within a reasonable period of 4 working days.

38 Photographs were taken at the time of inspection.

Disclaimer: This report is intended for the exclusive use of the address solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by Absolute Appraisal Service Pte Ltd for any reliance on this report by any third party.

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Aug 2018		21 Aug 2018 16:13 <a href="#">Edit Adj Rpt</a>	<b>S\$2,600.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,600.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>



































  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>Hiew, Moo Yeng Pauline</b> , ID: S0071771A									
Main Claimant: <b>SJ MOTOR ENTERPRISE</b> , Co. Reg. No.: 52838801X									
Vehicle Reg. No.: <b>SMC2719C</b>		Date of Loss: 15/08/2018 19:00 - :59 [1 Months and 18 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 567829</b>		Policy/Cover Note No.: 80335810QMX Coverage: 27/09/2017 - 26/09/2018							
Vehicle Reg. No. (Insured): <b>SV56Z</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Kok Wang Car Grooming - Pioneer (HQ)</b> No. 1 Soon Lee Street, #06-40 Pioneer Centre, 627603 Pioneer - Tel: 91839633									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Pauline Tham</b> - 6594 2545]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 14/11/2018]									
Adj Asg. Remarks: on WP. OI non reporting. liability not clear. TP reject SJE - assign LKK Auto Consultants Pte Ltd. Contact: Mr. Liang - 9183 9633.									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>MSIG_SG (12/11/2018): Report Send Back Alerts - SMC2719C (TP)</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SMC2719C (567829)**  
**[SV56Z]**  
**TP**  
**SJ MOTOR ENTERPRISE**  
**Aug 15 2018 7:00PM**  
**[Hiew, Moo Yeng Pauline]**  
**Kok Wang Car Grooming - Pioneer**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/09/18 11:37	<b>Accident Statement</b> From: SC - Reg. No: SV56Z, Claimant: HIEW MOO YENG PAULINE	 Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/08/18 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
2	24/08/18 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
3	24/08/18 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
4	24/08/18 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
5	24/08/18 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
6	24/08/18 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
7	24/08/18 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
8	24/08/18 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
9	24/08/18 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
10	24/08/18 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
11	24/08/18 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
12	24/08/18 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
13	24/08/18 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
14	24/08/18 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
15	24/08/18 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
16	24/08/18 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
17	24/08/18 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
18	24/08/18 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
19	24/08/18 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
20	24/08/18 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
21	24/08/18 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
22	24/08/18 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
23	24/08/18 16:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
24	24/08/18 16:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
25	24/08/18 16:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
26	24/08/18 16:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
27	24/08/18 16:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
28	24/08/18 16:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
29	24/08/18 16:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
30	24/08/18 16:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
31	24/08/18 16:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
32	24/08/18 16:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
33	24/08/18 16:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
34	24/08/18 16:28	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
35	24/08/18 16:28	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
36	24/08/18 16:28	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
37	04/09/18 11:16	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
38	04/09/18 11:16	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
39	04/09/18 11:16	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
40	04/09/18 11:16	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
41	04/09/18 11:16	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
42	04/09/18 11:16	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	21/08/18 09:42	TP SMC2719C GIA REPORT		Load PDF	
2	29/10/18 14:36	LOD 4 - Tp survey report & photographs		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/11/18 12:26	Colour Photo		Load PDF	
2	27/11/18 12:26	PRS Invoice		Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18015249/R1VBE2-1

Date: 27/11/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 80335810QMX

Claimant Vehicle No : SMC2719C

Insured Vehicle No : SV56Z

Date of Loss: 15/08/2018

Nature of Claim: TP

Claim No: 567829

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SMC2719C

Make &amp; Model: TOYOTA SIENTA, 1.5 HYBRID (A)

Engine No: 1NZ8499797

Reg. Date: 28/06/2018 (Man. Year: 2018)

Chassis No: NHP1707122266

Colour: Black

Odometer: 11233 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,353.80	2,491.80	1,862.00	42.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,460.00	760.00	700.00	47.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,813.80</b>	<b>3,251.80</b>	<b>2,562.00</b>	<b>44.07</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,600.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,813.80</b>	<b>2,600.00</b>	<b>3,213.80</b>	<b>55.28</b>

## INSPECTION

Date of Assignment: 21/08/2018

Date Inspected: 21/08/2018 Inspected At:

Kok Wang Car Grooming - Pioneer (HQ)  
No. 1 Soon Lee Street, #06-40 Pioneer  
Centre  
Singapore 627603

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 27 Nov 2018)
<b>Parts:</b>	M1-MPV	TOYOTA SIENTA 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMC2719C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	1,230.60 FL	*1,230.60 FL
2	1		*FRONT BUMPER FOG LAMP COVER RH	Torn	167.60 FL	*167.60 FL
3	1		*FRONT BUMPER RETAINER LH/RH	O/S Cracked	191.60 FL	*95.80 FL
4	1		*FRONT BUMPER BRACKET	Serviceable	113.60 FL	*- FL
5	1		*FRONT BUMPER SEAL	Necessary	29.00 FL	*29.00 FL
6	1		*FRONT BUMPER EMBLEM	Necessary	69.00 FL	*69.00 FL
7	1		*FRONT BUMPER ABSORBER	Cracked	116.10 FL	*116.10 FL
8	1		*FRONT BUMPER REINFORCEMENT	Serviceable	374.60 FL	*- FL
9	1		*FRONT GRILLE	Serviceable	1,221.30 FL	*- FL
10	1		*HEADLAMP RH	Grazed / Cracked	1,300.00 FL	*1,300.00 FL
11	1		*RHF FENDER	Repair	650.70 FL	*- FL
12	1		*RHF FENDER INNER SHIELD	Torn	209.00 FL	*209.00 FL
13	1		*RHF FENDER NAMEPLATE HYBRID	Necessary	65.30 FL	*65.30 FL
14	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>5,788.40</b>	<b>3,312.40</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	<b>1,434.60</b>	<b>820.60</b>
<b>Total Parts (S\$)</b>	<b>4,353.80</b>	<b>2,491.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK LIGHTINGS & WIRINGS	New	60.00	30.00
2	RUST PROOFING ON AFFECTED & REPLACEMENT PANELS	New	50.00	30.00
3	SPRAY PAINTING ON AFFECTED & REPLACEMENT PANELS	New	600.00	300.00
4	CONDUCT PANEL BEATING, STRAIGHTENING, CUTTING & REFORMING. RENEW FRONT DAMAGED PARTS. RE-ALIGN ALL AFFECTED AREA	New	750.00	400.00
Gross Labour Cost (S\$)			<b>1,460.00</b>	<b>760.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >