

REPAIRING OF
MOTOR VEHICLES,
PANEL BEATING,
WELDING, SPRAYING,
INSURANCE AGENT,
CLAIMS
DEALING IN 2ND
HAND VEHICLE.

速 良 摩 哆 SOC LEON MOTOR WORKS

AUTOBAY @ KAKI BUKIT
1 Kaki Bukit Ave 6, Blk D, #01-91, Singapore 417883
Tel: 6747 7858, 6747 2343 Fax: 6742 0012
E-mail: slmoi@singnet.com.sg
Reg No. 206639/00K

修理 汽車 貨車 兼
打嗎 甲燒 杆 噴 漆
代理 保險 : 車 禍
賠償 及 買賣 汽車

M/S YONG LEE SENG HOLDINGS PTE LTD

DATE: 12/11/2018

DOA : 09/11/2018

*Not Adjust
also
2/s \$10,600/-
1 day.
13/11/18
Tel: 6747 7858*

ESTIMATE REPAIR FOR VEHICLE NO. SKB 1222D (LEXUS GS450H)

| | Description | | List Price | |
|--------|--|---------|-------------|---|
| 1 pc | Rear bootlid | But/Buc | \$ 1,217.85 | ✓ |
| 2 pcs | Bootlid hinge @S\$274.45 | 17 | \$ 548.90 | X |
| 1 pc | Bootlid lock | twi | \$ 581.90 | ✓ |
| 1 pc | Bootlid weatherstrip | lin | \$ 274.10 | ✓ |
| 1 pc | Hinge side garnish (near rear fender) 115.10 | Torn | \$ 278.45 | ✓ |
| 1 pc | Bootlid lower garnish | Tra | \$ 281.90 | ✓ |
| 1 pc | Logo | rec | \$ 121.10 | ✓ |
| 1 pc | Lexus emblem | rec | \$ 124.45 | ✓ |
| 1 pc | GS450h emblem | rec | \$ 131.35 | ✓ |
| 1 pc | Limited emblem | rec | \$ 121.10 | ✓ |
| 1 pc | Rear lh fender | ra | \$ 1,200.50 | α |
| 1 pc | Taillamp (lh) | 310 | \$ 581.90 | ✓ |
| 1 pc | Taillamp panel (lh) | 1 | \$ 374.45 | X |
| 1 pc | Rear bumper | 17.3 | \$ 978.10 | ✓ |
| 1 pc | Towing cover 60 | 10.1 | \$ 121.10 | ✓ |
| 1 pc | Bumper side retainer (lh) | but | \$ 134.45 | ✓ |
| 1 pc | Bumper reinforcement | but | \$ 581.90 | ✓ |
| 1 pc | Sponge | spin | \$ 78.00 | ✓ |
| 1 pc | Rear end panel | 3ed/10 | \$ 972.10 | ✓ |
| 1 pc | Panel top garnish | twi | \$ 561.60 | ✓ |
| 1 set | Rear windscreen moulding | 17 | \$ 274.85 | α |
| 1 pc | Front bumper | 10/10c | \$ 972.45 | ✓ |
| 2 pcs | Bumper side retainer @S\$171.10 | but | \$ 342.20 | ✓ |
| 1 pc | No plate garnish | but | \$ 182.25 | ✓ |
| 20 pcs | Bumper clips @S\$12.90 60 | rec | \$ 258.00 | ✓ |
| 1 pc | Lower grille | 1 | \$ 274.45 | α |
| 1 pc | Front grille | cm | \$ 591.60 | ✓ |
| 1 pc | Grille chrome | cm | \$ 377.75 | ✓ |
| 1 pc | Logo | rec | \$ 172.45 | ✓ |

cont. page 2

| | | | | |
|------|---------------|----|----|------------|
| 1 pc | Headlamp (rh) | cm | \$ | 1,712.85 |
| 1 pc | Chrome rim | 17 | \$ | 378.55 |
| | | | \$ | 14,802.60 |
| | | | \$ | (1,480.26) |
| | | | \$ | 13,322.34 |

Special Nett Items

| | | | | | |
|-------|--|------|----|------------------|------|
| | <u>Towing fee (By king dolley)</u> | | \$ | 150.00 | 420 |
| 1 set | No. plate & housing | cm | \$ | 60.00 | 40 |
| 1 set | Reverse sensor | Shub | \$ | 280.00 | 200 |
| | To remove & fix reverse sensor | | \$ | 80.00 | 50 |
| | To spray anti-rust | | \$ | 180.00 | 60 |
| | To remove & fix rear windscreen glass | 17 | \$ | 150.00 | x |
| | Rear windscreen gum | 17 | \$ | 50.00 | x |
| | Labour charges for knocking & replacing parts. | | \$ | 1,600.00 | 1200 |
| | Spraypainting | | \$ | 1,500.00 | 1400 |
| | TOTAL : | | \$ | <u>17,372.34</u> | |

3070

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: