

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/LCR18020529/KEA3Q2

**Date:** 16/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994788

**Claimant**  
**Vehicle No :** SHD351X **Insured Vehicle No :** SLL6401G

Date of Loss: 08/11/2018 Nature of Claim: TP Claim No: 9889919864SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHD351X</b>	Engine No:	M9R8839C003002
Make & Model:	RENAULT LATITUDE, 2.0 D dCi (A)	Chassis No:	VF1ABL15AUC282620
Reg. Date:	17/05/2016 (Man. Year: 2015)	Odometer:	238134 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Giti 7 mm	Rear Left Side:	Giti 7 mm
Front Right Side:	Giti 7 mm	Rear Right Side:	Giti 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,831.02	0.00	8,831.02	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,070.00	590.00	5,480.00	90.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>14,901.02</b>	<b>590.00</b>	<b>14,311.02</b>	<b>96.04</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>1,043.07</b>	<b>41.30</b>	<b>1,001.77</b>	<b>96.04</b>
<b>Nett Amount (\$\$)</b>	<b>15,944.09</b>	<b>631.30</b>	<b>15,312.79</b>	<b>96.04</b>
<b>+ Loss of Use (3.5 x S\$50.00/day) (\$\$)</b>		175.00		
<b>+ Car Rental (3.5 x S\$103.60/day) (\$\$)</b>		362.60		
<b>+ Doc/Search Fee (\$\$)</b>		7.49		
<b>Nett Liability (\$\$)</b>		<b>1,176.39</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>1,170.00</b>		

### INSPECTION

Date of Assignment: 12/11/2018

Date Inspected: 12/11/2018 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)  
2, Ang Mo Kio Street 63  
Singapore 569111

Estimated Period of Repair: 2.0 days

---

**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Repair	1,259.42 FL	*- FL
2	1		*BUMPER SPOILER FRT	Serviceable	181.75 FL	*- FL
3	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
4	1		*BUMPER RETAINER FRT LH	Serviceable	151.41 FL	*- FL
5	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
6	1		*BUMPER RETAINER FRT RH	Serviceable	150.77 FL	*- FL
7	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
8	1		*BUMPER UNDERTRAY FRT	Serviceable	472.83 FL	*- FL
9	1		*BUMPER GRILLE LOWER FRT	Serviceable	266.80 FL	*- FL
10	1		*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	*- FL
11	1		*BUMPER BEAM FRT	Repair	914.08 FL	*- FL
12	1		*HEADLAMP LH	Serviceable	1,184.43 FL	*- FL
13	1		*HEADLAMP PANEL FRT LH	Repair	152.15 FL	*- FL
14	1		*FENDER PANEL FRT LH	Repair	783.83 FL	*- FL
15	1		*WHEELARCH FRT LH	Serviceable	278.84 FL	*- FL
16	1		*FENDER BRACKET LOWER LH	Serviceable	15.79 FL	*- FL
17	1		*FENDER UNSULATOR LH	Serviceable	130.84 FL	*- FL
18	1		*DOOR PANEL FRT LH	Repair	2,844.66 FL	*- FL
19	1		*SET BUMPER CLIP FRT	Not Necessary	66.00 FS	*- FS
20	1		*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*- FS
21	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*- FS
22	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,794.75</b>	<b>0.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	963.73	0.00
<b>Total Parts (\$\$)</b>	<b>8,831.02</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,100.00	150.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,100.00	440.00
3	TO RUST PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
6	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
8	TO TRANSFER OF FRONT FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
9	TO TRANSFER OF FRONT BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,070.00</b>	<b>590.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >