

ASS. REC. BY:

REF: CS/FCI/8020537 ASD3

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time: 13/11/18 @ 4:49pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PC6637T

Insured:

SHD 6756Y

at Workshop m/s

Chin Meng Motors

Tel:

67474810

of

1 Kaki Bkt Ave 6 # 01-40

Policy No:

Claim No:

D18008001MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

04/11/2018

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

5:05pm @ 13/11/18

Person Contacted:

Kim Seng

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	PC6637T-X
	SHD 6756Y-CC4/AXA/17016329/K16639.2 DoA: 19/05/2017
14/11/18-	called Kim Seng via yet, once in he will call.
22/1/18	@ 15:39 p.m. revert pending estimate from repairer to Karen via email.

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: PC6637T Yr Regn: 2017 / Oct.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Nissan NV350 c.c. 2488Colour: White A/C: Insured / Std / NI / NASp. Reading: 6299 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1TC2E2620015450Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195 R15CR: 195 R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 27/11/18Survey held at Chin MeryDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP 1st Cap.</u>
<u>12/12/18</u>	<u>Confirmed L/S \$1,250/- @ 2 days with Adrian.</u>
	<u>C \$ 1,205.93 Rd - 49%</u>
	<u>Resurvey No. of Trip : 0</u>
RECEIVED 13 DEC 2018	

Date/Time, File Pass to?

Date/Time, File Return to?

1) Typst

2)

3)

4)

5)

6)

Prel. Report:

Final Report: \$1,250/- L/S

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

1105013173

MOTOR SURVEY ASSIGNMENT

Date	08-11-2018	Our Ref No. D18008001MFSH
Accident Date	04-11-2018	Claim Type. Third Party
Insured Vehicle	SHD6756Y	Third Party Vehicle. PC6637T
Survey Location	1 KAKI BUKIT AVE 6 #01-40 AUTOBAY@KAKI BUKIT	
Contact Person.	QUEK KIM SENG	
Contact No.	67474810/ 91912829	Fax No. 67455018
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHIN MENG MOTORS	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 22 November 2018 3:39 PM
To: 'Karen Tan'; 'CWS Motor Claims'
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: SURVEY ASSESSMENT - D18008001MFSH/1

Dear Karen,

Please be informed that we have inspected the vehicle PC 6637T on 21/11/2018.

We are pending for estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 13 November 2018 5:09 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008001MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 13 November 2018 4:48 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008001MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System


Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

振明摩托 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

ESTIMATE

Our Ref: EST364/18/CIS

Your Ref: To be advised

17-Nov-18

Shirley

NTUC Income Insurance Co-operative Ltd

75 Bras Basah Road

Singapore 189557

1st Capital

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Estinmate cost of repair to Nissan NV350 no: PC6637T

Date of accident: 04-11-2018

Parts supply:

- 1 pc Rear end panal *Regr*
- 1 pc Tailgate emblem - NV350 (Nett) *3m*
- 1 pc Tailgate emblem - URVAN (Nett)
- 1 pc Rear bumper (Nett) *Deland*
- 6 pcs Rear bumper retainer sockets @\$12.10 (Nett) *new*
- 10 pcs Rear bumper clips @\$3.50 (Nett) *new*

812.10	455.60
	55.50
730.89	48.50
	600.50
	72.60
	35.00
	<u>1,267.70</u>
Less 10%:	(126.77)

S/Nett Items

- 1 set Rear reverse sensor (S/Nett) *Regr*
- 1 pc Tailgate sticker - Certis CISCO (S/Nett) *3m*
- 1 pc Tailgate sticker - AUXILIARY POLICE (S/Nett)
- 1 pc Tailgate sticker - 70km/h (S/Nett) *3m*
- 1 pc Tailgate sticker - Green disc (S/Nett)

435	250.00
	100.00
	100.00
	15.00
	20.00
	<u>1,625.93</u>

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc.

To respray affected part.

To check wirings.

430	300.00
	500.00
	30.00
SS	<u>2,455.93</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lij
2/5 21/11/18
02 amp

Totals 1555.89
L/S: 1250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18020537/Asd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 14-12-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6756Y	Veh. Inspected	PC 6637T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008001MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	13/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV350	c.c	2488	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JN1TC2E26Z0015450	Colour	WHITE	
Odometer	62991	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	BRIDGESTONE	6 mm	
L/H Front Tyre	195 R15C	BRIDGESTONE	6 mm	
R/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm	
L/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/11/2018	Inspection Date	21/11/2018	
Survey held at	CHIN MENG MOTORS 1 KAKI BUKIT AVE 6 #01-40/63 SINGAPORE 417883.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 6637T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR END PANEL (N)	TO REPAIR SEE LABOUR	455.60	-
1	TAILGATE EMBLEM-NV350 (N)	NECESSARY	55.50	55.50
1	TAILGATE EMBLEM-URVAN (N)	NECESSARY	48.50	48.50
1	REAR BUMPER (N)	DEFORMED	600.50	600.50
6	REAR BUMPER RETAINER SOCKETS @\$12.10 (N)	NECESSARY	72.60	72.60
10	REAR BUMPER CLIPS @\$3.50 (N)	NECESSARY	35.00	35.00
	LESS 10% DISCOUNT		-126.77	-81.21
			1,140.93	730.89
SPECIAL NETT ITEMS				
1	SET REAR REVERSE SENSOR (SN)	DAMAGED	250.00	200.00
1	TAILGATE STICKER-CERTIS CISCO (SN)	NECESSARY	100.00	100.00
1	TAILGATE STICKER-AUXILIARY POLICE (SN)	NECESSARY	100.00	100.00
1	TAILGATE STICKER-70KM/H (SN)	NECESSARY	15.00	15.00
1	TAILGATE STICKER-GREEN DISC (SN)	NECESSARY	20.00	20.00
			485.00	435.00
LABOUR				
	TO PANEL BEATING, WELDING, REMOVING DAMAGED PARTS AND REPLACEMENT OF THE NEW PARTS AS MENTIONED ABOVE ETC. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		300.00	200.00
	TO RESPRAY AFFECTED PART.		500.00	200.00
	TO CHECK WIRINGS.		30.00	30.00
			830.00	430.00
GRAND TOTAL			2,455.93	1,595.89
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,250.00

Report Ref No. CS/FCI18020537/Asd3n2

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.