

22/03/2002

ASS. REC. BY:

REF: CS/SMD18020543 /Kebn2 | Special Instruction:

SUNVAYOR

ASSIGNMENT (Office)From (Person): Thelma Choo of SMD Date/Time: 13/11/2018 4:54pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKX 5175P Insured: GBH 3101Gat Workshop m/s Ah Lim Motor Tel: 6483 1244of Bik W Amk Ind Park 2A #01-09Policy No: D18MTPCVE001309 Claim No: CMTD1801924

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 01/12/18
(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

14/11/2018 @ 1:30pm

H.O.D. Endorsement: _____

Date/Time: 13/11/2018 4:59pm Person Contacted: Eileen Vehicle IN / OUT

Date/Time Action/Instruction (✓) Estimate

SKX 5175P - xGBH 3101G - x15/11/18 @ 15:57 p.m. revised IA to Thelma Choo via mermer.11/4 @ 8:502.50 Cabman

REF: SMO

ASSIGNMENT

From:

Date: 14/11/2018

Estimated Cost:

OD ☒ TP ☐ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKX 5175P

at Workshop m/s

Ah Lim Motor

of 10 AMK Ind. Park 2A # 01-09

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

1:30 pm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07

days

Res.: Yes or No

Lum Sum:

1.31

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKX 5175P

Yr Regn:

12 15

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Accent

c.c.

1368

Colour:

M. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

79245

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMHC T413244068114

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/65R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MAXXIS

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

9/11/18

D.O.I.

14/11/18

Survey held at

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

15/11 File pass to Customer

(\$ 2,437.50 Red - 35%)

RECEIVED 02 APR 2019

Date/Time, File Pass to?

02/04/19

1)

Type

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair:

7

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

250

) Photos

) Others

TOTAL

260

Report Format :

Lump Sum / I.B.I: (\$ 4502.50 p/p)

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Thelma Choo

Date: 15 Nov 2018

Preliminary Advice

Insured Vehicle No	: GBH3101G	Accident Date	: 09/11/2018
TP Vehicle No	: SKX5175P	Assignment Date	: 13/11/2018
Make	: HYUNDAI ACCENT	Est. Duration of Repair	: 7 days
Date of Inspection	: 14/11/2018		
Inspection At	: Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint Singapore 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,940.00
Revised Amount	:S\$	3,161.25
Check Items (Estimated)	:S\$	698.75
Total	:S\$	3,860.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Some part items pending parts prices. TP : WP

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Nov 2018 16:15 Sendback Est	13 Nov 2018 16:22 S\$6,940.00	13 Nov 2018 16:54 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	YAKULT (SINGAPORE) PTE LTD, Co. Reg. No.: 197801922R								
Main Claimant:	ANG TIONG SENG, ID: S7920838H								
Vehicle Reg. No.:	SKX5175P	Date of Loss:	09/11/2018 08:00 - :59 [34 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1804924	Policy/Cover Note No.:	D18MTPCVE001309 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBH3101G	Policy No. (Claimant):	P1697356						
	Excess:								
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244								
Handling Insurer:	Sampo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/11/2018]								
Driver/Custodian (Insured):	TAN YUN LONG (), NRIC: F1753962X, Tel: +6581017990								
Adj Asg. Remarks:	PLS CONTACT EILEEN VEH CMG IN TOMORROW, 14/11/18								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 0838H

Vehicle Details

Vehicle No.: SKX5175P
Vehicle to be Exported: Yes
Intended Deregistration Date: 09 Nov 2018
Vehicle Make: HYUNDAI
Vehicle Model: ACCENT (RB) 1.4 MT ABS D/AIRBAG 2WD
Primary Colour: Blue
Manufacturing Year: 2015
Engine No.: G4LCFU537134
Chassis No.: KMHCT41BLGU068114
Maximum Power Output: 73.6 kW (98 bhp)
Open Market Value: \$10,856.00
Original Registration Date: 17 Dec 2015
First Registration Date: 17 Dec 2015
Transfer Count: 0
Actual ARF Paid: \$10,856.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 16 Dec 2025
PARF Rebate Amount: \$8,142.00

Intended COE Rebate Details

COE Expiry Date: 16 Dec 2025
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$59,200.00
COE Rebate Amount: \$42,044.00
Total Rebate Amount: \$50,186.00

The information contained herein is correct as at 09 Nov 2018

OK

AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A
 #01-09 AMK AUTOPOINT Singapore 568047
 Tel: 6483 1244 Fax: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST Reg No: M9-0009639-E

SURVEYOR COPY

TP INSURER: Somp Insurance Singapore Pte. Ltd. (HQ)

Claimant Insurer: AXA Insurance Pte Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP/SOMPO
Policy No:		Date of Loss:	09/11/2018
Vehicle Reg. No.:	SKX5175P	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	ANG TIONG SENG		
Make/Model:	HYUNDAI ACCENT, 1.4 (A)	Vehicle Reg. Date:	17/12/2015
Vehicle Colour:	BLUE		
Engine No:	G4LCFU537134	Chassis No:	KMHCT41BLGU068114
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	15 7 days		
Description of Accident/Loss	REFER TO THE ATTACHED SKETCH PLAN BY DRIVER.		
Remarks:	MAKE & MODEL: HYUNDAI ACCENT (RB) 1.4 MT ABS D/AIRBAG 2WD		
Present Location:	AH LIM MOTOR COMPANY (AMK)		

Not Notion
 Resumy B4 paint

COST OF CLAIMS	Amount
Parts	1,800.00
Miscellaneous Items	0.00
Labour	5,140.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,940.00
+ GST 7.00% (S\$)	485.80
Nett Amount (S\$)	7,425.80

This claim is handled by: EILEEN CHUA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG

Version: 1.0 (Last Synchronised: 13 Nov 2018)

Parts: 144

HYUNDAI ACCENT 1.4 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Ah Lim Motor Company/SKX5175P/13/11/2018 16:22**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*REAR WINDSCREEN MOULDING - CHECK PRICE	Nn	0.00	0.00	*-F X
2	1		*REAR BOOT - CHECK PRICE	Rn	0.00	0.00	480 *-F ✓
3	2		*REAR BOOT HINGE X 2 - CHECK PRICE		0.00	0.00	R *-F X
4	1		*REAR BOOT INSULATOR	Sn	0.00	0.00	*50.00F X
5	10		*REAR BOOT INSULATOR CLIPS X 10	Nn	0.00	0.00	*15.00F ✓
6	1		*REAR BOOT EMBLEM	Nn	0.00	0.00	*18.00F ✓
7	1		*REAR BOOT LOGO (ACCENT) LH	Nn	0.00	0.00	*20.00F ✓
8	1		*REAR BOOT RUBBER (AT BODY)	Dit	0.00	0.00	*45.00F ✓
9	1		*REAR BOOT INNER LOCK	Nn	0.00	0.00	*85.00F ✓
10	2		*REAR BOOT NUMBER PLATE LAMP	cm Sn	0.00	0.00	*30.00F ✓
11	1		*REAR BOOT NUMBER PLATE LAMP OUTER GARNISH	cat	0.00	0.00	*25.00F ✓
12	2		*TAILAMP LED LH & RH	mgmt	0.00	0.00	*290.00F ✓
13	82		*TAILAMP LED CLIPS LH & RH	Nn	0.00	0.00	*12.00F ✓
14	1		*TAILAMP PANEL RH	R	0.00	0.00	*80.00F X
15	1		*TAILAMP PANEL LH - CHECK PRICE	N	0.00	0.00	*-F X
16	1		*REAR BUMPER	Bn	0.00	0.00	*175.00F ✓
17	2		*REAR BUMPER SIDE RETAINERS X 2	bir	0.00	0.00	*32.00F ✓
18	12		*REAR BUMPER CLIPS	Nn	0.00	0.00	*18.00F ✓
19	1		*REAR BUMPER REINFORCEMENT	Rn	0.00	0.00	*165.00F ✓
20	2		*REAR BUMPER REINFORCEMENT BRACKET	Rn	0.00	0.00	*44.00F ✓
21	2		*REAR BUMPER REFLECTOR LH & RH	Sn	0.00	0.00	*44.00F X
22	1		*END PANEL - CHECK PRICE	Rn	0.00	0.00	200 *-F ✓
23	1		*END PANEL TOP GARNISH ASSY - CHECK PRICE	Nn	0.00	0.00	92 *-F ✓
24	1		*SPARE TYRE PANEL - CHECK PRICE	R	0.00	0.00	*-F X
25	1		*SPARE TYRE PANEL INTERTRIM - CHECK PRICE	Sn	0.00	0.00	*-F X
26	2		*REAR FENDER LH & RH - CHECK PRICE	R	0.00	0.00	*-F X
27	2		*REAR FENDER TOP TRIANGLE GARNISH BLACK	Nn	0.00	0.00	*40.00F X
28	2		*REAR REVERSE SENSOR X 2	Nn	0	0.00	*200.00FS ✓
29	1		*REAR NUMBER PLATE	Sn	0	0.00	*35.00FS X
30	1		*REAR WINDSCREEN SEALANT	Nn	0	0.00	*40.00FS X
31	1		*REAR WINDSCREEN INNER SEAL	Nn	0	0.00	*40.00FS X
32	1		*REAR REVERSE CAMERA - CHECK PRICE	Sn	0	0.00	*-FS X

F=Franchise part, S=SpcNett.

Sub Total (S\$)	1,503.00
+ Margin on L,N Items 25.00% (S\$)	297.00
Total Parts (S\$)	1,800.00

Ah Lim Motor Company/SKX5175P/13/11/2018 16:22. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount	
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00	201
2	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	New	nn 80.00	x
3	TO REMOVE & REFIT REAR WINDSCREEN	New	nn 150.00	x
4	TO REMOVE AND REINSTALL CUSHIONS; SEATS; BACKREST; INNER TRIM; GARNISH; ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	New	280.00	1001
5	TO DISMANTLE; REPLACE AND REINSTALL UNDERCARRIAGE. REAR CROSSMEMBER	New	nn 300.00	x
6	TO REMOVE AND REINSTALL FUEL TANK; FIXTURE AND ATTACHMENTS.	New	nn 100.00	x
7	TO REMOVE AND REINSTALL/REPLACE REAR REVERSE CAMERA	New	nn 80.00	x
8	TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.	New	80.00	501
9	LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	New	nn 200.00	x
10	TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	New	150.00	601
11	TO REALIGN; DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	New	nn 80.00	x
12	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD REAR FENDER LH & RH; END PANEL; SPARE TYRE PANEL; TAILLAMP PANEL LH & RH. TO KNOCK & REPAIR SPARE TYRE PANEL SIDE LH & RH; REAR CHASSIS FRAME LH & RH; REAR FENDER INNER LH & RH	New	2,000.00	9001
13	TO SPRAY REAR BOOT; REAR BUMPER; REAR BUMPER REINFORCEMENT; END PANEL; SPARE TYRE PANEL; TAILLAMP PANEL LH & RH; SPARE TYRE PANEL SIDE LH & RH; REAR CHASSIS FRAME LH & RH; REAR FENDER INNER LH & RH	New	1,600.00	10001
Gross Labour Cost (S\$)			5,140.00	

Ah Lim Motor Company/SKX5175P/13/11/2018 16:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18020543/KSBN2

Date: 04/04/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPCVE001309
Claimant Vehicle No :	SKX5175P	Insured Vehicle No :	GBH3101G
Date of Loss:	09/11/2018	Nature of Claim:	TP
		Claim No:	CMTD1804924

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX5175P	Engine No:	G4LCFU537134
Make & Model:	HYUNDAI ACCENT, 1.4 (A)	Chassis No:	KMHCT41BLGU068114
Reg. Date:	17/12/2015 (Man. Year: 2015)	Odometer:	79245 km
Colour:	Metallic Blue		
Engine Capacity:	1368 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R14	Rear Tyre Size:	185/65 R14
Front Left Side:	Maxxis 5 mm	Rear Left Side:	Maxxis 5 mm
Front Right Side:	Maxxis 5 mm	Rear Right Side:	Maxxis 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,800.00	2,372.50	-572.50	-31.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,140.00	2,130.00	3,010.00	58.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	6,940.00	4,502.50	2,437.50	35.12
+ GST 7.00/7.00% (\$\$)	485.80	315.18	170.62	35.12
Nett Amount (\$\$)	7,425.80	4,817.68	2,608.12	35.12

INSPECTION

Date of Assignment:	13/11/2018	Present Location:	Ah Lim Motor Company (AMK)
Date Inspected:	14/11/2018	Inspected At:	Ah Lim Motor Company (AMK)
			10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint
			Singapore 568047

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Apr 2019)
Parts: 144	HYUNDAI ACCENT 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKX5175P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING - CHECK PRICE (NPA)	Not Necessary	0.00 F	*- F
2	1		*REAR BOOT - CHECK PRICE	Bent	0.00 F	*480.00 F
3	2		*REAR BOOT HINGE X 2 - CHECK PRICE (NPA)	Repair	0.00 F	*- F
4	1		*REAR BOOT INSULATOR	Serviceable	50.00 F	*- F
5	10		*REAR BOOT INSULATOR CLIPS X 10	Necessary	15.00 F	*15.00 F
6	1		*REAR BOOT EMBLEM	Necessary	18.00 F	*18.00 F
7	1		*REAR BOOT LOGO (ACCENT) LH	Necessary	20.00 F	*20.00 F
8	1		*REAR BOOT RUBBER (AT BODY)	Distorted	45.00 F	*45.00 F
9	1		*REAR BOOT INNER LOCK	Dented	85.00 F	*85.00 F
10	2		*REAR BOOT NUMBER PLATE LAMP	Cracked	30.00 F	*30.00 F
11	1		*REAR BOOT NUMBER PLATE LAMP OUTER GARNISH	Cracked	25.00 F	*25.00 F
12	2		*TAILAMP LED LH & RH	Mtg Cracked	290.00 F	*290.00 F
13	1		*TAILAMP LED CLIPS LH & RH (6 PCS)	Necessary (2 PCS ONLY)	12.00 F	*4.00 F
14	1		*TAILAMP PANEL RH	Repair	80.00 F	*- F
15	1		*TAILAMP PANEL LH - CHECK PRICE (NPA)	Repair	0.00 F	*- F
16	1		*REAR BUMPER	Buckled	175.00 F	*175.00 F
17	2		*REAR BUMPER SIDE RETAINERS X 2	Distorted	32.00 F	*32.00 F
18	12		*REAR BUMPER CLIPS	Necessary	18.00 F	*18.00 F
19	1		*REAR BUMPER REINFORCEMENT	Bent	165.00 F	*165.00 F
20	2		*REAR BUMPER REINFORCEMENT BRACKET	Bent	44.00 F	*44.00 F
21	2		*REAR BUMPER REFLECTOR LH & RH	Serviceable	44.00 F	*- F
22	1		*END PANEL - CHECK PRICE	Bent	0.00 F	*200.00 F
23	1		*END PANEL TOP GARNISH ASSY - CHECK PRICE	Dented	0.00 F	*92.00 F
24	1		*SPARE TYRE PANEL - CHECK PRICE (NPA)	Repair	0.00 F	*- F
25	1		*SPARE TYRE PANEL INTERTRIM - CHECK PRICE (NPA)	Serviceable	0.00 F	*- F
26	2		*REAR FENDER LH & RH - CHECK PRICE (NPA)	Repair	0.00 F	*- F
27	2		*REAR FENDER TOP TRIANGLE GARNISH BLACK	Not Necessary	40.00 F	*- F
28	2		*REAR REVERSE SENSOR X 2	Dented	200.00 FS	*200.00 FS
29	1		*REAR NUMBER PLATE	Serviceable	35.00 FS	*- FS
30	1		*REAR WINDSCREEN SEALANT	Not Necessary	40.00 FS	*- FS
31	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	40.00 FS	*- FS
32	1		*REAR REVERSE CAMERA - CHECK PRICE (NPA)	Serviceable	0.00 FS	*- FS

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Sub Total (S\$)	1,503.00
					+ Margin on L,N Items 25.00/25.00% (S\$)	297.00
					Total Parts (S\$)	1,800.00

Report was unsubmitted during this print-out.
