

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: C0462939 Date: 21st Nov 2018

Our Ref: CS3/AXA17023774/Bsbe2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01 Axa Tower Singapore 068811 (The Motor Claims Department)

Attn: Chen Xinyou

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SGX 343B INSURED VEHICLE: GR 7385R ACCIDENT DATE: 13/12/2017

We thank you for your instruction on 12/11/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SGX 343B from M/s Par Automotive Consultancy.
- b) Singapore Accident Statement of Vehicles SGX 343B.
- c) Final Repair Bill of SGX 343B from N-51 Automotive Pte Ltd..
- d) Colour damaged vehicle photographs of SGX 343B.

Pre-Repair Inspection Date: 15/12/2017 at M/s N-51 Automotive Pte Ltd, 2 Kaki Bukit Ave 2, #01-17 Kaki Bukit Autohub, Singapore 417921.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Records	1: -	
------------------------	------	--

Registration Number :

: SGX 343B

Make & Model

: Toyota Yaris G Auto

Year of Registration

: 2007

Chassis Number

: MR054HY9104021086

Engine Capacity

: 1497 cc

- 2. We recommend that the repairs of the entire damage require about <u>8 (Eight)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.