

REF: NS/INC18020586/NH002

REF: NS/INC18020586/NH002

TAX/11/18/2012

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SLU 732Y

Policy No. 5096683201 13122017 - 121212018

Claims No. MT/1018520-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 Days days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHC 4470P Yr Regn: 12 OCT 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: TOYOTA PRINS C.G. 1,798

Colour: MAROON A/C: Insured / Std / NI / NA

Sp. Reading: BATT FLAT T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3 FU603573062

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

X TOYO / YOKO or FALKEN

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 4/11/18 D.O.I. 7/11/18

Survey held at SMART WOODLANDS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHC 4470P - NA / III17004316 / H/L
	SLU 732Y - X
22/11/18	CONFIRMED. PART BY PART REPAIR \$3764.41 / 4 DAYS.
	(Red: 8259.23; 68%)
	RECEIVED 03 DEC 2018

Date/Time, File Pass to?

1) 31/12 Typist

Date/Time, File Return to?

2) _____

☐ : Prelim Report

☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) S + RS _____

☐ : Interview (\$ _____) Photos _____

☐ : Tech. Invs (\$ _____) Others _____

☐ : Weekend (\$ _____)

TOTAL

Report Format :

Lump Sum / I.B.L. (\$) 3764.41

160
160

eBaqTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident
Vehicle No.(For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5096683201		HOEHOOI	53366550K	GPC	drivo CLASSIC	SLU7732Y	SLU7732Y	13/12/2017	12/12/2018

TP Claims against NTUC Income: Follow-Through Survey

Date : 30/11/2018

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate
1	MT/1010189-002	SMRT TAXIS PTE LTD	SHC 4183T	SKT 8314G	4/9/2018	19:30	\$ 9,330.90
2	MT/1018520-002	SMRT TAXIS PTE LTD	SHC 4470P	SLU 7732Y	4/11/2018	14:00	\$ 10,076.17
3	MT/1011111-002	SMRT BUS LTD	SMB 291L	SKJ 7218K	12/9/2018	7:20	\$ 298.38

Case Details

Case Reference Number : TAX/11/18/2012
Type of Repair : Accident Repair
Vehicle Registration Number : SHC4470P

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-4418-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income
Insurance Co-operative Ltd
Accident Date and Time : 04/11/2018 06:02 AM
Vehicle Age(In Months) : 13

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval		
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR RH	1	1,249.60	1,249.60	25.00	937.20	Replace	1	0	Repair * XR
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace * /NEC
One Time Key In	Main			PANEL SUB-ASSY, REAR DOOR, RH	1	1,243.90	1,243.90	25.00	932.93	Replace	1	932.93	Replace * /DEF
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace * /NEC
One Time Key In	Main			CHECK ASSY, REAR DOOR	1	153.50	153.50	25.00	115.13	Replace	0	0	Check * ? XSVL
One Time Key In	Main			WEATHERSTRIP, REAR DOOR RH	1	174.40	174.40	25.00	130.80	Replace	0	0	Not Give * XNN
One Time Key In	Main			WEATHERSTRIP, REAR DOOR, NO.2, RH	1	33.20	33.20	25.00	24.90	Replace	0	0	Not Give * XNN
One Time Key In	Main			RUN, REAR DOOR GLASS, RH	1	118.70	118.70	25.00	89.03	Replace	1	89.03	Replace * /NEC
One Time Key In	Main			BAR SUB-ASSY, REAR DOOR WINDOW DIVISION, RH	1	108.70	108.70	25.00	81.53	Replace	0	0	Check * ? XSVL
One Time Key In	Main			WEATHERSTRIP, REAR DOOR QUARTER WINDOW, RH	1	47.70	47.70	25.00	35.78	Replace	0	0	Not Give * XNN
One Time Key In	Main			HINGE ASSY, REAR DOOR, UPPER RH	1	83.30	83.30	25.00	62.47	Replace	0	0	Check * ? XSVL
One Time Key In	Main			HINGE ASSY, REAR DOOR, LOWER RH	1	73.30	73.30	25.00	54.97	Replace	0	0	Check * ? XSVL
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	824.80	25.00	618.60	Replace	1	618.60	Replace * /DD

Total Spare Part Cost 6,877.17

Surveyor Total 2,294.41

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 6,877.17

Final Sur Total 2,294.41

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation								Surveyor Approval		
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			LINER, REAR FENDER , RH	1	135.80	135.80	25.00	101.85	Replace	1	101.85	Replace	✓
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	✓ X SUL
Non-Standard	Main	VE		DOOR REAR MOTOR ASSY, POWER WINDOW REGULATOR , RH	1	768.60	768.60	10.00	691.74	Replace	0	0	Not Give	✓ X SUL
Non-Standard	Main	VE		DOOR REAR WINDOW REGULATOR SUB-ASSY, RH	1	200.70	200.70	25.00	150.52	Replace	0	0	Not Give	✓ X SUL
Non-Standard	Main	GLASS RH		CHANNEL SUB-ASSY, REAR DOOR GLASS , RH	1	27.20	27.20	25.00	20.40	Replace	0	0	Not Give	✓ X NN
Non-Standard	Main	BODY RH		DOOR OUTER HANDLE REAR , RH	1	93.90	93.90	25.00	70.43	Replace	0	0	Not Give	✓ X SUL
Non-Standard	Main	BODY RH		DOOR LOCK REAR , RH	1	544.70	544.70	10.00	490.23	Replace	0	0	Not Give	✓ X SUL
Non-Standard	Main	BODY RH		REINFORCE SUB-ASSY , ROCKER , OUTER RH	1	564.80	564.80	25.00	423.60	Replace	0	0	Not Give	✓ X NN
Non-Standard	Main	BODY RH		MOULDING ASSY, BODY ROCKER PANEL , RH	1	576.00	576.00	25.00	432.00	Replace	1	432.00	Replace	✓ DEF
Non-Standard	Main	UNDERCARRIAGE		WHEEL, DISC	1	1,555.10	1,555.10	25.00	1,166.32	Replace	1	0	Repair	✓ X R
									Total Spare Part Cost	6,877.17	Surveyor Total	2,294.41		
									Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0		
									Final Spare Part Cost	6,877.17	Final Sur Total	2,294.41		

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR RH PORTION	845.00	600	
Total:		845.00	600.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO RESPRAY FRONT DOOR RH	378.00	200	
2	TO RESPRAY REAR DOOR RH	378.00	200	
3	TO RESPRAY ROCKER PANEL MOULDING	180.00	100	
4	TO RESPRAY SILL MEMBER PANEL RH	180.00	0	CHECK
Total:		1,854.00	780.00	

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
5	TO RESPRAY REAR FENDER RH	378.00	200	
6	TO RESPRAY DOOR HANDLE	180.00	0	NN
7	TO RESPRAY RIM	180.00	80	
Total:		1,854.00	780.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO TRANSFER DOOR MECHANISM	120.00	50	
2	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	NN
3	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40	
4	TO WASH AND VACUUM	60.00	0	NN
5	TO REPLACE SUNDRY PARTS	100.00	0	NN
Total:		500.00	90.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	6,877.17	2,294.41
Total Labour Cost	845.00	600.00
Total Spray Painting	1,854.00	780.00
Other	500.00	90.00
Overall Total	10,076.17	3,764.41
Lump Sum Repair Option		
Lump Sum Total	0.00	3,764.41
Surveyor Approved Amount		3,764.41
No of Repair Days*	6	4
Remarks	-	PART BY PART REPAIR. 4 DAYS. CHECK ITEMS PHOTOS. BEFORE PAINT PHOTOS.
Surveyor Name		Naz
Signature		
		<input type="button" value="Save"/> <input type="button" value="Clear"/>

Estimator Assessment(\$)

Surveyor Assessment(\$)

Survey Date

07/11/2018

INAZ LKK
7/11/18
P/P

[Signature]
15/11/18

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

- CHECK ITEM PHOTOS -
- BEFORE PAINT PHOTOS -

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/11/2018 09:36
Date Of Accident	04/11/2018 14:00
Exact Location Of Accident	EAST COAST PK SERVICE RD CAR PARK B2 BUS PK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4470P
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	ONG ENG JOO
NRIC No	S1782119I
Date Of Birth	31/12/1966
Occupation	OUTDOOR
Date Of Driving Pass	02/05/1991
Driving Experience	27 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG EAST COAST PARK SERVICE ROAD AND SUDDENLY I FELT AN IMPACT AT THE RIGHT PORTION OF MY TAXI. A VEHICLE SLU7732Y WHICH WAS PARKED AT THE PARKING LOT (AGAINST THE FLOW OF TRAFFIC) HAD COLLIDED ONTO THE RIGHT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	MR TAN
Phone Number	
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLU7732Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	LIM KAH HOE
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[Handwritten Signature]
5/11/2018

Sketch Plan Pg. 2

A = 5444708
 B = 54477327
 11/11/18
 11/11/18

[illegible]

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature _____
Date & Time: _____



Driver's Signature _____
(If driver is not the policyholder)

Date & Time: 5/11/18

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Section A - Accident Details


Registration Number	SHC4470P
Case Reference Number	TAX/11/18/2012
Registration Date	12/10/17
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	ONG ENG JOO
Type of Accident	Head To Side
Accident Date and Time	04/11/18 2:02 PM
Accident Reported Date and Time	05/11/18 9:15 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24098612
Special Instruction to ARC, if any	TP
Prepared Date and Time	05/11/18 6:35 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Signature

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$600.00
Total Spray Cost	\$1,854.00	\$780.00
Total Spare Part Cost	\$6,877.17	\$2,294.41
Total Other Cost	\$500.00	\$90.00
TOTAL COST	\$10,076.17	\$3,764.41 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Kim Ming Chin	Naz (LKK) / NTUC
ARC / Surveyor Sign Off Date	05/11/2018 7:06 PM	07/11/2018 5:17 PM
Signature		
Remarks		PART BY PART REPAIR. 4 DAYS. CHECK ITEMS PHOTOS. BEFORE PAINT PHOTOS.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1811-0218	Invoice Number	
Quotation Date	15.11.2018	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$845.00	\$600.00
Total Labour	\$845.00	\$600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY REAR DOOR RH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO RESPRAY SILL MEMBER PANEL RH	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY DOOR HANDLE	\$180.00	\$0.00
TO RESPRAY RIM	\$180.00	\$80.00
Total Spray Painting & Panel Beating	\$1,854.00	\$780.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TRANSFER DOOR MECHANISM	\$120.00	\$50.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$40.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$500.00	\$90.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		6700147152	PANEL SUB-ASSY, FRONT DOOR RH	1.00	\$1,249.60	100.00	\$0.00	Replace	Repair X
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		6700347210	PANEL SUB-ASSY, REAR DOOR, RH	1.00	\$1,243.90	25.00	\$932.93	Replace	Replace
			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		6863047050	CHECK ASSY, REAR DOOR	0.00	\$153.50	0.00	\$0.00	Replace	Check X
		6787147051	WEATHERSTRIP, REAR DOOR RH	0.00	\$174.40	0.00	\$0.00	Replace	Not Given X
		6789547010	WEATHERSTRIP, REAR DOOR, NO.2, RH	0.00	\$33.20	0.00	\$0.00	Replace	Not Given X
		6814247051	RUN, REAR DOOR GLASS, RH	1.00	\$118.70	25.00	\$89.03	Replace	Replace
		6740747050	BAR SUB-ASSY, REAR DOOR WINDOW DIVISION, RH	0.00	\$108.70	0.00	\$0.00	Replace	Check X
		6818847030	WEATHERSTRIP, REAR DOOR QUARTER WINDOW, RH	0.00	\$47.70	0.00	\$0.00	Replace	Not Given X

		68750201 22	HINGE ASSY, REAR DOOR UPPER RH	0.00	\$83.30	0.00	\$0.00	Replace	Check	X	SVC
		68770520 31	HINGE ASSY, REAR DOOR LOWER RH	0.00	\$73.30	0.00	\$0.00	Replace	Check	X	SVC
		61601471 50	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$824.80	25.00	\$618.60	Replace	Replace	/	DR21C
		65637470 60	LINER, REAR FENDER, RH	1.00	\$135.80	25.00	\$101.85	Replace	Replace	/	TN
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X	SVC
VE		85720471 50	DOOR REAR MOTOR ASSY, POWER WINDOW REGULATOR, RH	0.00	\$768.60	0.00	\$0.00	Replace	Not Given	X	SVC
VE		69803470 20	DOOR REAR WINDOW REGULATOR SUB-ASSY, RH	0.00	\$200.70	0.00	\$0.00	Replace	Not Given	X	SVC
GLASS RH		69905520 60	CHANNEL SUB-ASSY, REAR DOOR GLASS, RH	0.00	\$27.20	0.00	\$0.00	Replace	Not Given	X	SVC
BODY RH		69211470 21A1	DOOR OUTER HANDLE REAR, RH	0.00	\$93.90	0.00	\$0.00	Replace	Not Given	X	SVC
BODY RH		69050522 50	DOOR LOCK REAR, RH	0.00	\$544.70	0.00	\$0.00	Replace	Not Given	X	SVC
BODY RH		61403479 00	REINFORCE SUB-ASSY, ROCKER, OUTER RH	0.00	\$564.80	0.00	\$0.00	Replace	Not Given	X	SVC
BODY RH		75850479 10	MOULDING ASSY, BODY ROCKER PANEL, RH	1.00	\$576.00	25.00	\$432.00	Replace	Replace	/	ARK
UNDERCA RRAGE		42611- 47140	WHEEL, DISC	1.00	\$1,555.10	100.00	\$0.00	Replace	Repair	X	R
Total					\$8,824.64		\$2,294.41				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

12023-64

2294.41
+ 600.00
+ 870.00

3764.41

CONFIRMED PART BY PART REPAIR \$3,764.41 / 4 days. NAR UKK
Hil



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18020586/Ntbe2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 20-12-2018

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLU 7732Y	Veh. Inspected	SHC 4470P
Policy No.	5096683201	Coverage (\$)	0.00
Claim No.	MT/1018520-002	Excess (\$)	0.00
Assign From		Assign Date	07/11/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU603573062	Colour	MAROON
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	04/11/2018	Inspection Date	07/11/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4470P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	PANEL SUB-ASSY, REAR DOOR, RH (DISC 25%)	DEFORMED	1,243.90	932.93
1	RUN, REAR DOOR GLASS, RH (DISC 25%)	NECESSARY	118.70	89.03
1	PANEL SUB-ASSY, FENDER REAR RH (DISC 25%)	DEFORMED	824.80	618.60
1	LINER, REAR FENDER, RH (DISC 25%)	TORN	135.80	101.85
1	MOULDING ASSY, BODY ROCKER PANEL, RH (DISC 25%)	CRACKED	576.00	432.00
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
1	PIXEL STICKER (SN)	NECESSARY	60.00	60.00
1	CHECK ASSY, REAR DOOR	SERVICEABLE	153.50	-
1	WEATHERSTRIP, REAR DOOR RH	SERVICEABLE	174.40	-
1	WEATHERSTRIP, REAR DOOR, NO. 2, RH	SERVICEABLE	33.20	-
1	BAR SUB-ASSY, REAR DOOR WINDOW DIVISION, RH	SERVICEABLE	108.70	-
1	WEATHERSTRIP, REAR DOOR QUARTER WINDOW, RH	SERVICEABLE	47.70	-
1	HINGE ASSY, REAR DOOR, UPPER RH	SERVICEABLE	83.30	-
1	HINGE ASSY, REAR DOOR, LOWER RH	SERVICEABLE	73.30	-
1	TYRE	SERVICEABLE	126.74	-
1	DOOR REAR MOTOR ASSY, POWER WINDOW REGULATOR, RH	SERVICEABLE	768.60	-
1	DOOR REAR WINDOW REGULATOR SUB-ASSY, RH	SERVICEABLE	200.70	-
1	CHANNEL SUB-ASSY, REAR DOOR GLASS, RH	SERVICEABLE	27.20	-
1	DOOR OUTER HANDLE REAR, RH	SERVICEABLE	93.90	-
1	DOOR LOCK REAR, RH	SERVICEABLE	544.70	-
1	REINFORCE SUB-ASSY, ROCKER, OUTER RH	SERVICEABLE	564.80	-
1	PANEL SUB-ASSY, FRONT DOOR RH	TO REPAIR SEE LABOUR	1,249.60	-
1	WHEEL, DISC	TO REPAIR SEE LABOUR	1,555.10	-
			8,824.64	2,294.41
<u>LABOUR</u>				
PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY, FRONT DOOR RH AND WHEEL, DISC.			845.00	600.00
SPRAY PAINT.			1,854.00	780.00

Report Ref No. NS/INC18020586/Ntbe2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER DOOR MECHANISM.		120.00	50.00
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	NOT NECESSARY	120.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	40.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
			3,199.00	1,470.00
GRAND TOTAL			12,023.64	3,764.41

RECOMMENDED COST OF REPAIRS (CONFIRMED)				3,764.41
---	--	--	--	----------

Report Ref No. NS/INC18020586/Ntbe2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.