

樹 發 汽 車 修 理 廠 SHU FATT AUTO WORKS



S\$.

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo 2nd November 2018 TP-AXA-50

SLK 3265 H MERCEDES BENZ E300

Spare Parts	1 Rear bumper. × No Pow 2 Rear bumper chrome mouldings. @\$175/- / A	× 1820.00 Nett
	2 Rear bumper chrome modulings. (4,3175/-	30 72.00 Nett
	1 Set rear bumper clips.	X 94:00 Nett
	2 Rear bumper side retainers. @\$47/- X WV	96.00 Nett
	1 Rt rear door chrome moulding. / NC	25- 145000 Spet
	1 Rt rear rim. / Cut.	250 1456.00? Snet
		3882.00 1726
	Less 10% on I	
	Less 1076 OII I	366.20 (55). 7
		3493.80
Labour	To knock, straighten rt rear fender, rt rear fender inner	400
	panel, rt rear door, rt rear door pillar, renew rear bump	
	rear door moulding and assembly.	
	To respray damaged parts	900.00 500 700
	To remove, replace rt rear tyre, rim, balance and	60.00 30
	assembly.	00.00 98
	To check and adjust wheel alignment.	150.00 60
	To check and reset ECU.	180.00 × A/A/
	To check and reset ECO.	180.00
		5463.80
	11	
	11am-12pm 29/1/19	2843.4
WDD21205	542A226804	20%: 2250
		20%: 2250

Spays.

Lumpsum Repair.

After nepair phass.

Gno Qiang - 82880282

29/1/19.

LICK Auto Consultants hence notify

- the Repairer of the following:
- To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary iten s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: