



Case Details

Case Reference Number : TAX/11/18/2036
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4313K

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-4458-ID
 Assigned By : Kok Wah Wong

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 08/11/2018 08:30 AM
 Vehicle Age(In Months) : 59

Documents / Photographs

View Documents / Photographs Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	0	Repair	X R
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	0	0	Check	?
One Time Key In	Main			LENS & BODY, FR TURN RH	1	511.80	511.80	10.00	460.62	Replace	0	0	Check	?
One Time Key In	Main			FENDER FRT/RH	1	723.40	723.40	25.00	542.55	Replace	1	542.55	Replace	DEF
One Time Key In	Main			FENDER LINER FRT/RH	1	171.70	171.70	25.00	128.77	Replace	0	0	Not Givr	X SUC
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	NEC
One Time Key In	Main		6503707	TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Givr	X SUC
One Time Key In	Main			WHEEL DISC. FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	1	0	Repair	X R
One Time Key In	Main			DOOR FRT/RH	1	894.40	894.40	25.00	670.80	Replace	0	0	Not Givr	X SUC
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	0	0	Not Givr	X NN
Total Spare Part Cost									3,560.35		Surveyor Total	581.47		
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)	20		
Final Spare Part Cost									2,848.28		Final Sur Total	485.18		

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR FRONT RH PORTION	845.00	400	
Total:		845.00	400.00	



Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY FRONT BUMPER	378.00	200	
2	TO RESPRAY FRONT FENDER RH	378.00	200	
3	TO RESPRAY RIM	180.00	50	
4	TO RESPRAY FRONT DOOR RH	378.00	0	NN
Total:		1,314.00	450.00	

Other Cost Detail

S.No.	Job Scope	SMART Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	
2	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40	
3	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	NN
4	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30	
5	TO WASH AND VACUUM	60.00	0	NN
6	TO REPLACE SUNDRY PARTS	100.00	0	NN
Total:		580.00	100.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	2,848.28	465.18
Total Labour Cost	845.00	400.00
Total Spray Painting	1,314.00	450.00
Other	580.00	100.00
Overall Total	5,587.28	1,415.18
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	5,600.00	1,400.00
Surveyor Approved Amount		1,400.00
No of Repair Days*	5	3
Remarks	-	LUMP SUM REPAIR. 3 DAYS. CHECK ITEMS PHOTOS. AFTER REPAIR PHOTOS.
Surveyor Name		Naz
Signature		
Survey Date	12/11/2018	

NAZ LKK
12/11/18
3 DAYS
CHECK ITEMS PHOTOS.
AFTER PAINT PHOTOS.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: