

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

#### **TAX INVOICE**

EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX SINGAPORE 069110 INV No. AC2003633

INV Date 04/05/2020

Reference CC4/EQI18020625/T1pa3q2

Code EQ

#### **PROFESSIONAL SERVICE FEE**

Vehicle No. GZ 396M

Insured Veh. GBC 1304C

Claim No. DM18HO03028-JG

Policy No. DMCPHQ18-004149

Accident Date 05/11/2018

Inspection Date 26/11/2018

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Affiliated to Federation Internationale Des Experts En Automobile					
EQ INSURANCE	COMPANY LTD	Ref : CC4/EQI1802062	Ref : CC4/EQI18020625/T1pa3q2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date: 04-05-2020 Code: EQI			
1.	Policy Particu	llars :- THIRD PARTY CLAIN			
Insured Ve		Veh. Inspected	GZ 396M		
Policy No.	DMCPHQ18-004149	Coverage (\$)	0.00		
Claim No.	DM18HO03028-JG	Excess (\$)	0.00		
Assign Fro		Assign Date	14/11/2018		
2.		Particulars & Condition	,, 25		
Make & Mo		C.C	2986		
Engine No.		Year of Reg.	2005		
Chassis No		Colour	SILVER		
Odometer	437019	Steering	IN ORDER		
Brakes	IN ORDER	Modification	NIL		
General	GOOD	in a mount on			
3.	Co	nditions of Tyres			
	Size	Make	Balance		
R/H Front 1	Tyre 185 R14	JOURNEY	6 mm		
L/H Front T	yre 185 R14	JOURNEY	6 mm		
R/H Rear T	yre 155 R12 (D)	JOURNEY	6/6 mm		
L/H Rear Ty	yre 155 R12 (D)	JOURNEY	6/6 mm		
4.	Desc	ription of Damages			
THE VEHICL	E SUSTAINED DAMAGES AT TH	E REAR PORTION.			
DAMAGES S	SEE DETAILS.				
5.	Ge	neral Information			
Accident D	ate 05/11/2018	Inspection Date	26/11/2018		
Survey held	d at MILLION AUTO SERVICE				
	4 PENJURU PLACE #01-12 2.8 PENJURU TECH HUP SINGAPORE 608782				
5a.		Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair					
ESTIMATED	NORMAL PERIOD FOR REPAIR:	5 Working Days			



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

#### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GZ 396M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE ASSY	BENT	1,218.60	1,218.60
1	TAILGATE 'TOYOTA' STICKER	NECESSARY	138.00	138.00
1	TAILGATE STOPPER BRACKET LH	BENT	100.30	100.30
1	TAILGATE LOWER LOCK ASSY	TO REPAIR SEE LABOUR	168.20	-
1	LH TAILLAMP ASSY	CRACKED	222.70	222.70
1	LH TAILLAMP BRACKET	TO REPAIR SEE LABOUR	51.60	-
1	REAR NUMBER PLATE HOLDING PLATE	BENT	157.60	157.60
	LESS 25% DISCOUNT		-514.25	-459.30
			1,542.75	1,377.90
	SPECIAL NETT ITEMS			
1	TAILGATE '70KM/H' STICKER (SN)	NECESSARY	15.00	15.00
1	TAILGATE ALUMINIUM BACKPLATE RIVET (SN)	NECESSARY	6.00	6.00
1	REAR NUMBER PLATE (SN)	BENT	35.00	35.00
			56.00	56.00
	LABOUR			
	TO CHECK WIRING AT THE AFFECTED AREAS FOR CONDITION ANAD REPAIR WHERE NEEDED.		40.00	30.00
	PANEL BEATING CHARES TO DISMANTLE AND REMOVE ALL DAMAGED PARTS,RENEW AND INSTALL THE SAME ,TO CUT OUT THE DAMAGED BODY,RENEW AND WELD THE SAME,TO KNOCK AND RESHAPE SURROUNDING PANELS BACK TO SHAPE AND ALIGNMENT.INCLUSIVE OF THE REPAIR OF TAILGATE LOWER LOCK ASSY AND LH TAILLAMP BRACKET.		900.00	700.00
	SPRAY PAINT ALL AFFECTED PARTS AND REPAIRED AREAS -TAILGATE ,REAR DECK END PANEL,REAR DECK LH SIDE PANEL ,TAILGATE STOPPER BRACKET,STEP BRACKET AND NECESSARY AREAS.		1,000.00	700.00
	TO REMOVE AND REPLACE REVERSE SENSORS AND CHECK SENSING DISTANCE.	NOT NECESSARY	80.00	-
			2,020.00	1,430.00
	GRAND TOTAL		3,618.75	2,863.90

Report Ref No. CC4/EQI18020625/T1pa3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,300.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/EQI18020625/T1pa3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

**Automotive Assessor** 

Amonto

**HO LEONG CHUAN** 

**Automotive Assessor** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION

# PHOTOGRAPHS FOR VEHICLE NO. GZ 396M















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Sngapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Sngapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Sngapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Sngapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

RE-INSPECTION

# PHOTOGRAPHS FOR VEHICLE NO. GZ 396M















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933









