

2/03/2002

ASS. REC. BY:

REF: CS/FCI18020627/Dvd3⁷²

Special Instruction:

Surveyor:

aws

ASSIGNMENT (Office)

From (Person):

Luvane Jew

of

FCI

Date/Time: 14/11/18 @ 3:51pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 3687Z

Insured:

SHA 8487B

at Workshop m/s

Chunni Motor

Tel:

6542 5119

of

AMK Autopoint #01-05/06

Policy No:

Claim No:

D18008076MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 11/11/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

4:01pm @ 14/11/18

Person Contacted:

Lynn

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SHA 3687Z - CS/FCI18002694/71td3n2

D.O.A. 24/01/2018

SHA 8487B - CS/FCI16004161/71qbc2

D.O.A. 12/02/2016

23/11/18

Email preli revised to FCI

REF:

ASSIGNMENT

COR J-2024

From

Date

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

to Inspect Vehicle No

at Workshop n/s

of

Insured

Policy No

Claims No

Sum Insured

Excess

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PB Seen: Consistent? : Yes or No

Est. Repairs: 14 ~~12~~ days Res.: Yes or No

Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No. SHA 3687 2

V. Regn 2016 Jan

Type: M. Car / M. Cycle / Bus / Van / Lorry / ☒ Prime Mover /

Truck / Trailer or

Make: Hyundai I40

C.V. 1685

Colour: Blue

A/C Insured / Std / Nil / NA

Sp. Reading 444945

T/Radio: Insured / Std / Nil / NA

Eng/No: D4FDFU579757

Ch/No: KMHLB41UMGU083033

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Interfer / Jammed / Leaked / Burnt orBrake: ☒ Interfer / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F:

205/60 R16

R:

— 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 11/11/2018

D.O.I. 14/11/2018

Survey held at Chummi AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Front y N/S Body y N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

First report SHA8487B

12/12/18 Insured L/S 25000/- with 14 days of rev (Red 19,8367, 4470)

RECEIVED 11 DEC 2018

Date/Time, File Pass to?

☐

: Prel. Report

R

☐

: Final Report

Date/Time, File Return to?

2)

11/12 - typist

Report Format:

CWS

Lump Sum / I.B.E. (\$) 25,000/2

Days Of Repair: 14

Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

Survey Fee:

Transportation

S + PS + GI

Photos

Others

580

650

12/12/18

34x15= 510

170+ 510

50

50+50

242

1072



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18008076MFSH

Our ref: CS/FCI18020627/Dvd3

Date: 23/11/2018

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHA 3687Z

We thank you for your instruction on 14/11/2018


Please be informed that we had conducted the inspection of the above mentioned vehicle on 14/11/2018 at the premises of M/s CHUNNI MOTOR WORK PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$44,836.72
Revised Estimate Amount	: S\$31,557.84
"Check" Items Amount	: S\$
Book Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s front portion, n/s rear portion and n/s body.

Comments/Present Status:
Damages Consistent



Yours faithfully,

Bryan Ang
Motor Surveyor / Investigator

MOTOR SURVEY ASSIGNMENT**Date** 12-11-2018 **Our Ref No.** D18008076MFSH**Accident Date** 11-11-2018 **Claim Type.** Third Party**Insured Vehicle** SHA8487B **Third Party Vehicle.** SHA3687Z**Survey Location** AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06.**Contact Person.** LYNN OR IRENE - 65421726**Contact No.** 654275119/ 65427162 **Fax No.** 65426039**Survey Type** WITHOUT PREJUDICE:**Appointed Surveyor** LKK AUTO CONSULTANTS PTE LTD**Contact Person** NA **Fax No.** 68416315**Contact Number.** NA**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST**Cc : Workshop** CHUNNI MOTOR WORK **Attention.** NIL
PTE LTD**Cc : TP Solicitor** NA **TP Solicitor Fax No.** NA**Officer Incharge** LURENE**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.



PRI Header Details

Claim No	D18008076MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & CHUNNI M
Workshop Name	CHUNNI MOTOR WORK PTE LTD (Contact Person : LYNN OR IRENE - 65421726)	Survey Location & Contact Details	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06. Mobile: 65427162 , Phone: 654275119 , Fax: 654260: EmailId: CHUNNIMOTOR@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA8487B	TP Vehicle No	SHA3687Z
PRI Recieved Date	12-11-2018 11:29:17 PM	Surveyor Appointed Date	14-11-2018 03:50:43 PM	Surveyor Accept Date	14-11-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	14-11-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Date	Job Remarks	Action
------	-------------	--------

FINAL SUMMARY

Surveyor Final Adjusted Amount	Surveyor Fees	Remarks	

Submit Assessment

Copyright © 2015 MS First Capital Insurance Limited (<http://www.msfirstcapital.com.sg/>). All rights reserved.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 23 November 2018 8:55 AM
To: 'CWS Motor Claims'
Cc: 'Lurene Jaw'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008076MFSH/1, SHA 3687Z
Attachments: SHA 3687Z PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHA 3687Z
Date of survey: 14/11/2018
Number of days : 12 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 14 November 2018 4:04 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Lurene Jaw' <LureneJaw@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008076MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 15/11/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 14 November 2018 3:51 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Lurene Jaw <LureneJaw@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008076MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHA 3687Z

DATE : 12.11.2018

MAKE :

TEL : 6542 5110

MODEL : HYUNDAI i40

FAX : 6542 6039

FCI

- Lrk

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Radiator Grille <i>crack</i>			\$ 1,110.10	✓
	Radiator Grille H Emblem <i>new</i>			\$ 39.50	✓
	Front Bumper Cover <i>broken</i>			\$ 1,052.20	✓
	Front Bumper Sponge <i>new</i>			\$ 99.20	X
	Front Bumper Reinforcement <i>new</i>			\$ 402.10	X
	Front Bumper Grille (LH) <i>mounty crack</i>			\$ 93.60	✓
	Front Bumper Grille Airduct (LH) <i>mounty crack</i>			\$ 26.20	✓
	Front Bumper Bracket Top (LH) <i>new</i>			\$ 22.40	X
	Front Bumper Bracket (LH) <i>broken</i>			\$ 24.60	✓
	Headlamp Support Top Cover <i>broken new</i>			\$ 222.60	X
	Headlamp Support Panel Assy <i>broken</i>			\$ 907.40	✓
	Headlamp (LH) <i>broken</i>			\$ 1,388.00	✓
	Headlamp Halogen Bulb (LH) <i>new</i>			\$ 14.40	X
	Radiator Guard, LH <i>new</i>			\$ 20.00	X
	Front Fender (LH) <i>dented</i>			\$ 566.30	✓
	Front Fender Apron Panel (LH) <i>dented</i>			\$ 637.00	✓
	Front Fender Shield (LH) <i>dented</i>			\$ 174.90	✓
	Air Cleaner Bottom Assy <i>mounty broken</i>			\$ 325.00	✓
	Front Door (LH) <i>new</i>			\$ 2,256.40	✓
	Front Door Rubber <i>dented</i>			\$ 290.50	✓
	Front Door Gear / Regulator (LH) <i>new</i>			\$ 250.60	✓
	Front Door Check (LH) <i>new</i>			\$ 39.20	X
	Front Door Power Motor, LH <i>new</i>			\$ 172.70	X
	Door Centre Pillar Outer (LH) <i>dented</i>			\$ 2,527.80	✓
	Front Windscreen Moulding <i>new</i>			\$ 113.30	✓
	Front Windscreen Pillar Outer (LH) <i>dented</i>			\$ 1,745.50	✓
	Front Wheel Rim (LH) <i>dented</i>			\$ 325.30	✓
	Front Wheel Hub Cap (LH) <i>new</i>			\$ 107.10	✓
	Front Wheel Bearing <i>new</i>			\$ 150.90	✓
	Front Shock Absorber (Assy) (LH) <i>dented</i>			\$ 342.20	✓
	Front Shock Absorber Mounting (LH) <i>new</i>			\$ 108.80	X
	Front Drive Shaft (LH) <i>dented</i>			\$ 1,030.80	✓
	Rack & Pinion Assy <i>new</i>			\$ 969.60	✓
	STG Tie End <i>dented</i>			\$ 62.60	✓
	Stabilizer Bar <i>dented</i>			\$ 252.30	✓
	Stabilizer Bar Bush (LH) <i>new</i>			\$ 16.40	X
	Stabilizer Bar Link <i>dented</i>			\$ 61.10	✓
	Stabilizer Bracket <i>new</i>			\$ 24.00	X
	Front Suspension Lower Arm (LH) <i>dented</i>			\$ 529.30	✓
	Knuckle Arm (LH) <i>dented</i>			\$ 552.00	✓
	Engine Under Cover <i>new</i>			\$ 334.60	X
	Engine Crossmember <i>dented</i>			\$ 2,094.40	✓
	Inter Cooler <i>new</i>			\$ 1,032.50	X
	Inter Cooler Mounting (2 PCS) <i>new</i>			\$ 25.90	X
	ABS Sensor, LH <i>new</i>			\$ 234.00	X

SHA 3687Z

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Wiring-Engine & track housing			\$ 3,326.00	✓
	Wiring-FEM NN			\$ 168.00	X
	Electric Power Steering NN			\$ 4,880.50	X
	SUB TOTAL		23332.80	\$ 31,149.80	
	LESS 20%		18666.24	\$ 6,229.96	
	DISCOUNTED TOTAL			\$ 24,919.84	
	Front Fender Advertisement Logo (LH) Huc			\$ 100.00	Nett ✓
	Front Door Comfort Logo (LH) Huc			\$ 75.00	Nett ✓
	Front Door Advertisement Logo (LH) Huc			\$ 100.00	Nett ✓
	Front Windscreen Sealant Huc			\$ 46.00	Nett ✓
	Front Tyre (LH) Svc		321.00	\$ 216.00	Nett X
				\$ 537.00	
	Rear Bumper deformed			\$ 553.00	✓
	Rear Bumper Clip 10 pcs Huc			\$ 22.00	✓
	Rear Bumper Bracket, LH Huc			\$ 35.60	X
	Rear Fender With Housing (LH) Svc			\$ 4,736.80	✓
	Rear Fender Inner Lining (LH) Svc			\$ 169.30	X
	Rear Windscreen Moulding Huc			\$ 28.30	✓
	Rear Door (LH) Deformed			\$ 2,201.10	✓
	Rear Door Rubber (LH) Huc			\$ 280.50	✓
	Rear Door Gear/Regulator (LH) & deformed			\$ 242.80	✓
	Rear Door Power Motor (LH) Huc			\$ 158.60	X
	Rear Tyre Rim (LH) & deformed			\$ 325.30	✓
	Rear Wheel Hup-Cap (LH) cut			\$ 107.10	✓
	Rear Wheelbearing ING & Hub & Dem			\$ 362.00	✓
	Rear Trailing Arm (LH) & deformed			\$ 192.00	✓
	Rear Assist (LH) & deformed			\$ 145.70	✓
	Rear Shock Absorber (LH) & deformed			\$ 276.30	✓
	Rear Shock Absorber Mounting (LH) Huc			\$ 81.30	X
	Rear Crossmember Huc			\$ 1,021.50	X
	Stabilizer Bar & deformed			\$ 199.60	✓
	Stabilizer Link & deformed			\$ 85.90	✓
	Rear Upper Arm (LH) & deformed			\$ 335.75	✓
	Rear Lower Arm (LH) & deformed			\$ 353.80	✓
	Rear Knuckle Arm (LH) & deformed			\$ 545.60	✓
	SUB TOTAL		10993.55	\$ 12,459.85	
	LESS 20%		8794.84	\$ 2,491.97	
	DISCOUNTED TOTAL			\$ 9,967.88	

SHA 3687Z

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper Advertisement Logo <i>Huc</i>			\$ 50.00	Nett ✓
	Rear Bumper Rubber Mat <i>Huc</i>			\$ 50.00	Nett ✓
	Rear Fender Advertisement Logo (LH/RH) <i>Huc</i>		\$ 100.00	\$ 200.00	Nett ✓
	Rear Windscreen Sealant <i>Huc</i>			\$ 46.00	Nett ✓
	Rear Door Advertisement Logo (LH) <i>Huc</i>			\$ 100.00	Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (LH) <i>Huc</i>			\$ 80.00	Nett ✓
	Rear Tyre (LH) <i>3/4</i>		526.00	\$ 216.00	Nett X
				\$ 742.00	
	Labour Charge				
	Panel Beating			\$ 2,400.00	1200/-
	Spray Painting Charge			\$ 2,000.00	1000/-
	Wiring Charge			\$ 100.00	30/-
	Tuff Kote			\$ 150.00	60/-
	Towing Charge			\$ 50.00	Hu
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00	80/-
	Remove/Refix Reverse Sensor			\$ 120.00	40/-
	Remove/Refix Fuel Tank			\$ 150.00	Hu
	Transfer of Door	\$ 120.00	\$ 240.00	120/-	
	Remove/Refix Undercarriage (FRT)		\$ 200.00	2 150/-	
	Remove/Refix Undercarriage (RR)		\$ 200.00	2 150/-	
	Four Wheel Alignment		\$ 120.00	60/-	
	Re-set Frt & Rear Power Window System	\$ 200.00	\$ 400.00	Hu	
	Re-set Frt & Rear ABS System	\$ 200.00	\$ 400.00	Hu	
	Remove/Refix Aircon & Refill Gas		\$ 150.00	Hu	
	Remove/Refix Engine		\$ 500.00	Hu	
	Remove/Refix Dashboard		\$ 350.00	2 150/-	
	Remove/Refix Fuse Box		\$ 180.00	2 50/-	
	Remove/Refix Front Windscreen Glass		\$ 120.00	80/-	
	Remove/Refix Cushion & Upholstery Front		\$ 90.00	Hu	
	Diagnostic & Resetting To Erase Fault Code		\$ 480.00	Hu	
	TOTAL LABOUR			\$ 8,670.00	
	ESTIMATE TOTAL			\$ 44,836.72	
	14/11/2018 @ 1045hrs		31557.84		
			4525000/-		
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting. - To display damaged part(s) during resurvey. - Parts prices are subject to confirmation. - Third party survey is on a "Without Prejudice" basis. - No illegal modification(s) is allowed. - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company. Acknowledged by Repairer: <i>Not Actual</i> Signature: <i>2/1/2018 14 days</i> Date: <i>14/11/2018</i> <i>LKK Auto</i>					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHA 3687 Z

Technician:

Mileage: 444945

Time Printed 14.11.18 1:30 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°23'		-3°00' 3°00'
4°11'		-0°19' 5°41'
-6°55'		-1°30' 1°30'
16°30'		
16°07'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°40'		-3°00' 3°00'
4°12'		-0°19' 5°41'
0°41'		-1°30' 1°30'
15°35'		
14°55'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
0°18'		-3°00' 3°00'
-0°02'		-3°00' 3°00'
0°55'		-3°00' 3°00'
-6°13'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
2°31'		-3°30' 2°30'
5°17'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
1°08'		-3°30' 2°30'
0°25'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
1°22'		-3°00' 3°00'
5°42'		-3°00' 3°00'
2°26'		-3°00' 3°00'



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18020627/Dvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 19-12-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8487B	Veh. Inspected	SHA 3687Z	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18008076MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	14/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHLB41UMGU083033	Colour	BLUE	
Odometer	444945	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	HANKOOK	5 mm	
L/H Front Tyre	205/60 R16	HANKOOK	5 mm	
R/H Rear Tyre	205/60 R16	HANKOOK	5 mm	
L/H Rear Tyre	205/60 R16	HANKOOK	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT, N/S REAR PORTION AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/11/2018	Inspection Date	14/11/2018	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 3687Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	RADIATOR GRILLE	CRACKED	1,110.10	1,110.10
1	RADIATOR GRILLE H EMBLEM	NECESSARY	39.50	39.50
1	FRONT BUMPER COVER	BROKEN	1,052.20	1,052.20
1	FRONT BUMPER SPONGE	NOT NECESSARY	99.20	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	402.10	-
1	FRONT BUMPER GRILLE (LH)	MOUNTING CRACKED	93.60	93.60
1	FRONT BUMPER GRILLE AIRDUCT (LH)	MOUNTING CRACKED	26.20	26.20
1	FRONT BUMPER BRACKET TOP (LH)	SERVICEABLE	22.40	-
1	FRONT BUMPER BRACKET (LH)	BROKEN	24.60	24.60
1	HEADLAMP SUPPORT TOP COVER	NOT NECESSARY	222.60	-
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	907.40	907.40
1	HEADLAMP (LH)	BROKEN	1,388.00	1,388.00
1	HEADLAMP HALOGEN BULB (LH)	NOT NECESSARY	14.40	-
1	RADIATOR GUARD LH	NOT NECESSARY	20.00	-
1	FRONT FENDER (LH)	DENTED	566.30	566.30
1	FRONT FENDER APRON PANEL (LH)	DENTED	637.00	637.00
1	FRONT FENDER SHIELD (LH)	DEFORMED	174.90	174.90
1	AIR CLEANER BOTTOM ASSY	MOUNTING BROKEN	325.00	325.00
1	FRONT DOOR (LH)	BUCKLED	2,256.40	2,256.40
1	FRONT DOOR RUBBER	DEFORMED	290.50	290.50
1	FRONT DOOR GEAR/REGULATOR (LH)	CRACKED	250.60	250.60
1	FRONT DOOR CHECK (LH)	NOT NECESSARY	39.20	-
1	FRONT DOOR POWER MOTOR,LH	NOT NECESSARY	172.70	-
1	DOOR CENTRE PILLAR OUTER (LH)	DENTED	2,527.80	2,527.80
1	FRONT WINDSCREEN MOULDING	NECESSARY	113.30	113.30
1	FRONT WINDSCREEN PILLAR OUTER (LH)	DENTED	1,745.50	1,745.50
1	FRONT WHEEL RIM (LH)	DISTORTED	325.30	325.30
1	FRONT WHEEL HUB CAP (LH)	BENT	107.10	107.10
1	FRONT WHEEL BEARING	DAMAGED	150.90	150.90

Report Ref No. CS/FCI18020627/Dvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT SHOCK ABSORBER (ASSY)(LH)	DISTORTED	342.20	342.20
1	FRONT SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	108.80	-
1	FRONT DRIVE SHAFT (LH)	DISTORTED	1,030.80	1,030.80
1	RACK & PINION ASST	DAMAGED	969.60	969.60
1	STG TIE END	DISTORTED	62.60	62.60
1	STABILIZER BAR	DISTORTED	252.30	252.30
1	STABILIZER BAR BUSH (LH)	NOT NECESSARY	16.40	-
1	STABILIZER BAR LINK	DISTORTED	61.10	61.10
1	STABILIZER BRACKET	NOT NECESSARY	24.00	-
1	FRONT SUSPENSION LOWER ARM (LH)	DISTORTED	529.30	529.30
1	KNUCKLE ARM (LH)	DISTORTED	552.00	552.00
1	ENGINE UNDER COVER	NOT NECESSARY	334.60	-
1	ENGINE CROSSMEMBER	DISTORTED	2,094.40	2,094.40
1	INTER COOLER	NOT NECESSARY	1,032.50	-
1	INTER COOLER MOUNTING (2 PCS)	NOT NECESSARY	25.90	-
1	ABS SENSOR,LH	NOT NECESSARY	234.00	-
1	WIRING-ENGINE	HOUSING CRACKED	3,326.00	3,326.00
1	WIRING-FEM	NOT NECESSARY	168.00	-
1	ELECTRIC POWER STEERING	NOT NECESSARY	4,880.50	-
1	REAR BUMPER	DEFORMED	553.00	553.00
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
1	REAR BUMPER BRACKET,LH	NOT NECESSARY	35.60	-
1	REAR FENDER WITH HOUSING (LH)	BUCKLED	4,736.80	4,736.80
1	REAR FENDER INNER LINING (LH)	SERVICEABLE	169.30	-
1	REAR WINDSCREEN MOULDING	NECESSARY	28.30	28.30
1	REAR DOOR (LH)	DENTED	2,201.10	2,201.10
1	REAR DOOR RUBBER (LH)	NECESSARY	280.50	280.50
1	REAR DOOR GEAR/REGULATOR (LH)	CRACKED	242.80	242.80
1	REAR DOOR POWER MOTOR (LH)	NOT NECESSARY	158.60	-
1	REAR TYRE RIM (LH)	DISTORTED	325.30	325.30
1	REAR WHEEL HUP-CAP (LH)	CUT	107.10	107.10
1	REAR WHEELBEARING ING & HUB	DAMAGED	362.00	362.00

Report Ref No. CS/FCI18020627/Dvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TRAILING ARM (LH)	DISTORTED	192.00	192.00
1	REAR ASSIST (LH)	DISTORTED	145.70	145.70
1	REAR SHOCK ABSORBER (LH)	DISTORTED	276.30	276.30
1	REAR SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	81.30	-
1	REAR CROSSMEMBER	NOT NECESSARY	1,021.50	-
1	STABILIZER BAR	DISTORTED	199.60	199.60
1	STABILIZER LINK	DISTORTED	85.90	85.90
1	REAR UPPER ARM (LH)	DISTORTED	335.75	335.75
1	REAR LOWER ARM (LH)	DISTORTED	353.80	353.80
1	REAR KNUCKLE ARM (LH)	DISTORTED	545.60	545.60
	LESS 20% DISCOUNT		-8,721.93	-6,865.21
			34,887.72	27,460.84
	SPECIAL NETT ITEMS			
1	FRONT FENDER ADVERTISEMENT LOGO (LH)(SN)	NECESSARY	100.00	100.00
1	FRONT DOOR COMFORT LOGO (LH)(SN)	NECESSARY	75.00	75.00
1	FRONT DOOR ADVERTISEMENT LOGO (LH)(SN)	NECESSARY	100.00	100.00
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	FRONT TYRE (LH)(SN)	SERVICEABLE	216.00	-
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR DOOR ADVERTISEMENT LOGO (LH)(SN)	NECESSARY	100.00	100.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (LH) (SN)	NECESSARY	80.00	80.00
1	REAR TYRE (LH)(SN)	SERVICEABLE	216.00	-
			1,279.00	847.00
	LABOUR			
	PANEL BEATING.		2,400.00	1,200.00
	SPRAY PAINTING CHARGE.		2,000.00	1,000.00
	WIRING CHARGE.		100.00	30.00
	TUFF KOTE.		150.00	60.00

Report Ref No. CS/FCI18020627/Dvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	40.00
	REMOVE/REFIX FUEL TANK.	NOT NECESSARY	150.00	-
	TRANSFER OF DOOR.		240.00	120.00
	REMOVE/REFIX UNDERCARRIAGE (FRT).		200.00	150.00
	REMOVE/REFIX UNDERCARRIAGE (RR).		200.00	150.00
	FOUR WHEEL ALIGNMENT.		120.00	60.00
	RE-SET FRT & REAR POWER WINDOW SYSTEM.	NOT NECESSARY	400.00	-
	RE-SET FRT & REAR ABS SYSTEM.	NOT NECESSARY	400.00	-
	REMOVE/REFIX AIRCON & REFILL GAS.	NOT NECESSARY	150.00	-
	REMOVE/REFIX ENGINE.	NOT NECESSARY	500.00	-
	REMOVE/REFIX DASHBOARD.		350.00	150.00
	REMOVE/REFIX FUSE BOX.		180.00	50.00
	REMOVE/REFIX FRONT WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX CUSHION & UPHOLSTERY FRONT.	NOT NECESSARY	90.00	-
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	480.00	-
			8,670.00	3,250.00
	GRAND TOTAL		44,836.72	31,557.84
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			25,000.00

Report Ref No. CS/FCI18020627/Dvd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.