Veh No: State St	nneth AS	SIGNMENT
Estimated Cost: OD_TF / WS / TP RES / OD RES / EVA / INV / MV To Inspect Vehicle No: at Workshop mils of Insured: Policy No. Claims No. Sum Insured: CRNo: CR	nnern	1
Truck / Trailer or Truck / Trailer or Make: Toy Cash		
To Inspect Vehicle No: at Workshop m/s of struction for set Workshop m/s (Claims No. Claims No. Claims No. Claims No. Claims Record) Make: Colour white Make: Sp. Reading Pd y 8 9 5 TrRadio: Insured I Std I NI I I Sp. Reading Pd y 8 9 5 TrRadio: Insured I Std I NI I I Sp. Reading Pd y 8 9 5 TrRadio: Insured I Std I NI I I Stering: Inorder Jammed / Leaked / Burnt or Modi: NIS OIS Brake: Inorder Jammed / Leaked / Burnt or Modi: NIS I Size in forder Jammed / Leaked / Burnt or Modi: NIS INIS I Size in F: To Alrian or Tyre Size: F: ### ### ### ### ### ### ### ### ### #		_
at Workshop m/s of Insured: Policy No. Claims No. Sum Insured: Excess: Client's Record) Make of Veh: CPolicy Condition) Remark: The veh had commenced its repair at the time of inspection. Bail or Market Value: DAC Accident Rport: Consistent?: Yes or No Lum Sum: 2	OD/TP/WS/TP RES/OD RES/EVA/INV/MV	
Sp. Reading Sp. Re		
Insured: Policy No. Claims No. Sum Insured: Eng/No: C/No: C/No: C	at Workshop m/s Trais Cab	
Policy No. Claims No. Sum Insured: (Clent's Record) Make of Veh: (Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: IDAC Accident Rport: Consistent?: Yes or No Est. Repairs: Cadys Res.: Yes or No Lum Sum: CA / REV / REP. / 24 HRS Date / Time Action / Inistruction Date / Time Action / Inistructi	of	Sp.Reading 924885 T/Radio: Insured / Std / NI / NA
Claims No. Sum Insured: Excess: (Client's Record) Make of Veh: (Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: IDAC Accident Rport: Consistent? : Yes or No Lum Sum: 2 % 3 Val.: Yes or No Lum Sum: 2 % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Ocha / Time Action / Instruction Date / Time Action / Instruction SHI FAST CG / INA 3015112 / Kapaa List Report Resurvey No. of Trip: Days Of Repair: Gen. Cond: Good / Fair / Poor / Burnt Steering: Inorder / Jammed / Leaked / Burnt or Modi: Nii / SITD A/Rim or Tyre Size: F: / # 3	Insured:	
Steering: Inorder? Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or Modi: Nii / Skim / Sto Aking of Veh: Policy Condition Remark: The veh had commenced its repair at the time of inspection. Nis O/S repair at the time of inspection. Nis O/S	Policy No.	C/No: 2X S12 0026484
Collent's Record) Make of Veh:	Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Make of Veh: Modi: Nii Sirkim STD A/Rim or Tyre Size: F: F3 B R R	Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: Cd days Res.: Yes or No Lum Sum: CA / REV / REP. / 24 HRS Vehicle: IN / OUT Date: Person Contacted: Vehicle: IN / OUT Date / Time Action / Instruction CA / Instruction CA / Rev / Rep. / 24 HRS Vehicle: IN / OUT Date / Time Action / Instruction CA / Rev / Rep. / Read / O/S / N/S / U/C / Rooftop or The U/C / Chassis frame / Body Structure affected due to collic Date / Time Action / Instruction CA / Rev / Rep. / Read / O/S / N/S / U/C / Rooftop or The U/C / Chassis frame / Body Structure affected due to collic Date / Time Action / Instruction CA / Rev / Rep. / Read / O/S / N/S / U/C / Rooftop or The U/C / Chassis frame / Body Structure affected due to collic Date / Time Action / Instruction CA / Rev / Rep. / Read / O/S / N/S / U/C / Rooftop or The U/C / Chassis frame / Body Structure affected due to collic Date / Time / Report / Transportation: CA / Rev / Rep. / Read / O/S / N/S / U/C / Rooftop or The U/C / Chassis frame / Body Structure affected due to collic Date / Time / Report / Transportation: CA / Rev / Rep. / Read / O/S / N/S / U/C / Rooftop or CA / Rev / Rep. / Read / O/S / N/S / U/C / Rooftop or The U/C / Chassis frame / Body Structure affected due to collic Date / Time / Read / O/S / N/S / U/C / Rooftop or The U/C / Chassis frame / Body Structure affected due to collic Date / Time / Read / O/S / N/S / U/C / Rooftop or The U/C / Chassis frame / Body Structure affected due to collic Date / Time / Read / O/S / N/S / U/C / Rooftop or The U/C / Chassis frame / Body Structure affected due to collic Date / Time / Read / O/S / N/S / U/C / Rooftop or The U/C / Chassis frame / Body Structure affected due to collic Date / Time / Read / O/S / N/S / U/C / Rooftop or The U/C / Chassis frame / Body Structure affected due to collic Date / Time / Read / O/S / N/S / U/	(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
(Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: Cod days Res.: Yes or No Lum Sum: CA / REV / REP. / 24 HRS Date: Person Contacted: Date / Time Action / Instruction Action / Instruction CRECEIVED 1 6 NOV 2019 Resurvey No. of Trip: Person Contact Toryo / Yoko or Front Resar R/Bal. Do.O.A. 6/5 IH DO.O.I. 7/5 / O Survey held at Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or The U/C / Chassis frame / Body Structure affected due to collis Date / Time Action / Instruction RECEIVED 1 6 NOV 2019 Cote/Time, File Pass to? Person Cote/Time, File Pass to? Person Cote/Time, File Pass to? Person Cote/Time, File Return to? Cote/Tim	Make of Veh:	
Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: IDAC Accident Rport: Consistent? : Yes or No GIA / PR Seen: Consistent? : Yes or No Est. Repairs: OC days Res.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Date / Time		Tyre Size: F: 175/80R19
repair at the time of inspection. Bal. or Market Value: IDAC Accident Rport: Consistent? : Yes or No GIA / PR Seen: Consistent? : Yes or No Est. Repairs: Cod days Res.: Yes or No Lum Sum: CA / REV / REP. / 24 HRS Date: Person Contacted: Person Contacted: Person Contacted: The U/C / Chassis frame / Body Structure affected due to collist Date / Time Action / Instruction CA / REV Rep. / CA / Rev. Read II. 0.77 - H5, 83 fb) LIS II. 8	(Policy Condition)	R:
Bal. or Market Value: IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: Codays Res.: Yes or No Lum Sum: Lum Sum: Lum Sum: Person Contacted: Date: Person Contacted: Date / Time Action / Instruction CA / REV / REP. / 24 HRS Vehicle: IN / OUT The U/C / Chassis frame / Body Structure affected due to collist Date / Time Action / Instruction CA / REV Repairs: Person Contacted: Date / Time Action / Instruction CA / REV Repairs: Person Contacted: Date / Time Action / Instruction CA / REV Repairs: Person Contacted: Date / Time Action / Instruction CA / REV Repairs: Person Contacted: Date / Time Action / Instruction CA / REV Repairs: Person Contacted: Date / Time Action / Instruction CA / REV Repairs: CA / REV / Repairs: CA /	Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
IDAC Accident Rport: Consistent? : Yes or No R/Bal. Amm R/Bal. Gla / PR Seen: Consistent? : Yes or No Est. Repairs: Obdays Res.: Yes or No D.O.A. Gls III D.O.I. T. Survey held at Des. of Damages : Frt Rear O/S N/S U/C Rooftop or The U/C Chassis frame Body Structure affected due to collist Date Time Action / Instruction Action / Instruction Action / Instruction The U/C Chassis frame Body Structure affected due to collist Des. of Damages : Frt Rear O/S N/S U/C Rooftop or The U/C Chassis frame Body Structure affected due to collist Des. of Damages : Frt Rear O/S N/S U/C Rooftop or The U/C Chassis frame Body Structure affected due to collist Date Time Action / Instruction Action / Instruction Date Time	repair at the time of inspection.	TOYO/YOKO or Westlelle
GIA / PR Seen: Consistent? : Yes or No Est. Repairs: O days Res.: Yes or No Lum Sum: 2 % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Vehicle: IN / OUT Date / Time Action / Instruction SH (5/37 7 () / MA 3 USI) / A S S S S S S S S S S S S S S S S S S	Bal. or Market Value:	<u>Front</u> <u>Rear</u>
Est. Repairs:	IDAC Accident Rport: Consistent? : Yes or No	R/Bal. A mm R/Bal. 6 mm
Lum Sum: 26 % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Vehicle: IN / OUT Date / Time Action / Instruction Action / Instruction Action / Instruction SHC 54367	GIA / PR Seen: Consistent? : Yes or No	L/Bal. 7 mm L/Bal. 6 mm
Date: Person Contacted: Vehicle: IN/OUT Date: Person Contacted: The U/C / Chassis frame / Body Structure affected due to collise Date / Time	Est. Repairs: O 6 days Res.: Yes or No	D.O.A. 6/5/14 D.O.I. 7/5/14
Date: Person Contacted: Vehicle: IN/OUT Date / Time Action / Instruction Action / Inst	Lum Sum: 2 6 % 3 Val.: Yes or No	Survey held at
Date / Time Person Contacted: The U/C / Chassis frame / Body Structure affected due to collise Date / Time Action / Instruction Action / Instruction SHI 5439Z - CCS / MAN 3019112 Kny363 OUA- 691030B IS III 8	CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date / Time Action / Instruction SHI 563872 - 763 / MA 3019112 Knp363 Out of 102013 IS 11 18 LS	Vehicle: IN / OU	л т
SHI 5439Z - 763 AXA 13 USIII Knys Dut 61 102013 IS III 8		The U/C / Chassis frame / Body Structure affected due to collision
S S S S S S S S S S		2.2
Date/Time, File Pass to? Preli. Report Days Of Repair: Resurvey No. of Trip: Survey Fee: Transportation: Add Fee: Site Insp (\$)s+Rs_si Photos Pho	3H(34312 - ((3/11X) 13017111/1	NBC2 041 01(0.2615
Date/Time, File Pass to? Preli. Report Days Of Repair: Resurvey No. of Trip: Survey Fee: Transportation: Add Fee: Site Insp (\$)s+Rs_si Photos Pho	15 1 12 15 to 2200 (Pal 1) 07	THE 83% (110 000)
Pate/Time, File Pass to? Preli. Report Days Of Repair: 6 3x19=10	15/11/16 12 \$ 2300 CKER 11, 07	ministration (NO NES)
Date/Time, File Pass to? Preli. Report Days Of Repair: 6 3x15=15	16/11/18 Soud Invoice Pirst before	Sand report to Trans-Cab
Date/Time, File Pass to? : Preli. Report : Final Report Days Of Repair: Resurvey No. of Trip: Date/Time, File Return to? Add Fee: : Site Insp (\$)S+RSSI : Interview (\$) Photos 73 Report Format: Tech. Invs (\$) Others	77.5	1 (6/11/59)
Date/Time, File Pass to? Preli. Report Survey Fee: Transportation: Add Fee: Site Insp (\$) _s+Rs_si Interview (\$) Photos Photos Tech. Invs (\$) Others	RECEIVED 1	6 NOV 2018
Survey Fee:		
Survey Fee:	Date/Time, File Pass to? : Preli. Report	Days Of Repair:
Date/Time, File Return to? Transportation: 50 2) 16 11 - typist Add Fee: : Site Insp (\$)s+Rssi : Interview (\$) Photos 73 : Tech. Invs (\$) Others 80		7/1/207
2) 16 11 - tupist Add Fee: : Site Insp (\$)s+Rssi : Interview (\$) Photos 73 Report Format : TP : Tech. Invs (\$) Others		
: Interview (\$) Photos 73/2	2) 16/11- tubist Add Fe	
Report Format: TP : Tech. Invs (\$) Others		
		: Interview (\$) Photos 77
COURT COLUMN 12 NOTE 1 1 I WEEKENN 12		

Veron Chen (LKKAuto)

From:

calvin.er <calvin.er@transcab.com.sg>

Sent:

Wednesday, 31 October 2018 1:52 PM

To:

Veron Chen (LKKAuto)

Cc:

'Jasmine Tan'; claims@transcab.com.sg

Subject:

FW: AAD1405-073-request for survey report

Attachments:

SHC5939Z 06.05.14 - GIA.pdf; AAD1405-073 - EATIMATE MARKING.pdf

Dear Veron

Please refer to preceding email.

Any update on the survey report for this mention case?

Attached GIA report and estimate marking for your reference.

Thank You Best Regards, Calvin Er Finance Department TEL: 6603 1265 Ext.307

*** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111 Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764

Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Ng Wai Yin [mailto:waiyin.ng@transcab.com.sg]

Sent: Friday, 2 February, 2018 11:40 AM

To: 'Veron Chen (LKKAuto)' <veronchen@lkkauto.com>

Cc: 'Jasmine Tan' <jasminetan@transcab.com.sg>; 'yuqing.teo@transcab.com.sg' <yuqing.teo@transcab.com.sg>;

'claims@transcab.com.sg' <claims@transcab.com.sg>; 'SUR' <sur@lkkauto.com>

Subject: RE: AAD1405-073-survey report

Dear Veron

Enclosed is the GIA report and estimate marking for your action.

Thank You Best Regards, Ng Wai Yin Finance Department

TEL: 6603 1265 Ext.308

*** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111 Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764 Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message

or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Friday, 5 January, 2018 8:39 AM

To: yuqing.teo <<u>yuqing.teo@transcab.com.sg</u>>; SUR <<u>sur@lkkauto.com</u>> **Cc:** 'Jasmine Tan' <<u>jasminetan@transcab.com.sg</u>>; <u>claims@transcab.com.sg</u>

Subject: RE: AAD1405-073-survey report,

Dear Yu Qing,

Kindly forward us GIA report and surveyor's mark estimate.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: yuqing.teo [mailto:yuqing.teo@transcab.com.sg]

Sent: Thursday, 4 January, 2018 5:51 PM

To: SUR <sur@lkkauto.com>

Cc: 'Jasmine Tan' < jasminetan@transcab.com.sg >; claims@transcab.com.sg

Subject: RE: AAD1405-073-survey report

Dear Sir,

Details of the accident are as follow:

1) DOA: 06.05.14

3rd party vehicle number: SHD 2068B

3) TCS Vehicle number: SHC 5939Z

4) Place of accident: PIE slip road towards CTE (City)

Thank you.

Best Regards, Teo Yu Qing Finance Department

*** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111 Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764 Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: yuqing.teo [mailto:yuqing.teo@transcab.com.sg]

Sent: Thursday, 4 January, 2018 5:26 PM

To: 'SUR' < sur@lkkauto.com >

Cc: 'Jasmine Tan' < jasminetan@transcab.com.sg'; 'claims@transcab.com.sg' < claims@transcab.com.sg'

Subject: AAD1405-073-survey report

Dear Sir,

Please send the survey report to FCIL.

Thank you.

Best Regards, Teo Yu Qing Finance Department TEL: 6603 1265 Ext.306

*** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111 Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764 Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

Veron Chen (LKKAuto)

From:

Ng Wai Yin <waiyin.ng@transcab.com.sg>

Sent:

Friday, 2 February 2018 11:40 AM

To:

Veron Chen (LKKAuto)

Cc:

'Jasmine Tan'; yuqing.teo@transcab.com.sg; claims@transcab.com.sg; SUR

Subject:

RE: AAD1405-073-survey report

Attachments:

SHC5939Z 06.05.14 - GIA.pdf; AAD1405-073 - EATIMATE MARKING.pdf

Dear Veron

Enclosed is the GIA report and estimate marking for your action.

Thank You Best Regards, Ng Wai Yin Finance Department TEL: 6603 1265 Ext.308

*** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111 Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764 Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Friday, 5 January, 2018 8:39 AM

To: yuqing.teo <yuqing.teo@transcab.com.sg>; SUR <sur@lkkauto.com>
Cc: 'Jasmine Tan' <jasminetan@transcab.com.sg>; claims@transcab.com.sg

Subject: RE: AAD1405-073-survey report,

Dear Yu Qing,

Kindly forward us GIA report and surveyor's mark estimate.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: yuqing.teo [mailto:yuqing.teo@transcab.com.sg]

Sent: Thursday, 4 January, 2018 5:51 PM

To: SUR < sur@lkkauto.com>

Cc: 'Jasmine Tan' < jasminetan@transcab.com.sg >; claims@transcab.com.sg

Subject: RE: AAD1405-073-survey report

Dear Sir,

Details of the accident are as follow:

1) DOA: 06.05.14

2) 3rd party vehicle number: SHD 2068B

3) TCS Vehicle number: SHC 5939Z

4) Place of accident: PIE slip road towards CTE (City)

Thank you.

Best Regards, Teo Yu Qing Finance Department TEL: 6603 1265 Ext.306

*** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111 Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764 Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: yuqing.teo [mailto:yuqing.teo@transcab.com.sg]

Sent: Thursday, 4 January, 2018 5:26 PM

To: 'SUR' <sur@lkkauto.com>

Cc: 'Jasmine Tan' < jasminetan@transcab.com.sg'; 'claims@transcab.com.sg' < claims@transcab.com.sg'

Subject: AAD1405-073-survey report

Dear Sir,

Please send the survey report to FCIL.

Thank you.

Best Regards, Teo Yu Qing Finance Department TEL: 6603 1265 Ext.306

*** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg

Text size +

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

200303878K

Vehicle Details

Vehicle No.:

SHC5939Z

Vehicle to be

Exported:

Yes

Intended De-

07 May 2014

registration Date: Vehicle Make:

TOYOTA

Vehicle Model:

CROWN TAXI

Primary Colour:

Red

Secondary Colour.

White

Manufacturing Year: 2006

Engine No.:

5L5657134

Chassis No.:

LXS120026494

Maximum Power

Output:

65.0 kW (87 bhp)

28 Sep 2006

Open Market Value: \$17,148.00 Original Registration

First Registration Date:

28 Sep 2006 0

Transfer Count:

Actual ARF Paid:

\$18.863.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

27 Sep 2014

PARF Rebate

Amount:

\$11,317.00

Intended COE Rebate Details

COE Expiry Date:

27 Sep 2014

COE Category:

A - Car (1600cc & below)

COE Period(Years): 8

QP Paid:

\$10,392.00

COE Rebate

Amount

\$505.00

Total Rebate

Amount:

\$11,822.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 07 May 2014



Please read through the Privacy Statement, Terms of Use and Disclaimer. Please do not use the Back or Forward buttons on your browser as this may after the results of the transactions.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

EMail Address

Was driver an employee of the Insured's Company No

Address

Postcode

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible, Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	07/05/2014 09:48
Date Of Accident	06/05/2014 16:45
Exact Location Of Accident	PIE slip road towards CTE (City)
Country/State of Loss	Singapore
TO DO THE STATE OF	DETAILS OF OWN VEHICLE
/ehicle Registration Number	SHC5939Z
nsured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Vehicle Particulars	
Manufacturer	ТОУОТА
Model	CROWN-3.0 (M)
Exact Purpose for which vehicle was being used at time of accident	Hire and Reward
Are you claiming under your own insurance policy or repair to your vehicle?	No
f No, Please state action to be taken	Third Party
/ehicle Category	Taxi
nsurance Company	
Name of Insurance Company	First Capital Insurance Ltd
Type Of Coverage	Third Party
Fleet Policy	Yes
Policy Number	D-12047359MFSH/1574
Cover Note Number	
Driver	
Name of Driver	CHONG BENG SIAH
NRIC No	S1553411G
Date Of Birth	30/03/1962
Occupation	Outdoor
Date Of Driving Pass	24/08/1982
Driving Experience	31 Years And 8 Months
Gender	Male
Mobile Number	(Local) +65-98242316
Fax Number	
Contact Number	

NOEMAIL

#03-62

526794

BLK 61 SIMEI RISE

If No. Relationship of the Driver with the Insured

isureu

Vehicle Registration Number of Driver's Own Vehicle

-

Other - Hirer

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

Collision- Head to Rear (TP Hit Insured)

Weather Conditions

Clear

Road Surface

Dry

Other Information

Was any foreign vehicle involved in this accident?

No

Was any body injured in the Accident?

No

Was any other material or property damaged?

Yes

Was there any video captured by Car Camera?

No

Details of Police Action

Was the accident reported to the police?

No

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

No

If Yes, against whom?

Circumstances of Accident

On 06.05.2014 at about 1645hrs, I was traveling straight from the slip road of PIE slip road towards CTE (City) when vehicle in front of me suddenly jammed his brake. I immediately applied brake to avoid the collision and manage to stop in time. Subsequently, I felt an impact from the rear. Vehicle B (SHD20686B) collided onto my taxi's rear portion. Vehicle A: 3 passengers Vehicle B: 2 passengers /rc

Are accident photos available for attachment?

Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHD2068B

Vehicle Make/Model/Colour

PRIME TAXI

Details Of Properties

Name of Driver

HAMZAH BIN DOLMAT

NRIC/Passport Number

S1475911E

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number


Email Address

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Sketch Plan



Describe Circumstances of the Accident

PLS -	REFUR	70	GLA	REPORT	

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date

Pour Witnessed by Reporting Centre







Accident Scene Photo















TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346 TEL NO.6287 6666 FAX NO.6366 8862 CO/GST REG NO.201019626G

Third Party Insurer:

1 Set Rear Bumper Side Clip

1 Set Rear Bumper Side Clip Holder

1 Set Rear End Panel Inner Trim Cover Clip

SHC 5939Z - FCIL

Popse USing 82300/

Vehicle No.: Chassis No.: Vehicle Make: Vehicle Model: Date of Accident:

SHC 5939Z - ROEL LXS12-0026785 **TOYOTA** CROWN TAXI 06.05.2014 FCIL

ROEL

re 10.00 -

Ma 18.58 -

Ma 21.00-

		PART			LIST
1	1	Rear Bumper Assembly		\$	Br 460.12
2	1	Rear Bumper Beam		\$	By 119.97 -
3	1	Rear Bumper Centre Absorber Foam		\$	€ 125.00 X
4	1	Rear End Panel		\$	By 427.75
5	1	Rear End Panel Inner Trim Cover		\$	CM 193.80
6	1	Rear Luggage Floor Panel		\$	n 917.80 X
7	1	Rear Luggage Floor Panel Trim Board		\$	S~ 245.95 X
8	1	Rear Luggage Floor Panel Insulator		\$	250.00 X
9	1	Rear Lamp (Tail Lamp) LH		\$	CP 298.49 -
10	1	Rear Lamp Panel LH		\$ \$ \$	By 90.64
11	1	Rear Lamp (Tail Lamp) RH		\$	CM 298.49
12	1	Bootlid		\$	By 791.04 —
13	1	Bootlid 'TOYOTA' Badge		\$ \$ \$ \$	35.53
14	1	Bootlid 'CROWN' Badge		\$	May 39.49 —
15	1	Bootlid Centre Logo Badge		\$	32.23
16	1	Bootlid Weatherstrip		\$	102.08 Dismis 204.1550ba
17	1	Bootlid Lock - Top		\$	ns 59.26
18	1	Bootlid Lock - Bottom		\$	№ 21.42 X
19	1	Bootlid Outer Chrome Garnish		\$	0 5 ~ 70.20 X
20	1	Rear Fender LH		\$	Br 854.13 -
21	1	Rear Exhaust Box		\$	₹ 832.37 X
				\$	6,367.83
			25%	\$	1,591.96
			TOTAL	\$	4,775.87
		Specical Nett			
	1 Set	Rear Bumper Parking Sensor		\$	PU 300.00
		Rear Bumper Fastener Clip		\$	May 12.00
	=5011F6=120				14

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346 TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHC 5939Z - FCIL

1 012		
Rear Fender Inner Trim Cover Clip KH	\$	Ner 10.00 -
Rear Bootlid Sticker 'Trans-Cab'		Na 30.00
		na 30.00 -
		Mer 30.00 -
Rear Windscreen Glass Sealant		Ma 80.00 405m
		Ma 40.00 30sn
		250.00 ₹
		250.00 1
		150.00 X
Rear Exhaust Mounting	\$	№ 80.00 X
TOTAL	\$	1,311.58
TOTAL PARTS	\$	6,087.45
Panel Beating, Knocking And Straightening		
The Necessary Portion, Remove And renewal		
Of Parts, Adjust And Realign The Same	\$	2,800.00 /2001
To Rust-Proofing Of The Affected Areas.	\$	220.00 90
To Check Electrical Lighting Concerned.	\$	120.00 201
To Reinstall Rear Bumper Parking Sensor.	\$	170.00 50
Putty And Spray Painting Of The Affected		
Portion.	\$	2,700.00 F201
To Remove And Refit Interior Fittings,		
		250 00 10-1
Enable Repair.	\$	270.00 100
To Transfer Of Rootlid Fittings Attachments		
And Perform Water Seepage Test.	\$	170.00 501
To Transfer Of Fender Fittings, Attachments		0
And Perform Water Seepage Test.	\$	Report 170.00 X
To remove and replace corporate sticker	\$	~~ 330.00 X
	Rear Bootlid Sticker 'Trans-Link' Rear Bootlid Sticker '6555-3333' Rear Windscreen Glass Sealant Rear Windscreen Glass Inner Seal Rear Bootlid advetisement sticker Rear Fender advetisement sticker LH Rear Bumper advetisement sticker Rear Exhaust Mounting TOTAL TOTAL PARTS Panel Beating, Knocking And Straightening The Necessary Portion, Remove And renewal Of Parts, Adjust And Realign The Same To Rust-Proofing Of The Affected Areas. To Check Electrical Lighting Concerned. To Reinstall Rear Bumper Parking Sensor. Putty And Spray Painting Of The Affected Portion. To Remove And Refit Interior Fittings, Trimings, Garnish, Fittings And Other, To Enable Repair. To Transfer Of Bootlid Fittings, Attachments And Perform Water Seepage Test.	Rear Bootlid Sticker 'Trans-Cab' \$ Rear Bootlid Sticker 'Trans-Link' \$ Rear Bootlid Sticker '6555-3333' \$ Rear Windscreen Glass Sealant \$ Rear Windscreen Glass Inner Seal \$ Rear Bootlid advetisement sticker \$ Rear Fender advetisement sticker LH \$ Rear Bumper advetisement sticker LH \$ Rear Exhaust Mounting \$ TOTAL \$ TOTAL PARTS \$ Panel Beating, Knocking And Straightening The Necessary Portion, Remove And renewal Of Parts, Adjust And Realign The Same \$ To Rust-Proofing Of The Affected Areas. \$ To Check Electrical Lighting Concerned. \$ To Reinstall Rear Bumper Parking Sensor. \$ Putty And Spray Painting Of The Affected Portion. \$ To Remove And Refit Interior Fittings, Trimings, Garnish, Fittings And Other, To Enable Repair. \$ To Transfer Of Bootlid Fittings, Attachments And Perform Water Seepage Test. \$ To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test. \$

ROEL

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346 TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHC 5939Z - FCIL

To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.

\$

170.00 1201

ROEL

To Drop Rear Exhaust Box, Renew The Same, To Repair And Realign Centre Exhaust Pipe.

170.00 601

TOTAL \$ 7,290.00

Over All Total \$ 13,377.45

REPAIR DAYS

10 DAYS



5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

			nationale Des Experts En Autor	
TRA	NS-CAB AUTO SE	ERVICES PTE LTD	Ref : CS/TP1802067	72/Kvbe2
NO.	2 ANG MO KIO ST	REET 63SINGAPORE 569	9111 Date: 28-11-2018	
			Code: TP378	***************************************
1.		Policy Particul	ars :- THIRD PARTY CLA	IM
	Insured Veh.		Veh. Inspected	SHC 5939Z
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	07/05/2014
2.		Vehicle P	articulars & Condition	
	Make & Model	TOYOTA CROWN	c.c	2986
	Engine No.	HIDDEN	Year of Reg.	2006
	Chassis No.	LXS120026494	Colour	WHITE / RED
	Odometer	924895	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.		Cor	nditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	175/80 R14	WEST LAKE	7 mm
	L/H Front Tyre	175/80 R14	WEST LAKE	7 mm
	R/H Rear Tyre	175/80 R14	WEST LAKE	6 mm
	L/H Rear Tyre	175/80 R14	WEST LAKE	6 mm
4.	a Trial trial and the	Descr	ription of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	E REAR PORTION.	
	DAMAGES SEE D	ETAILS.		
5.		Ger	neral Information	
	Accident Date	06/05/2014	Inspection Date	07/05/2014
	Survey held at	TRANS-CAB AUTO SERVIO	CES PTE LTD	
		NO. 42 SUNGEI KADUT ST SINGAPORE 729346	1	
5a.			Remarks	

Estimate Days of Repair

6 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5939Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER ASSEMBLY	BUCKLED	460.12	460.12
1	REAR BUMPER BEAM	BENT	119.97	119.97
1	REAR BUMPER CENTRE ABSORBER FOAM	SERVICEABLE	125.00	-
1	REAR END PANEL	BENT	427.75	427.75
1	REAR END PANEL INNER TRIM COVER	CRACKED	193.80	193.80
1	REAR LUGGAGE FLOOR PANEL	TO REPAIR SEE LABOUR	917.80	-
1	REAR LUGGAGE FLOOR PANEL TRIM BOARD	SERVICEABLE	245.95	
1	REAR LUGGAGE FLOOR PANEL INSULATOR	NOT NECESSARY	250.00	
1	REAR LAMP (TAIL LAMP) LH	CRACKED	298.49	298.49
1	REAR LAMP PANEL LH	BENT	90.64	90.64
1	REAR LAMP (TAIL LAMP) RH	CRACKED	298.49	298.49
1	BOOTLID	BENT	791.04	791.04
1	BOOTLID 'TOYOTA' BADGE	NECESSARY	35.53	35.53
1	BOOTLID 'CROWN' BADGE	NECESSARY	39.49	39.49
1	BOOTLID CENTRE LOGO BADGE	NECESSARY	32.23	32.23
1	BOOTLID LOCK - TOP	DENTED	59.26	59.26
1	BOOTLID LOCK - BOTTOM	TO REPAIR SEE LABOUR	21.42	-
1	BOOTLID OUTER CHROME GARNISH	SERVICEABLE	70.20	-
1	REAR FENDER LH	BUCKLED	854.13	854.13
1	REAR EXHAUST BOX	TO REPAIR SEE LABOUR	832.37	-
	LESS 25% DISCOUNT		-1,540.92	-925.24
			4,622.76	2,775.70
1	BOOTLID WEATHERSTRIP (SN) (50%)	DISTORTED	204.15	102.08
	LESS 25% DISCOUNT		-51.04	-
			153.11	102.08
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER PARKING SENSOR (SN)	DENTED	300.00	220.00
	SET REAR BUMPER FASTENER CLIP (SN)	NECESSARY	12.00	12.00
1	SET REAR BUMPER SIDE CLIP (SN)	NECESSARY	10.00	10.00
1	SET REAR BUMPER SIDE CLIP HOLDER (SN)	NECESSARY	18.58	18.58

Report Ref No. CS/TP18020672/Kvbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR END PANEL INNER TRIM COVER CLIP (SN)	NECESSARY	21.00	21.00
1	SET REAR FENDER INNER TRIM COVER CLIP LH (SN)	NECESSARY	10.00	10.00
1	REAR BOOTLID STICKER 'TRANS-CAB' (SN)	NECESSARY	30.00	30.00
1	REAR BOOTLID STICKER 'TRANS-LINK' (SN)	NECESSARY	30.00	30.00
1	REAR BOOTLID STICKER '6555-3333' (SN)	NECESSARY	30.00	30.00
2	REAR WINDSCREEN GLASS SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR WINDSCREEN GLASS INNER SEAL (SN)	NECESSARY	40.00	30.00
1	REAR BOOTLID ADVERTISEMENT STICKER (SN)	NOT NECESSARY	250.00	-
1	REAR FENDER ADVERTISEMENT STICKER LH (SN)	NOT NECESSARY	250.00	-
1	REAR BUMPER ADVERTISEMENT STICKER (SN)	NOT NECESSARY	150.00	-
2	REAR EXHAUST MOUNTING (SN)	SERVICEABLE	80.00	2
			1,311.58	451.58
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR LUGGAGE FLOOR PANEL, BOOTLID LOCK - BOTTOM AND REAR EXHAUST BOX.		2,800.00	1,200.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		220.00	90.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		120.00	20.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	50.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		2,700.00	720.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.		270.00	100.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	50.00
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	REPEATED	170.00	-
	TO REMOVE AND REPLACE CORPORATE STICKER.	NOT NECESSARY	330.00	-
	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.		170.00	120.00
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.		170.00	60.00
			7,290.00	2,410.00
	GRAND TOTAL		13,377.45	5,739.36

RECOMMENDED COST OF LUMP SUM REPAIRS	2,300.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/TP18020672/Kvbe2





Report Ref No. CS/TP18020672/Kvbe2

KONG SENG CHEONG

Licensed Appraiser