

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: EQ Insurance Company Ltd  
5 Maxwell Road, #17-00 Tower Block  
MND Complex  
Singapore 069110

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: JANET TAN

Date: 16 Nov 2018

## **Preliminary Advice**

Vehicle No	: SGN2315Y	Accident Date	: 11/11/2018
Make	: HONDA AIRWAVE	Policy No.	: DMPPHQ18-007332
Assignment Date	: 15/11/2018	Excess	: S\$500.00
Date of Inspection	: 15/11/2018	Est. Duration of Repair	: 11 days
Inspection At	: S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity Singapore 575722		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s body, n/s front & o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,534.85
Revised Amount	:S\$	6,339.85
Check Items (Estimated)	:S\$	898.25
Total	:S\$	7,238.10

Lump Sum Repair	:S\$
-----------------	------

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	18,500.00
COE / PARF Rebate	:S\$	15,484.00
Salvage Value	:S\$	
Margin for Repair	:S\$	3,016.00

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : WE ARE STILL PENDING REPAIR COST FROM REPAIRER.