

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CC3/III18020698/K1ES3Q2  
**Date:** 16/07/2021

**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant Vehicle No :</b>	SHB8703Y	<b>Insured Vehicle No :</b>	SH8235U
Date of Loss:	02/11/2018	Nature of Claim:	TP
		Claim No:	MCT18110012

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHB8703Y</b>		
Make & Model:	KIA OPTIMA, 1.7 D (A)	Engine No:	D4FDDH308049
Reg. Date:	27/09/2013 (Man. Year: 2013)	Chassis No:	KNAGM414ME5446593
Colour:	Silver	Odometer:	604346 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	205/65R16	Rear Tyre Size:	205/65R16
Front Left Side:	Hankook 7 mm	Rear Left Side:	Hankook 7 mm
Front Right Side:	Hankook 7 mm	Rear Right Side:	Hankook 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	575.90	525.90	50.00	8.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,210.00	380.00	830.00	68.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>1,785.90</b>	<b>905.90</b>	<b>880.00</b>	<b>49.27</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>700.00</b>		

(S\$)	1,785.90	700.00	1,085.90	60.80
<b>+ GST 7.00/7.00% (S\$)</b>	125.01	49.00	76.01	60.80
<b>Nett Amount (S\$)</b>	<b>1,910.91</b>	<b>749.00</b>	<b>1,161.91</b>	<b>60.80</b>
<b>+ Loss of Use (1.5 x S\$40.00/day) (S\$)</b>		60.00		
<b>+ Car Rental (1.5 x S\$102.51/day) (S\$)</b>		153.77		
<b>(S\$)</b>		962.77		
<b>Liabe Amount (50.00%) (S\$)</b>		<b>481.39</b>		
<b>Global Sum Settlement (S\$)</b>		<b>480.00</b>		

INSPECTION

Date of Assignment: 14/11/2018

Date Inspected: 14/11/2018

Inspected At:

Premier Automotive Services Pte Ltd (HQ)  
 23 Changi South Ave 2, #01-02  
 Singapore 486443

Estimated Period of Repair: 2.0 days

**Adjuster:** KALVIN ANG WEI KUN**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jul 2021)
<b>Parts:</b>	143	KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHB8703Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	531.00 FL	*531.00 FL
2	1		*FRONT BUMPER CLIP (1SET)	Necessary	48.00 FS	*48.00 FS
3	1		*SUNDRY	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
<b>Sub Total (\$\$)</b>					<b>629.00</b>	<b>579.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>					53.10	53.10
<b>Total Parts (\$\$)</b>					<b>575.90</b>	<b>525.90</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO DISMANTLE / REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPRT, ETC TO FACILITATE REPAIRERS.	New	180.00	0.00
2	TO LABOUR CHARGE FOR DIAMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE FRONT O/S FENDER	New	550.00	200.00
3	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER, FRONT O/S FENDER	New	400.00	180.00
4	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	80.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>1,210.00</b>	<b>380.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >