



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 7438H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	1,052.20	1,052.20
1	FRONT BUMPER BRACKET TOP LH	NO DAMAGED	22.40	-
1	FRONT BUMPER BRACKET LH	NO DAMAGED	24.60	-
1	FRONT FENDER SHIELD LH	NO DAMAGED	174.90	-
1	FRONT WHEEL HUB CAP LH	NOT IN USE	107.10	-
	LESS 20% DISCOUNT		-276.24	-210.44
			1,104.96	841.76
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT FENDER ADVERTISEMENT LOGO (LH) (SN)	NECESSARY	100.00	100.00
			100.00	100.00
	<u>LABOUR</u>			
	LABOUR CHARGES.		440.00	200.00
	SPRAY PAINTING.		440.00	400.00
	WIRING CHARGES.	NOT NECESSARY	50.00	-
	FRONT WHEEL ALIGNMENT.		80.00	60.00
			1,010.00	660.00
	GRAND TOTAL		2,214.96	1,601.76
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,200.00

Report Ref No. CS1/SPF18020719/K1vbs2

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,200.00 - \$1,500.00

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.