

ASS. REC. BY:

REF: CS/FCL18020738/Klgbm2

Special Instruction:

Survivor:

ASSIGNMENT (Office)From (Person): CWS Lucre Juw of FCL Date/Time: 15/11/2018 602pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 6426E Insured: SHC 844Xat Workshop m/s Premier Tel: 6544 6689of 33 Changi South Ave 2 #01-02Policy No: _____ Claim No: D18008081MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 12/11/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement: _____

Date/Time: 15-11-2018 Person Contacted: Vincent Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 6426E - call 1811 13013711 / 18020738
	SHC 844X - CS/FCL17020328 / Klgbm2
16/11/18 @ 9.39am	revised to Lucre by email.

DIA: 29072013

DIA: 21103017

Surveyor: Kelvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 6426E Yr Regt: 19 Nov 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA Optima 7.6LColour: Silver A/C: Insured / Std / NI / NASp. Reading: 370872 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAH M44 MF5588361

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD/Rim or

Tyre Size: F: 205/65R16R: 7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or MaxxFront 7 mm Rear 7 mmR/Bal. 7 mm L/Bal. 7 mmL/Bal. 7 mm D.O.A. 12/1/18 D.O.I. 16-11-2018Survey held at Premise

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
21/11/18	Continued up \$500 / 2 hrs. Chd 67582.90, 84% / 6) FCI

RECEIVED 26 NOV 2018

Date/Time, File Pass to? ☐ : Prel. Report1) 26/11/18 Final ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 2Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Survey Fee: 130Transportation: 50S + RS: 50Photos: 28

Others: _____

TOTAL

258Report Format: TrLump Sum / I.B.I: (\$ 500)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008081MFSH

Date: 16 November 2018

Our Ref: CS/FCI18020738/K1qb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 6426E

Please be informed that we had conducted the inspection of the abovementioned vehicle on 16/11/2018 at the premises of M/s PREMIER AUTOMOTIVE, and have the following to report:-

Workshop Estimate Amount	: S\$ 3,082.90 .
Revised Estimate Amount	: S\$ 635.40 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

Kalvin Ang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	13-11-2018	Our Ref No. D18008081MFSH
Accident Date	12-11-2018	Claim Type. Third Party
Insured Vehicle	SHC0844X	Third Party Vehicle. SHC6426E
Survey Location	23 CHANGI SOUTH AVENUE 2 #01-02	
Contact Person.	VINCENT CHUA	
Contact No.	62148880/ 65446689	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 16 November 2018 9:39 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Lurene Jaw'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008081MFSH/1
Attachments: CSFCI18020738K1qb.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SHC 6426E.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 15 November 2018 6:07 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Lurene Jaw' <LureneJaw@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008081MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 15 November, 2018 6:02 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Lurene Jaw <LureneJaw@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008081MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	19 Mar 2015 / 09:14:41	Receipt No.:	AACCK001-AX239-150319-000005
Asset Type:	Vehicle	Transaction Amount:	\$65,391.00
Asset ID:	SHC6426E	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150319091441008297		
Vehicle No.:	SHC6426E		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	19 Mar 2015		
Original Registration Date:	19 Mar 2015		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414MF5588361		
Engine No.:	D4FDEH313625		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2014		
Open Market Value:	\$21,185.00		
Minimum PARF Benefit:	\$8,495.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	19 Mar 2015 09:14:41		
COE No.:	2015031901002265W		
COE Expiry Date:	18 Mar 2023		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$51,092.00		
Lifespan Expiry Date:	18 Mar 2023		

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

14-Nov-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6426 E

1 pc	Rear bumper <i>x mpr</i>	\$ 696.00
1 pc	Rear bumper lower cover <i>- 1st</i>	\$ 206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>x m</i>	\$ 58.00
1 pc	Rear bumper inner sponge <i>x m</i>	\$ 114.00
1 pc	Rear bumper reinforcement <i>x m</i>	\$ 607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>x m</i>	\$ 108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>x m</i>	\$ 36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>x m</i>	\$ 36.00
		\$ 1,861.00
Less 10%		\$ 186.10
		\$ 1,674.90

S/NETT

1 set	Rear bumper clips <i>x m</i>	\$ 48.00
1 set	Reverse sensor <i>x m</i>	\$ 280.00
1 pc	Rear bumper top protector <i>m</i>	\$ 80.00 50
	Sundry	\$ 50.00 20 net
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00 114
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 171
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc	\$ 450.00 200
	To putty and spray painting on rear bumper	\$ 200.00 180
		\$ 3,082.90

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed & is subject to final approval from LKK Auto Consultants

Not acknowledged by Repairer
Signature:
Date:

/Ca/104 Ckk

16.11.2018 @ 9am

2 days

*4/5
After Repair photo*



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18020738/K1qbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 27-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 844X	Veh. Inspected	SHC 6426E	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008081MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	15/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KNAGM414MF5588361	Colour	SILVER	
Odometer	370872	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	MAXXIS	7 mm	
L/H Front Tyre	205/65 R16	MAXXIS	7 mm	
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/11/2018	Inspection Date	16/11/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6426E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	TO REPAIR SEE LABOUR	696.00	-
1	REAR BUMPER LOWER COVER	CUT	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	SERVICEABLE	58.00	-
1	REAR BUMPER INNER SPONGE	SERVICEABLE	114.00	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	607.00	-
2	REAR BUMPER STAY O/S & N/S	SERVICEABLE	108.00	-
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	SERVICEABLE	36.00	-
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	SERVICEABLE	36.00	-
	LESS 10% DISCOUNT		-186.10	-20.60
			1,674.90	185.40
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
1	SET REVERSE SENSOR (SN)	SERVICEABLE	280.00	-
1	REAR BUMPER TOP PROTECTOR (SN)	NECESSARY	80.00	50.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			458.00	70.00
LABOUR				
	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.	NOT NECESSARY	120.00	-
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE SAME, ETC. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		450.00	200.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER.		200.00	180.00
			950.00	380.00
GRAND TOTAL			3,082.90	635.40

Report Ref No. CS/FCI18020738/K1qbn2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			500.00
---	--	--	--------

Report Ref No. CS/FCI18020738/K1qbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.