

ASS. REC. BY:

REF:

CS3/IPC18018364/Units-1

Special Instruction:

Surveyor:

Morales

ASSIGNMENT (Office)

From (Person):

Gerald Poh

of

HPC

Date/Time:

16-11-2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGG 4127Y

Insured:

8KB 9085E

at Workshop m/s

Paul Hwe Batteries

Tel:

9623 5068

of

1Keki Bkt Ave 6 # 01-109

Policy No:

Claim No:

18/18/18 / VP05/021001

Sum Insured:

Excess:

Make of Veh:

D.O.A.

7/10/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

12:12pm @ 10/10/18

Person Contacted:

paul

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SGG 4127Y - NA/DAT/18018280/24

DOA: 7/10/18

8KB 9085E - NA/DAT/18018280/24

DOA: 7/10/18

Submit PRS report

19/11/18 Sumat 4/5 4022 Tdy

Red: \$1500, 27%.

Repair days 67

RECEIVED 19 NOV 2018

TGRim lin

16/11/18

ASSIGNMENT

From

Estimated total

00 TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. _____

at $W_{\text{cutoff}} = 1.5$

of

Insurance

Polio Inc.

Claims

Sum insured

May 1971

Remarks: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report

GSA / PR Seen:

Est. Repairs

Left: Sam.

CA / REV / REP. / 24 HRS

Date _____

Person Contacted

Date	Time	Action / Instruction
------	------	----------------------

Date/Time: Fri Feb 10 17:07

typist

Due Date: File Return 10/

1

Report Format

Lump Sum / L.B.F.: IS

☐ : Prel. Report
☒ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

Site Insp. (\$

Interview 15


Tech. Inves. 46

Wagland, J.

Survey Fee

Transportation

450



LONPAC INSURANCE BHD

(S98FC5635C)

Our Ref : 18/18/18/VP05/021001

Your Ref :

13 November 2018

M/s LKK Auto Consultants Pte Ltd
51 Ubi Ave 1
#01-25 Paya Ubi Industrial Pk
Singapore 408933

Dear Sirs/Madam

PAPER SURVEY OF SGG4127Y

We refer to the above matter.

We enclose the following documents :-

- a) Survey report & photos of SGG4127Y
- b) GIA report of SGG4127Y
- c) GIA report & photos of SKB9085E

Kindly study the documents and let us have your report by 23 November 2018.

Yours faithfully

GERALD POH
SENIOR EXECUTIVE
(CLAIMS)
Email : mt_claim@lonpac.com

PAUL HOE BATTERIES & MOTOR SERVICES

1 KAKI BUKIT AVENUE 6
#01-109, AUTOBAY @KAKI BUKIT
SINGAPORE 417883
TEL: 9623 5068 FAX: 6747 6918

Date: 25th October 2018

MAIDEEN MOHAMMED
Block 437 Tampines Street 33
#04-402
Singapore 520347

FINAL REPAIR COSTS

SGG 4127 Y

HONDA CIVIC 1.8L A

Contract Lump Sum Cost of Repair

\$5,500.00 NETT

DOLLARS FIVE THOUSAND AND FIVE HUNDREDS ONLY

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Fax: 6315 3298, Mobile: 9061 0543

ACCIDENT VEHICLE INSPECTION REPORT

Report no : 416M1018.PH
Vehicle no : SGG4127Y

1 REFERENCE

Date of inspection : 9 October 2018
Requested by : Maideen Mohammed
Blk 437 Tampines Street 33
#04-402
Singapore 520347
Type of survey : Independent
Repairer : Paul Hoe Batteries & Motor Services
Blk 1 Kaki Bukit Ave 6, #01-109 AutoBay @ Kaki Bukit, Singapore 417883
Date of accident : 7 October 2018

2 VEHICLE DATA

Make/model : Honda Civic 1.8L A
Chassis no : JHMFD16306S207795
Engine no : Engine No.
Date of registration : 11 May 2006 COE Expiry Date: 30 Apr 2021
Engine capacity : 1799 cc
Odometer reading : 248899 km
Colour : Silver

3 STATIC CONDITION CHECK

Steering : Serviceable
Foot brakes : Serviceable
Hand brakes : Serviceable
Paintwork : Good
General Condition : Good

4 TIRE CONDITION CHECK

	<u>RH/MAKE</u>	<u>LH/MAKE</u>	<u>SIZE</u>
Front tread	: 5 mm/Michelin	5 mm/Michelin	205/55R16
Rear tread	: 5 mm/Michelin	5 mm/Michelin	205/55R16

5 BRIEF DESCRIPTION OF DAMAGE

Rear bumper dented/squashed/deformed, rear end panel dented/bent, spare tyre panel crumpled/distorted, taillamps broken, rear boot lid dented/buckled, etc. Please see para. 8 of this report for more details.

6 REMARKS

This inspection is carried out on a "WITHOUT PREJUDICE" basis and I have not authorized any repairs.

7 RECOMMENDATION

Cost of repairs : \$5,500.00 (lump sum)
No. of days taken : Ten (10)

8 ASSESSMENT OF DAMAGE AND COSTS

Report no: 416M1018.PH
Vehicle no: SGG4127Y

A SPARE PARTS

Description	Qty	Assessed Condition	Repairer's Amount	Revised Amount
Rear boot lid	1	dented/buckled	610.80	610.80 DD✓
Rear boot lid hinge LH/RH	2	buckled	83.60	83.60 BT✓
Rear boot lid inner lock assy	1	bent/distorted	90.50	90.50 BT
Rear boot lid inner lock lower catch	1	to repair	17.10	0.00 X
Rear boot lid 'CIVIC' emblem	1	necessary	28.90	28.90
Rear boot lid 'H' logo	1	necessary	23.10	23.10
Rear boot lid 'i-VTEC' emblem	1	necessary	34.10	34.10
Rear boot lid '1.8' emblem	1	necessary	22.90	22.90
Rear boot weatherstrip	1	torn	97.60	97.60 TN✓
Rear boot lid reflector LH/RH	2	casing split	145.90	145.90 CRU✓
Rear boot lid reflector gasket	2	necessary	145.90	145.90
LH tailamp assy	1	broken	226.20	226.20 BR✓
RH tail lamp assy	1	broken	226.20	226.20 BR✓
Tail lamp side clip	2	necessary	7.00	7.00
Tail lamp gasket	2	necessary	41.20	41.20
Tail lamp lower bracket	2	bent	22.40	22.40 BT✓
Taillamp base panel LH/RH	2	bent/distorted	142.40	142.40 X
Rear bumper	1	dented/squashed/deformed	638.20	638.20 DD✓
Rear bumper side retainer LH/RH	2	necessary	29.00	29.00 NEC✓
Rear bumper plastic clip	8	necessary	31.20	31.20 NEC✓
Rear end panel	1	dented/bent	320.50	320.50 DD✓
Rear end panel trim cover	1	bent/deformed	60.80	60.80 BT✓
Rear end panel trim cover clip	4	necessary	15.60	15.60 NEC
Exhaust silencer	1	bent	494.20	494.20 X
Spare tyre panel	1	crumpled/distorted	985.10	985.10 X
Spare tyre board	1	to reuse	301.50	0.00
Subtotal of the above			4,841.90	4,523.30
Discount			968.38	904.66
Subtotal 1:			3,873.52	3,618.64
Reverse sensor set	1	dislodged/dead	280.00	280.00
Spare tyre panel sound insulation pad	1	necessary	250.00	250.00
Subtotal 2:			530.00	530.00
Total cost of parts:			4,403.52	4,148.64

B LABOUR

To check wiring.	40.00	30.00
To re-apply rustproofing for the affected portion.	200.00	120.00
Labour charges to remove and replace, to cut and weld, to panel beat and reshape damaged body parts & panels.	1,200.00	900.00
Spray painting charges to putty and spray all affected parts and body panels – rear end panel, spare tyre panel, taillamp base panels, rear boot lid, rear boot lid hinges, rear bumper, etc.	1,500.00	1,250.00
To remove and refit rear fender inner covers and attachments, rear passenger seat and affected carpet and upholstery to facilitate the repairs.	350.00	240.00

Report no: 416M1018.PH
Vehicle no: SGG4127Y

To remove and replace exhaust silencer.

90.00 60.00

To install reverse sensors and check sensing distance.

80.00 60.00

Total cost of labour:

3,460.00 2,660.00

Total cost of repair:

7,863.52 6,808.64

9 CONCLUSION

The revised or adjusted cost of repairs to restore the vehicle is

\$6,808.64

(a) The final cost of repair based on lump sum repairs would be

\$5,500.00

(b) The number of days taken for the repairs would be

Ten (10)

(1st Reinspection conducted on 10th October 2018)

(Post Repair Inspection conducted on 19th October 2018)

The above recommendations in my view are fair and reasonable for the restoration of the vehicle to its pre-accident condition.

Yours faithfully

Repair days 7 + 1/2

Liaw Leong San
Licensed Automotive Appraiser

TG Lim
16/11/18

Dated: 25 October 2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC18018364/Urd3n2-1

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 20-11-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKB 9085E	Veh. Inspected	SGG 4127Y
Policy No.	Z18VP05016880	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/021001	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	16/11/2018

2. Vehicle Particulars & Condition

Make & Model	HONAD CIVIC (A)	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	JHMFD16306S207795	Colour	SILVER
Odometer	248899	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	MICHELIN	6 mm
L/H Front Tyre	205/55 R16	MICHELIN	6 mm
R/H Rear Tyre	205/55 R16	MICHELIN	6 mm
L/H Rear Tyre	205/55 R16	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	07/10/2018	Inspection Date	10/10/2018
Survey held at	PAUL HOE BATTERIES & MOTOR SERVICES BLK 1 KAKI BUKIT AVE 6 #01-109 AUTOBAY SINGAPORE 417833		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGG 4127Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID	DENTED	610.80	610.80
2	REAR BOOT LID HINGE LH/RH	BENT	83.60	83.60
1	REAR BOOT LID INNER LOCK ASSY	BENT	90.50	90.50
1	REAR BOOT LID INNER LOCK LOWER CATCH	NOT NECESSARY	17.10	-
1	REAR BOOT LID "CIVIC" EMBLEM	NECESSARY	28.90	28.90
1	REAR BOOT LID "H" LOGO	NECESSARY	23.10	23.10
1	REAR BOOT LID "I-VTEC" EMBLEM	NECESSARY	34.10	34.10
1	REAR BOOT LID "1.8" EMBLEM	NECESSARY	22.90	22.90
1	REAR BOOT WEATHERSTRIP	TORN	97.60	97.60
2	REAR BOOT LID REFLECTOR LH/RH	CRUMPLED	145.90	145.90
2	REAR BOOT LID REFLECTOR GASKET	NECESSARY	145.90	145.90
1	LH TAILLAMP ASSY	BROKEN	226.20	226.20
1	RH TAILLAMP ASSY	BROKEN	226.20	226.20
2	TAIL LAMP SIDE CLIP	NECESSARY	7.00	7.00
2	TAIL LAMP GASKET	NECESSARY	41.20	41.20
2	TAIL LAMP LOWER BRACKET	BENT	22.40	22.40
2	TAILLAMP BASE PANEL LH/RH	TO REPAIR SEE LABOUR	142.40	-
1	REAR BUMPER	DENTED	638.20	638.20
2	REAR BUMPER SIDE RETAINER LH/RH	NECESSARY	29.00	29.00
8	REAR BUMPER PLASTIC CLIP	NECESSARY	31.20	31.20
1	REAR END PANEL	DENTED	320.50	320.50
1	REAR END PANEL TRIM COVER	BENT	60.80	60.80
4	REAR END PANEL TRIM COVER CLIP	NECESSARY	15.60	15.60
1	EXHAUST SILENCER	NOT NECESSARY	494.20	-
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	985.10	-
1	SPARE TYRE BOARD	NOT NECESSARY	301.50	-
	LESS 20% DISCOUNT		-968.38	-580.32
			3,873.52	2,321.28



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SPARE TYRE PANEL SOUND INSULATION PAD (SN)	NOT NECESSARY	250.00	-
			530.00	200.00
	LABOUR			
	TO CHECK WIRING.		40.00	30.00
	TO RE-APPLY RUSTPROOFING FOR THE AFFECTED PORTION.		200.00	120.00
	LABOUR CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO PANEL BEAT AND RESHAPE DAMAGED BODY PARTS & PANELS, INCLUSIVE OF THE REPAIR OF TAILLAMP BASE PANEL LH/RH AND SPARE TYRE PANEL.		1,200.00	900.00
	SPRAY PAINTING CHARGES TO PUTTY AND SPRAY ALL AFFECTED PARTS AND BODY PANELS-REAR END PANEL, SPARE TYRE PANEL, TAILLAMP BASE PANELS, REAR BOOT LID, REAR BOOT LID HINGES, REAR BUMPER, ETC.		1,500.00	1,250.00
	TO REMOVE AND REFIT REAR FENDER INNER COVERS AND ATTACHMENTS, REAR PASSENGER SEAT AND AFFECTED CARPET AND UPHOLSTERY TO FACILITATE THE REPAIRS.		350.00	120.00
	TO REMOVE AND REPLACE EXHAUST SILENCER.	NOT NECESSARY	90.00	-
	TO INSTALL REVERSE SENSOR AND CHECK SENSING DISTANCE.		80.00	60.00
			3,460.00	2,480.00
	GRAND TOTAL		7,863.52	5,001.28
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,000.00

Report Ref No. CS3/LPC18018364/Urd3n2-1

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.