

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park , Singapore 408933

TEL : 6256 3561 FAX : 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

**Affiliated to Federation Internationale Des Experts En Automobile**

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18020770/K1ja3n2

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 18-01-2019



Code : CTI

**1. Policy Particulars :- THIRD PARTY CLAIM**

<b>Insured Veh.</b>	SJT 5748U	<b>Veh. Inspected</b>	SHB 8358K
<b>Policy No.</b>	DMPCSN3066471801	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	SNM18D05395C02	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	15/11/2018

**2. Vehicle Particulars & Condition**

<b>Make &amp; Model</b>	HYUNDAI I30	<b>c.c</b>	1582
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2016
<b>Chassis No.</b>	TMAD281UVHJ121480	<b>Colour</b>	SILVER
<b>Odometer</b>	278358	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	FAIR		

**3. Conditions of Tyres**

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	195/65 R15	MAXXIS	7 mm
<b>L/H Front Tyre</b>	195/65 R15	MAXXIS	7 mm
<b>R/H Rear Tyre</b>	195/65 R15	MAXXIS	7 mm
<b>L/H Rear Tyre</b>	195/65 R15	MAXXIS	7 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.  
DAMAGES SEE DETAILS.

**5. General Information**

<b>Accident Date</b>	14/11/2018	<b>Inspection Date</b>	15/11/2018
<b>Survey held at</b>	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park , Singapore 408933

TEL : 6256 3561 FAX : 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8358K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR N/S FENDER	BUCKLED	1,525.73	1,525.73
1	REAR N/S FENDER INNER SHIELD	TORN	205.29	205.29
1	REAR BUMPER N/S SIDE BRACKET	CRACKED	32.50	32.50
1	REAR BUMPER	CRACKED	811.11	811.11
1	REAR BUMPER N/S REFLECTOR	SERVICEABLE	107.50	-
1	FUEL CAP	TO REPAIR SEE LABOUR	34.10	-
1	RIM	TO REPAIR SEE LABOUR	246.00	-
	LESS 20% DISCOUNT		-592.45	-514.93
			2,369.78	2,059.70
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET BOOTLID STICKERS (SN)	NECESSARY	100.00	100.00
1	SET N/S DOOR STICKER (SN)	NECESSARY	100.00	100.00
1	REAR N/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			358.00	328.00
	<b><u>LABOUR</u></b>			
	TO DISMANTLE/REFIT REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	30.00
	TO DISMANTLE/REFIT THE INNER GARNISHES,INNER LININGS,INNER TRIMS,CUSHION SEAT,CARPET,ETC TO FACILITATE REPAIRS.		180.00	50.00
	TO DISMANTLE AND FIT THE REAR N/S FENDER QUARTER GLASS TO FACILITATE REPAIR ON THE REAR N/S FENDER.		80.00	50.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.TO HEAT/WELD,CUT-OFF THE THE REAR N/S FENDER INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF THE SAME ETC.INCLUSIVE OF THE REPAIR OF FUEL CAP AND RIM.		1,000.00	600.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER,REAR N/S FENDER,REAR N/S DOOR,TAILGATE LOWER GARNISH,N/S ROCKER PANEL.		1,000.00	720.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		150.00	50.00
			2,530.00	1,500.00
	<b>GRAND TOTAL</b>		<b>5,257.78</b>	<b>3,887.70</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>3,887.70</b>

Report Ref No. CC3/CTI18020770/K1ja3n2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park , Singapore 408933

TEL : 6256 3561 FAX : 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

**Automotive Assessor / Investigator**

**Automotive Assessor**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

**PHOTOGRAPHS FOR VEHICLE NO. SHB 8358K**

**INSPECTION**