

ASS. REC. BY:

REF:

CF/FCI/8020806/ D+ d3⁷²

Special Instruction:

Surveyor:

FCI

ASSIGNMENT (Office)

From (Person):

May chua

of

FCI

Date/Time:

16/11/18 @ 2:02pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 7107P

Insured:

SHD 34604

at Workshop m/s

Chunni Motor

Tel:

65425119

of

AMK Autopoint #01-05/06

Policy No:

Claim No:

D18008172MFSH

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A.

14/11/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time: 16/11/18 @ 3:50pm

Person Contacted:

Lynn

Vehicle:

IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SHD 7107P-X

SHD 34604-CS / QW18010082 / K14652

20A: 24/05/2018

27/11/2018 @ 9:18am Revised via email preli advise

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No. _____
 at Workshop no. _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No. 8HD 7107 P Yr Reqn. 2016 / Nov
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Car Prime Mover /
 Truck / Trailer or
 Make: Hyundai I40 C.V. 1685
 Colour: Blue A/C: _____ Insured / Std / NI / NA
 Sp. Reading: 288501 T/Radio: Insured / Std / NI / NA
 Eng/No: D4FDGU684291
 C/No: KMHLB41UMHU095373
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: NR / S/Rim / STD A/Rim or
 Tyre Size: F: 205/60 R16
 R: — " —
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Atenkok
 Front Rear
 R/Bal. S mm R/Bal. S mm
 L/Bal. S mm L/Bal. S mm
 D.O.A. 14/11/2018 D.O.I. 17/11/2018
 Survey held at Chunni AMK
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S Front
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

First Contact SHD 3460u

10/12/18 jnmw 2/5 81501 - with 6 dgs 2/12
 (Red: 6196.88, 43%)

RECEIVED 12 DEC 2018

Date/Time, File Pass to?

12/12/18

Date/Time, File Return to?

2)

Report Format:

Lump Sum / LB.1: (\$



TP
 8150

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS. SI

) Photos

) Others

) 12/12/18

107/1

4x15 = 60

170 + 60

50

50 + 50

126

506



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008172MFSH

Date: 27/11/2018

Our Ref: CS/FCI18020806/Dtd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 7107P

Please be informed that we had conducted the inspection of the abovementioned vehicle 17/11/2018 at the premises of M/s ChunNi Motor have the following to report: -

Workshop Estimate Amount	: S\$ <u>14,346.88</u>
Revised Estimate Amount	: S\$ <u>10,221.52</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the
O/S Front
portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Bryan

Automotive Assessor

MOTOR SURVEY ASSIGNMENT**Date** 15-11-2018 **Our Ref No.** D18008172MFSH**Accident Date** 14-11-2018 **Claim Type.** Third Party**Insured Vehicle** SHD3460U **Third Party Vehicle.** SHD7107P**Survey Location** AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06**Contact Person.** LYNN OR IRENE - 65421726**Contact No.** 65427162/ 65425119 **Fax No.** 65426039**Survey Type** WITHOUT PREJUDICE: LIABILITY UNCLEAR:**Appointed Surveyor** LKK AUTO CONSULTANTS PTE LTD**Contact Person** NA **Fax No.** 68416315**Contact Number.** NA**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST**Cc : Workshop** CHUNNI MOTOR WORK PTE LTD **Attention.** NIL**Cc : TP Solicitor** NA **TP Solicitor Fax No.** NA**Officer Incharge** MAY CHUA**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 27 November 2018 9:18 AM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008172MFSH/1
Attachments: PRELI ADVISED SHD 7107P.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHD 7107P**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 16 November 2018 3:52 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008172MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 19/11/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 16 November 2018 2:02 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008172MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHD 7107 P

Technician:

Mileage: 288501

Time Printed 17.11.18 11:46 AM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°31'		-3°00' 3°00'
4°10'		-0°19' 5°41'
0°21'		-1°30' 1°30'
21°55'		
21°24'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-4°55'		-3°00' 3°00'
4°30'		-0°19' 5°41'
8°08'		-1°30' 1°30'
18°32'		
13°38'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
4°24'		-3°00' 3°00'
-0°20'		-3°00' 3°00'
3°23'		-3°00' 3°00'
8°30'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-2°03'		-3°30' 2°30'
0°08'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°29'		-3°30' 2°30'
0°13'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-0°34'		-3°00' 3°00'
0°21'		-3°00' 3°00'
-0°03'		-3°00' 3°00'

(LKK)

FCI

X	
X	
✓	
X	
X	
✓	2 10
✓	
✓	
✓	2 10
✓	
✓	
X	
2	✓
✓	
2	✓
2	✓
X	
2	✓
2	✓
2	✓
2	✓
2	✓
X	
2	✓
X	
Nett	✓
Nett	X

SHD 7107P

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,500.00
	Spray Painting Charge			\$ 750.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Towing Charge			\$ 50.00
	Remove/Refix Undercarriage (FRT)			\$ 200.00
	FRT Wheel Alignment			\$ 120.00
	Re-set Frt ABS System			\$ 200.00
	Remove/Refix Aircon & Refill Gas			\$ 150.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
			1360.00	
	TOTAL LABOUR			\$ 3,550.00
	ESTIMATE TOTAL			\$ 14,346.88
	17/11/2018 @ 1000hrs		10221.52	
	Not Author		4/58150/-	
	1/5m			
	<u>Ryan</u> 6 days.			
	LKK Auto			
				
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

600/-
500/-
400/- 500/-
30/-
20/-
HN
150/-
60/-
HN
HN
HN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18020806/Dtd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 17-12-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3460U	Veh. Inspected	SHD 7107P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008172MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	16/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHLB41UMHU095373	Colour	BLUE	
Odometer	288501	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	HANKOOK	5 mm	
L/H Front Tyre	205/60 R16	HANKOOK	5 mm	
R/H Rear Tyre	205/60 R16	HANKOOK	5 mm	
L/H Rear Tyre	205/60 R16	HANKOOK	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/11/2018	Inspection Date	17/11/2018	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 7107P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RADIATOR GRILLE	NOT NECESSARY	1,110.10	-
1	RADIATOR GRILLE H EMBLEM	NOT NECESSARY	39.50	-
1	FRONT BUMPER COVER	DISTORTED	1,052.20	1,052.20
1	FRONT BUMPER BRACKET (RH)	NOT NECESSARY	24.60	-
1	HEADLAMP SUPPORT TOP COVER	NOT NECESSARY	222.60	-
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	907.40	907.40
1	HEADLAMP (RH)	MOUNTING CRACKED	1,388.00	1,388.00
1	FRONT FENDER (RH)	DENTED	566.30	566.30
1	FRONT FENDER APRON PANEL (RH)	DENTED	637.00	637.00
1	FRONT FENDER SHIELD (RH)	DEFORMED	174.90	174.90
1	WIPER CONTAINER	DEFORMED	61.90	61.90
1	WIPER CONTAINER MOTOR	SERVICEABLE	75.00	-
1	FRONT WHEEL RIM (RH)	BENT	325.30	325.30
1	FRONT WHEEL HUB CAP (/RH)	CUT	107.10	107.10
1	FRONT WHEEL BEARING	DAMAGED	150.90	150.90
1	FRONT SHOCK ABSORBER (ASSY)(RH)	BENT	342.20	342.20
1	FRONT SHOCK ABSORBER MOUNTING (RH)	NOT NECESSARY	108.80	-
1	FRONT DRIVE SHAFT (RH)	DISTORTED	1,030.80	1,030.80
1	RACK & PINION ASSY	DAMAGED	969.60	969.60
1	STG TIE END	DISTORTED	62.60	62.60
1	FRONT SUSPENSION LOWER ARM (RH)	DISTORTED	529.30	529.30
1	KNUCKLE ARM (RH)	DISTORTED	552.00	552.00
1	ENGINE UNDER COVER	NOT NECESSARY	334.60	-
1	ENGINE CROSSMEMBER	DISTORTED	2,094.40	2,094.40
1	ABS SENSOR,RH	NOT NECESSARY	234.00	-
	LESS 20% DISCOUNT		-2,620.22	-2,190.38
			10,480.88	8,761.52
SPECIAL NETT ITEMS				
1	FRONT FENDER ADVERTISEMENT LOGO (RH)(SN)	NECESSARY	100.00	100.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT TYRE (RH)(SN)	SERVICEABLE	216.00	-
			316.00	100.00
	LABOUR			
	PANEL BEATING.		1,500.00	600.00
	SPRAY PAINTING CHARGE.		750.00	500.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		50.00	20.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX UNDERCARRIAGE (FRT).		200.00	150.00
	FRT WHEEL ALIGNMENT.		120.00	60.00
	RESET FRT ABS SYSTEM.	NOT NECESSARY	200.00	-
	REMOVE/REFIX AIRCON & REFILL GAS.	NOT NECESSARY	150.00	-
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	480.00	-
			3,550.00	1,360.00
	GRAND TOTAL		14,346.88	10,221.52
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,150.00

Report Ref No. CS/FC118020806/Dtd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.