

Photographs of the Accident Vehicle



Front View of MID 21026



Rear View of MID 21026



Left Side View of MID 21026



Right Side View of MID 21026

Photographs of the Accident Vehicle



Damage Assessment:

MID 21026 suffered graze marks on right front tyre rim, fuel tank and BII compartment box. Right headlight guard and driver step pedal were broken.

View of Accident Site



Photograph of Impact Point



Damage Assessment:

The front, right body above the wheel of civilian saloon car (SMD 6048Z) was torn and crumpled inwards. There were scratches and dents along the right body of civilian saloon car (SMD 6048Z). The window of the driver seat was shattered.

Point of Collisions

