

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CS3/MSG18003503/GSD3E2-1  
**Date:** 19/11/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A27710566QMX  
Claimant Vehicle No: SLT1357S Insured Vehicle No: SGG7362P  
Date of Loss: 21/02/2018 Nature of Claim: TP Claim No: 550353

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT1357S**  
Make & Model: HONDA SHUTTLE HYBRID, 1.5 (A) Engine No: LEB6325921  
Reg. Date: 19/10/2017 (Man. Year: 2017) Chassis No: GP71121020  
Colour: Silver Odometer: 35577 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15  
Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm  
Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,810.52	1,737.08	5,073.44	74.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,190.00	840 1,130.00	3,060.00	73.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,000.52</b>	<b>1603.92 2,867.08</b>	<b>8,133.44</b>	<b>73.94</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1250 2,300.00</b>		
(S\$)	11,000.52	2,300.00	8,700.52	79.09
<b>+ GST 7.00/7.00% (S\$)</b>	770.04	161.00	609.04	79.09
<b>Nett Amount (S\$)</b>	<b>11,770.56</b>	<b>2,461.00</b>	<b>9,309.56</b>	<b>79.09</b>

INSPECTION

Date of Assignment: 23/02/2018  
Date Inspected: 09/03/2018 Inspected At: N-51 Automotive Pte Ltd (HQ)  
Singapore 417921  
Estimated Period of Repair: 5.0 days

**Adjuster:** XING GUO QIANG **Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

**Part Source:** (Last Synchronised: 19 Nov 2018)  
**Parts:** N/A HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)  
**Labour:** Repairer's (Price-denominated Standard List)  
**Print Code:** LKK Auto Consultants Pte Ltd/SLT1357S/19/11/2018 16:25  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Not Necessary	1,150.60 FL	*-FL
2	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	53.00 FL	*-FL
3	1		*REAR RH ABS SENSOR	Not Necessary	210.00 FL	*-FL
4	1		*REAR RH DOOR	Dented	799.40 FL	*799.40 FL
5	1		*REAR RH DOOR BLACK FRAME STICKER	Necessary	25.00 FL	*25.00 FL
6	1		*REAR RH DOOR BOTTOM RUBBER SEAL	Deformed	55.40 FL	*55.40 FL
7	1		*REAR RH DOOR CHECKER	Reuse	37.20 FL	*-FL
8	1		*REAR RH DOOR FRONT WEATHERSTRIP	Not Necessary	69.50 FL	*-FL
9	1		*REAR RH DOOR GLASS OUTER LOCK HANDLE	Reuse	81.70 FL	*-FL
10	1		*REAR RH DOOR GLASS OUTER MOULDING	Not Necessary	53.80 FL	*-FL
11	2		*REAR RH DOOR HINGES (TOP & LOWER)	Repair	97.20 FL	*-FL
12	1		*REAR RH DOOR INNER TRIM BOARD	Broken	385.25 FL	*385.25 FL X
13	1		*REAR RH DOOR MECHANISM LOCK	Bent	240.20 FL	*240.20 FL X
14	1		*REAR RH DOOR REAR WEATHERSTRIP	Cut	75.10 FL	*75.10 FL
15	2		*REAR RH DOOR RUBBER GUIDE STOPPER	Not Necessary	31.00 FL	*-FL
16	1		*REAR RH FENDER	Repair	1,010.90 FL	*-FL
17	1		*REAR RH FENDER GLASS MOULDING	Reuse	155.00 FL	*-FL
18	1		*REAR RH FENDER INNER SHIELD	Reuse	53.70 FL	*-FL
19	1		*REAR RH FENDER INNER TRIM BOARD	Reuse	489.60 FL	*-FL
20	1		*REAR RH SHOCK ABSORBER	Not Necessary	530.00 FL	*-FL
21	1		*REAR RH WHEEL CAP	Cut	195.00 FL	*195.00 FL X
22	1		*REAR RH WHEEL HUB BEARING	Dislodged	321.00 FL	*321.00 FL X
23	1		*REAR SUSPENSION AXLE	Not Necessary	1,080.00 FL	*-FL
24	1		*ROCKER RH SIDE GARNISH	Reuse	363.60 FL	*-FL
25	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS X
26	1		*REAR RH 15 RIM	Not Necessary	180.00 FS	*-FS
27	1		*REAR RH 185/60R15 TYRE	Not Necessary	350.00 FS	*-FS
28	1		*SET REAR RH DOOR INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS X
29	1		*REAR RH FENDER GLASS SEALANT	Reuse	80.00 FS	*-FS
30	1		*SET REAR RH FENDER INNER SHIELD CLIPS	Not Necessary	30.00 FS	*-FS
31	1		*SET REAR RH FENDER INNER TRIM BOARD CLIPS	Reuse	30.00 FS	*-FS
32	1		*SET ROCKER RH SIDE GARNISH CLIPS	Reuse	30.00 FS	*-FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,323.15</b>	<b>2,156.35</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>1,512.63</b>	<b>419.27</b>
<b>Total Parts (\$\$)</b>	<b>6,810.52</b>	<b>1,737.08</b>

LKK Auto Consultants Pte Ltd/SLT1357S/19/11/2018 16:25. Not valid without Reference section.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REINSTALL WINDOW GLASS (TO FR) }	New	150.00	80.00 X
2	TO TRANSFER DOOR GLASS, REGULATOR GEAR, MOTOR, RAILING, CHANNEL, TRIM BOARD, MECHANISM LOCK AND HANDLE }	New	200.00	0.00
3	TO REMOVE, REINSTALL FENDER GLASS	New	150.00	0.00
4	TO REMOVE, CHANGE REAR SUSPENSION PARTS, AXLE CARRIAGE, ABSORBER, LOWER ARM, TOP ARM, TRAILING ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB AND ETC	New	550.00	150.00 X
5	TO ROAD TEST DRIVING, CHECK AND RESETTING WHEEL ALIGNMENTS SYSTEM	New	180.00	60.00 X
6	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET (TO FR)	New	140.00	0.00
7	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	400.00
8	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,700.00	400.00
9	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	40.00
<b>Gross Labour Cost (S\$)</b>			<b>4,190.00</b>	<b>1,130.00</b>

LKK Auto Consultants Pte Ltd/SLT1357S/19/11/2018 16:25. Not valid without Reference section.

< END OF ESTIMATES >