

SERVICE ESTIMATE

94457 - C00001 SL: SERVICE SALES - PC
 Mr Heah Kwan Seek
 88 Surin Avenue

Singapore 535656

Closed by : Paul Ong Qing Yong
 Svc Consultant :
 Remarks : Mr Heah Kwan Seek

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 1
 Inv.date. : 16/11/2018
 WIP No. . : 38632
 Veh.In/Out:
 *Tel.No. . : Mobile: 96238490
 Reg.No. . : SLU1088M
 Reg.date . : 17/11/2017
 Mileage .. : 0
 Chassis No: SALVA2AGXHH245629

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
			1200			2400.	
802	TO REPLACE FRONT BUMPER, FRT BRACKET, FRT SENSOR, FRT BEAM, REAR BUMPER, REAR SKID PLATE, REAR SENSOR, REAR BEAM, ETC	0	6000.00	0		6,000.00	S
800	TO PUTTY SPRAY PAINT ON FRT BUMPER, REAR BUMPER, ETC	0	3000.00	0		3,000.00	S
802	TO REPLACE REAR EXHAUST	0	1200.00	0		1,200.00	S <i>7. photo</i>
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	486.00	0		486.00	S ✓
	BUMPER - FRONT	1.0 EA	2497.30			2,497.30	S <i>de</i>
	MOULDING - BUMPER BA <i>LH</i>	1.0 EA	224.70			224.70	S <i>X</i>
	MOULDING - BUMPER BA <i>RH</i>	1.0 EA	224.70			224.70	S <i>side</i>
	COVER - TOW HOOK	1.0 EA	599.70			599.70	S <i>?</i>
	BUMPER BRACKET FRT R	1.0 EA	80.90			80.90	S <i>?</i>
	BUMPER BRACKET FRT L	1.0 EA	47.50			47.50	S <i>?</i>
	BUMPER BRACKET FRT R	1.0 EA	46.90			46.90	S <i>?</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Tanpin 97445749
WP
20/11/18 @ 4:20 pm
Resurvey before paint -
5-6 days
sure@lkkauto.com

SERVICE ESTIMATE

94457 - C00001 SL: SERVICE SALES - PC

Mr Heah Kwan Seek
88 Surin Avenue

Singapore 535656

Closed by : Paul Ong Qing Yong
Svc Consultant :
Remarks : Mr Heah Kwan Seek

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 2
Inv.date. : 16/11/2018
WIP No. . : 38632
Veh.In/Out:
*Tel.No. . : Mobile: 96238490
Reg.No. . : SLU1088M
Reg.date. : 17/11/2017
Mileage . : 0
Chassis No: SALVA2AGXHH245629

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER BRACKET FRT L	1.0 EA	46.90			46.90	S?
	DEFLECTOR - AIR	1.0 EA	112.30			112.30	S?
	DEFLECTOR - AIR	1.0 EA	112.30			112.30	S?
	BUMPER BRACKET FRT C	1.0 EA	398.70			398.70	S?
	WASHER COVER RH EVOQ	1.0 EA	61.30			61.30	S?
	WASHER COVER LH EVOQ	1.0 EA	70.90			70.90	SX
	RADIATOR GRILLE EVO	1.0 EA	863.00			863.00	S?
	BUMPER BEAM FRT EVOQ	1.0 EA	1008.00			1,008.00	S?
	BUMPER - REAR	1.0 EA	2652.50			2,652.50	S de
	HEAT SHIELD REAR EVO	1.0 EA	124.40			124.40	S bt
	BRACKET - BUMPER MOU	1.0 EA	60.90			60.90	S?
	BRACKET - BUMPER MOU	1.0 EA	68.10			68.10	S?
	BUMPER BRACKET REAR	1.0 EA	120.40			120.40	S?
	BUMPER BRACKET REAR	1.0 EA	80.40			80.40	S?
	BUMPER MOULDING REAR	1.0 EA	131.20			131.20	S de
	BUMPER BEAM REAR EVO	1.0 EA	1225.20			1,225.20	S?
	MUFFLER - REAR	1.0 EA	1699.80			1,699.80	S?



SERVICE ESTIMATE

94457 - C00001 SL: SERVICE SALES - PC

Mr Heah Kwan Seek
88 Surin Avenue

Singapore 535656

Closed by : Paul Ong Qing Yong
Svc Consultant :
Remarks : Mr Heah Kwan Seek

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 3
Inv.date. : 16/11/2018
WIP No. . : 38632
Veh.In/Out:
*Tel.No. . : Mobile: 96238490
Reg.No. . : SLU1088M
Reg.date. : 17/11/2017
Mileage . : 0
Chassis No: SALVA2AGXHH245629

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	EXHAUST CLAMP 65mm E	1.0 EA	87.70			87.70	S ?
	BODY PANEL SEALANT X	1.0 EA	883.20			883.20	S ?
	ADHESIVE SEALER FL2	1.0 EA	549.10			549.10	S ?

Gross Total. 24,764.00

Labour Total 10,686.00
Parts Total 14,078.00
Package Total 0.00

Net..... 24,764.00
GST @ 7.0% 1,733.48
Total..... 26,497.50
Paid..... 0.00
Please Pay.. 26,497.50

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated