

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III18020970/APA3Q2
Date: 27/06/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SKR4476J	Insured Vehicle No :	SHC1465A
Date of Loss:	15/11/2018	Nature of Claim:	TP
		Claim No:	MCT18110476

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR4476J	Engine No:	G4FGFU180996
Make & Model:	HYUNDAI ELANTRA, 1.6 ABS D/AB 2WD 4DR (A)	Chassis No:	KMHDH41CMFU439933
Reg. Date:	10/02/2015 (Man. Year: 2015)	Odometer:	48361 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,301.08	1,296.60	1,004.48	43.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,040.00	1,330.00	710.00	34.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,341.08	2,626.60	1,714.48	39.49
Approved Total (Overridden) (S\$)		2,100.00		

(S\$)	4,341.08	2,100.00	2,241.08	51.62
+ GST 7.00/7.00% (S\$)	303.88	147.00	156.88	51.63
Nett Amount (S\$)	4,644.96	2,247.00	2,397.96	51.62
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
Nett Liability (S\$)		2,547.00		
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 19/11/2018

Date Inspected: 26/11/2018

Estimated Period of Repair: 5.0 days

Inspected At:

BLK 1 KAKI BUKIT AVE 6 #01-90 AUTOBAY
Repairer: Auto N Cars Services Pte Ltd (HQ)**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Aug 2019)
Parts:	143	HYUNDAI ELANTRA 1.6 ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKR4476J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	790.20 FL	*482.00 FL
2	1		*REAR BUMPER RETAINER	N/S Necessary	119.00 FL	*59.50 FL
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	389.50 FL	*- FL
4	1		*REAR BUMPER SPONGE	Not Necessary	310.10 FL	*- FL
5	1		*REAR BUMPER LH REFLECTOR	Cut	75.20 FL	*75.20 FL
6	1		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	129.20 FL	*- FL
7	1		*REAR END PANEL	Dented	480.20 FL	*480.20 FL
8	12		*REAR BUMPER CLIP	Necessary	60.00 FL	*30.00 FL
9	1		*REAR BUMPER LOWER EXTENSION	Cut	380.50 FL	*380.50 FL
10	1		*REAR BUMPER LOWER BRACKET LH	Not Necessary	29.10 FL	*- FL
11	1		*REAR END PANEL LH AIR VENT	Cracked	82.10 FL	*82.10 FL
12	1		*SEALANT	Necessary	25.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,870.10	1,614.50
- List Item Discount on L Items 20.00/20.00% (\$)	569.02	317.90
Total Parts (\$)	2,301.08	1,296.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCK & STRAIGHTEN THE NECESSARY PORTION ,CUT & WELD DAMAGED PANEL ,ADJUST & REALIGN THE SAME	New	1,000.00	700.00
2	TO PUTTY & SPRAY TRUNK LID ,REAR END PANEL ,REAR & LH REAR BUMPER	New	900.00	600.00
3	TO RUST PROOF THE AFFECTED AREAS	New	80.00	0.00
4	TO CHECK WIRING & ALL LIGHTING	New	60.00	30.00
Gross Labour Cost (\$)			2,040.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >