



HUA HONG PRIVATE LIMITED

25D Sungei Kadut Street 1 Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

15 November 2018

HHTPClaims18-125

EQ Insurance Company Ltd
5 Maxwell Road
#17-00 Tower Block MND Complex
Singapore 069110

Attn: Motor Claims Department

ACCIDENT INVOLVING SLW 5844 K & GBG 1451 P ON 15/4/2018 AT BLK 154 BUKIT BATOK CARPARK AT ABOUT 0520 HOURS

Insured : SEE SIEW ENG JULIN
Vehicle Registration No : SLW 5844 K
Vehicle Make : B.M.W
Vehicle Model : X5 XL
Vehicle Chassis No : GJ11118442
Policy No : GA230850/1
Date of Accident : 15/4/2018

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

				Type of Claim: Third Party	
S/N	Quantity	Description	Unit Price S\$	Amount S\$	
1	1	Rear Bumper / <i>re</i>		\$	1,546.05
2	10	Rear Bumper Clip / <i>ML</i>	\$ 5.00	\$	50.00
3	1	Rear Bumper Tow Cover / <i>scr</i>		\$	36.60
4	4	Rear Bumper Sensor <i>x NN</i>	\$ 236.85	\$	947.40
5	1	Rear Reinforcement <i>?</i>		\$	724.80
				\$	3,304.85
				Less 10%	\$ (330.49)
					\$ 2,974.37

To dismantle & change rear bumper, rear reinforcement, knocking & pull straight rear panel and all area affected by accident

\$ 600.00 *200*

To perform wire checking

\$ 20.00 *x NN*

To dismantle & refit rear bumper sensor

\$ 60.00 *40*

To perform P/Steering and 4x4 diagnostic check

\$ 250.00 *x NN*

To spray rear panel, rear reinforcement and tail gate

\$ 700.00 *200*



Authorised by Claims Dept
Mrs Tan @ 9639 9195

*2 days.
part by mt.
before/after repair photos.
Gino Qiao - 82880282
03/12/18.*

7% GST
Total

\$ 4,604.37
\$ 322.31
\$ 4,926.67