

ASS. REC. BY:

REF:

es/FC118020993/Usd3

Special Instruction:

Survivor:

Marius

ASSIGNMENT (Office)

CWS

From (Person):

Eileen Lee

of

FCP

Date/Time: 20/11/18 @ 3:43pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMD 9034T

Insured:

SHD 8518E

at Workshop m/s

Ace Autolution

Tel:

68441184

of

13 kaki Bukit Rd 4 #03-29/30

Policy No:

Claim No:

D18008223 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 19/11/2018

(Client's Record)

20/11/18

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

(up)

Date/Time:

4:12pm @ 20/11/18

Person Contacted:

Anna

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

Repairer said estimate not yet rdy. therefore arrange survey tomorrow
on (21/11/18)

SMD 9034T-X

SHD 8518E-X

22/11/18

@ 15:38 p.m. revised PA to Eileen Lee via email.

(08/11/13) wef

REF:

F01

ASS. REC. BY: Marcus

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 46601

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMD 90347

Yr Regn:

9.18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Verel Hybrid

c.c

1496

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

23118

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

R431307579

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60-216

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

19/11/18

D.O.I.

21/11/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

14/12/18 L/S \$5500 confirmed with Anne.

17/12/18 Confirmed L/S \$5,500/- @ 6 days with Marcus.
(\$9,652.16 Rep - 64%)

RECEIVED 17 DEC 2018

Date/Time, File Pass to?

17/12/18

1)

Typist

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

6

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$I

Photos

Others

TOTAL

1704 75
50
50 + 50
121
516

Report Format :

Lump Sum / I.B.I. (\$) 5,500/- L/S)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008223MFSH

Date: 22 November 2018

Our Ref: CS/FCI18020993/Usd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SMD 9034T

Please be informed that we had conducted the inspection of the abovementioned vehicle on 21/11/2018 at the premises of M/s Ace Autolution Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 15,232.16
Revised Estimate Amount	: S\$ 8,936.40
"Check" Items Amount	: S\$ 444.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 6 Days

Yours faithfully,
Marcus Chua
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	19-11-2018	Our Ref No. D18008223MFSH
Accident Date	19-11-2018	Claim Type. Third Party
Insured Vehicle	SHD8518E	Third Party Vehicle. SMD9034T
Survey Location	13 KAKI BUKIT ROAD 4 BARTLEY BIZ CENTRE#03-29 & #03-30	
Contact Person.	SIM TEO KOON	
Contact No.	68441184/ 96572134	Fax No. 65369339
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ACE AUTOLUTION PTE LTD	Attention. NIL
Cc : TP Solicitor	JUSEQUITY LAW CORPORATION	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 22 November 2018 3:38 PM
To: 'Eileen Lee'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D18008223MFSH/1
Attachments: SMD 9034T - Preli Advise.pdf

Dear Eileen,

Enclosed preliminary revised of vehicle SMD 9034T.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 20 November 2018 4:15 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008223MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer arrange survey on 21/11/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 20 November 2018 3:43 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008223MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	6632D
Vehicle Details	
Vehicle No.:	SMD9034T
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Nov 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X AUTO
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	LEB6727589
Chassis No.:	RU31307579
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$26,041.00
Original Registration Date:	11 Sep 2018
First Registration Date:	11 Sep 2018
Transfer Count:	0
Actual ARF Paid:	\$18,458.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Sep 2028
PARF Rebate Amount:	\$13,843.00
Intended COE Rebate Details	
COE Expiry Date:	10 Sep 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$33,420.00
COE Rebate Amount:	\$32,758.00
Total Rebate Amount:	\$46,601.00

The information contained herein is correct as at 22 Nov 2018

OK



ACE AUTOLUTION PTE LTD
13 Kaki Bukit Road 4 Bartley Biz Centre #02-29
Singapore 417807
Tel: 6702 4282 Fax: 6702 4202

Not Affected
nkt
2/5 #5300
62
The Sh. Hing
Page No. 1
21/11/18

Vehicle No. SMD9034T HONDA VEZEL

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR ADJUSTMENT
PARTS (LIST ITEMS)				
1	TAILGATE		1950.00	✓ 953
1	TAILGATE HANDLE COVER		55.00	X
1	TAILGATE GARNISH		550.00	X
2	TAILGATE RUBBER STOPPER @\$6.00		12.00	X
1	TAILGATE "VEZEL" EMBLEM		130.00	✓ 18.20
1	TAILGATE "HYBRID" EMBLEM		145.00	✓ 78.50
1	TAILGATE EDGE WEATHERSHIP		310.00	✓ 135.70
1	TAILGATE INNER TRIM GARNISH		350.00	✓ 321.70
1	TAILGATE HONDA LOGO		110.00	X
1	TAILGATE LOCK		250.00	✓ 198.50
1	TAILGATE CENTRE GARNISH		530.00	X
9	TAILGATE CENTRE GARNISH CLIPS @\$5.80		52.20	X
1	REAR TAILLAMP RH		910.00	✓ 460.50
2	REAR TAILGATE LAMP LH & RH @ 555.00		1110.00	✓ 400.00
1	REAR BUMPER		830.00	✓ 762.70
1	REAR BUMPER SIDE RETAINER LH		110.00	X
1	REAR BUMPER SIDE BRACKET LH		80.00	✓ 35.20
1	END PANEL		810.00	✓ 514.00
1	END PANEL OUTER BEAM		175.00	X
1	END PANEL TOP GARNISH		280.00	✓ 185.00
1	SPARE TYRE BOX		1258.00	X
1	REAR SPARE TYRE BOX LOWER COVER		180.00	✓
1	REAR SPARE TYRE BOX TOP GARNISH		650.00	✓
1	REAR EXHAUST MOUNTINGS		98.00	X
1	REAR EXHAUST SILENCE ASSY		980.00	X
1	REMOTE CONTROL SENSOR		1200.00	✓ 280.00
			13115.20	P
less 20%			2623.04	20%
			10492.16	
SPECIAL NETT ITEMS				
1 SET	REVERSE SENSOR		280.00	200
1	REAR END SEALANT		100.00	50
1	REAR END PANEL TOP GARNISH CLIPS		80.00	X
1 SET	TAILGATE INNER TRIM CLIPS		60.00	50
1	REAR WINDSCREEN SEALANTS		100.00	40
1 SET	REAR BUMPER CLIPS		80.00	50
Ren exhaust chrome DO for S.M				80
Total Parts			11192.16	

470

4091
4072.8



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

Page No. 2

Vehicle No. SMD9034T HONDA VEZEL

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1800.00	1000
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1200.00	1000
3	To remove and refix wiring at damaged areas	200.00	30
4	To perform anti rust treatment on affected areas	240.00	80
5	To remove & refix / replace rear trims, garnish and fitting so as to facilitate repairs as rear compartment	250.00	80
6	To remove and replace reverse sensors and check for proper functions	120.00	50
7	To remove and refix rear tailgate windscreen	150.00	120
	Labour Total :	3960.00	
	TOTAL (PARTS & LABOUR) :	15152.16	

15232.16 2360

P-5091
202
4072.80
S.N 470.00
1clan 2360.00
6902.80
less 202
5522.24

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18020993/Usd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 19-12-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 8518E	Veh. Inspected	SMD 9034T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008223MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	20/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL HYBRID (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	RU31307579	Colour	BLUE	
Odometer	23119	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	8 mm	
L/H Front Tyre	215/60 R16	DUNLOP	8 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	8 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/11/2018	Inspection Date	21/11/2018	
Survey held at	ACE AUTOLUTION PTE LTD 13 KAKI BUKIT ROAD 4 #03-29 BARTLEY BIZ CENTRE SINGAPORE 417807			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 9034T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE	BADLY DENTED	1,950.00	953.00
1	TAILGATE HANDLE COVER	NOT NECESSARY	55.00	-
1	TAILGATE GARNISH	NOT NECESSARY	550.00	-
2	TAILGATE RUBBER STOPPER @\$6.00	NOT NECESSARY	12.00	-
1	TAILGATE "VEZEL" EMBLEM	NECESSARY	130.00	56.20
1	TAILGATE "HYBRID" EMBLEM	NECESSARY	145.00	78.50
1	TAILGATE EDGE WEATHERSTRIP	TWISTED	310.00	135.70
1	TAILGATE INNER TRIM GARNISH	TWISTED	350.00	321.70
1	TAILGATE HONDA LOGO	NOT NECESSARY	110.00	-
1	TAILGATE LOCK	TWISTED / SHORTED	250.00	198.50
1	TAILGATE CENTRE GARNISH	REPEATED	530.00	-
9	TAILGATE CENTRE GARNISH CLIPS @\$5.80	NOT NECESSARY	52.20	-
1	REAR TAILLAMP RH	CRACKED	910.00	460.50
2	REAR TAILGATE LAMP LH & RH @\$555.00	O/S CRACKED	1,110.00	280.00
1	REAR BUMPER	DENTED	830.00	762.70
1	REAR BUMPER SIDE RETAINER LH	NOT NECESSARY	110.00	-
1	REAR BUMPER SIDE BRACKET LH	BENT	80.00	35.20
1	END PANEL	BADLY DENTED	810.00	514.00
1	END PANEL OUTER BEAM	NO SUCH PARTS	175.00	-
1	END PANEL TOP GARNISH	TWISTED	280.00	185.00
1	SPARE TYRE BOX	TO REPAIR SEE LABOUR	1,258.00	-
1	REAR SPARE TYRE BOX LOWER COVER	TWISTED	180.00	180.00
1	REAR SPARE TYRE BOX TOP GARNISH	CRACKED	650.00	650.00
1	REAR EXHAUST MOUNTINGS	NOT NECESSARY	98.00	-
1	REAR EXHAUST SILENCE ASSY	TO REPAIR SEE LABOUR	980.00	-
1	REMOTE CONTROL SENSOR	CRACKED	1,200.00	280.00
LESS 20% DISCOUNT			-2,623.04	-1,018.20
			10,492.16	4,072.80

Report Ref No. CS/FCI18020993/Usd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR END SEALANT (SN)	NECESSARY	100.00	50.00
1	REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	80.00	-
1	SET TAILGATE INNER TRIM CLIPS (SN)	NECESSARY	60.00	50.00
1	REAR WINDSCREEN SEALANTS (SN)	NECESSARY	100.00	40.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	80.00	50.00
1	REAR EXHAUST CHROME (SN)	DENTED	80.00	80.00
			780.00	470.00
	<u>LABOUR</u>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS INCLUSIVE OF THE REPAIR OF SPARE TYRE BOX AND REAR EXHAUST SILENCE ASSY.		1,800.00	1,000.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED.		1,200.00	1,000.00
	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS.		200.00	30.00
	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS.		240.00	80.00
	TO REMOVE & REFIX/REPLACE REAR TRIMS, GARNISH AND FITTING SO AS TO FACILITATE REPAIRS AS REAR COMPARTMENT.		250.00	80.00
	TO REMOVE AND REPLACE REVERSE SENSORS AND CHECK FOR PROPER FUNCTIONS.		120.00	50.00
	TO REMOVE AND REFIX REAR TAILGATE WINDSCREEN.		150.00	120.00
			3,960.00	2,360.00
	GRAND TOTAL		15,232.16	6,902.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,500.00

Report Ref No. CS/FCI18020993/Usd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.