

AS REC. BY:

REF:

CS/FCL18021039/Avbn2

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

CWS

Sithara

of

FCL

Date/Time:

21/12/18 1001am

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 4918T

Insured:

SHC 3326

at Workshop m/s

Success United

Tel:

6746 1515

of

2 Kaki Bukit Ave 2 #01-33

Policy No:

Claim No:

D18008015MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

07-11-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time:

21-12-2018 1016am

Person Contacted:

Siringu

Vehicle ~~IN~~ / OUT

Date/Time

Action/Instruction (✓) Estimate

SLC 4918T - X

SHC 3326 - NA / 0227701944 / h4

DUA: 17-10-2017

22/11/18

Informed FCI pending est from repairer by email

20/12/18

Adrian confirmed LS \$ 6750 (Red 5490.74, 45%)

21/12/18

Email preli revised to FCI

REF: FCI

ASSIGNMENT

From:

Date: 21-11-2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLC 4918T

at Workshop m/s

Success United

of

2 Kaki Bukit Ave 2 #01-33

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GI/A / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SLC 4918T. Yr Regn: 2016 May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda City.

CC

1497

Colour:

Black.

A/C: Insured / Std / NI / NA

Sp. Reading:

70979.

T/Radio: Insured / Std / NI / NA

Eng/No:

ChNo:

MRHGM66606P000457.

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/55R16.

R:

185/55R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

21/11/18

Survey held at

Success United.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP 1st Cap.

RECEIVED 21 DEC 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 21/12 - typist

Report Format:

CWS

Lump Sum / I.B.I. (\$)

6750/2

Days Of Repair: 11

Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

) \$ + P.C. \$

) Photos

) Others

TOTAL

2x15² 30

1707 30
50
50+50
88

438



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18008015MFSH

Our ref: CS/FCI18021039/Avb

Date : 21/12/2018

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLC 4918T


We thank you for your instruction on 21/11/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21/11/2018 at the premises of M/s SUCCESS UNITED PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$12,240.74
Revised Estimate Amount	: S\$6,750.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front and rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	09-11-2018	Our Ref No. D18008015MFSH
Accident Date	07-11-2018	Claim Type. Third Party
Insured Vehicle	SHC0332G	Third Party Vehicle. SLC4918T
Survey Location	2 KAKI BUKIT AVE 2 #01-33 / #02-29KAKI BUKIT AUTOHUB	
Contact Person.	SIRINA SOON	
Contact No.	67461515/ 0	Fax No. 67485015
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SUCCESS UNITED PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 21 December 2018 10:15 AM
To: 'CWS Motor Claims'
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008015MFSH/1, SLC 4918T
Attachments: SLC 4918T PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLC 4918T
Date of survey: 21/11/2018
Number of days : 11 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 22 November 2018 8:44 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008015MFSH/1, SLC 4918T

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLC 4918T on 21/11/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 21 November 2018 10:17 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008015MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Wednesday, 21 November, 2018 10:01 AM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D18008015MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 22 November 2018 8:44 AM
To: 'CWS Motor Claims'
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008015MFSH/1, SLC 4918T

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLC 4918T on 21/11/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 21 November 2018 10:17 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008015MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 21 November, 2018 10:01 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008015MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

6607Z

Vehicle Details

Vehicle No.:

SLC4918T

Vehicle to be Exported:

No

Intended Deregistration Date:

21 Nov 2018

Vehicle Make:

HONDA

Vehicle Model:

CITY 1.5 SV CVT

Primary Colour:

Brown

Manufacturing Year:

2016

Engine No.:

L15Z12720050

Chassis No.:

MRHGM6660GP000457

Maximum Power Output:

88.0 kW (118 bhp)

Open Market Value:

\$18,503.00

Original Registration Date:

17 May 2016

First Registration Date:

17 May 2016

Transfer Count:

1

Actual ARF Paid:

\$13,503.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

16 May 2026

PARF Rebate Amount:

\$10,127.00

Intended COE Rebate Details

COE Expiry Date:

16 May 2026

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$47,889.00

COE Rebate Amount:

\$35,843.00

Total Rebate Amount:

\$45,970.00

The information contained herein is correct as at 20 Nov 2018

OK



聯成汽車維修

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29 Kaki Bukit AutoHub Singapore 417921

Tel: 6746 1515 / 6747 1787 Fax: 6748 5015

www.successunited.com.sg Co. / GST Reg: Z06402570G

MS First Capital Insurance Limited

36 Robinson Road

#16-01 City House

Singapore 068877

Attention : Motor Claim Department

Contact : 65073848 Fax No. : 65073849

Vernon

Estimate : TP18-125

Date : 21/11/2018

Vehicle Num. : SLC4918T

Make/Model : Honda City-2016

Chassis/Eng# : MRHGM6660GP000457/L15Z1272005

Accident Date : 21/11/2018

Claim No. : D18008015MFSH

Reference :

Policy No. : (01/06/2019)

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	Rear Boot lid <i>Buckeed</i>		598.70
2.	1	Rear Boot 'City' Emblem <i>3/4</i>		28.70
3.	1	Rear Boot 'i-vtec' Emblem <i>3/4</i>		34.00
4.	1	Rear Boot Weatherstrip <i>at</i>		98.10
5.	1	Rear Boot Lid Mechanism Lock <i>2nd</i>		181.50
6.	1	Rear Boot Reflector Lamp LH <i>at</i>		94.80
7.	1	Rear Boot Reflector Lamp RH <i>new</i>		94.80
8.	1	Rear Lamp LH <i>at</i>		235.70
9.	1	Rear Lamp RH <i>at</i>		235.70
10.	1	Rear Bumper Assy <i>2nd</i>		514.70
11.	8	Rear Bumper Clips <i>3/4</i>	3.90	31.20
12.	1	Rear Bumper Side Holder LH <i>3/4</i>		19.20
13.	1	Rear Bumper Side Holder RH <i>3/4</i>		19.20
14.	1	Rear End Panel <i>2nd</i>		410.10
15.	1	Rear Bumper Reflector Lamp LH <i>new</i>		45.00
16.	1	Rear Bumper End Panel Inner Top Garnish <i>2nd</i>		116.86
17.	1	Rear Fender Inner upholstery Trim LH <i>new</i>		135.90
18.	1	Bonnet <i>2nd</i>		561.40
19.	1	Bonnet Hinge LH <i>3/4</i>		31.70
20.	1	Bonnet Hinge RH <i>3/4</i>		31.70
21.	1	Bonnet Mechanism Lock <i>2nd</i>		87.70
22.	1	Bonnet Weatherstrip <i>new</i>		26.10
23.	1	Headlamp LH <i>3/4</i>		432.20
24.	1	Headlamp RH <i>3/4</i>		432.20
25.	1	Frt Grille Assy <i>cracked</i>		394.80
26.	1	Frt Grille Honda Logo <i>3/4</i>		34.00
27.	1	Frt Bumper Assy <i>2nd</i>		698.12
28.	10	Frt Bumper Clips <i>3/4</i>	3.90	39.00
29.	1	Frt Bumper Side Holder LH <i>3/4</i>		13.10
30.	1	Frt Bumper Side Holder RH <i>3/4</i>		13.10
31.	1	Frt Fender LH <i>Buckeed</i>		290.62
32.	1	Frt Fender RH <i>3/4</i>		290.62
33.	1	Frt Bumper Lower Air Grille <i>new</i>		98.00
34.	1	Frt Grille Chrome Trim <i>cracked</i>		218.60
35.	1	Frt Bumper Reinforcement <i>2nd</i>		268.00
36.	1	Headlamp Bracket LH <i>cracked</i>		32.50
37.	1	Radiator Assy <i>new</i>		1,100.50
38.	1	Radiator Support Top Cover Garnish <i>2nd</i>		39.10
39.	7	Radiator Support Top Cover Garnish Clips <i>3/4</i>	3.90	27.30

CONTINUE / ...



聯成汽車維修

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29 Kaki Bukit AutoHub Singapore 417921
 Tel: 6746 1515 / 6747 1787 Fax: 6748 5015
 www.successunited.com.sg Co. / GST Reg: 200402570G

MS First Capital Insurance Limited
 36 Robinson Road
 #16-01 City House
 Singapore 068877
 Attention : Motor Claim Department
 Contact : 65073848 Fax No. : 65073849

Estimate : TP18-125

Date : 21/11/2018
 Vehicle Num. : SLC4918T
 Make/Model : Honda City-2016
 Chassis/Eng# : MRHGM6660GP000457/L15Z1272005
 Accident Date : 21/11/2018
 Claim No. : D18008015MFSH
 Reference :
 Policy No. : (01/06/2019)

S/N	Quantity	Particular	Unit Price	Amount S\$
40.	1	Rear Spare Tyre Panel <i>Rjs</i>	508.90	508.90 +
		List Total S\$:		8,563.42
		20.00% Discount S\$:		1,712.68
				6,850.74
1.	1 set	NETT ITEMS :		
2.	1	Reverse Sensor <i>Best</i>	480.00	480.00 ²⁰⁰
3.	1	Frt No. Plate w/frame <i>Best</i>	100.00	100.00 ⁵⁰
		Rear No. Plate w/frame <i>not in</i>	100.00	100.00 +
		Nett Total S\$:		680.00
		LABOUR :		
		To remove, rearrange electrical wirings, check lighting	60.00	60.00 ✓
		To remove, instal inner trim garnishes & upholstery.	300.00	300.00 ⁶⁰
		To remove, instal aircon parts, vacuum, refill gas.	250.00	250.00 x
		Respray tuff kote sealant	300.00	300.00 ⁶⁰
		To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident	1,800.00	1,800.00 ¹⁴⁰
		To putty and respray painting on affected area.	2,000.00	2,000.00 ¹⁶⁰
		Labour Total S\$:		4,710.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: *[Signature]*

Date:

E. & O.E.

Total S\$: 12,240.74

Total: 8440.88

1/5: 6750

for SUCCESS UNITED PTE LTD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18021039/Avbn2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 26-12-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 332G	Veh. Inspected	SLC 4918T
Policy No.		Coverage (\$)	0.00
Claim No.	D18008015MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	21/11/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA CITY	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MRHGM6660GP000457	Colour	BLACK
Odometer	70979	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/55 R16	YOKOHAMA	6 mm
L/H Front Tyre	185/55 R16	YOKOHAMA	6 mm
R/H Rear Tyre	185/55 R16	YOKOHAMA	6 mm
L/H Rear Tyre	185/55 R16	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/11/2018	Inspection Date	21/11/2018
Survey held at	SUCCESS UNITED PTE LTD 2 KAKI BUKIT AVE 2 #01-33 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	11 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 4918T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT LID	BUCKLED	598.70	598.70
1	REAR BOOT "CITY" EMBLEM	NECESSARY	28.70	28.70
1	REAR BOOT "I-VTEC" EMBLEM	NECESSARY	34.00	34.00
1	REAR BOOT WEATHERSTRIP	CUT	98.10	98.10
1	REAR BOOT LID MECHANISM LOCK	DAMAGED	181.50	181.50
1	REAR BOOT REFLECTOR LAMP LH	CUT	94.80	94.80
1	REAR BOOT REFLECTOR LAMP RH	NOT NECESSARY	94.80	-
1	REAR LAMP LH	CUT	235.70	235.70
1	REAR LAMP RH	CUT	235.70	235.70
1	REAR BUMPER ASSY	DEFORMED	514.70	514.70
8	REAR BUMPER CLIPS @\$3.90	NECESSARY	31.20	31.20
1	REAR BUMPER SIDE HOLDER LH	NECESSARY	19.20	19.20
1	REAR BUMPER SIDE HOLDER RH	NECESSARY	19.20	19.20
1	REAR END PANEL	DENTED	410.10	410.10
1	REAR BUMPER REFLECTOR LAMP LH	NOT NECESSARY	45.00	-
1	REAR BUMPER END PANEL INNER TOP GARNISH	DEFORMED	116.86	116.86
1	REAR FENDER INNER UPHOLSTERY TRIM LH	NOT NECESSARY	135.90	-
1	BONNET	DENTED	561.40	561.40
1	BONNET HINGE LH	BENT	31.70	31.70
1	BONNET HINGE RH	BENT	31.70	31.70
1	BONNET MECHANISM LOCK	DAMAGED	87.70	87.70
1	BONNET WEATHERSTRIP	NOT NECESSARY	26.10	-
1	HEADLAMP LH	CRACKED	432.20	432.20
1	HEADLAMP RH	CRACKED	432.20	432.20
1	FRT GRILLE ASSY	CRACKED	394.80	394.80
1	FRT GRILLE HONDA LOGO	NECESSARY	34.00	34.00
1	FRT BUMPER ASSY	DISTORTED	698.12	698.12
10	FRT BUMPER CLIPS @\$3.90	NECESSARY	39.00	39.00
1	FRT BUMPER SIDE HOLDER LH	NECESSARY	13.10	13.10
1	FRT BUMPER SIDE HOLDER RH	NECESSARY	13.10	13.10
1	FRT FENDER LH	BUCKLED	290.62	290.62

Report Ref No. CS/FCI18021039/Avbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRT FENDER RH	TO REPAIR SEE LABOUR	290.62	-
1	FRT BUMPER LOWER AIR GRILLE	NOT NECESSARY	98.00	-
1	FRT GRILLE CHROME TRIM	CRACKED	218.60	218.60
1	FRT BUMPER REINFORCEMENT	BENT	268.00	268.00
1	HEADLAMP BRACKET LH	CRACKED	32.50	32.50
1	RADIATOR ASSY	NOT NECESSARY	1,100.50	-
1	RADIATOR SUPPORT TOP COVER GARNISH	CRACKED	39.10	39.10
7	RADIATOR SUPPORT TOP COVER GARNISH CLIPS @ \$3.90	NECESSARY	27.30	27.30
1	RADIATOR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	508.90	-
	LESS 20% DISCOUNT		-1,712.68	-1,252.72
			6,850.74	5,010.88
	<u>SPECIAL NETT ITEMS</u>			
1	SET REVERSE SENSOR (SN)	DAMAGED	480.00	200.00
1	FRT NO PLATE W/FRAME (SN)	BENT	100.00	50.00
1	REAR NO PLATE W/FRAME (SN)	NOT NECESSARY	100.00	-
			680.00	250.00
	<u>LABOUR</u>			
	TO REMOVE,REARRANGE ELECTRICAL WIRINGS,CHECK LIGHTING.		60.00	60.00
	TO REMOVE,REINSTALL INNER TRIM GARNISHES & UPHOLSTERY.		300.00	60.00
	TO REMOVE,REINSTALL AIRCON PARTS,VACUM,REFILL GAS.	NOT NECESSARY	250.00	-
	RESPRAY TUFF KOTE SEALANT.		300.00	60.00
	TO REMOVE,REPAIR AND REPLACED DAMAGED BODYPARTS,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT.INCLUSIVE OF THE REPAIR OF FRT FENDER RH AND RADIATOR SPARE TYRE PANEL.		1,800.00	1,400.00
	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA.		2,000.00	1,600.00
			4,710.00	3,180.00
	GRAND TOTAL		12,240.74	8,440.88

Report Ref No. CS/FCI18021039/Avbn2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,750.00
---	--	--	----------

Report Ref No. CS/FCI18021039/Avbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.