

ASS. REC. BY:

REF: CS/MSG18021043/Uq bnf

Special Instruction:

Supervisor:

Mei/mina

ASSIGNMENT (Office)

From (Person):

Pauline Thom

of

mslh

Date/Time:

21-11-2018 10:09am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBH 8882C

Insured:

YL 6446Z

at Workshop m/s

Joo Hak Kee Auto

Tel:

6743 1913

of

Blk 3007 Ubi Rd 1 #01-406

Policy No:

A27667922TMV

Claim No:

576454

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A.

16-11-2018

CA / REV / REP. / REV 24 HRS 'wp'

23-11-2018 @ 10am

H.O.D. Endorsement:

Date/Time:

21-11-2018 10:42am

Person Contacted:

Grace

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	GBH 8882C - X
	YL 6446Z - X
26/11/18@	7.12pm revised to Pauline Thom via Mei/mina.

REF: MS1G

ASSIGNMENT

From: Date: 23/11/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBH 8882C
at Workshop m/s: JOO HAK KEE
of: BIK 3007 Ubi Rd | #01-406

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: 109M

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS Cup

Vehicle: IN / OUT

Date: Person Contacted: LIA 21316

Veh No: GBH 8882C Yr Regn: 1217

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make: Toyota hiace DX C.C 2982

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 25567 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KDM 2010233113

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/80R15
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front R/Bal: 6 mm Rear R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. 16/11/18 D.O.I. 22/11/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear
The UIC / Chassis frame / Body Structure affected due to collision.

12/12/18 4/5 @ 1650 cont. work with Kelvin. (Red to 880.15, 35%)

RECEIVED 13 DEC 2018

Signature
12/12/2018

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 2

Resurvey No. of Trip:

Date/Time, File Return to? 2)

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

Report Format: MEE-TL
Lump Sum / I.B.F. (\$) 1650

Survey Fee	
Transportation	150
3 + RS. \$	10
Photos	
Others	
TOTAL	160

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 26 Nov 2018

Preliminary Advice

Insured Vehicle No	: YL6446Z	Accident Date	: 16/11/2018
TP Vehicle No	: GBH8882C	Assignment Date	: 21/11/2018
Make	: TOYOTA HIACE	Est. Duration of Repair	: 2.00
Date of Inspection	: 23/11/2018		
Inspection At	: JOO HAK KEE AUTO PTE LTD (HQ) BLK 3007 UBI ROAD 1, #01-406 SINGAPORE 408701		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,530.15
Revised Amount	:S\$	2,091.90
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,091.90
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Nov 2018		21 Nov 2018 10:09 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	TONG SENG CHIANG, ID: S1188637Z, Tel: +6596742310, Email: NOEMAIL								
Main Claimant:	BRIGHT SOLUTION ELECTRICAL WORKS PTE LTD, Co. Reg. No.: 201524652R								
Vehicle Reg. No.:	GBH8882C	Date of Loss: 16/11/2018 17:00 - :59 [11 Months and 2 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / 576454	Policy/Cover Note No.: A27667922TMV (Third Party Only) Coverage: 16/03/2018 - 15/03/2019							
Vehicle Reg. No. (Insured):	YL6446Z	Policy No. (Claimant): Excess:							
Repairer:	Joo Hak Kee Auto Pte Ltd (HQ) Blk 3007 Ubi Road 1, #01-406, 408701 Ubi - Tel: 67431913								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/11/2018]								
Driver/Custodian (Insured):	TONG SENG CHIANG (62 / Male), NRIC: S1188637Z, Tel: +6596742310								
Adj Asg. Remarks:	LIABLTYY 100%. TP AGREE WITH SJE -ASSIGN MARCUS CHUA OF LKK AUTO CONSULTANTS PTE LTD.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4652R
Vehicle Details	
Vehicle No.:	GBH8882C
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DX 3.0 M
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	1KD2749724
Chassis No.:	KDH2010233113
Maximum Power Output:	-
Open Market Value:	\$31,333.00
Original Registration Date:	14 Dec 2017
First Registration Date:	14 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$1,567.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Dec 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$23,543.00
COE Rebate Amount:	\$21,316.00
Total Rebate Amount:	\$21,316.00

The information contained herein is correct as at 23 Nov 2018

OK

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER: BRIGHT SOLUTION ELECTRICAL WORKS PTE LTD
 INSURER: NTUC INCOME INSURANCE CO-OPERATIVE LTD
 POLICY NO: 5096594736
 REFERENCE: TP CLAIM
 DATE OF ACCIDENT: 16/11/2018

- Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary items are subject to final approval from Insurance Company

REPAIR ESTIMATE

Est. No. : E18110008
 Date : 21/11/2018
 Vehicle Num. : GBH8882C
 Make/Model : TOYOTA HIACE DX 3.0M
 Chassis/Eng# : KDH2010233113
 Yr. of Manu : 2017

No	Description	Qty	U/P	Amt
----	-------------	-----	-----	-----

Section: LIST ITEMS

1	TAILGATE	1.00	1,950.10	1,950.10 ✓
2	TAILGATE HINGE	2.00	55.50	111.00 X
3	TAILGATE LOGO EMBLEM	1.00	59.10	59.10 ✓

p-2009.2
25%
1506.90

Amt S\$ 2,120.20
Discount (25.00%) S\$ 530.05
Subtotal S\$ 1,590.15

Section: SPECIAL NETT ITEMS

4	TAILGATE '1250KG' STICKER	1.00	15.00	15.00 ✓
5	TAILGATE '70KM/H' STICKER	1.00	15.00	15.00 10
6	REAR WS SILICON SEALANT	1.00	60.00	60.00 40

Amt S\$ 90.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 90.00

Section: LABOUR

7	TO PANEL BEAT AND RENEWAL OF ALL DAMAGED PARTS	1.00	350.00	350.00 200
8	TO PUTTY & SPRAY PAINTING ON ACCIDENT DAMAGED PORTION	1.00	300.00	300.00 200
9	TO DISMANTLE AND REFIT TAILGATE COMPONENTS	1.00	80.00	80.00 X
10	TO DISMANTLE AND REFIT REAR WINDSCREEN	1.00	120.00	120.00 ✓

Amt S\$ 850.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 850.00

Surveyed by/Company : Marcus Hhh
 Contact Number : 90096608
 Date/Time : 23/11/18
 Licensed Automotive Surveyor's Sign : John photo after repair

4/5 @ 1650

2091.90



Joo Hak Kee Auto Pte. Ltd.

LIST ITEMS Subtotal S\$ 1,590.15
SPECIAL NETT ITEMS Subtotal S\$ 90.00
LABOUR Subtotal S\$ 850.00
Total S\$ 2,530.15

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18021043/UQBN2

Date: 14/12/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A27667922TMV
Claimant Vehicle No :	GBH8882C	Insured Vehicle No :	YL6446Z
Date of Loss:	16/11/2018	Nature of Claim:	TP
		Claim No:	576454

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH8882C	Engine No:	1KD2749724
Make & Model:	TOYOTA HIACE, 3.0 D DX (M)	Chassis No:	KDH2010233113
Reg. Date:	14/12/2017 (Man. Year: 2017)	Odometer:	25567 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/80 R15	Rear Tyre Size:	195/80 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,680.15	1,571.90	108.25	6.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	850.00	520.00	330.00	38.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,530.15	2,091.90	438.25	17.32
Approved Total (Overridden) (S\$)		1,650.00		
(S\$)	2,530.15	1,650.00	880.15	34.79
+ GST 7.00/7.00% (S\$)	177.11	115.50	61.61	34.79
Nett Amount (S\$)	2,707.26	1,765.50	941.76	34.79

INSPECTION

Date of Assignment:	21/11/2018		
Date Inspected:	23/11/2018	Inspected At:	Joo Hak Kee Auto Pte Ltd (HQ) Blk 3007 Ubi Road 1, #01-406 Singapore 408701

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 Dec 2018)
Parts: 213	TOYOTA HIACE 3.0 D DX (M) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GBH8882C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*TAILGATE	Dented/Buckled	1,950.10 FL	*1,950.10 FL	
2	2		*TAILGATE HINGE	Not Necessary	111.00 FL	*- FL	
3	1		*TAILGATE LOGO EMBLEM	Necessary	59.10 FL	*59.10 FL	
4	1		*TAILGATE 1250KG STICKER	Necessary	15.00 FS	*15.00 FS	
5	1		*TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*10.00 FS	
6	1		*REAR WS SILICON SEALANT	Necessary	60.00 FS	*40.00 FS	
					Sub Total (\$\$)	2,210.20	2,074.20
					- List Item Discount on L Items 25.00/25.00% (\$\$)	530.05	502.30
					Total Parts (\$\$)	1,680.15	1,571.90

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT AND RENEWAL OF ALL DAMAGED PARTS }	New	350.00	200.00
2	TO DISMANTLE AND REFIT TAILGATE COMPONENTS }	New	80.00	-
3	TO PUTTY & SPRAY PAINTING ON ACCIDENT DAMAGED PORTION	New	300.00	200.00
4	TO DISMANTLE AND REFIT REAR WINDSCREEN	New	120.00	120.00
Gross Labour Cost (S\$)			850.00	520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >