

22/03/2002

ASS. REC. BY:

REF:

CS/FCI18021134/Ktd3

Special Instruction:

Surveyor:

CNS

ASSIGNMENT (Office)

From (Person):

Serene Ler

of

FCI

Date/Time: 22/11/18 @ 12.30pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SGL 1204B

Insured:

SHA 8789E

at Workshop m/s

C.S. Ong

Tel:

64841933

of

10 AMK Ind. Park 2A #02-16

Policy No:

Claim No:

D18008271MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 21/11/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 12:48pm @ 22/11/18

Person Contacted:

Jun Wu

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SGL1204B -X
	SHA 8789E - NS/INC17012706/M1vbe2 DOA: 24/6/17
29/11	11pm @ 265d email & confirm (Red: 1467.70; 35%)

REF:

PCI

ASSIGNMENT

From:

Date: 26/11/18

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SGL1204B

at Workshop n/s: C.S. Ong

of 10 Amk Ind. Park 2A # 02-16

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$18k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'up'

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGL 1204B

Yr Regn:

09 / 06

Type: ☒ M. Car / ☐ M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic

C.C.

1595

Colour:

A. Silver

A/C:

Insured / Std / NI / NA

Sp Reading:

170174

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMI-D 462 0658200143

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

R/Bal.

mm

Rear

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

21/11/18

D.O.I.

26/11/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/11 File parts continue work

RECEIVED 30 NOV 2018

Date/Time, File Pass to?

1) 30/11 Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I: (\$) 2650/-



Preli. Report



Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation

) \$ + R5.00

) Photos

) Others

TOTAL

160

50

50

20

280

MOTOR SURVEY ASSIGNMENT

Date	21-11-2018	Our Ref No. D18008271MFSH
Accident Date	21-11-2018	Claim Type. Third Party
Insured Vehicle	SHA8789E	Third Party Vehicle. SGL1204B
Survey Location	10 ANG MO KIO IND PARK 2A #02-16 AMK AUTO POINT	
Contact Person.	HUILING	
Contact No.	64841933/ 0	Fax No. 64841922
Survey Type	WITHOUT PREJUDICE: NO EST. COR	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	C.S. ONG AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	RIAZ LLC	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Not Authorized
 61 Lm @ 2650p
 Missing After Repair
 5 days

C. S. ONG AUTO PTE. LTD.

Business.Reg.No.: 201408916W

GST Reg.No.: 201408916W

10, Ang Mo Kio Ind. Park 2A, #02-16 AMK Autopoint, Singapore (568047).

Tel: 6484 1933 Fax: 6484 1922

E-Mail: csongauto@yahoo.com.sg

To: Motor Claims Department,
 MS FIRST CAPITAL INSURANCE LIMITED

Date: 21-11-2018

Accident Involving Vehicles SKX2230H & SHA8789E [Your Insured] on 21/11/2018 @
 0930Hrs along CHOA CHU KANG DRIVE

Estimated Repair Costs For SGL1204B [Honda Civic] JHMFD46206S100143

1Pc	Rear Bumper	\$ ^B 738.00 ✓
1Set	Rear Bumper Clips	\$ ^{nc} 40.00 ✓
2Pcs	Rear Bumper Side Retainer LH & RH @ \$24.90 Each	^{misc} \$ 49.80 ✓
1Pc	Rear End Panel	\$ ^B 350.50 ✓
1Set	Rear End Panel Inner Top Garnish with Clips	ⁿⁿ \$ 65.10 X
2Pcs	Rear Headlamp RH & LH (Fender) @ \$256.80 Each	^{sn} \$ 513.60 X
2Pcs	Rear Tail Lamp RH & LH (Bootlid) @ \$168.90 Each	^{sn} \$ 337.80 X
2Pcs	Rear Tail Lamp Bracket RH & LH @ \$20.90 Each	\$ ^{sn} 41.80 X
1Pc	Rear Bootlid	^B \$ 650.70 ✓
1Pc	Rear BootLid Inner Weatherstrip Rubber	^{sn} \$ 107.60 X
1Set	Rear Boot Lid Inner Lock Assy	ⁿ \$ 95.10 X
1Pc	Rear Boot Lid Striker Lock	ⁿ \$ 37.50 X
1Pc	Rear Boot Lid No Plate Garnish	\$ ^{sn} 151.60 X
1Pc	Rear BootLid "Honda" Emblem	\$ ^{nc} 35.70 ✓
1Pc	Rear Windscreen Mldg	\$ ⁿⁿ 60.00 X
1Pc	Rear LH Fender	\$ ⁿ 781.50 X
1Pc	Rear LH Fender Shield	\$ ^{sn} 26.40 X
1Set	Rear LH Fender Shield Clips	\$ ⁿⁿ 35.00 X
Total:		\$ 4,117.70
Parts Less (20%)		\$ 823.54
Parts Total:		\$ 3,294.16

Special Nett. Items

2Pcs	Rear Bumper Reverse Sensors @ \$150.00 Each	^{short} \$ 300.00 ^{200sn}
1Set	Rear End Panel Sealants	ⁿⁿ \$ 150.00 30%
1Pc	Rear Windscreen Sealant.	ⁿⁿ \$ 100.00 X
1Set	Rear Number Plate with Holder	^{sn} \$ 100.00 X
Special Nett. Items Total:		\$ 650.00

Labour & MISC Charges

* To remove all interior upholstery items on all rear affected areas to facilitate repair and to replace all back once repair is done.	\$	200.00	60/
* To cut out rear bumper, rear end panel, lamp panel, repair RH Fender, reweld, replace new parts and realign all the above.	\$	1,800.00	700/
* To remove and refit rear windscreen to facilitate repair.	<i>nn</i> \$	200.00	X
* To putty and re-spray new paintwork on all rear affected areas.	\$	1,800.00	800/
* To refit & re-check New Rear Reverse Sensors on New Rear Bumper.	\$	150.00	50/
* To check all wiring systems on all affected areas.	\$	150.00	20/
* To apply anti-rust agent & coating on all affected areas.	\$	200.00	30/
Labour & MISC Charges Total:	\$	4,500.00	

Parts Total:	\$	4,117.70
Special Nett. Items Total:	\$	650.00
Labour & MISC Charges Total:	\$	4,500.00
Grand Total:	\$	9,267.70

8444.16

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18021134/Ktd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 30-11-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8789E	Veh. Inspected	SGL 1204B	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008271MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	22/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC (A)	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	JHMFD46206S200143	Colour	METALLIC SILVER	
Odometer	170174	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	CONTINENTAL	8 mm	
L/H Front Tyre	205/55 R16	CONTINENTAL	8 mm	
R/H Rear Tyre	205/55 R16	CONTINENTAL	8 mm	
L/H Rear Tyre	205/55 R16	CONTINENTAL	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/11/2018	Inspection Date	26/11/2018	
Survey held at	C. S. ONG AUTO PTE LTD BLOCK 10 ANG MO KIO IND PK 2A #04-01/#03-11 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGL 1204B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BENT	738.00	738.00
1	SET REAR BUMPER CLIPS	NECESSARY	40.00	40.00
2	REAR BUMPER SIDE RETAINER LH & RH @\$24.90	N/S CRACKED	49.80	24.90
1	REAR END PANEL	BENT	350.50	350.50
1	SET REAR END PANEL INNER TOP GARNISH WITH CLIPS	NOT NECESSARY	65.10	-
2	REAR LAMP RH & LH (FENDER) @\$256.80	SERVICEABLE	513.60	-
2	REAR TAIL LAMP RH & LH (BOOTLID) @\$168.90	SERVICEABLE	337.80	-
2	REAR TAIL LAMP BRACKET RH & LH @\$20.90	SERVICEABLE	41.80	-
1	REAR BOOTLID	BENT	650.70	650.70
1	INNER WEATHERSTRIP RUBBER	SERVICEABLE	107.60	-
1	SET REAR BOOT LID INNER LOCK ASSY	TO REPAIR SEE LABOUR	95.10	-
1	REAR BOOT LID STRIKER LOCK	TO REPAIR SEE LABOUR	37.50	-
1	REAR BOOT LID NO PLATE GARNISH	SERVICEABLE	151.60	-
1	REAR BOOT LID "HONDA" EMBLEM	NECESSARY	35.70	35.70
1	REAR WINDSCREEN MLDG	NOT NECESSARY	60.00	-
1	REAR LH FENDER	TO REPAIR SEE LABOUR	781.50	-
1	REAR LH FENDER SHIELD	SERVICEABLE	26.40	-
1	SET REAR LH FENDER SHIELD CLIPS	NOT NECESSARY	35.00	-
	LESS 20% DISCOUNT		-823.54	-367.96
			3,294.16	1,471.84
SPECIAL NETT ITEMS				
2	REAR BUMPER REVERSE SENSORS @\$150.00 (SN)	SHORTED	300.00	200.00
1	SET REAR END PANEL SEALANTS (SN)	NECESSARY	150.00	30.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	100.00	-
1	SET REAR NUMBER PLATE WITH HOLDER (SN)	SERVICEABLE	100.00	-
			650.00	230.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS ON ALL REAR AFFECTED AREAS TO FACILITATE REPAIR AND TO REPLACE ALL BACK ONCE REPAIR IS DONE.		200.00	60.00
	TO CUT OUT REAR BUMPER, REAR END PANEL, LAMP PANEL, REPAIR RH FENDER, REWELD, REPLACE NEW PARTS AND REALIGN ALL THE ABOVE. INCLUSIVE OF THE REPAIR OF SET REAR BOOT LID INNER LOCK ASSY, REAR BOOT LID STRIKER LOCK AND REAR LH FENDER.		1,800.00	700.00
	TO REMOVE AND REFIT REAR WINDSCREEN TO FACILITE REPAIR.	NOT NECESSARY	200.00	-
	TO PUTTY AND RE-SPRAY NEW PAINTWORK ON ALL REAR AFFECTED AREAS.		1,800.00	800.00
	TO REFIT & RE-CHECK NEW REAR REVERSE SENSORS ON NEW REAR BUMPER.		150.00	50.00
	TO CHECK ALL WIRING SYSTEMS ON ALL AFFECTED AREAS.		150.00	20.00
	TO APPLY ANTI-RUST AGENT & COATING ON ALL AFFECTED AREAS.		200.00	30.00
			4,500.00	1,660.00
	GRAND TOTAL		8,444.16	3,361.84
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,650.00

Report Ref No. CS/FC118021134/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.