

22/03/2002

ASS. REC. BY:

REF:

CS/CNB18021154 / Ngber

Special Instruction:

Surveyor:

Ngz

ASSIGNMENT (Office)

From (Person):

Muhammad Hafiz

of

CNB

Date/Time:

14.11.2018 9:02am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GX 1282 T

Insured:

SLB 7598D

at Workshop m/s

Atstop

Tel:

9364 0007 / 9818 1144 (Alvin)

of

17 Kaki Bukit Rd 4 #01-58

Policy No:

Claim No:

HOMCNBEP018301041

Sum Insured:

Excess:

Make of Veh:

D.O.A.

24.10.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS WP

23-11-2018

H.O.D. Endorsement:

Date/Time:

22.11.2018 1:15pm

Person Contacted:

Eddy

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLB 7598D - X
	SL 9173U - X
	No such vehicle. plz check
	Material Parts: B2522.85; Man hrs: 20 hrs.

Surveyor: NAZ REF: CNB

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: \_\_\_\_\_  
at Workshop m/s PITSTOP  
of 23 SUNGEI KADUT DRIVE  
Insured: ALVIN 98181144  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: 4 days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

N/S	O/S

Veh No: SLS 7598D Yr Regn: 1  
Type: M.Car / M.Cycle / BUS / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_  
Make: MAZDA 6 C.G. - \_\_\_\_\_  
Colour: GREY A/C: Insured / Std / NI / NA  
Sp. Reading: \_\_\_\_\_ T/Radi: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: 2  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: Inorder / Jammed / Leaked / Burnt or  
Brake: Inorder / Jammed / Leaked / Burnt or  
Modl: NII / S/Rim / STD A/Rim or  
Tyre Size: F: 225 155 R17  
R: 11  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or \_\_\_\_\_  
Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.I. \_\_\_\_\_ D.O.I. 23/11/18  
Survey held at PITSTOP  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Repair range \$3.5K - \$4.5K

RECEIVED 05 DEC 2018

Date/Time, File Pass to?

1) 05/12/18

Date/Time, File Return to?

2) \_\_\_\_\_

Report Format: \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: \_\_\_\_\_

☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Insp (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

\$ + RS \$ \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL

200

200

## Catherine Chong (LKK Auto)

---

**From:** Olivia Lau (LKKAuto) <olivialau@lkkauto.com>  
**Sent:** Thursday, 22 November, 2018 12:49 PM  
**To:** assignments  
**Cc:** SUR  
**Subject:** [CNB]: Assessment for 1 CNB vehicle  
**Attachments:** QX1282T Police report.pdf; QX1282T SOW.revised.xlsx; QX1282T Photos.revised.doc; HOMCNBEPO18301041.PDF

**Importance:** High

Hi Catherine,

Email from 14/11/2018. As spoken – please convey to CNB our correct email address.

Best Regards,

Olivia Lau | Admin Manager

LKK Auto Consultants

phone: 6256-3561 | email: [olivialau@lkkauto.com](mailto:olivialau@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



---

**From:** Muhammad Hafiz ABDUL HASSAN from.TP (CNB)  
[mailto:Muhammad\_Hafiz\_ABDUL\_HASSAN\_from.TP@cnb.gov.sg]  
**Sent:** Wednesday, 14 November, 2018 9:02 AM  
**To:** assessments@lkkauto.com  
**Cc:** Olivia Lau (LKKAuto) <olivialau@lkkauto.com>; Shirlene YEO (CNB) <Shirlene\_YEO@cnb.gov.sg>; Aden POT (CNB) <Aden\_POT@cnb.gov.sg>  
**Subject:** FW: Assessment for 1 CNB vehicle  
**Importance:** High

### *Message Classification: Unclassified*

Dear Sir / Madam,

Please note that there has been a change in location of the vehicle.

Vehicle location is at:-

Pit Stop @ Bartley  
17 Kaki Bukit Road 4 #01-58/59/60/61/62  
Bartley BizCentre S417809

Contact person: Eddy hp no: 93690007

Thanks and regards,

**Muhammad Hafiz**  
Logistics, Corporate Services Division  
DID: (65) 63256595  
Central Narcotics Bureau



**HOME TEAM**  
TRANSFORMATION 2025  
One Home, One Team  
Building Our Future Together

*Keeping Singapore Drug-Free*

**Central Narcotics Bureau** W [cnb.gov.sg](http://cnb.gov.sg) FB [fb.com/CNB.DrugFreeSG](https://fb.com/CNB.DrugFreeSG) IG [Instagram.com/cnb.drugfreesg](https://Instagram.com/cnb.drugfreesg)

**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

---

**From:** Muhammad Hafiz ABDUL HASSAN from.TP (CNB)  
**Sent:** Friday, 9 November 2018 2:54 PM  
**To:** 'assessments@lkkauto.com' <[assessments@lkkauto.com](mailto:assessments@lkkauto.com)>  
**Cc:** 'Olivia Lau (LKKAuto)' <[olivialau@lkkauto.com](mailto:olivialau@lkkauto.com)>; Shirlene YEO (CNB) <[Shirlene\\_YEO@cnb.gov.sg](mailto:Shirlene_YEO@cnb.gov.sg)>; Aden POT (CNB) <[Aden\\_POT@cnb.gov.sg](mailto:Aden_POT@cnb.gov.sg)>  
**Subject:** Assessment for 1 CNB vehicle

Dear Sir / Madam,

Please assist to provide us with an assessment on the following CNB vehicle with details as attached and shown below.

1. Vehicle Number: QX1282T
2. Make and Model of the Vehicle: Mazda 6 Sedan 2.0L
3. Location/address of the vehicle: 2B Sungei Kadut Dr. Singapore 729555
4. Contact person : Mr. Alvin, H/P : 9818 1144

Please note that we have already raised a PO (attached) for this quotation. The PO number is HOMCNBEPO18301041.

Thanks and Regards,

**Muhammad Hafiz**  
Logistics, Corporate Services Division  
DID: (65) 63256595  
Central Narcotics Bureau



**HOME TEAM**  
TRANSFORMATION 2025  
One Home, One Team  
Building Our Future Together

*Keeping Singapore Drug-Free*

**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



**Scope Of Work**  
**Home Team Agency**

**SCOPE OF WORK**

1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR :	SMRT	VEH TYPE :	MARKED CAR	UNIT :	CNB HQ	Reference No.	1282/CNB/4W/18/10/06
VEH NO :	QX1282T	REPAIR TYPE :	ACCIDENT				
VEH MAKE/MODEL :	MAZDA 6	ODOMETER :	10774			iLMS No.	-

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1	<b>Scope Of Repairs</b>					
1.1	Rear Bumper	\$500.00	1	21%	605.00	605.00
1.2	Rear Bumper Reinforcement	\$245.00	1	21%	296.45	296.45
1.3	Rear End Panel	\$380.00	1	21%	459.80	459.80
1.4	Rear End Panel Garnish	\$110.00	1	21%	133.10	133.10
1.5	Boot Lid Cover	\$550.00	1	21%	665.50	665.50
1.6	Boot Lid Cover Hinges (Left & Right)	\$145.00	2	21%	175.45	350.90
1.7	Rear LH Bumper Tow Eye Cover	\$35.00	1	21%	42.35	42.35
1.8	Rear Number Plate with Casing	\$50.00	1	21%	60.50	60.50
1.9	LHS Boot Lid Cover Tail Lamp	\$215.00	1	21%	260.15	260.15
1.10	RHS Boot Lid Cover Tail Lamp	\$215.00	1	21%	260.15	260.15
2	<b>Additional Services</b>					
2.1	NA	\$0.00	0	0%	0.00	0.00
<b>Remarks:</b>					<b>Parts Total:</b>	<b>\$ 3,133.90</b>

DEF  
BT  
DD  
DEF  
DEF  
XSVL  
MIS  
MIS  
CRK  
XSVL

2522.85

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1	<b>Scope Of Repairs</b>			
1.1	<b>Rear Bumper:</b>	68.00	5	340.00
	Remove & Replace Rear Bumper			
	Remove & Re-Install Reverse Sensor onto new Rear Bumper			
	Putty & Spray Paint for Rear Complete Bumper			
1.2	<b>Rear Bumper Reinforcement:</b>	68.00	6	408.00
	Remove & Replace Rear Bumper Reinforcement			
1.3	<b>Rear End Panel &amp; Rear End Panel Garnish:</b>	68.00	8	544.00
	Remove & Replace Rear End Panel			
	Remove & Replace Rear End Panel Garnish			
1.4	<b>Boot Lid Cover &amp; Rear Number Plate:</b>	68.00	6	408.00
	Remove & Replace Both Side Boot Lid Cover Hinges			
	Remove & Replace Boot Lid Cover			
	Replace Rear Number Plate			
	Putty & Spray Paint for Boot Lid Cover			
1.5	<b>Boot Lid Cover Tail Lamp:</b>	68.00	2	136.00
	Remove & Replace Both Side Boot Lid Cover Tail Lamp			
	Wiring for Both Side Boot Lid Cover Tail Lamp			
<b>SUB-TOTAL</b>				<b>27 1836.00</b>
2	<b>Additional Services</b>			
2.1	Towing Service From Station to Workshop (SOR 10)	176.80	1	176.80
2.2	Return Service From Workshop to Station (SOR 9)	61.20	1	61.20
<b>SUB-TOTAL</b>				<b>2 238.00</b>
<b>Labour Total:</b>				<b>\$ 2,074.00</b>
<b>GRAND TOTAL :</b>				<b>\$ 5,207.90</b>
<b>Total sum billed under SOR only :</b>				<b>\$ 238.00</b>
<b>Total sum billed under CVR only :</b>				<b>\$ 4,969.90</b>
Contractor shall complete the entire repair within <u>18</u> working days upon approval date . (Include parts awaiting time)				

3 204

4 272

7 476

4 272

2 136

20 1,360

7

<b>Verification of Scope of Work</b>					
Contractor QC		Vetted By:		Approved By:	
Name:	KONG SEW KUI	Name:		Name:	
Date:	02.11.2018	Date:		Date:	
Sign:		Sign:		Sign:	

3/12/18

Verification of Completed Repairs					
Contractor QC		Home Team QC / Fleet Manager / Appointed Surveyor		Home Team Contract / Fleet Manager	
Name:		Name:		Name:	
Date:		Date:		Date:	
Sign:		Sign:		Sign:	
All completed repairs must be verified by Home Team Contract Manager / Fleet Manager before payment can be made					

## CVR Accident Photos



### VEHICLE DETAIL

Vehicle No	QX1282T	Date Of accident	
Date Booked In		Date of Submission	











### REPAIR DESCRIPTIONS

1. Remove Rear Bumper (Pic 1-4)
2. Remove Reverse Sensor to facilitate repair works
3. Remove Rear Bumper Reinforcement (Pic 6)
4. Remove Rear End Panel (Pic 7)
5. Remove Rear End Panel Garnish (Pic 8)
6. Remove Boot Lid Cover (Pic 9-12)
7. Remove Both Side Boot Lid Cover Hinges (Pic 11-12)
8. Remove LHS Boot Lid Cover Tail Lamp (Pic 14)
9. Remove RHS Boot Lid Cover Tail Lamp (Pic 15)
10. Replace Rear Bumper (Pic 1-4)
11. Re-Install back Reverse Sensor onto new Rear Bumper
12. Replace Rear LH Bumper Tow Eye Cover (Pic 5)
13. Replace Rear Bumper Reinforcement (Pic 6)
14. Replace Rear End Panel (Pic 7)
15. Replace Rear End Panel Garnish (Pic 8)
16. Replace Boot Lid Cover (Pic 9-12)
17. Replace Both Side Boot Lid Cover Hinges (Pic 11-12)
18. Replace Rear Number Plate (Pic 13)
19. Replace LHS Boot Lid Cover Tail Lamp (Pic 14)
20. Replace RHS Boot Lid Cover Tail Lamp (Pic 15)
21. Wiring for LHS & RHS Boot Lid Cover Tail Lamp (Pic 14-15)
22. Align Boot Lid Cover
23. Putty & Spray Paint for Rear Complete Bumper (Pic 1-4)
24. Putty & Spray Paint for Boot Lid Cover (Pic 9-12)




### PHOTOS OF DAMAGED PARTS

Rear Bumper Dented (Pic 1)	Rear Bumper Dented (Pic 2)
	
Rear Bumper Dented (Pic 3)	Rear Bumper Dented (Pic 4)

## CVR Accident Photos

 <p>Rear Bumper Dented</p>	 <p>Rear Bumper Dented</p>
Rear LH Bumper Tow Eye Cover Missing (Pic 5)	Rear Bumper Reinforcement Missing (Pic 6)
 <p>Rear LH Bumper Tow Eye Cover Missing</p>	 <p>Rear Bumper Reinforcement Dented</p>
Rear End Panel Dented (Pic 7)	Rear Bumper Reinforcement Dented (Pic 8)
 <p>Rear End Panel Dented</p>	 <p>Rear End Panel Garnish Dislodged</p>
Rear End Panel Dented (Pic 9)	Rear End Panel Garnish Dislodged (Pic 10)
 <p>Boot Lid Cover Dented</p>	 <p>Boot Lid Cover Dented</p>
Boot Lid Cover Dented (Pic 11)	Boot Lid Cover Dented (Pic 12)
 <p>Boot Lid Cover Misaligned</p>	 <p>Boot Lid Cover Misaligned</p>
Rear Number Plate Dislodged (Pic 13)	LHS Boot Lid Cover Tail Lamp Cracked (Pic 14)

## CVR Accident Photos



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CENTRAL NARCOTICS BUREAU

Ref : CS/CNB18021154/Nqbe2

CORPORATE SERVICES DIVISION

BLK B POLICE CANTONMENT COMPLEX 393 NEW Date : 05-12-2018

BRIDGE ROAD SINGAPORE 088763

ATTN : MUHAMMAD HAFIZ

Code : CNB



## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLS 7598D	Veh. Inspected	QX 1282T
Policy No.		Coverage (\$)	0.00
Claim No.	HOMCNBEP018301041	Excess (\$)	0.00
Assign From	MUHAMMAD HAFIZ	Assign Date	14/11/2018

## 2. Vehicle Particulars & Condition

Make & Model	MAZDA 6	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	JM6GL1071H0108302	Colour	GREY
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R17	TOYO	6 mm
L/H Front Tyre	225/55 R17	TOYO	6 mm
R/H Rear Tyre	225/55 R17	TOYO	6 mm
L/H Rear Tyre	225/55 R17	TOYO	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

## 5. General Information

Accident Date	24/10/2018	Inspection Date	23/11/2018
Survey held at	2B SUNGEI KADUT DRIVE		
Repairer	PITSTOP GARAGE		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------

Registration No. QX 1282T

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
<b>1</b>	<b>MATERIALS</b>					
1.1	REAR BUMPER	1	DEFORMED	\$605.00	\$605.00	
1.2	REAR BUMPER REINFORCEMENT	1	BENT	\$296.45	\$296.45	
1.3	REAR END PANEL	1	DENTED	\$459.80	\$459.80	
1.4	REAR END PANEL GARNISH	1	DEFORMED	\$133.10	\$133.10	
1.5	BOOT LID COVER	1	DEFORMED	\$665.50	\$665.50	
1.6	BOOT LID COVER HINGES (LEFT & RIGHT)	2	SERVICEABLE	\$350.90	\$0.00	
1.7	REAR LH BUMPER TOW EYE COVER	1	MISSING	\$42.35	\$42.35	
1.8	REAR NUMBER PLATE WITH CASING	1	MISSING	\$60.50	\$60.50	
1.9	LHS BOOT LID COVER TAIL LAMP	1	CRACKED	\$260.15	\$260.15	
1.10	RHS BOOT LID COVER TAIL LAMP	1	SERVICEABLE	\$260.15	\$0.00	
<b>2</b>	<b>SCOPE OF REPAIRS</b>					
<b>1.1</b>	<b>REAR BUMPER :</b>					<b>3</b>
	Remove & Replace Rear Bumper					
	Remove & Re-install Reverse Sensor onto new Rear Bumper					
	Putty & Spray Paint for Rear Complete Bumper					
<b>1.2</b>	<b>REAR BUMPER REINFORCEMENT :</b>					<b>4</b>
	Remove & Replace Rear Bumper Reinforcement					
<b>1.3</b>	<b>REAR END PANEL &amp; REAR END PANEL GARNISH :</b>					<b>7</b>
	Remove & Replace Rear End Panel					
	Remove & Replace Rear End Panel Garnish					
<b>1.4</b>	<b>BOOT LID COVER &amp; REAR NUMBER PLATE :</b>					<b>4</b>

	Remove & Replace Both Side Boot Lid Cover Hinges					
	Remove & Replace Boot Lid Cover					
	Replace Rear Number Plate					
	Putty & Spray Paint for Boot Lid Cover					
<b>1.5</b>	<b>BOOT LID COVER TAIL LAMP :</b>					<b>2</b>
	Remove & Replace Both Side Boot Lid Cover Tail Lamp					
	Wiring For Both Side Boot Lid Cover Tail Lamp					
<b>COSTING</b>		<b>TOTAL PARTS COST</b>			<b>\$2,522.85</b>	
		<b>TOTAL MAN-HOUR</b>				<b>20</b>

Vehicle Inspected By

MUHD NAZRIL (NAZ)

*Technical Investigator*

*LL.B. (Hons) London*

ADRIAN LING WAI PING

*B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI*

*Licensed Appraiser*

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.