



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	1 2010 BMW 135 I (SJZ8668R)
Date of Loss	18 November 2018
Time of Loss	16.30
Loss Description	SJZ8668R (INSD) C/W SJY7240C (TP)
Comment	

Workshop Details

Total Rebate Amount	32701
Nett Loss Amount	\$12,299.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (OD)
Days of work completion *	111



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SJZ8668R

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

20/07/2010



Mileage

84984

Age of Vehicle

8

CATEGORY

POLICY INFORMATION

ASSESSMENT
INFORMATIONManufacturing
Year

2010

2010

Make

BMW

B.M.W.

Model

135 I

135I M A

Driver Details

CATEGORY

FNOL INFORMATION

POST SURVEY
INFORMATION

Driver Name

SOMSAMAI KAEWSUWAN

Date of Birth

1 October 1975

dd/mm/yyyy



Age

43

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Female	
Marital status	Unknown	
Identification #	S7562816A	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

23/11/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

400

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

225/40ZR18

Rear Tyre Size

245/35ZR18

Front left side

MICHELIN8mm

Rear left side

MICHELIN5mm

Front right side

MICHELIN8mm

Rear right side

MICHELIN5mm



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1			FRONT BUMPER (WCP) (COST PLUS 10%)			Cracked	1227.6				1227.6	Reviewing	
		2	1			FRONT HEADLAMP LH (WCP) (COST PLUS 10%)			Cracked	2214.3				2214.3	Reviewing	
		3	1			FRONT HEADLAMP BRACKET LH (WCP) (COST PLUS 10%)			Cracked	69.3				69.3	Reviewing	
		4	1			FRONT SENSOR REVERSE			Serviceable	0	0	0	0	0	Deny	
		5	1			FRONT FENDER LH (WCP) (COST PLUS 10%)			Bent	581.9				581.9	Reviewing	
		6	1			FRONT FENDER INNER SHIELD (WCP) (COST PLUS 10%)			Cracked	165				165	Reviewing	

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	7	1			FRONT FENDER WHEEL HOUSE LH			Repair	0	0	0	0	0	Deny	
	8	1			FRONT BUMPER RENTANNER LH (WCP) (COST PLUS 10%)			Damaged	30.8				30.8	Reviewing	
	9	1			FRONT RIM LH (WCP) (COST PLUS 10%)			Dented	528				528	Reviewing	
	10	1			FRONT RIM LOGO COVER LH (WCP) (COST PLUS 10%)			Dented	16.5				16.5	Reviewing	
	11	1			FRONT TYRE LH			Serviceable	0	0	0	0	0	Deny	
	12	1			FRONT KNUCKER ARM LH			Serviceable	0	0	0	0	0	Deny	
	13	1			FRONT WHEEL HUP LH (WCP) (COST PLUS 10%)			Bent	139.7				139.7	Reviewing	
	14	1			FRONT LOWER AMP LH (WCP) (COST PLUS 10%)			Damaged	89.1				89.1	Reviewing	
	15	1			FRONT ABSORBER LH			Serviceable	0	0	0	0	0	Deny	

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		16	1			FRONT TIE ROD LH (WCP) (COST PLUS 10%)			Bent	165				165	Reviewing	
		17	1			FRONT TORSION BAR LINK LH (WCP) (COST PLUS 10%)			Damaged	41.8				41.8	Reviewing	

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		TO CHECK WIRING AND SYSTEM FUNCTION	20	0	0	Reviewing		
		2		TO WHEEL ALIGMENT	60	0	0	Reviewing		
		3		TO CUTING, WELDING, KNUCKING AND REMOVE AND REFIX UNDERCARRIAGE	500	0	0	Reviewing		
		4		TO RESPRAY ACCIDENT PORTION	500	0	0	Reviewing		

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Add

Approve

Deny

Submit All



1

DAYS OF REPAIR : 5 DAYS

Reviewing



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount
\$5,949.00

Claim Amount
\$5,949.00

Spare Parts

\$5,269.00

\$5,269.00

Labour

\$1,080.00

\$1,080.00

Excess

-\$400.00

-\$400.00

Submit for Review