

22/03/2003

ASS. REC. BY:

REF: CS3/MSG18017951/Gqo-1²²

Special Instruction:

Surveyor:
Mannan

Guo Qiang

ASSIGNMENT (Office)

From (Person):

Christine Wong

of

MSG

Date/Time: 22.11.2018

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGZ 72624

Insured:

PC 1587L

at Workshop m/s

Eng Shing Mechanical

Tel:

64537380

of

160 Sin Ming Drive # 06-21

Policy No:

A275883091MV

Claim No:

M571918

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/09/2018

4/10/2018

CA / REV / REP: / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time:

5:28pm @ 31/10/18

Person Contacted:

Mr. Tan

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate	Do Not Finalize
	SGZ 72624 - NA / MSG18017709 / h1	DOA: 29/9/18
	PC 1587L - NA / MSG18017709 / h1	DOA: 29/9/18
06/12/18	submit LS & 4000; 5 days	
	(Red \$ 2050, 34%)	

RECEIVED 07 DEC 2018

6/12/2018

PRS
Ked.

REF: MSIG

0113J

ASSIGNMENT

(-2027)
14 Nov 2007

From: Date: 4/10/18
Estimated Cost:
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No. SQZ 7262 U
at Workshop m/s Eng Shing Mechanical
of 160 Sin Ming Drive #06-21
Insured:
Policy No.
Claims No.
Sum Insured: Excess:
(Client's Record)
Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$52k
IDAC Accident Report: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: 5 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS lup

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: 562 72624 Yr Regn: 14 Nov 2007
Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: Honda Stream c.c. 1799
Colour: Grey A/C: Insured / Std / NI / NA
Sp. Reading: 23667 T/Radio: Insured / Std / NI / NA

Eng/No:
C/No: RN61050664

Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / Rim or

Tyre Size: F: 265/50 R17
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. D.O.I. 04-10-18

Survey held at w/s 4:15 pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$3000 \$4000

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) Date/Time, File Return to?
2)

Days Of Repair: 5

Resurvey No. of Trip: -

Survey Fee:

Transportation

___ \$ + R\$ ___ \$

) Photos

) Others

TOTAL

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format: PRE

Lump Sum / I.B.I. (\$))

120

10

130

Catherine Chong (LKK Auto)

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Thursday, 22 November, 2018 5:37 PM
To: Christina Wong; assignments
Subject: RE: Our ref:M571918 Your Ref:SGZ7262U - Paper survey is need URGENTLY

Dear Christina,

Thank you for the email.

Dear Assignment Team,

FYNA

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Christina Wong <Christina_Wong@sg.msig-asia.com>
Sent: Thursday, 22 November 2018 4:45 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: Our ref:M571918 Your Ref:SGZ7262U - Paper survey is need URGENTLY

Hi Veron

Please do paper survey there are another 2more photos attachments.

Best Regards

Christina Wong
Senior Executive, Claims Services (Motor) Direct line +65 6643 1311 | Direct fax +65 6225 7402 |
christina_wong@sg.msig-asia.com

MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us on

-----Original Message-----

From: ApeosPort-VI C5571 [mailto:24Flr_CLP-Mtr@sg.msig-asia.com]
Sent: Thursday, 22 November, 2018 4:22 PM
To: Christina Wong <Christina_Wong@sg.msig-asia.com>
Subject: Scan Data from FX-126223

Number of Images: 7
Attachment File Type: PDF

Device Name: ApeosPort-VI C5571
Device Location:

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Oct 2018		03 Oct 2018 16:08 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main		Reference		Claim Details		Documents		Show All																					
CLAIM SUBFOLDER DETAILS								[Created by insurer]																					
Insured:		WILLING HEARTS, Co. Reg. No.: -																											
Main Claimant:		TEE KIM TECK ADRIAN, ID: S7010113J																											
Vehicle Reg. No.:		SGZ7262U		Date of Loss:		29/09/2018 14:00 - :59 [130 Months and 15 Days From LTA Reg Date (Man Yr)]																							
Claim Type:		TP / 571918		Policy/Cover Note No.:		A27588309TMV (Third Party Only) Coverage: 31/10/2017 - 30/10/2018																							
Vehicle Reg. No. (Insured):		PC1587L		Policy No. (Claimant):																									
				Excess:																									
Repairer:		Eng Shing Mechanical Works (HQ) 160 Sin Ming Drive, #06-21 Sin Ming Autocity, 575722 Sin Ming - Tel: 64537380																											
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]																											
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 26/11/2018]																											
Driver/Custodian (Insured):		TEO TEE CHUAN (), NRIC: S6825894D, Tel: +6597806131																											
Adj Asg. Remarks:		on WP. Liability 100%. TP disagree with our SJE list, proceed to appoint LKK Auto Consultants. Contact No: 6453-7380																											
ASSOCIATED MAIL RECEIVED								View All Compose Case Mail																					
<ul style="list-style-type: none"> MSIG_SG (22/11/2018): Report Send Back Alerts - SGZ7262U (TP) 																													
<div> <div> <div>ALL ASSOCIATED TASKS</div> <div> <div>View All</div> <div>Search Tasks</div> <div>Create New Task</div> <div>Complete</div> </div> </div> <table> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> <tr> <td colspan="10">No results.</td> </tr> </table> </div>										Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?																				
No results.																													



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0413 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Vehicle Inspection Report

To: Tee Kim Teck Adrian
101 Bishan Street 12 #09-286
Singapore 570101

Date of report: 17.10.2018
Date of request: 01.10.2018
Date of inspection: 01.10.2018
Date of accident: 29.09.2018
Claim type: Third Party Claim

Report No: AAS/2018/418

Particulars of affected vehicle:

Registration no: SGZ7262U
Make/Model: Honda Stream RSZ (A)
Year of registration: 2007
Colour: Metallic Brown

Odometer: 213667 km
Engine Capacity: 1799 cc
Engine no: R18A1756459
Chassis no: RN61050664

Condition of tires:

Front Left: 6mm
Make: Yokohama
Rear Left: 6mm
Make: Yokohama

Front Right: 6mm
Make: Yokohama
Rear Right: 6mm
Make: Yokohama

Type of road wheel: Alloy (The above represent the remaining life of the tire thread)

Pre-accident condition (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : In order
Footbrake : In order
Steering : In order
Apparent engine modification : Nil

The Assignment

The inspection was conducted at M/s. Eng Shing Mechanical Works
160 Sin Ming Drive #06-21
Sin Ming AutoCity (S) 575722

(Subsequent inspection was conducted)

Assessment

Repairer's estimate: \$ 10,345.68
Revised estimate: \$ 7,532.48
Recommended reserve: \$ 6,050.00 (Lump sum)

Estimated normal duration of repairs : 8 Working days



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0413 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Vehicle No: SGZ7262U

Report No: AAS/2018/418

W/O PREJUDICE

Point of impact

At the rear portion.

General description of damages

The tailgate, RH tail lamp, rear bumper, exhaust silencer, rear end panel, floor panel, etc.

Other parts were also found damaged. (See schedule for details)

Recommendation

The estimate cost of repair submitted by M/s Eng Shing Mechanical Works as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$7,532.48

Conclusion

The repairer has agreed to undertake the repair at a lumpsum of SGD \$6,050.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of 8 working days.

We have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a '**Without Prejudice**' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes 69 photographs.

Your Faithfully
Absolute Appraisal Services Pte Ltd



Nicky Seah
Automobile Appraiser
MSAAA / MSMCTA



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
 160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
 Mobile: 9688-0413 Fax: 6266-7396
 Email: absolute.app.svcs@gmail.com

Vehicle No: SGZ7262U
 Appraisal Schedule

Report No: AAS/2018/418

S/N	Parts Description	Qty	Condition		Repairer's Est	Revised Est
1	Tailgate	1	Dented		\$ 1,235.20	\$ 1,235.20
2	Tailgate glass moulding	1	Necessary		\$ 85.00	\$ 85.00
3	Tailgate outer garnish	1	Cut/Cracked		\$ 250.40	\$ 250.40
4	Tailgate emblem	1	Necessary		\$ 45.30	\$ 45.30
5	Tailgate nameplate 'Stream'	1	Necessary		\$ 53.20	\$ 53.20
6	Tailgate nameplate 'RSZ'	1	Necessary		\$ 72.30	\$ 72.30
7	Tailgate absorber LH/RH	2	Serviceable	\$ 212.60	\$ 425.20	-
8	Tailgate wiper motor	1	Serviceable		\$ 560.60	-
9	Tailgate lock	1	Distorted		\$ 283.30	\$ 283.30
10	Tailgate catch	1	Serviceable		\$ 37.20	-
11	Tailgate trim board	1	Serviceable		\$ 455.70	-
12	Tailgate weather-strip	1	Necessary		\$ 150.60	\$ 150.60
13	Tailgate stopper LH/RH	2	Necessary	\$ 12.50	\$ 25.00	\$ 25.00 XNN
14	Tail lamp LH/RH	2	RH Cracked	\$ 495.60	\$ 991.20	\$ 495.60
15	Rear bumper	1	Dented		\$ 860.70	\$ 860.70
16	Rear bumper tow hook cover	1	Serviceable		\$ 22.30	-
17	Rear bumper side bracket LH/RH	2	Cracked	\$ 45.70	\$ 91.40	\$ 91.40
18	Rear bumper bracket LH/RH	2	Dented - RH, LH - S/C	\$ 40.00	\$ 80.00	\$ 80.00 40
19	Rear panel	1	Dented		\$ 590.30	\$ 590.30 XR
20	Rear panel top cover	1	Cracked		\$ 110.90	\$ 110.90
21	Spare tyre carrier	1	Serviceable		\$ 257.40	-
22	Exhaust silencer	1	Dented/Bent		\$ 865.60	\$ 865.60 XNN
23	Exhaust chrome tip	1	Dented		\$ 113.70	\$ 113.70 CUT
24	Exhaust mountings	2	Torn	\$ 22.30	\$ 44.60	\$ 44.60 XNN
Total:					\$ 7,707.10	\$ 5,453.10
-20%					\$ 1,541.42	\$ 1,090.62
List total:					\$ 6,165.68	\$ 4,362.48
1	Tailgate glass sealant	1	Necessary		\$ 60.00	\$ 40.00
2	Tailgate inner trim clips	1set	Necessary		\$ 50.00	\$ 50.00 30
3	Reverse sensor	1set	Cracked		\$ 300.00	\$ 250.00 200
4	Rear bumper clips	1set	Necessary		\$ 50.00	\$ 50.00 30
5	Joint sealant	1	Necessary		\$ 60.00	\$ 40.00 30
Special nett total:					\$ 520.00	\$ 430.00
Parts Total:					\$ 6,685.68	\$ 4,792.48



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Vehicle No: SGZ7262U

Report No: AAS/2018/418

S/N Labour Description

Repairer's Est

Revised Est

1	Check rear lightings & wirings for proper function.	\$ 50.00	\$ 30.00
2	Remove & transfer tailgate components.	\$ 150.00	\$ 100.00 60
3	Remove & transfer tailgate glass.	\$ 180.00	\$ 150.00 120
4	Drill hole & replace reverse sensors.	\$ 60.00	\$ 40.00
5	Renew exhaust silencer.	\$ 100.00	\$ 80.00 X
6	Anti rust proofing on rear damaged panels.	\$ 100.00	\$ 40.00 X NV
7	Remove & reinstall rear upholsteries to assist repairs.	\$ 120.00	\$ 100.00 60
8	To replace rear damaged parts. Repair, reform, realign all damaged area.	\$ 1,400.00	\$ 1,000.00 600
9	To conduct spray painting on rear replacement & affected area.	\$ 1,500.00	\$ 1,200.00 700
Labour Total:		\$ 3,660.00	\$ 2,740.00

Grand Total: \$ 10,345.68 \$ 7,532.48

The final adjusted lump sum amount is \$6,050.00

Under normal circumstances, the repair should be completed within a reasonable period of 8 working days.

5 days

69 Photographs were taken at the time of inspection.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Oct 2018		03 Oct 2018 16:08 Edit Adj Rpt	S\$4,000.00 Edit Estimates	S\$4,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured: WILLING HEARTS , Co. Reg. No.: -									
Main Claimant: TEE KIM TECK ADRIAN , ID: S7010113J									
Vehicle Reg. No.: SGZ7262U		Date of Loss: 29/09/2018 14:00 - :59 [130 Months and 15 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 571918		Policy/Cover Note No.: A27588309TMV (Third Party Only) Coverage: 31/10/2017 - 30/10/2018							
Vehicle Reg. No. (Insured): PC1587L		Policy No. (Claimant):							
		Excess:							
Repairer: Eng Shing Mechanical Works (HQ) 160 Sin Ming Drive, #06-21 Sin Ming Autocity, 575722 Sin Ming - Tel: 64537380									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 26/11/2018]									
Driver/Custodian (Insured): TEO TEE CHUAN (), NRIC: S6825894D, Tel: +6597806131									
Adj Asg. Remarks: on WP. Liability 100%. TP disagree with our SJE list, proceed to appoint LKK Auto Consultants. Contact No: 6453-7380									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
<ul style="list-style-type: none"> MSIG_SG (22/11/2018): Report Send Back Alerts - SGZ7262U (TP) 									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGZ7262U (571918)
[PC1587L]
TP
TEE KIM TECK ADRIAN
Sep 29 2018 2:00PM
[WILLING HEARTS]
Eng Shing Mechanical Works

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	02/10/18 15:43	Accident Statement <small>From: SC - Reg. No: PC1587L, Claimant: WILLING HEARTS</small>	Load HTM		

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	05/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>	
2	05/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>	
3	05/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>	
4	05/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>	
5	05/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>	
6	05/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>	
7	05/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>	
8	05/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>	
9	05/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>	
10	05/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>	
11	05/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>	
12	05/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>	
13	05/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>	
14	05/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>	
15	05/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>	
16	05/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>	
17	05/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>	
18	05/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>	
19	05/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>	
20	05/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>	
21	05/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>	
22	05/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>	
23	05/10/18 10:18	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>	
24	05/10/18 10:18	Chassis Number	Load JPG	<input checked="" type="checkbox"/>	

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	02/10/18 15:43	SGZ7262U GIA Rpt <small>From: SC - Reg. No: PC1587L, Claimant: WILLING HEARTS</small>	Load PDF		
2	02/10/18 15:46	PRI	Load PDF		
3	22/11/18 16:40	tP survey report & photos	Load PDF		

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	11/12/18 13:47	Colour Photo	Load PDF		
2	11/12/18 13:47	PRS Invoice	Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer
<small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18017951/GQBE2-1

Date: 11/12/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A27588309TMV

Claimant Vehicle No : SGZ7262U

Insured Vehicle No : PC1587L

Date of Loss: 29/09/2018

Nature of Claim: TP

Claim No: 571918

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGZ7262U

Make & Model: HONDA STREAM, 1.8 RSZ (A)

Engine No: R18A1756459

Reg. Date: 14/11/2007 (Man. Year: 2007)

Chassis No: RN61050664

Colour: Grey

Odometer: 213667 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17

Rear Tyre Size: 215/50 R17

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,685.68	3,440.08	3,245.60	48.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,660.00	1,610.00	2,050.00	56.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,345.68	5,050.08	5,295.60	51.19
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	10,345.68	4,000.00	6,345.68	61.34

INSPECTION

Date of Assignment: 03/10/2018

Date Inspected: 04/10/2018 Inspected At:

Eng Shing Mechanical Works (HQ)
160 Sin Ming Drive, #06-21 Sin Ming
Autocity
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Dec 2018)
Parts: M1-MPV	HONDA STREAM 1.8 RSZ (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGZ7262U)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAILGATE	Dented	1,235.20 FL	*1,235.20 FL
2	1	*TAILGATE GLASS MOULDING	Necessary	85.00 FL	*85.00 FL
3	1	*TAILGATE OUTER GARNISH	Cut / Cracked	250.40 FL	*250.40 FL
4	1	*TAILGATE EMBLEM	Necessary	45.30 FL	*45.30 FL
5	1	*TAILGATE NAMEPLATE STREAM	Necessary	53.20 FL	*53.20 FL
6	1	*TAILGATE NAMEPLATE RSZ	Necessary	72.30 FL	*72.30 FL
7	2	*TAILGATE ABSORBER LH/RH	Serviceable	425.20 FL	*- FL
8	1	*TAILGATE WIPER MOTOR	Serviceable	560.60 FL	*- FL
9	1	*TAILGATE LOCK	Distorted	283.30 FL	*283.30 FL
10	1	*TAILGATE CATCH	Serviceable	37.20 FL	*- FL
11	1	*TAILGATE TRIM BOARD	Serviceable	455.70 FL	*- FL
12	1	*TAILGATE WEATHER-STRIP	Necessary	150.60 FL	*150.60 FL
13	2	*TAILGATE STOPPER LH/RH	Not Necessary	25.00 FL	*- FL
14	1	*TAIL LAMP LH/RH	O/S Cracked	991.20 FL	*495.60 FL
15	1	*REAR BUMPER	Dented	860.70 FL	*860.70 FL
16	1	*REAR BUMPER TOW HOOK COVER	Serviceable	22.30 FL	*- FL
17	2	*REAR BUMPER SIDE BRACKET LH/RH	Cracked	91.40 FL	*91.40 FL
18	1	*REAR BUMPER BRACKET LH/RH	O/S Dented / N/S Serviceable	80.00 FL	*40.00 FL
19	1	*REAR PANEL	Repair	590.30 FL	*- FL
20	1	*REAR PANEL TOP COVER	Cracked	110.90 FL	*110.90 FL
21	1	*SPARE TYRE CARRIER	Serviceable	257.40 FL	*- FL
22	1	*EXHAUST SILENCER	Not Necessary	865.60 FL	*- FL
23	1	*EXHAUST CHROME TIP	Cut	113.70 FL	*113.70 FL
24	2	*EXHAUST MOUNTINGS	Not Necessary	44.60 FL	*- FL
25	1	*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
26	1	*SET TAILGATE INNER TRIM CLIPS	Necessary	50.00 FS	*30.00 FS
27	1	*SET REVERSE SENSOR	Cracked	300.00 FS	*200.00 FS
28	1	*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
29	1	*JOINT SEALANT	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,227.10	4,217.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,541.42	777.52
Total Parts (\$\$)	6,685.68	3,440.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK REAR LIGHTINGS & WIRINGS FOR PROPER FUNCTION	New	50.00	30.00
2	REMOVE & TRANSFER TAILGATE COMPONENTS	New	150.00	60.00
3	REMOVE & TRANSFER TAILGATE GLASS	New	180.00	120.00
4	DRILL HOLE & REPLACE REVERSE SENSORS	New	60.00	40.00
5	RENEW EXHAUST SILENCER	New	100.00	0.00
6	ANTI RUST PROOFING ON REAR DAMAGED PANELS	New	100.00	0.00
7	REMOVE & REINSTALL REAR UPHOLSTERIES TO ASSIST REPAIRS	New	120.00	60.00
8	TO REPLACE REAR DAMAGED PARTS. REPAIR, REFORM, REALIGN ALL DAMAGED AREA	New	1,400.00	600.00
9	TO CONDUCT SPRAY PAINTING ON REAR REPLACEMENT & AFFECTED AREAS	New	1,500.00	700.00
Gross Labour Cost (S\$)			3,660.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >