

22/03/2002

ASS. REC. BY:

REF: CS3/MSG/8015331/G167

Special Instruction:

Surveyor: Guo. Qiyang

ASSIGNMENT (Office)

From (Person): Pauline Thumof MSIGDate/Time: 22.11.2018

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLJ 8181MInsured: SGS 9696Aat Workshop m/s 6 speed AutowerkzTel: 8533 2934of 68 Kaki Blk Ave 6 # 02-05Policy No: A28867776QMXClaim No: 567840

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 18/08/2018CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 11:07am @ 23/8/18Person Contacted: Sun SunVehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate	Do Not Finalize
	<u>SLJ 8181M - NA / LPI 8015076 / h4</u>	<u>DOA: 18/8/18</u>
	<u>SGS 9696A - NA / LPI 8015076 / h4</u>	<u>DOA: 18/8/18</u>

4/9/18 Sum andledSubmit Lump Sum \$1650 (Red: 1300:44%)4 days

RECEIVED 03 JAN 2019

3/1/2019

1215  
Xml.

REF: MSG


4249F

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: \_\_\_\_\_  
at Workshop m/s 6 speed Autowerkz  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Rpt.: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: 3 days Res.: Yes or No  
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No. SLI8181M Tr Regn 08 Nov 2016  
Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_  
Make: Honda civic C.C. 1498  
Colour: black A/C: Insured / Std / NI / NA  
Sp. Reading: 48179 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: MRA HFC 166097000226  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: Good / Jammed / Leaked / Burnt or  
Brake: Good / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 235/40 R18  
R: 11  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Continental  
Front \_\_\_\_\_ Rear \_\_\_\_\_  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. \_\_\_\_\_ D.O.I. 23-08-18  
Survey held at W/S 1:530pm  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
\$2000 - \$3000

27/11/18 submit PRS Report.

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)  
☐ Interview (\$)  
☐ Tech. Invs (\$)  
☐ Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS, \$ SI

) Photos

) Others

TOTAL

120

10

130

Report Format :

Lump Sum / I.B.I.: (\$ )

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Aug 2018		23 Aug 2018 09:35 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <div style="float: right;">[Created by insurer]</div>									
Insured:		TAN TECK SAI, ID: S1711503J, Tel: +6596838885, Email: raymondtan8586@gmail.com							
Main Claimant:		TAN TAI JIA ( CHEN TAIJIA), ID: S8124249F							
Vehicle Reg. No.:		SLJ8181M	Date of Loss:	18/08/2018 13:00 - :59 [21 Months and 10 Days From LTA Reg Date (Man Yr)]					
Claim Type:		TP / 567840	Policy/Cover Note No.:	A2886776QMX (Comprehensive) Coverage: 24/12/2017 - 23/12/2018					
Vehicle Reg. No. (Insured):		SGS9696A	Policy No. (Claimant):						
		Excess:							
Repairer:		6 Speed Autowerkz Pte Ltd (HQ) 68 KAKI BUKIT AVENUE 6, #02-05 ARK@KB, 417896 Kaki Bukit - Tel: 85332934							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 26/11/2018]							
Driver/Custodian (Insured):		TAN TECK SAI (52 / Male), NRIC: S1711503J, Tel: +6596838885							
Adj Asg. Remarks:		liability: 100%. TP reject SJE -assign LKK Auto Consultants Pte Ltd. contact: Sun Sun (8533 2934)							
<b>ASSOCIATED MAIL RECEIVED</b> <div style="float: right;"> <a href="#">View All</a> <a href="#">Compose Case Mail</a> </div>									
<ul style="list-style-type: none"> <li>MSIG_SG (22/11/2018): Report Send Back Alerts - SLJ8181M (TP)</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <div style="float: right;"> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> </div>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

# Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters  
Blk 2 Rivervale Link, #09-02 Singapore 545040  
Tel/Fax: 6886 1106 Mobile: 9007 5234  
Email: constant\_as@yahoo.com.sg  
RCB No. 53138015K

## INVOICE


To: Tan Tai Jia  
Blk 208B Compassvale Lane  
#10-84  
Singapore 542208

Date : 02/10/2018  
Invoice No : IV18-10007/CAS

Particulars	Amount
Fee For Services Rendered In Respect Of:  Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle SLJ 8181M (Inclusive Of Photographs And Transport Charges)  Our reference : CAS/18-10/007	\$627.00
Total	\$627.00

E. & O.E

Constant Appraiser Services



Cheque Should Be Crossed And Made Payment To 'Constant Appraiser Services'

# Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant\_as@yahoo.com.sg

RCB No. 53138015K

## Automobile Inspection Report

To: Tan Tai Jia Blk 208B Compassvale Lane #10-84 Singapore 542208		Date : 02/10/2018  Reference No : CAS/18-10/007	
<b><u>General Information</u></b>			
Registration No.	: SLJ 8181M		
Accident Date	: 18/08/2018		
<b><u>Particulars of Damaged Vehicle</u></b>			
Colour	: Black	Make & Model : Honda Civic 1.5 Turbo	
Engine Capacity	: 1498 cc	Pre-Accident Condition : Good	
Mileage (KM)	: 048179	Engine No. : L15B71626355	
Chassis No.	: MRHFC1660GT000226	Steering : In Order	
Registration Date	: 08/11/2016	Brake : In Order	
<b><u>Tyre Condition</u></b>			
	Size	Make	Balance
R/H Front Tyre	235/40R18	CONTINENTAL	90%
L/H Front Tyre	235/40R18	CONTINENTAL	90%
R/H Rear Tyre	235/40R18	CONTINENTAL	90%
L/H Rear Tyre	235/40R18	CONTINENTAL	90%
<b><u>Inspection</u></b>			
Repairer	: 6 Speed Autowerks Pte Ltd 68 Kaki Bukit Avenue 6, #02-05 ARK@Kaki Bukit, Singapore 417896		
<b><u>Adjustment And Recommendation Cost Of Repair</u></b>			
Repairer's Estimate	: \$4,640.86		
Revised Amount	: \$2,950.00		
Less Excess	: -		
Nett Total	: \$2,950.00		
<b><u>Remarks</u></b>			
(A) Survey was done on 20/08/2018			
(B) Re-survey was done on 23/08/2018			
(C) Re-survey after repair was done on 27/08/2018			
(D) The survey was conducted entirely on WITHOUT PREJUDICE basis.			
(E) We have NOT given any instruction to authorize the repair of the vehicle.			

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Constant Appraiser Services

Vehicle No : SLJ 8181M

Our ref : CAS/18-10/007

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT – LIST ITEMS</u>					
1	1pc	Rear bumper	Dented/Deformed	661.28	661.28 ✓
2	1pc	Rear bumper lower lid	Grazed/Deformed	177.14	177.14 ✓
3	2pcs	Rear bumper reflector @ \$41.22	Serviceable	82.44	- X
4	2pcs	Rear bumper side garnish @ \$57.81	Deformed/Broken	115.62	115.62 ✓
5	1pc	Rear bumper reinforcement	Dented/Bent	171.42	171.42
6	4pcs	Rear bumper parking sensor @ \$171.00	Damaged	684.00	684.00 342 ✓
7	2pcs	Rear bumper retainer @ \$61.20	Necessary	122.40	122.40 ✓
8	2pcs	Rear bumper side bracket @ \$43.12	Necessary	86.24	86.24 ✓
9	1pc	Rear end panel	Dented	731.78	731.78 X R
		Less 20%		2,832.32 (566.46)	2,749.88 (549.97) 1676.1
		<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>	Sub total	2,265.86	2,199.91 1940.8
1	1set	Rear bumper clip	Necessary	55.00	55.00 30 ✓
		<u>LABOUR &amp; MISC. CHARGES</u>	Sub total	2,320.86	2,254.91
1		Labour to repair & replace damaged parts		800.00	500.00 300 ✓
2		Spray painting on affected area		800.00	400.00 350 ✓
3		Remove & refix rear trim board & garnish		100.00	80.00 30 ✓
4		Remove & refix reverse sensor		80.00	40.00 30 ✓
5		Check wiring system		60.00	20.00 ✓
6		To diagnose & reset system after repair		400.00	320.00 X
7		Spray anti rust on affected area		80.00	30.00 X
		Grand total		4,640.86	3,644.91
Recommended cost of lump sum repair (To its pre-accident condition)					2,950.00

2100.88  
20% = 1650

4 days

**Constant Appraiser Services**

Vehicle No : SLJ 8181M

Our ref : CAS/18-10/007


**Adjustment/Recommendations**

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$2,950.00** on a contractual basis. Under normal circumstances, the repair period would be about **5 (Five)** working days.

Yours faithfully,

**Constant Appraiser Services**



Lim Yong Tian (Sebastian)  
Licensed Appraiser  
Adv. Dip. In Mechanical Engineering (AUS)  
MSAAA

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Aug 2018		23 Aug 2018 09:35 <a href="#">Edit Adj Rpt</a>	<b>S\$1,650.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,650.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>















Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	TAN TECK SAI, ID: S1711503J, Tel: +6596838885, Email: raymondtan8586@gmail.com								
Main Claimant:	TAN TAI JIA ( CHEN TAIJIA), ID: S8124249F								
Vehicle Reg. No.:	SLJ8181M	Date of Loss:	18/08/2018 13:00 - :59 [21 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 567840	Policy/Cover Note No.:	A28867776QMX (Comprehensive) Coverage: 24/12/2017 - 23/12/2018						
Vehicle Reg. No. (Insured):	SGS9696A	Policy No. (Claimant):							
		Excess:							
Repairer:	6 Speed Autowerkz Pte Ltd (HQ) 68 KAKI BUKIT AVENUE 6, #02-05 ARK@KB, 417896 Kaki Bukit - Tel: 85332934								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 26/11/2018]								
Driver/Custodian (Insured):	TAN TECK SAI (52 / Male), NRIC: S1711503J, Tel: +6596838885								
Adj Asg. Remarks:	liability: 100%. TP reject SJE -assign LKK Auto Consultants Pte Ltd. contact: Sun Sun (8533 2934)								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>MSIG_SG (22/11/2018): Report Send Back Alerts - SLJ8181M (TP)</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*SLJ8181M (567840)  
[SGS9696A]  
TP  
TAN TAI JIA ( CHEN TAIJIA)  
Aug 18 2018 1:00PM  
[TAN TECK SAI]  
6 Speed Autowerkz Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)				Thumbnail		Print	
1	21/08/18 10:24	Accident Statement From:SC - Reg. No: SGS9696A, Claimant: TAN TECK SAI						Load HTM	
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail		Print	
1	28/08/18 11:45	General View						Load JPG <input checked="" type="checkbox"/>	
2	28/08/18 11:45	General View						Load JPG <input checked="" type="checkbox"/>	
3	28/08/18 11:45	General View						Load JPG <input checked="" type="checkbox"/>	
4	28/08/18 11:45	General View						Load JPG <input checked="" type="checkbox"/>	
5	28/08/18 11:45	General View						Load JPG <input checked="" type="checkbox"/>	
6	28/08/18 11:45	General View						Load JPG <input checked="" type="checkbox"/>	
7	28/08/18 11:45	General View						Load JPG <input checked="" type="checkbox"/>	
8	28/08/18 11:45	General View						Load JPG <input checked="" type="checkbox"/>	
9	28/08/18 11:45	General View						Load JPG <input checked="" type="checkbox"/>	
10	28/08/18 11:45	General View						Load JPG <input checked="" type="checkbox"/>	
11	28/08/18 11:45	General View						Load JPG <input checked="" type="checkbox"/>	
12	28/08/18 11:45	General View						Load JPG <input checked="" type="checkbox"/>	
13	28/08/18 11:45	General View						Load JPG <input checked="" type="checkbox"/>	
14	28/08/18 11:45	General View						Load JPG <input checked="" type="checkbox"/>	
15	28/08/18 11:45	General View						Load JPG <input checked="" type="checkbox"/>	
16	28/08/18 11:45	General View						Load JPG <input checked="" type="checkbox"/>	
17	28/08/18 11:45	General View						Load JPG <input checked="" type="checkbox"/>	
18	28/08/18 11:45	General View						Load JPG <input checked="" type="checkbox"/>	
19	28/08/18 11:45	General View						Load JPG <input checked="" type="checkbox"/>	
20	28/08/18 11:45	General View						Load JPG <input checked="" type="checkbox"/>	
21	28/08/18 11:45	Dismantled Parts						Load JPG <input checked="" type="checkbox"/>	
22	28/08/18 11:45	Dismantled Parts						Load JPG <input checked="" type="checkbox"/>	
23	28/08/18 11:45	Dismantled Parts						Load JPG <input checked="" type="checkbox"/>	
24	28/08/18 11:45	Dismantled Parts						Load JPG <input checked="" type="checkbox"/>	
25	28/08/18 11:45	Dismantled Parts						Load JPG <input checked="" type="checkbox"/>	
26	28/08/18 11:45	Dismantled Parts						Load JPG <input checked="" type="checkbox"/>	
27	28/08/18 11:45	Dismantled Parts						Load JPG <input checked="" type="checkbox"/>	
28	28/08/18 11:45	Dismantled Parts						Load JPG <input checked="" type="checkbox"/>	
29	28/08/18 11:45	Dismantled Parts						Load JPG <input checked="" type="checkbox"/>	
30	28/08/18 11:45	Dismantled Parts						Load JPG <input checked="" type="checkbox"/>	
31	28/08/18 11:45	Dismantled Parts						Load JPG <input checked="" type="checkbox"/>	
32	28/08/18 11:45	Dismantled Parts						Load JPG <input checked="" type="checkbox"/>	
33	28/08/18 11:45	Dismantled Parts						Load JPG <input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	28/08/18 11:45	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
35	28/08/18 11:45	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
36	28/08/18 11:45	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
37	28/08/18 11:45	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/08/18 10:21	TP PRI NOTICE	 Load PDF	
2	21/08/18 10:24	TP REJECT SJE - ASSIGN LKK.	 Load PDF	
3	21/08/18 10:24	SLM7706R e-file report From: SC - Reg. No: SGS9696A, Claimant: TAN TECK SAI	 Load PDF	
4	21/08/18 10:24	SHD4504X e-file report From: SC - Reg. No: SGS9696A, Claimant: TAN TECK SAI	 Load PDF	
5	21/08/18 10:24	SLJ8181M e-file report From: SC - Reg. No: SGS9696A, Claimant: TAN TECK SAI	 Load PDF	
6	21/08/18 10:24	SLA6389S e-file report From: SC - Reg. No: SGS9696A, Claimant: TAN TECK SAI	 Load PDF	
7	21/11/18 12:36	SURVEY REPORT.	 Load PDF	
8	21/11/18 12:37	SURVEY PHOTOS	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/01/19 14:38	PRS Invoice	 Load PDF	
2	03/01/19 14:39	Colour Photo	 Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18015331/GTBE2-1

Date: 03/01/2019

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A28867776QMX  
 Claimant Vehicle No: SLJ8181M Insured Vehicle No: SGS9696A  
 Date of Loss: 18/08/2018 Nature of Claim: TP Claim No: 567840

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SLJ8181M**  
 Make & Model: HONDA CIVIC, 1.5 TURBO VTI-S SR (A) Engine No: L15B71626355  
 Reg. Date: 08/11/2016 (Man. Year: 2016) Chassis No: MRHFC1660GT000226  
 Colour: Black Odometer: 48179 km  
 Engine Capacity: 1498 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 235/40 R18 Rear Tyre Size: 235/40 R18  
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm  
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,320.86	1,370.88	949.98	40.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	730.00	1,590.00	68.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,640.86</b>	<b>2,100.88</b>	<b>2,539.98</b>	<b>54.73</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,650.00</b>		
<b>Nett Amount (S\$)</b>	<b>4,640.86</b>	<b>1,650.00</b>	<b>2,990.86</b>	<b>64.45</b>

## INSPECTION

Date of Assignment: 23/08/2018  
 Date Inspected: 23/08/2018 Inspected At: 6 Speed Autowerkz Pte Ltd (HQ)  
 68 KAKI BUKIT AVENUE 6, #02-05  
 ARK@KB  
 Singapore 417896

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jan 2019)
<b>Parts:</b>	143	HONDA CIVIC 1.5 TURBO VTI-S SR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLJ8181M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	661.28 FL	*661.28 FL
2	1		*REAR BUMPER LOWER LID	Grazed / Deformed	177.14 FL	*177.14 FL
3	2		*REAR BUMPER REFLECTOR	Serviceable	82.44 FL	*- FL
4	2		*REAR BUMPER SIDE GARNISH	Deformed / Broken	115.62 FL	*115.62 FL
5	1		*REAR BUMPER REINFORCEMENT	Dented / Bent	171.42 FL	*171.42 FL
6	1		*REAR BUMPER PARKING SENSOR (4PCS)	Damaged-2pcs only	684.00 FL	*342.00 FL
7	2		*REAR BUMPER RETAINER	Necessary	122.40 FL	*122.40 FL
8	2		*REAR BUMPER SIDE BRACKET	Necessary	86.24 FL	*86.24 FL
9	1		*REAR END PANEL	Repair	731.78 FL	*- FL
10	1		*SET REAR BUMPER CLIP	Necessary	55.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,887.32</b>	<b>1,706.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>566.46</b>	<b>335.22</b>
<b>Total Parts (\$\$)</b>	<b>2,320.86</b>	<b>1,370.88</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REPAIR & REPLACE DAMAGED PARTS	New	800.00	300.00
2	SPRAY PAINTING ON AFFECTED AREA	New	800.00	350.00
3	REMOVE & REFIX REAR TRIM BOARD & GARNISH	New	100.00	30.00
4	REMOVE & REFIX REVERSE SENSOR	New	80.00	30.00
5	CHECK WIRING SYSTEM	New	60.00	20.00
6	TO DIAGNOSE & RESET SYSTEM AFTER REPAIR	New	400.00	0.00
7	SPRAY ANTI RUST ON AFFECTED AREA	New	80.00	0.00
Gross Labour Cost (S\$)			2,320.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >